

State of California—Health and Human Services Agency California Department of Public Health



Food and Drug Branch – Device Recalls

## CALIFORNIA DEVICE RECALL INFORMATION SHEET

Philips North America Recalls Brightview Gamma Camera For Component Failure Resulting In The Detector Unexpectedly Falling

| Recall Date | Product Description   | Recalling Firm  | Recall Reason   |
|-------------|---|---|---|
| 2/7/2023    | Brightview, Gamma Camera<br>System<br>Model Nos.: 6-digit format<br>882480; 12-digit format<br>453560279781 453560279791<br>453560279801; 4x4 digit<br>format 2170-3000A 2170-<br>3001A 2170-3002A 2170-<br>3003A | PHILIPS NORTH<br>AMERICA<br>Cambridge,<br>Massachusetts | Detector may unex-<br>pectedly fall due to<br>component failure. If<br>the detector is posi-<br>tioned below center<br>of gantry, there is<br>potential for abra-<br>sion, contusion, lace-<br>ration, and/or fract-<br>ure to patient's lower<br>limbs, as well as<br>interruption to normal<br>system operation. If<br>detector is positioned<br>above center of<br>gantry, there may be<br>an interruption to nor-<br>mal system opera-<br>tion. |
| 2/7/2023    | Brightview XCT, Gamma<br>Camera For Spect<br>Model Nos.: 6-digit format<br>882482;12-digit format<br>453560462131 453560749161  | PHILIPS NORTH<br>AMERICA<br>Cambridge,<br>Massachusetts | Detector may unex-<br>pectedly fall due to a<br>component failure. If<br>the detector is posi-<br>tioned below center<br>of gantry, there is<br>potential for abra-<br>sion, contusion, lace-<br>ration, and/or fract-<br>ure to patient's lower<br>limbs, as well as<br>interruption to normal<br>system ope-ration. If<br>detector is positioned<br>above center of<br>gantry, there may be<br>interruption to nor-<br>mal system opera-<br>tion. |

| 2/7/2023 Brightview X, Gamma Camera<br>For Spect<br>Model Nos.: 6-digit format<br>882478; 12-digit format<br>453560824741 453560829261 | Philips North<br>America<br>Cambridge,<br>Massachusetts | Detector may unex-<br>pectedly fall due to a<br>component failure. If<br>the detector is posi-<br>tioned below center<br>of gantry, there is a<br>potential for abra-<br>sion, contusion, lace-<br>ration, and/or fract-<br>ure to the patient's<br>lower limbs, as well<br>as an interruption to<br>normal system ope-<br>ration. If detector is<br>positioned above<br>center of gantry,<br>there may be an<br>interruption to nor-<br>mal system opera-<br>tion. |
|--|---|---|
|--|---|---|

| Recall<br>Class | Product Identification  | Distribution            | Affected Dates              |
|-----------------|---|-------------------------|-----------------------------|
| 1               | Brightview, Gamma Camera<br>System<br>All serial numbers are affected.<br>No UDI-DI available for this<br>product.        | 302 Units<br>Nationwide | December, 2023<br>and prior |
| I               | Brightview XCT, Gamma<br>Camera For Spect<br>All serial numbers are affected.<br>No UDI-DI available for this<br>product. | 106 Units Nationwide    | December, 2023<br>and prior |
| Ι               | BrightView X, Gamma Camera<br>For Spect<br>All serial numbers are affected.<br>No UDI-DI available for this<br>product.   | 56 Units Nationwide     | December, 2023<br>and prior |

FOR ADDITIONAL INFORMATION, PLEASE VISIT THE FDA WEBSITE <u>Brightview</u>, <u>BrightView XCT</u>, <u>BrightView X</u>

CDPH Food and Drug Branch MS 7602 ● P.O. Box 997435 ● Sacramento, CA 95899-7435 (916) 650-6500 ● (916) 650-6650 FAX Internet Address: <u>www.cdph.ca.gov</u>

