RECEIVED
CA DEPT OF PUBLIC HEALTH
FORM APPROVED

FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD			•••	8 2019	COM	SURVEY PLETED
	·	555585	B. WING	_	LICENS	ING & C	ERTIFICE (ATION DFF10&	l 3/2019
NAME OF F	PROVIDER OR SUPPLIER			5	LICENS STREET AD SAMES, CH	, , इसिस्, इ	P CODE		
THE SHO	RES POST-ACUTE		-	2	2828 MEADOWLARK SAN DIEGO, CA 92	DRIVE 2123			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SCIDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER (EACH CORR CROSS-REFER	ECTIVE ACT	HE APPROP	BE	(X5) COMPLETION DATE
E 000	Initial Comments		.E (000					
	Surveyor: 40325				*				
	Department of Pub Emergency Prepar The findings are in	ets the findings of the California lic Health, during an edness recertification survey, accordance with 42 Code of is (CFR) 483.73, Requirement et (LTC) Facilities.							
	The facility is in sul Code of Federal Ro	ostantial compliance with 42 egulations (CFR) 483.73, ong Term Care (LTC) Facilities.							
	Representing the C Health: 40325	California Department of Public							
K 000	Census = 280 INITIAL COMMEN	TS	K	000					
	Surveyor: 40325								
	K3 BUILDING: 01 K6 PLAN APPROV K7 SURVEY UNDE	'AL: 1/31/1994 ER: 2012 EXISTING	•						
	LEVEL OPEN TO (LAUNDRY, MAINT STORAGE) & UPP	E: ONE STORY + LOWER GRADE (KITCHEN, ENANCE SHOP AND PER LEVEL (MEZZANINE AND TRUCTION TYPE V (111), RED.							
	Department of Pub Life Safety Code re findings are in acco Federal Regulation	ots the findings of the California lic Health, during an annual ecertification survey. The ordance with 42 Code of is (CFR) §483.90(a)(b)(c)(j),							
LABORATOR	Y PIRECTOR'S OR PROVI	DER/SUPPLIER REPRESENTATIVE'S SIG	NATURE		TIT	LE			(X6) DATE

Any deliciency statement ending with an asterisk (*) denotes a deliciency which the institution may be excused from correcting providing it is determined that other salegoards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Approved 11/22/2019 per Jose Gonzalez, SSM I

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUI A. BUILD		E CONSTRUCTION 02		SURVEY PLETED
		555585	B. WING			10/	23/2019
•	PROVIDER OR SUPPLIER DRES POST-ACUTE			2	TREET ADDRESS, CITY, STATE, ZIP CODE 828 MEADOWLARK DRIVE 6AN DIEGO, CA 92123		٠
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRÉCEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 321 SS=D	National Fire Prote Life Safety Code, 2 Health Care Faciliti Representing the C Health: 40325 The facility is not in 42 CFR §483.90 for Census = 280 Hazardous Areas - CFR(s): NFPA 101 Hazardous Areas - Hazardous areas a having 1-hour fire r fire rated doors) or system in accordar When the approve system option is us separated from oth partitions and door Doors shall be self and permitted to he protective plates th from the bottom of Describe the floor hazardous areas to 19.3.2.1, 19.3.5.9 Area Separation N/ a. Boiler and Fuel- b. Laundries (large c. Repair, Mainten	ction Association (NFPA) 101 - 2012 Edition, and NFPA 99 - 2012 Edition. California Department of Public California Care Facilities. Enclosure Enclosure Enclosure Enclosure Enclosure A creating (with 3/4 hour an automatic fire extinguishing nee with 8.7.1 or 19.3.5.9. d automatic fire extinguishing sed, the areas shall be ner spaces by smoke resisting in accordance with 8.4closing or automatic-closing ave nonrated or field-applied nat do not exceed 48 inches the door. and zone locations of nat are deficient in REMARKS. Automatic Sprinkler A Fired Heater Rooms or than 100 square feet) ance, and Paint Shops oms (exceeding 64 gallons)		321	This Plan of Correction is being submitted in compliance with specific regulatory requirements. Neither its completion nor content is to be construed as an admission by this provider of the validity of any finding or citation contained herein. K321 How corrective action(s) will be accomplis for those residents found to have been affected by the deficient practice. The stone was immediately removed from propping the door to the Laundry/Emerger Water Storage Room by the Maintenance Director on 10/23/2019. How the facility will identify other resident having the potential to be affected by the same deficient practice and what correctinaction will be taken. No other residents were identified to be affected by the deficient practice.	, ncy nts	11/8/19

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		E CONSTRUCTION 02		SURVEY PLETED
		555585	B. WING			10/2	23/2019
	PROVIDER OR SUPPLIER DRES POST-ACUTE	,		28	TREET ADDRESS, CITY, STATE, ZIP CODE B28 MEADOWLARK DRIVE AN DIEGO, CA 92123		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	D BE	(XS) COMPLETION DATE
K 351	(over 50 square ferg. Laboratories (if of Hazard - see K322 This REQUIREME by: Surveyor: 40325 Based on observatifialed to maintain the evidenced by a selpropped open by a cause smoke and open door and affer This affected the ENFPA 101, Life Sa 19.3.6.3.10* Doors devices other than door is pushed or principle of the ENFPA 101, Life Sa 19.3.6.3.10* Doors devices other than door is pushed or principle. On 10/23/19, during Maintenance Directive observed. At 9:49 a.m., the directive observed. At 9:49 a.m., the directive observed of the room in square feet and conductible mater water storage in pilotte of the exit conference of the exit conference of the conference of th	cons) rage Rooms/Spaces et) classified as Severe) NT is not met as evidenced cion and interview, the facility heir hazardous areas. This was f-closing door which was stone. During a fire, this could flames to pass through the ect residents, visitors, and staff. clasement. fety Code, 2012 Edition. Is shall not be held open be those that release when the coulled. g a facility tour with the ector (MD), the hazardous areas coor to the Laundry/Emergency m was propped open by a neasured approximately 440 contained laundry appliances and rials as well as emergency astic containers. acknowledged the finding at		321	What measures will be put into place or a systemic changes the facility will make to ensure that the deficient practice does no occur. The Maintenance Director conducted an It Service on 10/24/2019 with the Maintena Housekeeping, and Laundry staff regardin hazards and regulations of propping doors with any object. How the facility plans to monitor its performance to make sure solutions are sustained. The facility must develop a plaensuring that correction is achieved and sustained. This plan must be implemente and the corrective action evaluated for it effectiveness. The POC is integrated into quality assurance system. The Maintenance Director will make roundaily to ensure that the door is not being propped open by any object. In addition, the Maintenance Director will post a sign on the door informing staff that the door cannot propped open by any object. Results will be presented to the QA&A committee month for the following three months. If there are findings during the three consecutive meetings, the audits will be discontinued, there are findings, the audits with findings be continued for three consecutive month until there are no findings.	ont n- nce, g the s in for d s the de	

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL .A. BUILD		E CONSTRUCTION 02		E SURVEY IPLETED
		555585	B. WING			10/	23/2019
	PROVIDER OR SUPPLIER PRES POST-ACUTE			2	STREET ADDRESS, CITY, STATE, ZIP CODE 1828 MEADOWLARK DRIVE SAN DIEGO, CA 92123		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPROPROPROPROPROPROPROPROPROPROPROPRO	BE	(X5) COMPLETION DATE
K 353 SS=D	CFR(s): NFPA 101 Sprinkler System - Automatic sprinkler inspected, tested, a with NFPA 25, Star Testing, and Mainta Protection Systems maintenance, inspendintained in a secavailable. a) Date sprinkler: b) Who provided c) Water systems Provide in REMAR any non-required of system. 9.7.5, 9.7.7, 9.7.8, This REQUIREME by: Surveyor: 40325 Based on observatifailed to maintain till system. This was evithin 18 inches of could cause a malifand affect resident affected the Basen NFPA 101 - Life Satings be protected througs upervised automatics.	Maintenance and Testing r and standpipe systems are and maintained in accordance hadrof for the Inspection, alning of Water-based Fire s. Records of system design, ection and testing are cure location and readily system last checked system last checked system test Supply source KS information on coverage for r partial automatic sprinkler and NFPA 25 NT is not met as evidenced ion and interview, the facility heir automatic sprinkler evidenced by material stored a sprinkler. During a fire, this function of the sprinkler system is, visitors, and staff. This nent. If ety Code, 2012 Edition containing nursing homes shall ghout by an approved, atic sprinkler system in ection 9.7, unless otherwise		353	How corrective action(s) will be accomplist for those residents found to have been affected by the deficient practice. The items blocking the sprinkler inside the walk-in freezer located in the kitchen were removed by the Dietary Supervisor and the Dietary staff on 10/23/2019. How the facility will identify other residenthaving the potential to be affected by the same deficient practice and what correctivaction will be taken. No other residents were identified to be affected by the deficient practice. On 10/24/2019, the Maintenance Director applied red tape measuring 18" around the sprinkler to alert the staff not to block the sprinkler with any boxes and/or food.	nts ve	11/8/19

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUİLD		E CONSTRUCTION 02		E SURVEY (PLETED
		555585	B. WING			10,	/23/2019
	PROVIDER OR SUPPLIER DRES POST-ACUTE			2	ETREET ADDRESS, CITY, STATE, ZIP CODE 1828 MEADOWLARK DRIVE SAN DIEGO, CA 92123		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS;REFERENCED TO THE APPROVIDENCY)	D BE	(X5) COMPLETION DATE
K 353	9.7.5 Maintenance sprinkler and stand Code shall be inspering accordance with Inspection, Testing Water-Based Fire In NFPA 25, Standard and Maintenance of Systems, 2011 Edit 5.2.1.1* Sprinklers floor level annually. 5.2.1.1.1* Sprinklers floor level annually. 5.2.1.1.1* Sprinkler leakage; shall be from the installed in the cupright, pendent, on 5.2.1.2* The minim installation standar sprinkler deflectors 5.2.1.3 Stock, furnithe sprinkler deflectors 5.2.1.3 Stock, furnithe sprinkler deflectors 5.2.1.3 Stock, furnithe sprinkler deflectors 5.2.1.3 Continuous obstructions less the below the sprinkler pattern from fully defended by the sprinkler accordance with the special requirement section 8.12 so the	and Testing. All automatic pipe systems required by this ected, tested, and maintained NFPA 25, Standard for the and Maintenance of Protection Systems. I for the Inspection, Testing, of Water-Based Fire Protection tion shall be inspected from the shall be inspected from the ect of corrosion, foreign ad physical damage; and shall correct orientation (e.g., or sidewall), um clearance required by the dishall be maintained below all shall be maintained by the the installation standard shall of the Installation of Sprinkler tion ons to Sprinkler Discharge		353	What measures will be put into place or systemic changes the facility will make to ensure that the deficient practice does noccur. The Dietary Supervisor conducted an In-Service on 10/24/2019 to the Dietary staf regarding the safety violations of blocking sprinkler systems. How the facility plans to monitor its performance to make sure solutions are sustained. The facility must develop a placensuring that correction is achieved and sustained. This plan must be implemented and the corrective action evaluated for it effectiveness. The POC is integrated into quality assurance system. The Dietary Supervisor will check the wall freezer daily for three consecutive month ensure that there are no boxes or other objects blocking the sprinkler. Results will presented to the QA&A committee month for the following three months. If there are findings during the three consecutive meetings, the audits will be discontinued, there are findings, the audits with finding be continued for three consecutive month until there are no findings.	of of f g the an for ed ts the c-in s to l be nly re no	

	F CORRECTION	IDENTIFICATION NUMBER:	A, BUILD		02		PLETED
		555585	B. WING			10/2	23/2019
	PROVIDER OR SUPPLIER DRES POST-ACUTE			2	STREET ADDRESS, CITY, STATE, ZIP CODE 2828 MEADOWLARK DRIVE SAN DIEGO, CA 92123		
(X4) ID PREFIX TAG	(EACH DEFICIENC	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	DBE	(X5) COMPLETION DATE
K 353	chords, pipes, colu 8.5.5.3 * Obstruction Discharge from Re Continuous or none interrupt the water more than 18 in. (4 deflector in a mann reaching the protect 8.5.5.3. 8.5.5.3.1 Sprinklers obstructions over 4 decks, open grate overhead doors. 8.5.5.3.2 Sprinklers obstructions that at conference tables. 8.5.5.3.3 * Sprinkle gratings shall be of storage type or oth discharge of overh 8.5.6 * Clearance 8.5.6.1 * Unless the 8.5.6.3, 8.5.6.4, or between the deflect be 18 in. (457 mm) Findings: On 10/23/19, durin	mns, and fixtures. ons That Prevent Sprinkler aching the Hazard. continuous obstructions that discharge in a horizontal plane 57 mm) below the sprinkler her to limit the distribution from oted hazard shall comply with s shall be installed under fixed if (1.2 m) wide such as ducts, flooring, cutting tables, and s shall not be required under re not fixed in place such as ers installed under open if the intermediate level/rack erwise shielded from the ead sprinklers. to Storage. e requirements of 8.5.6.2, 8.5.6.5 are met, the clearance stor and the top of storage shall		353			
	Basement, the spri was blocked by sh and other frozen fo side-pendent type within one inch of i	Kitchen, located in the inkler inside the walk-in freezer elved containers of ice cream bods. The sprinkler was a and the foods were stored t. The MD said when kitchen the freezer, they stored the sprinkler.					

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUI A. BUILC		E CONSTRUCTION 02		E SURVEY MPLETED
		555585	B. WING			10.	/23/2019
	PROVIDER OR SUPPLIER DRES POST-ACUTE			2	TREET ADDRESS, CITY, STATE, ZIP CODE 828 MEADOWLARK DRIVE SAN DIEGO, CA 92123		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TÁG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 353			K	353			
K 920 SS=E	the exit conference Electrical Equipme	nt - Power Cords and Extens	K	920	How corrective action(s) will be accomplis for those residents found to have been affected by the deficient practice.	sned	
	Extension Cords Power strips in a p used for componer patient-care-relater (PCREE) assemble by qualified person 10.2.3.6. Power st may not be used for electronics), excep rooms that do not in PCREE meet UL 1 strips for non-PCR (outside of vicinity) care rooms, power standards. All power precautions. Extension cords us immediately upon which it was install 10.2.4. 10.2.3.6 (NFPA 99 (NFPA 70), 590.3(I This REQUIREME by: Surveyor: 40325 Based on observat failed to maintain elevidenced by the use	atient care vicinity are only nts of movable delectrical equipment es that have been assembled and meet the conditions of trips in the patient care vicinity or non-PCREE (e.g., personal of in long-term care resident use PCREE. Power strips for 363A or UL 60601-1. Power EE in the patient care rooms meet UL 1363. In non-patient of strips meet other UL ver strips are used with general nation cords are not used as a wiring of a structure. Seed temporarily are removed completion of the purpose for led and meets the conditions of the purpose for led and meets as evidenced to nand interview, the facility electrical safety. This was use of an extension cord, by were electrically overloaded,			On 10/23/2019, the Maintenance Director disconnected the coffeemaker and the extension cord from the duplex receptacle outlet and removed the extension cord from the Social Services office. On 10/23/2019, the Maintenance Director disconnected the microwave oven in the Services office from the power strip and connected it directly into the duplex receptacle wall outlet. On 10/23/2019, the Maintenance Director disconnected the refrigerator, coffeemake and microwave oven from the power strip connected all the appliances found in the Director of Nurses office directly to the dureceptacle outlet. On 10/23/2019, the Maintenance Director disconnected the computer monitor cord in the Tripp-Lite power strip, releasing the tension that was causing the power strip to suspended mid-air.	e om cocial er, and plex from	11/8/19

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTII A. BUILDIN	PLE CONSTRUCTION G 02		TE SURVEY MPLETED
		555585	B. WING		10	/23/2019
	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	STREET ADDRESS, CITY, STATE, ZI 2828 MEADOWLARK DRIVE SAN DIEGO, CA 92123 PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO T K920 DEFICIENCE	CORRECTION ION SHOULD BE HE APPROPRIATE	(X5) COMPLETION DATE
K 920	electrical device. T smoke and flames visitors, and staff. compartments. NFPA 99, Health C Edition 10.2.3.5 Cord Stra 10.2.3.5.1 Cord st the attachment of the southeast of the southeast of the southeast of the supply power to plus or more power flexible cord shall I supply power to plus or more power flexible cord shall I supply power to plus or movable equipment assistant of the equipment assistant of the connected to the connected to the opercent of the ampsupplying the outlet (3) The ampacity of accordance with N Code. (4)* The electrical assembly is regular (5)* Means are emadditional devices cannot be connected.	ip tensioned by the cord of an his could cause sparking, and could affect residents, This affected two of 16 smoke are Facilities Code, 2012 in Relief. Train relief shall be provided at the power cord to the appliance I stress, either pull, twist, or nitted to internal connections. I relief molded onto the cord the jacket and shall be of al. Dutlet Connection. The receptacles supplied by a be permitted to be used to ug-connected components of a not assembly that is rack-, table-, mounted, provided that all of itions are met: Is are permanently attached to embly. The ampacity of all appliances outlets does not exceed 75 pacity of the flexible cord	K 92	How the facility will identify o	teted by the hat corrective fied to be ce. o place or what will make to cice does not	

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILDI		E CONSTRUCTION 02		SURVEY PLETED
		555585	B. WING			10/	23/2019
	PROVIDER OR SUPPLIER DRES POST-ACUTE		·	2	TREET ADDRESS, CITY, STATE, ZIP CODE 828 MEADOWLARK DRIVE AN DIEGO, CA 92123		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	×	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP K920 DEFICIENCY)	BE	(X5) COMPLETION DATE
K 920	400.10 Pull at Joint Flexible cords and devices and to fittin transmitted to joints. Findings: On 10/23/19, during the electrical equipment and cord, who duplex receptacle is services staff connumbers. At 10:11 a.m., all office, a microwave devices were connumbers which was the receptacle wall out measuring electric equipment of the ror amps. The ampinot be determined. 12 A. The maximum The power strip was minimum of 4 A. Selectrical appliance way for five years possible to make the connected to was then connected to was then connected.	Electrical Code, 2011 Edition: its and Terminals. cables shall be connected to higs so that tension is not is or terminals. g a facility tour with the MD, ment was observed. I the Social Services office, a if was connected to an ich was then connected to the wall outlet. The MD said social ected the extension cord. I so in the Social Services oven, fan, and two electronic ected to a Tripp-Lite power en connected to the duplex let. The ampere [unit current flow drawn by microwave was 13 A [amperes pere of the other devices could and the power strip was rated at impermissible is 9 A [12 x .75]. Its therefore overloaded by a ocial Services staff said the es had been connected that	К	120	How the facility plans to monitor its	d sthe all perly l-air.	

STATEMENT	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUI A. BUILD		E CONSTRUCTION 02		E SURVEY IPLETED
		555585	B. WING	·		10/	23/2019
	PROVIDER OR SUPPLIER PRES POST-ACUTE			28	TREET ADDRESS, CITY, STATE, ZIP CODE 828 MEADOWLARK DRIVE AN DIEGO, CA 92123		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 923 SS=D	refrigerator was 1.7 The power strip was permissible is 11.2 was therefore over said the devices harecently. 4. At 10:37 a.m., at computer, monitor, to a Tripp-Lite power connected to the day the power strip was tensioned by the content of the MD said works and the power strip. The Administrator at the exit conference Gas Equipment - CCFR(s): NFPA 101 Gas Equipment - CCCFR(s): NFPA 101	A. The devices totaled 24.5 A. Is rated at 15 A. The maximum 5 A [15 x .75]. The power strip loaded by 13.25 A. The DON ad been connected that way a thurses Station Two, a and adapter were connected er strip, which was then uplex receptacle wall outlet. It is suspended mid-air, ord of the computer monitor. It is suspended the power supply to got suspended. Cylinder and Container Storage uply the constructed, and dance with 5.1.3.3.2 and ubic feet are designed, constructed, and dance with flammables, and are mbustibles by 20 feet (5 feet if closed in a cabinet of construction having a minimum on rating.		920	How corrective action(s) will be accomplised for those residents found to have been affected by the deficient practice. A "No Smoking" sign was posted in the oxycylinder storage located in Station 3 by the Maintenance Director on 10/23/2019. A "No Smoking" sign was posted in the oxycylinder storage located in Station 2 by the Maintenance Director on 10/23/2019. How the facility will identify other resider having the potential to be affected by the same deficient practice and what correctinaction will be taken. No other residents were identified to be affected by the deficient practice.	/gen /gen e	11/8/19

STATEMENT	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUI A. BUILD		E CONSTRUCTION 02	(X3) DATI	E SURVEY PLETED
		555585	B. WING	·	····	10/	23/2019
	PROVIDER OR SUPPLIER DRES POST-ACUTE			2	TREET ADDRESS, CITY, STATE, ZIP CODE 828 MEADOWLARK DRIVE SAN DIEGO, CA. 92123		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 923	care areas with an or equal to 300 cub stored in an enclos handled with preca A precautionary sige each door or gate of where the sign inclininum "CAUTIC STORED WITHIN Storage is planned of which they are rempty cylinders and cylinders. When faintegral pressure gronsidered empty are marked to avoid in the open are produced in the open are produced in the open are produced by: Surveyor: 40325 Based on observation failed to maintain the evidenced by oxyglacked required sign chance of fire and and staff. This affect compartments. Findings: On 10/23/19, during the gas cylinder staff. At 9:59 a.m., at Storage room did to the staff.	for immediate use in patient aggregate volume of less than bic feet are not required to be ure. Cylinders must be utions as specified in 11.6.2. In readable from 5 feet is on of a cylinder storage room, udes the wording as a DN: OXIDIZING GAS(ES) NO SMOKING." so cylinders are used in order eceived from the supplier. It is esegregated from full acility employs cylinders with auge, a threshold pressure is established. Empty cylinders d confusion. Cylinders stored tected from weather. 3, 11.3.4, 11.6.5 (NFPA 99) NT is not met as evidenced ion and interview, the facility heir gas equipment. This was en cylinder rooms which mage. This could increase the could affect residents, visitors, cted three of 16 smoke g a facility tour with the MD, orage was observed. Station 3, the Oxygen Cylinder not have a sign which stated, ZING GAS(ES) STORED		923	What measures will be put into place or visystemic changes the facility will make to ensure that the deficient practice does not occur. The Maintenance Director will conduct monthly rounds to ensure that all safety hazard signs are placed properly and accordingly. How the facility plans to monitor its performance to make sure solutions are sustained. The facility must develop a platensuring that correction is achieved and sustained. This plan must be implemente and the corrective action evaluated for its effectiveness. The POC is integrated into equality assurance system. The Maintenance Director will conduct monthly rounds for three consecutive most to ensure that all safety hazard signs are placed properly and accordingly. Results when the following three months. If there are findings during the three consecutive meetings, the audits will be discontinued, there are findings, the audits with findings be continued for three consecutive month until there are no findings.	n for d s the nths vill nthly e no lf will s	Dogs. 11 of 15

ND PLAN OF COR	FICIENCIES	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1 ' '		ONSTRUCTION	(X3) DATE	SURVEY PLETED
	,		A. BUILOI				_ ,
NAME OF PROVID	DER OR SUPPLIER	555585	B. WING		ET ADDRESS, CITY, STATE, ZIP GODE	10/2	23/2019
	POST-ACUTE			2828	MEADOWLARK DRIVE I DIEGO, CA 92123		
	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	K	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROPRIES OF THE	D BE	(X5) COMPLETION DATE
WIT 2. A Cylin state STC The outs	nder Storage ro ed, CAUTION: DRED WITHIN MD said the side of the door	KING. It Station 2, the Oxygen from did not have a sign which OXIDIZING GAS(ES) NO SMOKING. Igns were missing from the res. acknowledged the findings at	К 9	23	DEFICIENCY)		