PRINTED: 08/26/2024 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
555319		B. WING			08/13/2024		
NAME OF PROVIDER OR SUPPLIER SUNRISE POST ACUTE				STREET ADDRESS, CITY, STATE, ZII 3476 W. WILSON ST. BANNING, CA 92220	P CODE		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	((EACH CORRECTIVE A CROSS-REFERENCED T	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)		
E 000	Initial Comments		E 0	000			
K 000	Emergency Prepared The findings are in ac Federal Regulations (for Long Term Care (I The facility is in subst	t of Public Health, during an ness recertification survey. Scordance with 42 Code of CFR) 483.73, Requirement LTC) Facilities. antial compliance with 42 Term Care (LTC) Facilities.	К 0	000			
	Department of Public Life Safety Code rece findings are in accord Federal Regulations (National Fire Protecti Life Safety Code, 201 Health Care Facilities	the findings of the California Health, during an annual ertification survey. The ance with 42 Code of CFR) §483.90(a)(b)(c)(j), on Association (NFPA) 101 - 2 Edition, and NFPA 99 -					
SS=E	42 CFR §483.90 for L Alcohol Based Hand CFR(s): NFPA 101	ong Term Care Facilities. Rub Dispenser (ABHR) SUPPLIER REPRESENTATIVE'S SIGNATURE	K 3	TITLE		8/23/24 (X6) DATE	

Electronically Signed 08/23/2024

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

PRINTED: 08/26/2024 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTI A. BUILDIN	ULTIPLE CONSTRUCTION DING 02		(X3) DATE SURVEY COMPLETED		
55531		555319	B. WING _			08/13/2024		
NAME OF PROVIDER OR SUPPLIER SUNRISE POST ACUTE				STREET ADDRESS, CITY, STATE, ZIP CODE 3476 W. WILSON ST. BANNING, CA 92220	Ē			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF COF (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE		
K 325	Continued From page	e 1	K 3	25				
	Alcohol Based Hand Rub Dispenser (ABHR) ABHRs are protected in accordance with 8.7.3.1, unless all conditions are met: * Corridor is at least 6 feet wide * Maximum individual dispenser capacity is 0.32 gallons (0.53 gallons in suites) of fluid and 18 ounces of Level 1 aerosols * Dispensers shall have a minimum of 4-foot horizontal spacing * Not more than an aggregate of 10 gallons of fluid or 135 ounces aerosol are used in a single smoke compartment outside a storage cabinet, excluding one individual dispenser per room * Storage in a single smoke compartment greater than 5 gallons complies with NFPA 30 * Dispensers are not installed within 1 inch of an ignition source * Dispensers over carpeted floors are in sprinklered smoke compartments * ABHR does not exceed 95 percent alcohol * Operation of the dispenser shall comply with Section 18.3.2.6(11) or 19.3.2.6(11) * ABHR is protected against inappropriate access 18.3.2.6, 19.3.2.6, 42 CFR Parts 403, 418, 460, 482, 483, and 485 This REQUIREMENT is not met as evidenced by: Based on observation and interview, the facility failed to follow the installation requirements for Alcohol based hand rub dispenser (ABHR). This was evidenced by ABHR's in the facility being installed over an ignition source. This could result in the ABHR leaking alcohol over the ignition source and result in ignition of a fire. This affected 18 of 59 residents in two of two smoke compartments.			Alcohol based hand rub dispet (ABHR) removed and reinstall regulation specification (Dispet to be installed within 1 inch of source) on 8/13/2024. Inservice of maintenance staff conducted on Thursday 8/15/2 cover specific details of regular requirements for placement of prevent any future error or fail regulation guidelines.	led to enser are not an ignition f was 2024 to ation f ABHR to			

PRINTED: 08/26/2024 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED		
	555319 B. WING			08/13/2024			
NAME OF PROVIDER OR SUPPLIER SUNRISE POST ACUTE				34	TREET ADDRESS, CITY, STATE, ZIP CODE 176 W. WILSON ST. ANNING, CA 92220		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PREFIX (EACH CORRECTIVE ACTION SHOULD			(X5) COMPLETION DATE
K 712 SS=C	Alcohol based hand robserved and staff was 1. At 11:58 a.m., there hand rub dispenser (Alobby on the west wal directly over an ignitic concurrent interview, were unaware of the inverse ABHR's. 2. At 2:28 p.m., there rub dispenser (ABHR room area on the northinstalled directly over concurrent interview, were unaware of the inverse and inver	and interview with the sor (MS) on 8/13/2024, the sub dispensers were as interviewed. Was an alcohol based ABHR) located in the main I observed to be installed on source. During a the MS stated that they installation requirements for was an alcohol based hand located in the main dining the wall observed to be an ignition source. During a the MS stated that they installation requirements for transmission of a fire alarm of emergency fire are held at expected and der varying conditions, at his hift. The staff is familiar is aware that drills are part of where drills are conducted in 6:00 AM, a coded in used instead of audible		712	All ABHR dispensers in the facility were double checked to ensure compliance with placement regulation maintenance director and administrator conducted withrough and measurements on 8/20/24 Please see email with attached images repair	e alk	8/23/24

PRINTED: 08/26/2024 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		555319	B. WING			08/13/2024	
NAME OF PROVIDER OR SUPPLIER SUNRISE POST ACUTE				STREET ADDRESS, CITY, STATE, ZIP CODE 3476 W. WILSON ST. BANNING, CA 92220			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE API DEFICIENCY)	OULD BE		(X5) COMPLETION DATE
K 712	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL		K	to ensure that we are in compliar regulation, Sunrise Post Acute a 2024 has contracted Fire Drill Se (FDS) to conduct monthly Fire d is contracted and responsible to conducing drills for shifts during evening, and night while ensurin each shift has received no less t test per quarter. To verify that Sunrise Post Acute to remain compliant we review the invoice during out monthly Safet to make sure that drills are being that each shift is being drilled on quarterly basis. Please see email of invoices to Please see email attachment	s of Q1 ervice rills. Fl the day g that han 1 c contin ne FDS y meeti j held a	DS y, drill ue ing	