PRINTED: 03/07/2024 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDIN	PLE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED				
. 05A110			B. WING _				03/04/2024	
NAME OF P	ROVIDER OR SUPPLIER			STREET ADDRESS 13435 PEACH A LIVINGSTON,		CODE		
(X4) ID PREFIX TAG			ID PREFIX TAG	(EA	PROVIDER'S PLAN OF CH CORRECTIVE ACT SS-REFERENCED TO DEFICIENC	TION SHOULD B		(X5) COMPLETION DATE
E 000	Initial Comments		ΕO	00				
	Department of Public Emergency Prepared The findings are in ac Federal Regulations for Long Term Care (ness recertification survey. cordance with 42 Code of (CFR) 483.73, Requirement				RECEIVED By LSC at 2:	15 pm, Mar 15,	2024
K 000		antial compliance with 42 Term Care (LTC) Facilities.	ΚO	00				
	Surveyor: 43379 K3 BUILDING: 01 K6 PLAN APPROVAL K7 SURVEY UNDER STRUCTURE TYPE: CONSTRUCTION TY SPRINKLERED.	: 2012 EXISTING ONE STORY,						
	Department of Public Life Safety Code rece findings are in accord Federal Regulations (National Fire Protection Life Safety Code, 201	the findings of the California Health, during an annual ertification survey. The ance with 42 Code of CFR) §483.90(a)(b)(c)(j), on Association (NFPA) 101 - 2 Edition, and NFPA 99 -						
_ABORATORY [DIRECTOR'S OR PROVIDER/S	SUPPLIER PEPERSENTATIVE'S SIGNATURE			TITLE		(X6)) DATE

Any deficiency statement ending with an asterist (1) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Administrator

3/15/24

AND BLAN OF CORRECTION IN INDENTIFICATION NUMBER:		A. BUILDIN	PLE CONSTRUCTION IG 02	(X3) DATE SURVEY COMPLETED	
		05A110	B. WING _		03/04/2024
NAME OF PROVIDER OR SUPPLIER GRACE HOME INC.			•	STREET ADDRESS, CITY, STATE, ZIP CODE 13435 PEACH AVENUE LIVINGSTON, CA 95334	,
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPR DEFICIENCY)	ULD BE COMPLETION
K 325 SS=D	Health: 43379 The facility is not in s 42 CFR §483.90 for I Alcohol Based Hand CFR(s): NFPA 101 Alcohol Based Hand ABHRs are protected unless all conditions * Corridor is at least 6 * Maximum individual gallons (0.53 gallons ounces of Level 1 ae * Dispensers shall ha horizontal spacing * Not more than an affluid or 135 ounces a smoke compartment excluding one individ * Storage in a single than 5 gallons compli * Dispensers are not ignition source * Dispensers over call sprinklered smoke compartment excluding one individ * Storage in a single than 5 gallons compli * Dispensers over call sprinklered smoke compartment excluding one individ * Storage in a single than 5 gallons compli * Dispensers over call sprinklered smoke compartment excluding one individ * Storage in a single than 5 gallons compli * Dispensers over call sprinklered smoke compartment excluding one individed * ABHR does not excluded * ABHR does not excluded * ABHR is protected * ABHR is	ifornia Department of Public ubstantial compliance with Long Term Care Facilities. Rub Dispenser (ABHR) Rub Dispenser (ABHR) in accordance with 8.7.3.1, are met: 6 feet wide dispenser capacity is 0.32 in suites) of fluid and 18 rosols ve a minimum of 4-foot ggregate of 10 gallons of erosol are used in a single outside a storage cabinet, ual dispenser per room smoke compartment greater es with NFPA 30 installed within 1 inch of an repeted floors are in mpartments eed 95 percent alcohol penser shall comply with	К 3	written allegation of complice the deficiencies cited. However submission of the Plan of Connot an admission that a deficient contact of the	ance for ver, ver, ver, verection is ficiency correctly. bibmitted ished by Rub on(s) will residents d by the director a 7 and area. I identify potential deficient ve action fect all an 3/12/24 HRs and

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED		
05A110			B. WING _	B. WING		03/04/2024	
NAME OF PI	ROVIDER OR SUPPLIER			13	TREET ADDRESS, CITY, STATE, ZIP CODE 8435 PEACH AVENUE IVINGSTON, CA 95334		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 341 SS=D	Based on observation failed to maintain the (ABHR) dispensers. ABHR that was install source. This affected compartments and two result in an electrical Findings: During a tour of the famount of the famous observed. At 12:05 p.m., Reside observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed. At 12:05 p.m., Reside observed with an ABH approximately four incurrence of the famous observed. The famous observed of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four incurrence of the famous observed with an ABH approximately four	and interview, the facility Alcohol-Based Hand Rub This was evidenced by led directly above an ignition one of two smoke to of 32 residents and could fire. Acility and interview with 3/4/24, the ABHR dispenser and the AB		325	into place or what systemic charthe facility will make to ensure the deficient practice does not a ABHR placement education (attawas provided to the maintenance director on 3/12/24. A PIP was sto ensure proper ABHR placeme (attached). 4. How the facility plans to monitor its performance to masure that solutions are sustained facility must develop a plan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective action evaluated for its effective action evaluated for its effective The POC is integrated into the quality assurance system; The ABHR placement audit (attawill be performed monthly by the maintenance director for 3 month directed by the PIP. The PIP will reviewed monthly and evaluated quarterly QAPI/QA to ensure effectiveness.	nges that recur; ached) e tarted nt ke d. The eved be eeness.	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIF	PLE CONSTRUCTION G 02	(X3) DATE COMF	SURVEY PLETED
05A110			B. WING		03/	04/2024
NAME OF P	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CO 13435 PEACH AVENUE LIVINGSTON, CA 95334		
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD BE		
K 341	Continued From pag	e 3	K 34	K341 Fire Alarm System Installation	m -	
	by: Surveyor: 43379 Based on observation failed to maintain the This was evidenced means for the fire also identified with red maresidents and two of could result in staff in breaker in the event NFPA 101, Life Safet 19.3.4 Detection, Also Systems. 19.3.4.1 General. He be provided with a finaccordance with Section of Fire Detection, Also Systems. 9.6.1* General. 9.6.1.1 The provision only where specifical section of this Code. 9.6.1.2 Fire detection communications system alternative permit considered required provisions of this Cosystems. 9.6.1.3 A fire alarm shall be installed, test accordance with the NFPA 70, National Expressions of the section of the section of the section of this Cosystems.	ry Code, 2012 Edition rm, and Communications realth care occupancies shall e alarm system in tion 9.6. larm, and Communications as of Section 9.6 shall apply ly required by another		1. How corrective be accomplished for the found to have been affed deficient practice. On 3/5/24 the maintent applied red tape marking the fire alarm circuit distance. How the facility other residents having to be affected by the samp practice and what correwill be taken; This had the potential to residents in the building 3. What measures into place or what system the facility will make to the deficient practice deficient p	ance director ig to identify sconnect. will identify the potential me deficient ective action o affect all g. will be put emic changes o ensure that loes not recur; ing education if to the in 3/12/24. A re proper E	

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTI A. BUILDIN	PLE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED		
05A110			B. WING _		03/04/2024	
NAME OF PROVIDER OR SUPPLIER GRACE HOME INC.				STREET ADDRESS, CITY, STATE, ZIP CODE 13435 PEACH AVENUE LIVINGSTON, CA 95334		
(X4) ID PREFIX TAG					BE COMPLETION	
K 341	is an approved existing installation, which shall be permitted to be continued in use. NFPA 72: National Fire Alarm and Signaling Code, 2010 edition 10.5.5.2 Circuit Identification and Accessibility. 10.5.5.2.1 The location of the dedicated branch circuit disconnecting means shall be permanently identified at the control unit. 10.5.5.2.2 For fire alarm systems the circuit disconnecting means shall be identified as "FIRE ALARM CIRCUIT." 10.5.5.2.3 For fire alarm systems the circuit disconnecting means shall have a red marking. 10.5.5.2.4 The circuit disconnecting means shall be accessible only to authorized personnel. Findings: During a tour of the facility and interview with Maintenance Staff on 3/4/24, the fire alarm systems circuit disconnecting means was observed. At 11:42 a.m., electrical panel E located in the generator room was observed without red identification for the fire alarm circuit disconnecting means. Upon interview, the Maintenance Staff stated that he was not aware of the code requirement. K 355 Portable Fire Extinguishers		К3	4. How the facility plans to monitor its performance to me sure that solutions are sustained facility must develop a plan for ensuring that correction is ach and sustained. This plan must implemented, and the correction action evaluated for its effective. The POC is integrated into the quality assurance system; An E panel identification audit performed monthly by the maintenance director for 3 more directed by the PIP. The PIP wireviewed monthly and evaluate quarterly QAPI/QA to ensure effectiveness.	ake ed. The r ieved be ve veness. e will be aths as ll be	
K 355 SS=D			K 3	55		

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA ND PLAN OF CORRECTION IDENTIFICATION NUMBER:		` '	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING			SURVEY LETED	
05A110						B. WING _	03/04/2024
NAME OF PROVIDER OR SUPPLIER GRACE HOME INC.				13	REET ADDRESS, CITY, STATE, ZIP CODE 8435 PEACH AVENUE IVINGSTON, CA 95334	, ,	
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	×	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE
K 355	by: Surveyor: 43379 Based on observation failed to maintain the This was evidenced inspections. This after a that was located and could result in a extinguisher. NFPA 101 Life Safet 19.3.5.12 Portable for provided in all health accordance with 9.7 9.7.4 Manual Exting 9.7.4.1* Where require another section of the extinguishers shall be inspected, and main NFPA 10, Standard Extinguishers. NFPA 10, Standard Extinguishers, 2010 7.2 Inspection. 7.2.1 Frequency. 7.2.1.1* Fire extinguinspected when initiant 7.2.1.2* Fire extinguisher manually or be served in spected when initiant results in the served	n, NFPA 10 T is not met as evidenced on and interview, the facility e portable fire extinguishers. by missing monthly visual fected the maintenance shop ad in the exterior of the facility, malfunction of the fire ty Code 2012 edition re extinguishers shall be a care occupancies in .4.1. uishing Equipment. ired by the provisions of his Code, portable fire be selected, installed, tained in accordance with for Portable Fire	K	355	1. How corrective action(s) be accomplished for those reside found to have been affected by deficient practice. On 3/5/24 the maintenance directly performed and recorded the movisual inspection on the fire extinguisher located in the exterior the facility. 2. How the facility will identify the potential to be affected by the same deficient practice and what corrective active active and what corrective active	will lents the ctor nthly for of ntify ntial ient tion he ct for hed). out nges that recur; cation	

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(3) DATE SURVEY COMPLETED	
		05A110	B. WING _			03/	04/2024
NAME OF PROVIDER OR SUPPLIER GRACE HOME INC.				13	TREET ADDRESS, CITY, STATE, ZIP CODE 3435 PEACH AVENUE IVINGSTON, CA 95334	, ,	
(X4) ID PREFIX TAG	(EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE					(X5) COMPLETION DATE	
K 355	During a tour of the Maintenance Staff of extinguishers were at the Maintenance Staff of the Mai	facility and interview with the on 3/4/24, the fire		355	4. How the facility plans to monitor its performance to make sure that solutions are sustained facility must develop a plan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective action evaluated for its effective action evaluated into the quality assurance system; The fire extinguisher inspection will be performed monthly by the maintenance director and record the PIP for 3 months as directed PIP. The PIP will be reviewed meand evaluated at the quarterly QA to ensure effectiveness. K363 Corridor – Doors 1. How corrective action (be accomplished for those resificant to have been affected by deficient practice. On 3/5/24 the maintenance directly adjusted the closure on the DO office door and it closes and lat	ke d. The eved be ee eness. audit e led in by the onthly API/ (s) will idents y the ector N	

AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 02 COMPLETED O3/04/202	OLIVILIV	O T OIL MEDIO TILE A	MEDIO/ ND OEITTIOEO				OWID 110	. 0000 0001
STREET ADDRESS, CITY, STATE, ZIP CODE 13435 FEACH AMENUE LIVINGSTON, CA 95334 REGULATORY OR LSC DENTHYMG INFORMATION) K 363 Continued From page 7 of unlimited height are permitted. Dutch doors meeting 19.3.6.3.6 are permitted. Dutch doors meeting 19.3.6.3.6 are permitted. Dutch doors make small be labeled and made of steel or other materials in compliance with 8.3. unless the smoke compartment is sprinklered. Fixed fire window assemblies are allowed per 8.3. In sprinklered compartments there are no restrictions in area or fire resistance of glass or frames in window assemblies. 19.3.6.3.42 CFR Parts 403, 418, 460, 482, 483, and 485 Show in REMARKS details of doors such as fire protection ratings, automatics closing devices, etc. This REQUIREMENT is not met as evidenced by: Surveyor: 43379 Based on observation and interview, the facility failed to maintain the corridor doors. This was evidenced by conflor doors that failed to latch when tested. This could result in the passage of smoke in the event of a fire, and affected one of two smoke compartments and 12 of 32 residents. Findings: During a tour of the facility and interview with Maintenance Staff on 3/4/24, the corridor doors were observed and tested. At 12:19 p.m., the corridor door with a self-closing device to the Director of Nurse office failed to	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION						(X3) DATE SURVEY COMPLETED	
CALL DEFICIENCY MIST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY MIST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) PREEK TAG PROVIDERS PLAN OF CORRECTION GEACH CORRECTIVE ACTIONS ADOLLD BE CROSS-REFERENCE TO THE APPROPRIATE DEFICIENCY			05A110	B. WING			03/0	04/2024
Regulatory or LSC IDENTIFYING INFORMATION K 363 Continued From page 7 of unlimited height are permitted. Dutch doors meeting 19.3.6.3.6 are permitted. Dutch doors meeting 19.3.6.3.6 are permitted. Dor frames shall be labeled and made of steel or other materials in compliance with 8.3, unless the smoke compartment is sprinklered. Fixed fire window assemblies are allowed per 8.3. In sprinklered compartments there are no restrictions in area or fire resistance of glass or frames in window assemblies. 19.3.6.3, 42 CFR Parts 403, 418, 460, 482, 483, and 485 Show in REMARKS details of doors such as fire protection ratings, automatics closing devices, etc. This REQUIREMENT is not met as evidenced by: Surveyor: 43379 Based on observation and interview, the facility failed to maintain the corridor doors. This was evidenced by corridor doors that failed to latch when tested. This could result in the passage of smoke in the event of a fire, and affected one of two smoke compartments and 12 of 32 residents. Findings: During a tour of the facility and interview with Maintenance Staff on 34/424, the corridor doors were observed and tested. At 12:19 p.m., the corridor of or with a self-closing device to the Director of Nurse office failed to					1:	3435 PEACH AVENUE		
of unlimited height are permitted. Dutch doors meeting 19.3.6.3.6 are permitted. Door frames shall be labeled and made of steel or other materials in compliance with 8.3, unless the smoke compartment is sprinklered. Fixed fire window assemblies are allowed per 8.3. In sprinklered compartments there are no restrictions in area or fire resistance of glass or frames in window assemblies. 19.3.6.3. 42 CFR Parts 403, 418, 460, 482, 483, and 485 Show in REMARKS details of doors such as fire protection ratings, automatics closing devices, etc. This REQUIREMENT is not met as evidenced by: Surveyor: 43379 Based on observation and interview, the facility failed to maintain the corridor doors. This was evidenced by corridor doors that failed to latch when tested. This could result in the passage of smoke in the event of a fire, and affected one of two smoke compartments and 12 of 32 residents. Findings: During a tour of the facility and interview with Maintenance Staff on 3/4/24, the corridor doors were observed and tested. At 12:19 p.m., the corridor door with a self-closing device to the Director of Nurse office failed to	PRÉFIX	(EACH DEFICIENC	Y MUST BE PRECEDED BY FULL	PREF		(EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA		(X5) COMPLETION DATE
tested three times and failed to latch on all three occasions. Upon interview, the Maintenance Staff stated that the self-closing device needed to be adjusted to allow sufficient closing force to close	K 363	of unlimited height arm meeting 19.3.6.3.6 ar shall be labeled and in materials in complian smoke compartment window assemblies a sprinklered compartmestrictions in area or frames in window ass 19.3.6.3, 42 CFR Parand 485 Show in REMARKS of protection ratings, au etc. This REQUIREMENT by: Surveyor: 43379 Based on observation failed to maintain the evidenced by corridor when tested. This consmoke in the event of two smoke compartments of the familiar and the evidenced and tested three times an occasions. Upon intestated that the self-cleated in the self-cleated	e permitted. Dutch doors re permitted. Door frames made of steel or other ce with 8.3, unless the is sprinklered. Fixed fire re allowed per 8.3. In ments there are no fire resistance of glass or semblies. Its 403, 418, 460, 482, 483, details of doors such as fire tomatics closing devices, is not met as evidenced and interview, the facility corridor doors. This was r doors that failed to latch and result in the passage of fa fire, and affected one of ments and 12 of 32 residents. acility and interview with 3/4/24, the corridor doors ested. rridor door with a self-closing of Nurse office failed to o self close. The door was d failed to latch on all three rview, the Maintenance Staff osing device needed to be	K	363	2. How the facility will ident other residents having the potent to be affected by the same deficing practice and what corrective act will be taken; This had the potential to affect all residents in the building in the end a fire. On 3/12/24 an audit was defined all corridor doors and all were in compliance for latching (attached). What measures will be printo place or what systemic characteristic does not recorridor door latching education (attached) was provided to the maintenance director on 3/12/24 PIP was started to ensure complication door latching (attached) corridor door latching (attached).	ntial ient ion Il went of one of d). but nges that ecur; n	

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTI A. BUILDIN	PLE CONSTRUCTION IG 02	(X3) DATE SURVEY COMPLETED	
		05A110	B. WING _		03/04/2024
NAME OF PROVIDER OR SUPPLIER GRACE HOME INC.				STREET ADDRESS, CITY, STATE, ZIP CODE 13435 PEACH AVENUE LIVINGSTON, CA 95334	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	N (X5) BE COMPLETION RIATE DATE	
				4. How the facility plans to monitor its performance to monitor its performance to move that solutions are sustain facility must develop a plan for ensuring that correction is act and sustained. This plan must implemented, and the correction evaluated for its effective. The POC is integrated into the assurance system; The corridor door latching aud (attached) will be performed months as directed by the PIP. will be reviewed monthly and evaluated at the quarterly QAP ensure effectiveness.	ake ed. The r tieved be ive veness. quality it onthly : 3 The PIP