PRINTED: 08/10/2017 FORM APPROVED OMB NO. 0938-0391

|                          | OF DEFICIENCIES<br>F CORRECTION   | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:  |                    |      | ONSTRUCTION MAIN BUILDING 01   | ` '  | E SURVEY<br>MPLETED        |
|--------------------------|---|--|--------------------|------|--|------|----------------------------|
|                          |   | 555892   | B. WING            |      |  | 06/  | /29/2017                   |
|                          | PROVIDER OR SUPPLIER  | SPITAL   |                    | 2108 | ET ADDRESS, CITY, STATE, ZIP CODE<br>STILLMAN<br>MA, CA 93662  |      |                            |
| (X4) ID<br>PREFIX<br>TAG | (EACH DEFICIENC)  | TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)  | ID<br>PREFI<br>TAG | - 1  | PROVIDER'S PLAN OF CORRECTION<br>(EACH CORRECTIVE ACTION SHOULD<br>CROSS-REFERENCED TO THE APPROF<br>DEFICIENCY) | D BE | (X5)<br>COMPLETION<br>DATE |
| K 000                    | INITIAL COMMEN  | TS   | K                  | 000  |  |      | •                          |
|                          | STRUCTURE TYP BASEMENT, CON FULLY SPRINKLE  The following reflect Department of Pub Life Safety Code refindings are in accord Federal Regulation Fire Protection Ass Safety Code 2012 Care Facilities Cod Representing the CHealth: 29752  The facility is not in | ER: 2012 EXISTING  E: TWO STORY AND STRUCTION TYPE V(111), RED.  ets the findings of the California dic Health, during an annual ecertification survey. The ordance with 42 Code of as(CFR) 483.70 (a), National ociation (NFPA) 101, Life Edition, and NFPA 99 Health |                    |      |  |      |                            |
| K 293<br>SS≂D            | Exit Signage 2012 EXISTING Exit and directiona accordance with 7. also served by the 19.2.10.1 (Indicate N/A in on- with less than 30 o   | I signs are displayed in 10 with continuous illumination emergency lighting system. e-story existing occupancies ccupants where the line of exit   |                    | 293  |  |      | 7/11/17                    |
| LABORATOR                | Y DIRECTOR'S OR PROVI   | DER/SUPPLIER REPRESENTATIVE'S SIG  | NATURE             |      | TITLE  |      | (X6) DATE                  |

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

07/17/2017

|       | OF DEFICIENCIES<br>OF CORRECTION   | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:  | l ' '              |        | E CONSTRUCTION<br>02 - MAIN BUILDING 01  |   | SURVEY<br>PLETED           |  |
|-------|--|--|--------------------|--------|--|---|----------------------------|--|
|       |  | 555892   | B. WING            |        |  | 06/2  | 29/2017                    |  |
|       | (EACH DEFICIENC)   | SPITAL  ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)   | ID<br>PREFI<br>TAG | S<br>X | TREET ADDRESS, CITY, STATE, ZIP CODE  108 STILLMAN ELMA, CA 93662  PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP  | BE  | (X5)<br>COMPLETION<br>DATE |  |
| K 293 | travel is obvious.) This STANDARD is STANDARD is STANDARD is Surveyor: 29752 Based on observative review, the facility from the facility. This was evivilluminated exit signinspections of the facility. This context is affected two on the facility. This context is affected two on the facility. This affected two on the facility is affected to one of the facility is affected to one of the facility. The facility is affected to one of the facility is affected to one of the facility is affected to one of the facility. The facility is affected to one of the facility is affected t | is not met as evidenced by:  ion, interview, and record failed to maintain their exit idenced by three partially ns and no monthly records for exit signs located throughout ould result in a delayed acility during an emergency, of five smoke compartments. |                    | 293    | Maintenance replaced light bulbs signs on 6/30/17. No residents were found to be affer Maintenance inspected all of the esigns on 6-30-17 and replaced light as needed.  Maintenance will inspect all of the lights on a monthly basis and docuon the exit light checklist and reconstructed within 48 hours by maint On 7/11/17 Environmental supervisin-serviced maintenance on process monthly exit sign inspections.  Administrator will present any issue exit signs to the monthly QAA commeeting. | ected.  xit at bulbs  exit ument rd. Any be tenance. sor dure for |                            |  |

|                          | OF DEFICIENCIES<br>F CORRECTION   | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:  | ` '               |     | E CONSTRUCTION<br>02 - MAIN BUILDING 01   |      | SURVEY<br>PLETED           |
|--------------------------|---|--|-------------------|-----|---|------|----------------------------|
|                          |   | 555892   | B. WING           |     |   | 06/2 | 29/2017                    |
|                          | PROVIDER OR SUPPLIER  | SPITAL   |                   | 2   | TREET ADDRESS, CITY, STATE, ZIP CODE<br>108 STILLMAN<br>ELMA, CA 93662  |      |                            |
| (X4) ID<br>PREFIX<br>TAG | (EACH DEFICIENC)  | NTEMENT OF DEFICIENCIES<br>Y MUST BE PRECEDED BY FULL<br>SC IDENTIFYING INFORMATION)   | ID<br>PREF<br>TAG |     | PROVIDER'S PLAN OF CORRECTIO<br>(EACH CORRECTIVE ACTION SHOULD<br>CROSS-REFERENCED TO THE APPROP<br>DEFICIENCY) | D BE | (X5)<br>COMPLETION<br>DATE |
| K 293                    | 7.9.3.1.1(2). (2)*The test interval extended beyond 3 authority having jur (3) Functional testifor a minimum of 1 lighting system is b (4) The emergency fully operational for required by 7.9.3.1 (5) Written records shall be kept by the authority having jur 7.9.3.1.2 Testing of systems shall be p follows: (1) Self-testing/self emergency lighting (2) Not less than of self-testing/self-dialemergency lighting perform a test with seconds and a diag (3) Self-testing/self emergency lighting failures by a status (4) A visual inspect intervals not exceed (5) Functional testifor a minimum of 1 (6) Self-testing/self emergency lighting operational for the (7) Written records | s otherwise permitted by  all shall be permitted to be to days with the approval of the isdiction. In shall be conducted annually 1/2 hours if the emergency teattery powered. I lighting equipment shall be the duration of the tests 1(1) and (3). In of visual inspections and tests to owner for inspection by the isdiction. If required emergency lighting termitted to be conducted as I-diagnostic battery-operated the equipment shall be provided. The every 30 days, I gnostic battery-operated the equipment shall automatically a duration of a minimum of 30 to gnostic routine. I-diagnostic battery-operated the equipment shall indicate the indicator. I tion shall be performed at the ding 30 days. I gnostic battery-operated the equipment shall be fully a duration of the 1 1/2-hour test. I diagnostic battery-operated the equipment shall be fully duration of the 1 1/2-hour test. I do visual inspections and tests the owner for inspection by the | K                 | 293 |   |      |                            |

| STATEMENT OF DEFICIENCIES<br>AND PLAN OF CORRECTION   | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:   | (X2) MULTIF<br>A. BUILDING |   | (X3) DATE SURVEY<br>COMPLETED |                            |
|---|--|----------------------------|---|-------------------------------|----------------------------|
|   | 555892   | B. WING _                  |   | 06                            | /29/2017                   |
| NAME OF PROVIDER OR SUPPL   |  |                            | STREET ADDRESS, CITY, STATE, ZIP CODE<br>2108 STILLMAN<br>SELMA, CA 93662                               | -                             |                            |
| PREFIX (EACH DEFICIE  | STATEMENT OF DEFICIENCIES NCY MUST BE PRECEDED BY FULL OR LSC IDENTIFYING INFORMATION)   | ID<br>PREFIX<br>TAG        | PROVIDER'S PLAN OF CORREC<br>(EACH CORRECTIVE ACTION SHO<br>CROSS-REFERENCED TO THE APPI<br>DEFICIENCY) | OULD BE                       | (X5)<br>COMPLETION<br>DATE |
| Maintenance St inspection log was 1. At 8:45 a.m., records for the f Maintenance St not document a During the facility Maintenance St were observed.  First Floor  2. At 12:02 p.m. partially illuminate p.m., Maintenance of the two bulbs bulb holders we the north, east, NFPA 101 Spring Testing  Sprinkler System Automatic spring inspected, tested with NFPA 25, Stepting, and Material Protection System maintenance, in maintained in a available. | iew and record review with aff 1 on 6/29/17, the exit sign ras requested.  there were no monthly inspection acility's exit signs. At 8:46 a.m., aff 1 acknowledged that they did monthly exit sign inspection.  ty tour and interview with aff 1 on 6/29/17, the exit signs  , three of five exit signs were ted on the first floor. At 12:03 are Staff 1 acknowledged that one in each fixture were out or the re removed from the fixtures at and south corridor exits. kler System - Maintenance and  m - Maintenance and Testing kler and standpipe systems are d, and maintained in accordance standard for the Inspection, intaining of Water-based Fire ems. Records of system design, spection and testing are secure location and readily  er system last checked | K 29                       |   |                               | 7/29/17                    |

|                          | OF DEFICIENCIES<br>F CORRECTION  | (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  | l ` '             |     | E CONSTRUCTION<br>02 - MAIN BUILDING 01   |   | SURVEY                     |
|--------------------------|--|---|-------------------|-----|---|---|----------------------------|
| NAME OF F                | PROVIDER OR SUPPLIER   | 555892  | B. WING           | S   | TREET ADDRESS, CITY, STATE, ZIP CODE  | 06/2                                    | 29/2017                    |
| SELMA (                  | CONVALESCENT HO  | SPITAL  |                   |     | 108 STILLMAN<br>SELMA, CA 93662   |   |                            |
| (X4) ID<br>PREFIX<br>TAG | (EACH DEFICIENC)   | ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)  | ID<br>PREF<br>TAG |     | PROVIDER'S PLAN OF CORRECTION<br>(EACH CORRECTIVE ACTION SHOULD<br>CROSS-REFERENCED TO THE APPROPE<br>DEFICIENCY)   | BE                                      | (X5)<br>COMPLETION<br>DATE |
| K 353                    | Continued From pa  | age 4   | K                 | 353 |   |   |                            |
|                          | c) Water system s  | supply source   |                   |     |   | İ                                       |                            |
|                          | any non-required of system.  9.7.5, 9.7.7, 9.7.8, This STANDARD of Surveyor: 29752  Based on interview failed to maintain the system. This was complete semi-annuthe tamper switch a signals. This could of a malfunctioning and affected five of NFPA 101, Life Sat 19.3.5.1 Buildings of a malfunctioning and affected through supervised automatic supervised automatic supervised automatic sprinkler system.  9.7.2 Supervision.  9.7.2 Supervision.  9.7.2.1* Supervision automatic sprinkler sprinkler another section of attachments shall be integrity in accordation for a signal shall be provided that would impair the sprinkler system. So and shall be displating protected build integrity in accordation of signal shall be displating the protected build. | and record review, the facility neir automatic fire sprinkler evidenced by the failure to nual tests and inspections on and corresponding supervisory result in a delayed notification automatic sprinkler system five smoke compartments.  Tety Code, 2012 Edition containing nursing homes shall ghout by an approved, atic sprinkler system in section 9.7, unless otherwise |                   |     | a)Sprinkler system was last checked 1-10-17 b) by sprinkler inspection vendor c) Water source is city water system California Water Service.  Environmental Supervisor contacte vendor and scheduled semi annual sprinkler tamper alarm inspections.  No residents were found to be affect Fire sprinkler tamper switch and au inspection was completed by fire protection vendor on 8/08/17.  Environmental Supervisor will present the sprinkler or temper alarm to monthly QAA metals. | n by  d  cted.  dibles  ent any ers and |                            |

|                          | OF DEFICIENCIES<br>OF CORRECTION   | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:   | l ` ′              |     | CONSTRUCTION<br>2 - MAIN BUILDING 01   |      | E SURVEY<br>PLETED         |
|--------------------------|--|---|--------------------|-----|--|------|----------------------------|
|                          |  | 555892  | B. WING            |     |  | 06/  | 29/2017                    |
|                          | PROVIDER OR SUPPLIER   | SPITAL  |                    | 210 | REET ADDRESS, CITY, STATE, ZIP CODE<br>08 STILLMAN<br>:LMA, CA 93662   |      |                            |
| (X4) ID<br>PREFIX<br>TAG | (EACH DEFICIENCY   | TEMENT OF DEFICIENCIES  MUST BE PRECEDED BY FULL  SC IDENTIFYING INFORMATION)   | ID<br>PREFI<br>TAG | (   | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPRIED TO THE | D BE | (X5)<br>COMPLETION<br>DATE |
| K 353                    | remotely located re  9.7.5 Maintenance sprinkler and stand Code shall be inspering accordance with Inspection, Testing, Water-Based Fire F  NFPA 25, Standard and Maintenance of Systems, 2011 Edit 4.3 Records. 4.3.1* Records shalt ests, and maintenance of the system and it made available to the upon request.  4.3.2 Records shall performed (e.g., insimalitenance), the office the work, the result 5.1.1 Minimum Reconstant for the system and maintenance of the work, the result 5.1.1 This chapter requirements for the system and maintenance of the work and maintenance of the work and maintenance of the work all the work and maintenance of the work all th | and Testing. All automatic pipe systems required by this ected, tested, and maintained NFPA 25, Standard for the and Maintenance of Protection Systems  I for the Inspection, Testing, If Water-Based Fire Protection sion  If be made for all inspections, ance to components and shall be the authority having jurisdiction.  I indicate the procedure spection, test, or corganization that performed is, and the date.  I quirements. In shall provide the minimum the routine inspection, testing, if sprinkler systems.  I arm Devices. The protection is and pressure switch-type vices shall be tested. | K 3                | 53  |  |      |                            |

| NAME OF PROVIDER OR SUPPLIER  555892  B. WING 06/29/20'  STREET ADDRESS, CITY, STATE, ZIP CODE  |  | IN OF CORK   | ND PLAN OF    |  | 1  |  | וטו  | JENIII  | FICATE   | ON NUM   | IBER:   | A. BU | ILDIN | NG I | 02 - MAIN BUILDING 01                                   |       | COM  | PLETED                     |   |
|---|--|--|---------------|--|--|--|--|---|--|--|---|-------|-------|------|---|-------|------|----------------------------|---|
|   |  |  |               |  |  |  |  |   | 555  | 5892   |   | B. WI | NG_   |      |   |       | 06/2 | 29/2017                    |   |
| SELMA CONVALESCENT HOSPITAL  2108 STILLMAN SELMA, CA 93662  |  |  |               |  |  | SPI  | ITAL   | L   |  |  |   |       |       | 2    | 108 STILLMAN  | DE    |      |                            |   |
| PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE COMPI   | (EACH DEFICIENCY MUS   | IX (E  | PREFIX        | IENCY  | CY   | ΥM   | UST  | BE PI   | RECE   | DED BY   | FULL  | PR    | EFIX  |      | (EACH CORRECTIVE ACTION S<br>CROSS-REFERENCED TO THE AF | HOULD | BE   | (X5)<br>COMPLETION<br>DATE | 1 |
| K 353 Continued From page 6 during either the first two revolutions of a hand wheel or when the stem of the valve has moved one-fifth of the distance from its normal position.  13.3.3.5.3 The signal shall not be restored at any valve position except the normal position.  Findings:  During document review and interview with Maintenance Staff 1 on 6/29/17, the automatic fire sprinkler system inspection and testing records were requested.  1. At 8.48 a.m., the facility provided annual and quarterly inspection reports for review. The records did not indicate that semi-annual supervisory signal tests on the tamper switch were completed. At 8.49 a.m., Maintenance Staff 2 acknowledged that there was no semi-annual supervisory signal test for the tamper switch included with quarterly testing.  K 541 K 541 RVFA 101 Rubbish Chutes, Incinerators, and Laundry Chutes 2012 EXISTING (1) Any existing linen and trash chute, including pneumatic rubbish and linen systems, that opens directly onto any corridor shall be sealed by fire resistive construction to prevent further use or shall be provided with a fire door assembly having a fire protection rating of 1-hour. All new chutes shall comply with 9.5. (2) Any rubbish chute or linen chute, including pneumatic rubbish and linen systems, shall be provided with a fire door assembly having a fire protection rating of 1-hour. All new chutes shall comply with 9.5. (2) Any rubbish chute or linen chute, including pneumatic rubbish and linen systems, shall be provided with a fire door assembly having a fire protection rating of 1-hour, all new chutes shall comply with 9.5. (2) Any rubbish chute or linen chute, including pneumatic rubbish and linen systems, shall be provided with a fire door assembly having a fire protection fating of 1-hour, all new chutes shall comply with 9.5. | during either the first tweel or when the sten one-fifth of the distance 13.3.3.5.3 The signal servalve position except the Findings:  During document review Maintenance Staff 1 on fire sprinkler system instructions were requested 1. At 8:48 a.m., the fact quarterly inspection reprecords did not indicate supervisory signal tests were completed. At 8:48 a.m., the fact quarterly inspection reprecords did not indicate supervisory signal tests were completed. At 8:48 a.m., the fact quarterly inspection reprecords did not indicate supervisory signal test included with quarterly NFPA 101 Rubbish Chutes 10.12 EXISTING (1) Any existing linen and pneumatic rubbish and directly onto any corridor resistive construction for shall be provided with a fire protection rating of shall comply with 9.5. (2) Any rubbish chute consumatic rubbish and | during whee one-fi 13.3.3 valve Findir Durin Maint fire sprecord 1. At quart record super were 2 ack super include NFPA Laund Rubb Chute 2012 (1) Air pneur direct resist shall a fire shall (2) Air pneur | K 541<br>SS=E | ent restaff ysten excelled who had been to be been to b | refires star green refine son did to the short of the sho | evice of the evice | two cem concepts the second se | of the from all nor and 5/29/ bection that so | e valuits not be mal p inter 17, thon an ovide or revise tam as not e tam as not e tam system of the control of | ve has ormal prestore osition view whe automotesti dannual per swaintena osemiper swainte | moved position.  ed at any n.  with comatic ring  ual and The new staff annual witch ance Staff annual witch and dry  cluding nat opens by fire use or bly having chutes duding nall be |       |       |      |   |       |      | 7/28/17                    |   |

|                          | OF DEFICIENCIES<br>OF CORRECTION  | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:  |                    |     | E CONSTRUCTION<br>02 - MAIN BUILDING 01   |  | SURVEY<br>PLETED           |
|--------------------------|---|--|--------------------|-----|---|--|----------------------------|
|                          |   | 555892   | B. WING            |     |   | 06/2                                   | 29/2017                    |
|                          | PROVIDER OR SUPPLIER  | SPITAL   | :                  | 2   | TREET ADDRESS, CITY, STATE, ZIP CODE<br>108 STILLMAN<br>ELMA, CA 93662  |  |                            |
| (X4) ID<br>PREFIX<br>TAG | (EACH DEFICIENCY  | TEMENT OF DEFICIENCIES  MUST BE PRECEDED BY FULL  SC IDENTIFYING INFORMATION)  | ID<br>PREFI<br>TAG |     | PROVIDER'S PLAN OF CORRECTION<br>(EACH CORRECTIVE ACTION SHOULD<br>CROSS-REFERENCED TO THE APPROPE<br>DEFICIENCY)   | BE                                     | (X5)<br>COMPLETION<br>DATE |
| K 541                    | collection room use protected in accord laundry chutes perr room are protected accordance with 19 (4) Existing fuel-fed by fire resistive con use.  19.5.4, 9.5, 8.4, NF This STANDARD is STANDARD is Surveyor: 29752. Based on observatifailed to maintain the This was evidenced chute room, in the lift from closing. This fire or smoke affect on each floor for two compartments.  NFPA 101, Life Saft 19.5.4 Rubbish Chutes.  19.5.4.1 Existing ruincluding pneumatithat open directly of sealed by fire-resist further use or shall assembly having a protection rating. All Section 9.5.  8.4.3.4* Door clears. | shall discharge into a trash of for no other purpose and ance with 8.4. (Existing mitted to discharge into same by automatic sprinklers in 1.3.5.9 or 19.3.5.7.) Incinerators shall be sealed struction to prevent further  PA 82 or not met as evidenced by: In and interview, the facility reir laundry chute enclosures of by a door to the soiled linen casement, that was obstructed could result in the spread of ring one smoke compartment or of five smoke  Pattern Code, 2012 Edition rates, incinerators, and Laundry bbish chutes or linen chutes, incrubbish and linen systems, into any corridor shall be tive construction to prevent be provided with a fire door minimum 1-hour fire I new chutes shall comply with ences shall be in accordance and and for Fire Doors and Other es. | K                  | 541 | Environmental supervisor ensured door was closed in the laundry chur the soiled linen room on 6/29/17.  No other fire doors were found to be improperly kept open on 6/29/17.  Laundry staff were in-serviced by the environmental supervisor on 7-5-17 regarding requirements for doors rest to fire safety.  Environmental supervisor will monitarea weekly for any doors being propen. Administrator or Environmental supervisor will present any trends to monthly QAA committee. | te and e ne r elated tor the opped tal |                            |

| STATEMENT OF DEFICIENCIES<br>AND PLAN OF CORRECTION |   | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:   | (X2) MULTIPLE CONSTRUCTION A. BUILDING 02 - MAIN BUILDING 01 |   |   | (X3) DATE SURVEY<br>COMPLETED |                            |
|---|---|---|--|---|---|-------------------------------|----------------------------|
|   |   | 555892  | B. WING  |   | · · · · · ·   | 06/2                          | 29/2017                    |
|   | ROVIDER OR SUPPLIER   | SPITAL  |  | 2 | TREET ADDRESS, CITY, STATE, ZIP CODE<br>108 STILLMAN<br>ELMA, CA 93662                                      |                               |                            |
| (X4) ID<br>PREFIX<br>TAG                            | (EACH DEFICIENC)  | TEMENT OF DEFICIENCIES<br>MUST BE PRECEDED BY FULL<br>SC IDENTIFYING INFORMATION)   | ID<br>PREFI<br>TAG   |   | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI<br>DEFICIENCY) | BE                            | (X5)<br>COMPLETION<br>DATE |
| K 901<br>SS=E                                       | 8.6.2* Continuity. Obe enclosed with fire continuous from flos shall be protected a resistance rating of Findings:  During the facility to Maintenance Staff laundry chute room  Basement  1. At 12:35 p.m., the room was obstructed handle that was we the door and the flowith a self closing copen position. At 12 confirmed that the area at that time.  NFPA 101 Fundame Categories  Fundamentals - Burndame Categories  Fundamentals - Burndame Categories are determined to the second | penings through floors shall be barrier walls, shall be or to floor, or floor to roof, and as appropriate for the fire the barrier.  Our and interview with 1 and 2 on 6/29/17, the is were observed.  Determined by a mop added between the bottom of foor. The door was equipped device but was kept in the fully 2:36 p.m., Maintenance Staff for was no laundry staff in the entals - Building System  Idding System Categories are designed to meet Category ments as detailed in NFPA 99. Formined by a formal and assessment procedure fied personnel. | K  |   |   |                               | 7/29/17                    |
|   |   |   |  |   |   |                               |                            |

| -                        | OF DEFICIENCIES<br>F CORRECTION   | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:   | ` '                 | LE CONSTRUCTION<br>G 02 - MAIN BUILDING 01  |                                   | E SURVEY<br>PLETED         |
|--------------------------|---|---|---------------------|---|-----------------------------------|----------------------------|
|                          | !   | 555892  | B. WING             |   | 06/                               | 29/2017                    |
|                          | PROVIDER OR SUPPLIER  | SPITAL  |                     | STREET ADDRESS, CITY, STATE, ZIP CODE<br>2108 STILLMAN<br>SELMA, CA 93662   |                                   |                            |
| (X4) ID<br>PREFIX<br>TAG | (EACH DEFICIENC)  | TEMENT OF DEFICIENCIES<br>( MUST BE PRECEDED BY FULL<br>SC IDENTIFYING INFORMATION)   | ID<br>PREFIX<br>TAG | PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL) CROSS-REFERENCED TO THE APPROPOLICIENCY)   | D BE                              | (X5)<br>COMPLETION<br>DATE |
| K 901                    | Surveyor: 29752 Based on record refailed to determine classification in according was evidenced by resystems risk assess residents, visitors, aprolonged duration insufficient assess systems.  NFPA 99, Health C Edition.  4.1 Building System in health care facility system Category 1 requirements as defended as a shall be designed to requirements as defended as a shall be designed to requirement as a defended as a caregory 2. For such equipment to patients or caregory 4.1.2 Category 2. For such equipment to patients or caregory in this code.  4.1.3 Category 3. For such equipment patients or caregory 3 required discomfort, shall be Category 3 required 4.1.4 Category 4. For such equipment patients or caregory 3 required 4.1.4 Category 4. For such equipment patients or caregory 4. For such equipment patients or caregory 3 required 4.1.4 Category 4. For such equipment patients or caregory 4. For such equipment patients or caregory 3 required 4.1.4 Category 4. For such equipment patients or caregory 4. | s not met as evidenced by:  view and interview, the facility their risk category cordance with NFPA 99. This no records of a building sment. This affected all and staff and could result in a of unsafe conditions due to ment of critical building  are Facilities Code, 2012  are Categories. Building systems ties shall be designed to meet through Category 4 etailed in this code.  Cacility systems in which failure or system is likely to cause th of patients or caregivers o meet system Category 1 | K 901               | No residents were found to be aff Facility will form a committee to e our Building systems risk assessment will complete risk assessment will incorporated in to the QAA prograthe assessment completion. | valuate<br>nent.<br>nent by<br>be |                            |

|                          | OF DEFICIENCIES<br>OF CORRECTION  | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:   | 1 ' '               | TIPLE CONSTRUCTION NG 02 - MAIN BUILDING 01   |       | E SURVEY<br>PLETED         |
|--------------------------|---|---|---------------------|---|-------|----------------------------|
|                          |   | 555892  | B. WING             |   | 06/   | 29/2017                    |
|                          | PROVIDER OR SUPPLIER  | SPITAL  |                     | STREET ADDRESS, CITY, STATE, ZIP CODE<br>2108 STILLMAN<br>SELMA, CA 93662                                   |       |                            |
| (X4) ID<br>PREFIX<br>TAG | (EACH DEFICIENCY  | ATEMENT OF DEFICIENCIES<br>Y MUST BE PRECEDED BY FULL<br>SC IDENTIFYING INFORMATION)  | ID<br>PREFIX<br>TAG | PROVIDER'S PLAN OF CORRECTI<br>(EACH CORRECTIVE ACTION SHOU<br>CROSS-REFERENCED TO THE APPRO<br>DEFICIENCY) | LD BE | (X5)<br>COMPLETION<br>DATE |
| K 901                    | Continued From pa   | age 10  | K 9                 | 01  |       |                            |
|                          |   | e designed to meet system<br>ments as defined in this code.   |                     |   |       |                            |
|                          |   | ent. Categories shall be<br>wing and documenting a<br>sment procedure.  |                     |   |       |                            |
|                          | 4.3 Application. The Category definitions in Chapter 4 shall apply to Chapters 5 through 11. Chapter 5 Gas and Vacuum Systems Chapter 6 Electrical Systems Chapter 9 Heating, Ventilation, and Air Conditioning (HVAC) Chapter 10 Electrical Equipment Chapter 11 Gas Equipment |   |                     |   |       |                            |
|                          | Findings:   |   |                     |   |       |                            |
|                          |   | with the Director of Nursing assessment corresponding to use was requested.   |                     |   |       |                            |
| K 920<br>SS=D            | failure of the building 99 was provided. A was not available to Maintenance Staff not have a document assessment.  NFPA 101 Electrical  | risk assessment related to the ng systems addressed in NFPA At 8:35 a.m., the Administrator but the Director of Nursing and 1 explained that the facility didented building systems risk al Equipment - Power Cords | К 9                 | 20  |       | 7/29/17                    |
|                          | Extension Cords Power strips in a pused for componer patient-care-related   | nt - Power Cords and atient care vicinity are only nts of movable d electrical equipment es that have been assembled  | · · ·               |   |       |                            |

|                          | FOF DEFICIENCIES<br>OF CORRECTION  | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:  | 1                  | TIPLE CONSTRUCTION<br>ING <b>02 - MAIN BUILDING 01</b>  |                                    | E SURVEY<br>IPLETED        |
|--------------------------|--|--|--------------------|---|------------------------------------|----------------------------|
|                          |  | 555892   | B. WING            |   | 06/                                | 29/2017                    |
|                          | PROVIDER OR SUPPLIER   | SPITAL   |                    | STREET ADDRESS, CITY, STATE, ZIP CODE<br>2108 STILLMAN<br>SELMA, CA 93662   |                                    |                            |
| (X4) ID<br>PREFIX<br>TAG | (EACH DEFICIENCY   | TEMENT OF DEFICIENCIES  MUST BE PRECEDED BY FULL  SC IDENTIFYING INFORMATION)  | ID<br>PREFI<br>TAG | · · · · · · · · · · · · · · · · · · ·   | JD BE                              | (X5)<br>COMPLETION<br>DATE |
| K 920                    | 10.2.3.6. Power stimay not be used for electronics), except rooms that do not used for the PCREE meet UL 13 strips for non-PCRI (outside of vicinity) care rooms, power standards. All power precautions. Extension cords us immediately upon of which it was installed 10.2.4. 10.2.3.6 (NFPA 99) (NFPA 70), 590.3 (DThis STANDARD is SURVEYOR: 29752. Based on observation failed to maintain we equipment. This we oven that was pluggextension cord. The smoke compartment increased risk of elefire.  NFPA 99 Health Care 9.1.2 Electrical Systemsion are appropriately appro | nel and meet the conditions of rips in the patient care vicinity r non-PCREE (e.g., personal tin long-term care resident is PCREE. Power strips for 363A or UL 60601-1. Power EE in the patient care rooms meet UL 1363. In non-patient strips meet other UL er strips are used with general sion cords are not used as a wiring of a structure. ed temporarily are removed completion of the purpose for ed and meets the conditions of (NFPA 70), TIA 12-5 is not met as evidenced by:  on and interview, the facility iring connections on electrical as evidenced by a microwave ged into a surge protected is affected affected one of five ints and could result in an electrical shock or an electrical are Facilities 2012 edition tems. Electrical wiring and in accordance with NFPA 70, | K9                 | Power strip was removed from Microwave on 6/29/17 by mainter Maintenance found no other improlugged items during inspection of 6/29/17.  Maintenance in-serviced staff on requirements for power strip use prohibition of such on 6/29/17  Environmental supervisor will mo prohibited power strips in use dur regular rounds. Environmental su will remove any power strips foun in violation and report any trends committee monthly. | and nitor for ing pervisor d to be |                            |

| STATEMENT OF DEFICIENCIES<br>AND PLAN OF CORRECTION      |  | (X1) PROVIDER/SUPPLIER/CLIA<br>IDENTIFICATION NUMBER:   | i ' '               | X2) MULTIPLE CONSTRUCTION<br>A. BUILDING <b>02 - MAIN BUILDING 01</b>                                |                 | (X3) DATE SURVEY<br>COMPLETED |  |
|--|--|---|---------------------|--|-----------------|-------------------------------|--|
| 555892   |  | B. WING   |                     | 06/29/2017   |                 |                               |  |
| NAME OF PROVIDER OR SUPPLIER SELMA CONVALESCENT HOSPITAL |  |   |                     | STREET ADDRESS, CITY, STATE, ZIP CODE 2108 STILLMAN SELMA, CA 93662                                  |                 |                               |  |
| (X4) ID<br>PREFIX<br>TAG                                 | SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)   |   | ID<br>PREFIX<br>TAG | PROVIDER'S PLAN OF CORRECTIO  (EACH CORRECTIVE ACTION SHOULD  CROSS-REFERENCED TO THE APPROFILIENCY) | D BE COMPLETION |                               |  |
| K 920  | permitted in 400.7, not be used for the (1) As a substitute structure (2) Where run throuseilings, suspended floors (3) Where run throusimilar openings (4) Where attached Exception to (4): Fl permitted to be attaccordance with the (5) Where concealed or located above sure (6) Where installed otherwise permitted (7) Where subject to Findings:  During the facility to Maintenance Staff devices and wiring Second Floor  1. At 12:08 p.m., in microwave oven plus which was plugged located on the north Maintenance Staff devices and Staff devices and Staff devices devices Staff devices Staff devices Staff devices devices Staff devices Staff devices devices Staff devices devices devices dev | flexible cords and cables shall following: for the fixed wiring of a augh holes in walls, structural discellings, dropped ceillings, or augh doorways, windows, or augh doorways, windows, or at to building surfaces exible cord and cable shall be ached to building surfaces in a provisions of 368.56(B) and by walls, floors, or ceilings aspended or dropped ceilings in raceways, except as a in this Code to physical damage.  Dur and interview with 2 on 6/29/17, the electrical connections were observed.  Room 204, there was a augged into a surge protector into an electrical wall outlet he wall. At 1:45 p.m., 2 explained that there were utlets in the room and that this | K 9:                | 20   |                 |                               |  |