DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/20/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION (X3) DATE SURVEY IDENTIFICATION NUMBER: COMPLETED A. BUILDING 01 B. WING 055079 09/12/2012 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE MISSION VIEW HEALTH CENTER 1425 WOODSIDE DR SAN LUIS OBISPO, CA 93401 SUMMARY STATEMENT OF DEFICIENCIES (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL PROVIDER'S PLAN OF CORRECTION PREFIX (X5) COMPLETION PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY) **INITIAL COMMENTS** K 000 K 000 K3 BUILDING: 01 K6 PLAN APPROVAL: 1958 K7 SURVEY UNDER: 2000 EXISTING STRUCTURE TYPE: TYPE V (111), ONE STORY, FULLY SPRINKLERED. The following reflects the findings of the California Department of Public Health, Life Safety Code, during an annual re-certification survey. The findings are in accordance with 42 CFR (Code of Federal Regulations) 483.70 (a) and NFPA (National Fire Protection Association) 101, Life Safety Code 2000 edition, Existing codes. Representing the California Department of Public Health: 29665 Census: 131 K 018 NFPA 101 LIFE SAFETY CODE STANDARD K 018 This plan of correction SS=D constitutes my written credible Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or allegation of compliance for the hazardous areas are substantial doors, such as deficiencies noted. those constructed of 1% inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors in sprinklered buildings are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Doors are provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3.6.3.6 are permitted. 19.3.6.3 Roller latches are prohibited by CMS regulations in all health care facilities. ABORATORY DIRECTOR'S OB PROVIDER SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE (X6) DATE 4DMINISTRATOR

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days lays following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued

ORM CMS-2567(02-99) Previous Versions Obsolete

0/1/12

ent D: BEF021

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/20/2012 FORM APPROVED OMB NO. 0938-0391

AND PLAN	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 055079		(X2) MULT A. BUILDIN B. WING	7	OMB NO. 0938-039 (X3) DATE SURVEY COMPLETED 09/12/2012	
MISSIO	PROVIDER OR SUPPLIER N VIEW HEALTH CE	NTER	1	REET ADDRESS, CITY, STATE, ZIP COI 425 WOODSIDE DR SAN LUIS OBISPO, CA 93401		1212012
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
	This STANDARD Based on observe maintain their corn one door that faile affected one of for could result in the the event of a fire. Findings: During a facility to doors were observe At 11:16 a.m., the failed to latch. NFPA 101 LIFE SA Medical gas storage protected in accord for Health Care Fa (a) Oxygen storage 3,000 cu.ft. are end separation. (b) Locations for si	is not met as evidenced by: ation, the facility failed to idor doors, as evidenced by d to close and latch. This ar smoke compartments and spread of smoke and fire, in ur on 9/12/12, the corridor red. door to Room 108 closed but AFETY CODE STANDARD ge and administration areas are clance with NFPA 99, Standards	K 018	K 018 Doors protecting corridor openings are substantial de a means suitable for keepi door closed. 1. The deficient practice we immediately corrected by the strike plate so that the latched in room 108 2. The Director of Environ services adjusted the strike that the door latched in room 3. The Director of Environ Services will audit the entibuilding weekly to make seall doors latch ensuring compliance. 4. All audits will be review the administrator or design Any non-compliance will brought to the quality assured committee for review and change to the policy and approcedure.	as adjusting door amental plate so om 108 amental are that wed by the and be rance possible	1

DÉPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/20/2012 FORM APPROVED OMB NO. 0938-0391

200	A STATE OF THE STA	RE & MEDICAID SERVICES				OMB NO. 0938-039	
	OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A BUILDING 01 B. WING			(X3) DATE SURVEY COMPLETED	
NAME OF PROVIDER OR SUPPLIER MISSION VIEW HEALTH CENTER			1	2/2012			
(X4) ID PREFIX TAG	(EACH DEFICIEN	SAN LUIS OBISPO, CA 93401 SUMMARY STATEMENT OF DEFICIENCIES ACH DEFICIENCY MUST BE PRECEDED BY FULL GULATORY OR LSC IDENTIFYING INFORMATION) BY PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		HOULD BE	(X5) COMPLETION DATE		
K 076	This STANDARD Based on observable delay in accessing damage to the liguiday in accessing 4-3.1.1.2 Storage Construction, Arra (a) Nonflammable In-Storage, Connumber 4-3.1.1.2 Storage, Connumber 4-3.1.2 Storage shall compare the control of the color o	is not met as evidenced by: vation and interview, the facility their oxygen storage areas. ced by empty and full cylinders parated, and by storage of with a light switch that was less the floor. This affected one of partments and could result in a g a full oxygen cylinder, and ght switch by a cylinder. ard for Health Care Facilities, e Requirements (Location, angement). e Gases (Any Quantity;	K 07	76	Medical gas storage and administration areas are production. 1. The 13 oxygen E cylinder immediately removed from hospice utility room. 2. The Director of Environt Services relocated the 13 E cylinders to the oxygen storroom. 3. The Director of Environt Services or designee will in all Licensed nursing staff regarding proper location of oxygen E cylinders. 4. The Director of Environt Services will audit weekly compliance and report any compliance to the quality assurance committee for reand possible change to the and procedure.	rss were the mental rage mental nservice of	9/24/1

cn

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/20/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 055079			E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED 09/12/2012	
NAME OF PROVIDER OR SUPPLIER MISSION VIEW HEALTH CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1425 WOODSIDE DR SAN LUIS OBISPO, CA 93401				
(X4) ID PREFIX TAG	(EACH DEFICIEN	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			PROVIDER'S PLAN OF COF (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE
K 147 SS=D	At 10:31 a.m., the oxygen E-cylinders we empty or full. Du determined which inspecting the garment of the oxygen cylin with a light switch from the floor. NFPA 101 LIFE SELECTRICAL WITHING A WITHING A TO, NOT This STANDARD Based on observation of the appliance the surge protector. Compartments arrisk of an electrical wiring a with NFPA 70, National August 100-8 Uses Not Fulless specifical flexible cords and following: (1) As a substitut structure (2) Where run the	ere were 13 full and 3 empty rs in the hospice utility room. re not segregated or labeled as ring an interview, Staff 2 or cylinders were full or empty by uges on the tanks. ders were stored against a wall or that was approximately 4 feet safety CODE STANDARD and equipment is in accordance ational Electrical Code. 9.1.2 is not met as evidenced by at was plugged into a multi-plug This affected one of four smoke and could result in an increased al fire. al Electrical Code, 1999 Edition.		147	Electrical wiring and edin accordance with NF National Electrical Cool 1. The six-plug surge primmediately removed fixitchen. 2. The Director of Envisorices removed the surge protector. 3. The Director of Envisorices will audit the building weekly for conwith six-plug surge production. 4. All audits will be rethe administrator or dead Any non-compliance with six-plug surge production of the quality accommittee for review a change to the policy and procedure.	per 70 le. Special de le se le	77750537

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 09/20/2012 FORM APPROVED OMB NO. 0938-0391

	TATEMENT OF DEFICIENCIES ND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 055079		(X2) MULTIPLE CONSTRUCTION A BUILDING 01 B. WING				(X3) DATE SURVEY COMPLETED 09/12/2012		
NAME OF PROVIDER OR SUPPLIER MISSION VIEW HEALTH CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1425 WOODSIDE DR SAN LUIS OBISPO, CA 93401						
(X4) ID PREFIX TAG	(EACH DEFICIEN	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PROVIDER'S PLAN O PREFIX (EACH CORRECTIVE AC TAG CROSS-REFERENCED TO DEFICIEN		CTION SHOULD BE O THE APPROPRIATE		(X5) COMPLETION DATE	
K 211 SS=D	similar openings (4) Where attache Exception: Fle permitted to be at accordance with the (5) Where concestructural ceilings ceilings, or floors (6) Where installed otherwise permitted Tindings: During a facility to wiring was observed. At 11:24 a.m., the into a six-plug surfing was observed. At 11:24 a.m., the into a six-plug surfing was observed. Where Alcohol Badispensers are into a compartment of the maximum in capacity shall be rooms) The dispensers from each other of the maximum of the compartment of the floor is call sprinklered.	ed to building surfaces exible cord and cable shall be stached to building surfaces in the provisions of Section 364-8. aled behind building walls, suspended ceilings, dropped ed in raceways, except as ed in this Code. Our on 9/12/12, the electrical ved. For was an ice machine plugged rege protector in the kitchen. For was hanging on the wall. AFETY CODE STANDARD estalled in a corridor: at least 6 feet wide individual fluid dispenser 1.2 liters (2 liters in suites of thave a minimum spacing of 4 ft to gallons are used in a single ent outside a storage cabinet, not installed over or adjacent to		211		SAM BERNARDING COGN.	27 M	STATE DEPT OF PUBLIC HEALTH	

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PKINTED: 09/20/2012 FORM APPROVED OMB NO. 0938-0391

AND PLAN OF CORRECTION IDE		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 055079	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 B. WING		(X3) DATE S COMPLI	URVEY ETED
MISSIO	PROVIDER OR SUPPLIER VIEW HEALTH CEI	NTER	5	STREET ADDRESS, CITY, STATE, ZIP O 1425 WOODSIDE DR SAN LUIS OBISPO, CA 93401	CODE	212012
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTI CROSS-REFERENCED TO THE DEFICIENCY	(X5) COMPLETION DATE	
	that ABHR dispension ignition sources. ABHR dispenser than ignition source, smoke compartment increased risk of a Findings: During the facility to dispensers were of At 10:02 a.m., the A	is not met as evidenced by: ation, the facility failed to ensure sers were not installed over This was evidenced by one nat was installed directly over This affected one of four ents, and could result in the fire. Dur on 9/12/12, the ABHR Deserved. ABHR dispenser in the soiled from 403, was installed directly	K 21	Where Alcohol Based F dispensers are installed corridor, Dispensers are installed corridor, Dispensers are installed over or adjacent ignition source. 1. The ABHR dispenser immediately removed from soiled linen room near 42. The Director of Envir Services removed the Addispenser from the soiled room near 403 3. The Director of Envir Services will immediate the entire building for Addispenser location comp 4. Any non-compliance and the assurance committee for and possible change to the and procedure.	in a not not not to an was om the 403. conmental BBR d linen SEP 20 minental bly audit linen bly audit line. with the the quality review	