PRINTED: 07/03/2024 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTI A. BUILDIN	PLE CONSTRUCTION IG 02	(X3) DATE SURVEY COMPLETED	
		055361	B. WING _		02	2/12/2024
	ROVIDER OR SUPPLIER	HOSPITAL		STREET ADDRESS, CITY, STATE, ZIP CODE 3662 PACIFIC AVENUE JURUPA VALLEY, CA 92509		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PREFIX (EACH CORRECTIVE ACTION SHOULD B		(X5) COMPLETION DATE
E 000	Initial Comments		E 0	00		
K 000	Department of Public Emergency Prepared The findings are in acceptable Emergency Prepared The findings are in acceptable Emergency Prepared The findings are in acceptable Emergency Prepared (In the facility is in substance Code of Federal Regular Requirement for Long Representing the Call Health: 40325 Census = 49 INITIAL COMMENTS Surveyor: 40325 K3 BUILDING: 01 K6 PLAN APPROVAL K7 SURVEY UNDER STRUCTURE TYPE: CONSTRUCTION TY SPRINKLERED. Resident Certified Be Resident Census: 49 The following reflects Department of Public Life Safety Code recepting the care in according to the consultation of the consultation of the consultation of the care findings are in according to the care of the c	ness recertification survey. cordance with 42 Code of (CFR) 483.73, Requirement LTC) Facilities. antial compliance with 42 ulations (CFR) 483.73, g Term Care (LTC) Facilities. ifornia Department of Public : 1971 : 2012 EXISTING ONE STORY, (PE V (111), FULLY ds: 49 the findings of the California Health, during an annual ertification survey. The	ΚO	00		
ABORATORY	DIRECTOR'S OR PROVIDER/S	SUPPLIER REPRESENTATIVE'S SIGNATURE	•	TITLE		(X6) DATE

03/04/2024 **Electronically Signed**

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDI	TIPLE CONSTRUCTION NG 02		(X3) DATE SURVEY COMPLETED	
		055361	B. WING _		02	2/12/2024	
	ROVIDER OR SUPPLIER	HOSPITAL		STREET ADDRESS, CITY, STATE, ZIP CODE 3662 PACIFIC AVENUE JURUPA VALLEY, CA 92509			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFII TAG	PROVIDER'S PLAN OF CORREC' X (EACH CORRECTIVE ACTION SHOUND CROSS-REFERENCED TO THE APPR DEFICIENCY)	JLD BE	(X5) COMPLETION DATE	
K 000	Life Safety Code, 201 Health Care Facilities Representing the Call Health: 40325 The facility is not in st 42 CFR §483.90 for L	on Association (NFPA) 101 - 2 Edition, and NFPA 99 - Code, 2012 Edition. ifornia Department of Public ubstantial compliance with ong Term Care Facilities.	K	000			
K 161 SS=D	Table 19.1.6.1, unless 19.1.6.2 through 19.1 19.1.6.4, 19.1.6.5 Construction	Type and Height type and stories meets otherwise permitted by .6.7	К-	161		2/28/24	
	1 I (442), I (33 stories sprinklered 2 II (111) non-sprinklered sprinklered 3 II (000) non-sprinklered 4 III (211) sprinklered 5 IV (2HH) 6 V (111) 7 III (200)	2), II (222) Any number of non-sprinklered and One story Maximum 3 stories Not allowed Maximum 2 stories Not allowed					

, ,		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILDIN	PLE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED
		055361	B. WING		02/12/2024
	ROVIDER OR SUPPLIER	HOSPITAL		STREET ADDRESS, CITY, STATE, ZIP CODE 3662 PACIFIC AVENUE JURUPA VALLEY, CA 92509	,
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE COMPLETION
K 161	system in accordance 19.3.5) Give a brief description construction, the numbasements, floors on location of smoke or approval. Complete splan of the building at This REQUIREMENT by: Surveyor: 40325 Based on observation failed to maintain the This was evidenced to in a ceiling. During a and flames to pass the affected visitors, staff one of three smoke of three smokes of	Maximum 1 story ust be sprinklered broved, supervised automatic ewith section 9.7. (See on, in REMARKS, of the other of stories, including which patients are located, fire barriers and dates of exetch or attach small floor is appropriate. To and interview, the facility in fire-rated construction. By an unsealed penetration fire, this could allow smoke brough the penetration. This is and 12 of 49 residents in compartments. To Code, 2012 Edition function and interview equipment, or safeguard provided to this Code shall be designed, and in accordance with	K 10	How corrective action(s) will be accomplished for those residents fou have been affected by the deficient practice; a) Maintenance assistant installed fin caulking around the cables at the hol the Social Services Office on 2/14/24 How the facility will identify other resi having the potential to be affected by same deficient practice and what corrective action will be taken; a) Maintenance supervisor conducter facility inspection on 2/16/24 to check any other penetrations missing fire caulking. What measures will be put into place what systemic changes the facility wi make to ensure that the deficient pradoes not recur;	e e in dents the d c for

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` '	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED	
		055361	B. WING _			02	/12/2024
	ROVIDER OR SUPPLIER	T HOSPITAL		366	REET ADDRESS, CITY, STATE, ZIP CODE 52 PACIFIC AVENUE RUPA VALLEY, CA 92509	,	
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	×	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD I CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	3E	(X5) COMPLETION DATE
K 161	authority having jurisdiction. 8.3.5 Penetrations. govern the materials used to protect through membrane penetrations. The proapply to approved e of construction used through-penetrations in fire wastance-rated horotherwise required to 8.4.4 Penetrations. govern the materials used to protect through membrane penetrations conduits, pipes, tube items to accommoda plumbing, and commoda plumbing, and commoda plumbing and commoda plumbing. On 2/12/24, during a Maintenance Assistance construction was obtained to the penetration measuri inches in diameter works and there was fire called the construction was diameter works and there was fire called the construction was diameter works and there was fire called the construction was diameter works and there was fire called the cal	The provisions of 8.3.5 shall and methods of construction agh-penetrations and tons in fire walls, fire barrier ance-rated horizontal positions of 8.3.5 shall not existing materials and methods to protect existing sound existing membrane walls, fire barrier walls, or fire izontal assemblies, unless by Chapters 11 through 43. The provisions of 8.4.4 shall so and methods of construction agh-penetrations and tons of smoke partitions. For cables, cable trays, es, vents, wires, and similar ate electrical, mechanical, munications systems that ke partition shall be protected erial that is capable of limiting e.	K	161	a) Maintenance supervisor will monito penetrations during each monhtly facilinspection b) Maintenance counseled I.T. Department on the importance of ensuring fire caulking on all penetration of comments of ensuring fire caulking on all penetration of the importance of notifying maintenance of any holes in the building maintenance of any holes in the building how the facility plans to monitor its performance to make sure that solutionare sustained. The facility must developlan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective accevaluated for its effectiveness. The Pois integrated into the quality assurance system; and a) The Maintenance supervisor will report to the Continuous Quality Improvement committee on the findings of his month inspections quarterly during Quality Assurance Meetings.	ns staff ng. st ction DC coort	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDII		CONSTRUCTION 2	(X3) DATE SURVEY COMPLETED	
		055361	B. WING _			02/	12/2024
	ROVIDER OR SUPPLIER	HOSPITAL		36	TREET ADDRESS, CITY, STATE, ZIP CODE 662 PACIFIC AVENUE URUPA VALLEY, CA 92509		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI TAG	×	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 161 K 352 SS=E	finding at the exit con Sprinkler System - St. CFR(s): NFPA 101 Sprinkler System - St. Automatic sprinkler system - St. Automatic sprinkler system attachments are instaintegrity in accordance Fire Alarm and Signal signal that sounds an continuously attended remote facility when simpaired. 9.7.2.1, NFPA 72 This REQUIREMENT by: Surveyor: 40325 Based on observation review, the facility fail sprinkler system. This supervisory switch wherequired notification of During a fire, this cou	inistrator acknowledged the ference. Ipervisory Signals Ipervisory Sig	K	352	How corrective action(s) will be accomplished for those residents found have been affected by the deficient practice; a) Troy Alarm repaired the PIV valve alarm on 2/16/24 and tested for compliance in the presence of the Maintenance Supervisor How the facility will identify other reside having the potential to be affected by the same deficient practice and what corrective action will be taken;	ents	2/28/24
	9.7.2.1* Supervisory sautomatic sprinkler sy another section of this attachments shall be	Signals. Where supervised vistems are required by some code, supervisory installed and monitored for e with NFPA 72, National			a) Maintenance supervisor conducted facility inspection on 2/16/24 to ensure any other PIV valves were functioning properly		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED	
		055361	B. WING		02/12/2024
	ROVIDER OR SUPPLIER	HOSPITAL	;	STREET ADDRESS, CITY, STATE, ZIP CODE 3662 PACIFIC AVENUE JURUPA VALLEY, CA 92509	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	
K 352	supervisory signal shacondition that would in operation of the sprint signals shall sound at at a location within the constantly attended be an approved, remotel Findings: On 2/12/24, during a Maintenance Assistant sprinkler system was At 2:42 p.m., during at Valve (PIV), the pane even though the sprint Observation of the PID between the PIV and Upon interview, the Morder. During a record inspection of 10/23/23 the PIV at street and The Maintenance Suptelephone interview the had been fixed at that report had a repair tice. At 3:55 p.m., the Admitsignals and a sprint of the Admitsignals are conditioned as the signal and the sprint of the Admitsignals.	ing Code, and a distinctive all be provided to indicate a mpair the satisfactory kler system. Supervisory and shall be displayed either a protected building that is y qualified personnel or at y located receiving facility. facility tour with the at (MA), the wet-pipe observed. I test of the Post Indicator I indication remained normal kler water was shut off. W showed exposed wiring the electric switch. IA stated there was a part on the review of the sprinkler B, the vendor reported that the OS&Y at Riser failed. Dervisor stated during a mat he believed the switch at time since the vendor kets. Inistrator acknowledged the	K 352	What measures will be put into place of what systemic changes the facility will make to ensure that the deficient practic does not recur; a) Maintenance supervisor will test the PIV valve every three months during the routine spirnkler testing to ensure proproperation. b) Maintenance supervisor inserviced son the Tamper Alarms funciton. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must develop plan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective act evaluated for its effectiveness. The PO is integrated into the quality assurance system; and a) The Maintenance supervisor will rep to the Continuous Quality Improvement committee on the findings of his quarte PIV valve testing quarterly during Quality Assurance Meetings.	e er staff staff st con cont tripy
K 353 SS=D	CFR(s): NFPA 101 Sprinkler System - Ma	ference. aintenance and Testing aintenance and Testing aintenance and Testing nd standpipe systems are	K 353		2/28/24
		d maintained in accordance			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055361	B. WING			02/	12/2024
	ROVIDER OR SUPPLIER	HOSPITAL	•	36	TREET ADDRESS, CITY, STATE, ZIP CODE 662 PACIFIC AVENUE URUPA VALLEY, CA 92509		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	Х	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 353	Protection Systems. I maintenance, inspect maintained in a secur available. a) Date sprinkler system sup b) Who provided system sup c) Water system sup provide in REMARKS any non-required or psystem. 9.7.5, 9.7.7, 9.7.8, and This REQUIREMENT by: Surveyor: 40325 Based on observation failed to maintain their This was evidenced by inches of sprinklers. It cause a malfunction of affected visitors, staff two of three smoke considered with the supervised automatic accordance with Section permitted by 19.3.5.5 9.7.5 Maintenance ar sprinkler and standpil Code shall be inspection.	and for the Inspection, ing of Water-based Fire Records of system design, ion and testing are to location and readily stem last checked stem test stem test stem test stem test stem and interview, the facility of the sprinkler system. This the sprinkler system in the systems required by this sted, tested, and maintained specific systems required by this sted, tested, and maintained specific systems required for the sprinkler system in the systems required by this sted, tested, and maintained specific systems required for the sprinkler system in the systems required by this sted, tested, and maintained specific systems required by this sted, tested, and maintained specific systems required for the sprinkler systems required by this sted, tested, and maintained specific systems required for the specific systems required by this sted, tested, and maintained specific systems required by this sted, tested, and maintained specific systems required by this sted, tested, and maintained specific systems required by this sted, tested, and maintained specific systems required by this sted systems required by this systems required by the systems required by this systems required by this systems required by this systems required by	K	353	How corrective action(s) will be accomplished for those residents found have been affected by the deficient practice; a) Maintenance assistant removed the shelves noted on the inspection on 2/16/24 How the facility will identify other reside having the potential to be affected by the same deficient practice and what corrective action will be taken; a) Maintenance supervisor conducted facility inspection on 2/16/24 to check from any other shelves less than 18 inchest clearance What measures will be put into place of what systemic changes the facility will	2 ents ne	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1 ' '	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED	
		055361	B. WING			02/	12/2024
	ROVIDER OR SUPPLIER	HOSPITAL		36	TREET ADDRESS, CITY, STATE, ZIP CODE 662 PACIFIC AVENUE URUPA VALLEY, CA 92509		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	х	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 353	and Maintenance of N Systems, 2011 Editio 5.2.1.1* Sprinklers shifloor level annually. 5.2.1.1.1* Sprinklers sheakage; shall be free materials, paint, and be installed in the corupright, pendent, or s 5.2.1.2* The minimun installation standard sprinkler deflectors. 5.2.1.3 Stock, furnish the sprinkler deflector clearance rules of the be corrected. NFPA 13, Standard for Systems, 2010 Editio 8.5.5.2* Obstruction Pattern Development 8.5.5.2.1 Continuous obstructions less than below the sprinkler depattern from fully dev 8.5.5.2. Sprinklers special requirements Section 8.12 so that the away from obstruction Discharge from Reac Continuous or noncord	or the Inspection, Testing, Vater-Based Fire Protection all be inspected from the shall not show signs of of corrosion, foreign ohysical damage; and shall rect orientation (e.g., idewall). In clearance required by the shall be maintained below all sings, or equipment closer to than permitted by the installation standard shall or the Installation of Sprinkler in s to Sprinkler Discharge or noncontinuous in or equal to 18 in. (457 mm) effector that prevent the eloping shall comply with thall be positioned in minimum distances and of Section 8.6 through they are located sufficiently as such as truss webs and as, and fixtures. s That Prevent Sprinkler	K	353	make to ensure that the deficient practice does not recur; a) Maintenance supervisor will monitor 18 inch clearance furing his monthly facility inspections. b) Maintenance supervisor inserviced son the importance of not blocking the fisprinklers, and being ensuring 18 inch clearance. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must develop plan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective act evaluated for its effectiveness. The PO is integrated into the quality assurance system; and a) The Maintenance supervisor will rep to the Continuous Quality Improvement committee on the findings of his month inspections quarterly during Quality Assurance Meetings.	for staff re ns p a st tion oC	

PRÉFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE COMPLE			(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPL A. BUILDING	E CONSTRUCTION 02		(X3) DATE SURVEY COMPLETED		
VISTA PACIFICA CONVALESCENT HOSPITAL 3662 PACIFIC AVENUE JURUPA VALLEY, CA 92509			055361	B. WING		0:	2/12/2024		
REGULATORY OR LSC IDENTIFYING INFORMATION) K 353 Continued From page 8 more than 18 in. (457 mm) below the sprinkler deflector in a manner to limit the distribution from reaching the protected hazard shall comply with 8.5.5.3. 8.5.5.3.1 Sprinklers shall be installed under fixed obstructions over 4 ft (1.2 m) wide such as ducts, decks, open grate flooring, cutting tables, and overhead doors. 8.5.5.3.2 Sprinklers installed under open gratings shall be of the intermediate level/rack storage type or otherwise shielded from the discharge of overhead sprinklers. 8.5.6.1 * Unless the requirements of 8.5.6.2, 8.5.6.3, 8.5.6.4, or 8.5.6.5 are met, the clearance between the deflector and the top of storage shall be 18 in. (457 mm) or greater. Findings: On 2/12/24, during a facility tour with the Maintenance Assistant (MA), the wet-pipe sprinkler system was observed.			IT HOSPITAL		3662 PACIFIC AVENUE	·			
more than 18 in. (457 mm) below the sprinkler deflector in a manner to limit the distribution from reaching the protected hazard shall comply with 8.5.5.3. 8.5.5.3.1 Sprinklers shall be installed under fixed obstructions over 4 ft (1.2 m) wide such as ducts, decks, open grate flooring, cutting tables, and overhead doors. 8.5.5.3.2 Sprinklers shall not be required under obstructions that are not fixed in place such as conference tables. 8.5.5.3.3 * Sprinklers installed under open gratings shall be of the intermediate level/rack storage type or otherwise shielded from the discharge of overhead sprinklers. 8.5.6.* Clearance to Storage. 8.5.6.1 * Unless the requirements of 8.5.6.2, 8.5.6.3, 8.5.6.4, or 8.5.6.5 are met, the clearance between the deflector and the top of storage shall be 18 in. (457 mm) or greater. Findings: On 2/12/24, during a facility tour with the Maintenance Assistant (MA), the wet-pipe sprinkler system was observed.	PRÉFIX	(EACH DEFICIEN	ICY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP	OULD BE	(X5) COMPLETION DATE		
deflector in a manner to limit the distribution from reaching the protected hazard shall comply with 8.5.5.3. 8.5.5.3.1 Sprinklers shall be installed under fixed obstructions over 4 ft (1.2 m) wide such as ducts, decks, open grate flooring, cutting tables, and overhead doors. 8.5.5.3.2 Sprinklers shall not be required under obstructions that are not fixed in place such as conference tables. 8.5.5.3.3 * Sprinklers installed under open gratings shall be of the intermediate level/rack storage type or otherwise shielded from the discharge of overhead sprinklers. 8.5.6.1 * Unless the requirements of 8.5.6.2, 8.5.6.3 * 8.5.6.4, or 8.5.6.5 are met, the clearance between the deflector and the top of storage shall be 18 in. (457 mm) or greater. Findings: On 2/12/24, during a facility tour with the Maintenance Assistant (MA), the wet-pipe sprinkler system was observed.	K 353	Continued From pag	ge 8	K 35	3				
Resident Sleeping Room 9, the top of the shelf unit was approximately 10 inches from the sprinkler deflector. 2. At 12:36 p.m., in the Storage room opposite Resident Sleeping Room 16, the top of the shelf unit was approximately 8 inches from the sprinkler deflector. Upon interview, the MA stated he would remove		more than 18 in. (45 deflector in a manner reaching the protect 8.5.5.3. 8.5.5.3.1 Sprinklers obstructions over 4 decks, open grate floverhead doors. 8.5.5.3.2 Sprinklers obstructions that are conference tables. 8.5.5.3.3 * Sprinkler gratings shall be of storage type or othe discharge of overhe 8.5.6 * Clearance to 8.5.6.1 * Unless the 8.5.6.3, 8.5.6.4, or 8 between the deflect be 18 in. (457 mm) Findings: On 2/12/24, during a Maintenance Assists sprinkler system was 1. At 12:16 p.m., in Resident Sleeping Funit was approximate sprinkler deflector. 2. At 12:36 p.m., in Resident Sleeping Funit was approximate sprinkler deflector.	for mm) below the sprinkler or to limit the distribution from the hazard shall comply with shall be installed under fixed ft (1.2 m) wide such as ducts, ooring, cutting tables, and shall not be required under enot fixed in place such as installed under open the intermediate level/rack envise shielded from the ad sprinklers. Storage. Trequirements of 8.5.6.2, 8.5.6.5 are met, the clearance for and the top of storage shall for greater. The Storage room near Room 9, the top of the shelf tely 10 inches from the stely 8 inches from the stell stelly 8 inches from the stell stelly 8 inches from the stell stelly 8 inches from the stell stel						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055361	B. WING			02/	12/2024
	ROVIDER OR SUPPLIER	HOSPITAL		36	TREET ADDRESS, CITY, STATE, ZIP CODE 662 PACIFIC AVENUE URUPA VALLEY, CA 92509		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 353	Continued From page At 3:55 p.m., the Adm	e 9 ninistrator acknowledged the	К	353			
K 355 SS=E			К	355			2/28/24
	inspected, and mainta NFPA 10, Standard for Extinguishers. 18.3.5.12, 19.3.5.12, This REQUIREMENT by: Surveyor: 40325 Based on observation failed to properly sect extinguishers. This we fire extinguishers four cabinets. This could of topple during a seism and possibly causing 49 residents in three compartments. NFPA 101, Life Safetty 9.7.4 Manual Extinguishers shall be inspected, and mainta NFPA 10, Standard for Extinguishers. NFPA 10, Standard for Extinguishers, 2010 Extinguisher, 201	shers are selected, installed, ained in accordance with or Portable Fire NFPA 10 In and interview, the facility are their portable fire as evidenced by portable and unsecured in their cause the extinguishers to aic event, inhibiting their use damage. This affected 49 of of three smoke y Code, 2012 ishing Equipment. The experimental end by the provisions of as Code, portable fire as selected, installed, ained in accordance with or Portable Fire or Portable Fire			How corrective action(s) will be accomplished for those residents found have been affected by the deficient practice; a) Maintenance assistant installe dmounting brackets in the fire extinguisher boxes and hung up the extinguishers on 2/16/24 How the facility will identify other reside having the potential to be affected by the same deficient practice and what corrective action will be taken; a) Maintenance supervisor conducted facility inspection on 2/16/24 to check for any other extinguishers freestanding in cabinets with loose plastic covers. What measures will be put into place of what systemic changes the facility will make to ensure that the deficient practic does not recur;	ents ne for r	

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055361	B. WING _			0:	2/12/2024
NAME OF P	ROVIDER OR SUPPLIER			S	TREET ADDRESS, CITY, STATE, ZIP CODE	1	
VICTA DA	CIEICA CONVALESCENT	LOCDITAL		36	662 PACIFIC AVENUE		
VISTAPAG	CIFICA CONVALESCENT	HOSPITAL		Jl	URUPA VALLEY, CA 92509		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI) TAG	x	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD E CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE
K 355	Continued From page	e 10	K 3	355			
K 355	wheeled extinguisher of the following mean (1) Securely on a har extinguisher (2) In the bracket supmanufacturer (3) In a listed bracket (4) In cabinets or wal 6.1.3.7 Fire extinguis conditions where they damage (e.g., from in environment) shall be Findings: On 2/12/24, during a Maintenance Assistant extinguishers were of At 12:22 p.m., four firthroughout the facility cabinets. The extinguinside the cabinets, we covers that could not fell over during a seis extinguishers were positive to the corridor across the corridor by Fall	s shall be installed using any s: ger intended for the plied by the extinguisher approved for such purpose recesses hers installed under y are subject to physical heact, vibration, the protected against damage. facility tour with the ht (MA), the portable fire beerved. e extinguishers, located y, were located in unsecured hishers were freestanding which had loose plastic support the extinguisher if it mic event. The besitioned as follows: hes from Resident Sleeping Resident Sleeping Room 7 hes from Resident Sleeping Resident Sleeping Room 21 has stated the extinguishers could fall through the plastic	K	355	a) Maintenance supervisor will monitor ensure extinguishers are being kept or brackets monthly during his facility inspection b) Maintenance supervisor inserviced on ensuring the fire extinguishers are hanging on the brakets inside the cabinets. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must developlan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective ac evaluated for its effectiveness. The PC is integrated into the quality assurance system; and a) The Maintenance supervisor will rept to the Continuous Quality Improvement committee on the findings of his month inspections quarterly during Quality Assurance Meetings.	ns p a st tion DC e	
	Upon interview, the N were unsecured and cover during a seismi	IA stated the extinguishers could fall through the plastic					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL		CONSTRUCTION 2	(X3) DATE SURVEY COMPLETED	
		055361	B. WING			02/	12/2024
	ROVIDER OR SUPPLIER	HOSPITAL		36	TREET ADDRESS, CITY, STATE, ZIP CODE 662 PACIFIC AVENUE URUPA VALLEY, CA 92509		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 355 K 711 SS=D	patients and for their an emergency. Employees are period informed with their ducopy of the plan is read operator or with secul basic response requir and provides for all of components per 18/1 18.7.1.1 through 18.7 18.7.2.3, 19.7.1.1 through 19.7.2.2, 19.7.2.3 This REQUIREMENT by: Surveyor: 40325 Based on observation review, the facility fail trained in all componerelocation plan. This cuntrained and unable This could delay facili notification of a fire. The residents in three of the NFPA 101, Life Safety 19.7.2.3 Staff Resport 19.7.2.3.1 All health of the residents in the patients of the safety 19.7.2.3.1 All health of the residents are period to the safety 19.7.2.3.1 All health of the safety 19.7.2.3.1	cation Plan cation Plan for the protection of all evacuation in the event of dically instructed and kept ties under the plan, and a adily available with telephone rity. The plan addresses the red of staff per 18/19.7.2.1.2 if the fire safety plan 9.2.2. 1.1.3, 18.7.2.1.2, 18.7.2.2, bugh 19.7.1.3, 19.7.2.1.2, is not met as evidenced a, interview, and record ed to ensure staff were ents of their evacuation and was evidenced by staff to activate the fire alarm. Ity and fire department this affected 49 of 49 three smoke compartments.		711	How corrective action(s) will be accomplished for those residents found have been affected by the deficient practice; a) Maintenance supervisor counseled to staff who were unable to activate the finalarm. How the facility will identify other reside having the potential to be affected by the same deficient practice and what corrective action will be taken; a) Maintenance supervisor inserviced so nhow to activate the fire alarm, include a demonstration of ensuring to remove the tamper alarm cover and pull down of the same activate the same activate the same activate to the same activate the same ac	the re ents ne staff ling	2/28/24

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED	
		055361	B. WING		02/12/2024	
NAME OF PROVIDER OR SUPPLIER VISTA PACIFICA CONVALESCENT HOSPITAL			STREET ADDRESS, CITY, STATE, ZIP CODE 3662 PACIFIC AVENUE JURUPA VALLEY, CA 92509			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	BE COMPLETION	
K 711	Continued From page 12 On 2/12/24, during a facility tour and record review with the Maintenance Assistant, the Evacuation and Relocation plan was reviewed and staff response assessed. At 2:30 p.m., during a fire alarm test, staff were unable to activate the fire alarm. The surveyor asked a staff member to find the nearest fire alarm pull station and activate it. She removed the tamper box, which covered the pull station. This set off a loud alarm. She did not further activate the pull station. She was prompted to activate the pull station but was still unable to activate it. Upon interview, the staff member stated she was trained on the activation of fire alarms about six years ago, but had never actually practiced setting one off. At 3:55 p.m., the Administrator acknowledged the finding at the exit conference.		K 7	what measures will be put into place what systemic changes the facility wil make to ensure that the deficient practions on to activate the fire alarm. b) Fire Drill consultants will meet with monthly for fire drills and be sure to include the actions needed to activate alarm. How the facility plans to monitor its performance to make sure that solutic are sustained. The facility must developlan for ensuring that correction is achieved and sustained. This plan mube implemented, and the corrective are evaluated for its effectiveness. The Pris integrated into the quality assurance system; and a) The Maintenance supervisor will reto the Continuous Quality Improveme committee on the findings of his mont quizing of staff quarterly during Quality Assurance Meetings.	or tice aff how staff the ins op a ist ction OC e port ht hly y	
K 753 SS=D	CFR(s): NFPA 101 Combustible Decorati	ons	K 75	53	2/28/24	
	unless one of the follo	ons shall be prohibited owing is met: or treated with approved				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA (X2) MU IDENTIFICATION NUMBER: A. BUILI		LE CONSTRUCTION 02	(X3) DATE SURVEY COMPLETED	
		055361	B. WING		02/12/2024	
NAME OF PROVIDER OR SUPPLIER VISTA PACIFICA CONVALESCENT HOSPITAL			STREET ADDRESS, CITY, STATE, ZIP CODE 3662 PACIFIC AVENUE JURUPA VALLEY, CA 92509			
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	_D BE COMPLÉTION	
K 753	fire-retardant coating product. o Decorations mere o Decorations, such and other art are attared and non-fire-rated do 18.7.5.6(4) or 19.7.5 o The decorations in such limited quant development or spreading to the such limited quant development of the such limited quant development of the following of the follo	et NFPA 701. ibit heat release less than ordance with NFPA 289. ch as photographs, paintings ached to the walls, ceilings fors in accordance with .6(4). in existing occupancies are ities that a hazard of fire ad is not present. T is not met as evidenced In and interview, the facility exafety in the use of fors. This was evidenced by ed with non-fire-rated cause the rapid spread of turing a fire. This affected for 49 residents in one of the the secondary unless criteria is met: Extra Code, 2012 edition expected and in to the material to which it is meet the requirements of Methods of Fire Tests for of Textiles and Films. exhibit a heat release rate	K 75	How corrective action(s) will be accomplished for those residents fo have been affected by the deficient practice; a) Activities staff removed the decorform the door on 2/12/24. How the facility will identify other rehaving the potential to be affected be same deficient practice and what corrective action will be taken; a) Maintenance supervisor conduct facility inspection on 2/16/24 to che any other combustable decorations covering corridor doors. What measures will be put into place what systemic changes the facility wake to ensure that the deficient predoes not recur;	rations sidents by the ed ck for	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED		
		055361	B. WING			02/	12/2024
NAME OF PROVIDER OR SUPPLIER VISTA PACIFICA CONVALESCENT HOSPITAL			STREET ADDRESS, CITY, STATE, ZIP CODE 3662 PACIFIC AVENUE JURUPA VALLEY, CA 92509				
(X4) ID PREFIX TAG	(EACH DEFICIENC)	Y MUST BE PRECEDED BY FULL	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 753			K	753	a) Maintenance supervisor will monitor inappropriate use of combustable decorations during each monhtly facility inspection b) Maintenance supervisor inserviced son the importance of keeping the fire doors free from flamables or decoration. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must develop plan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective act evaluated for its effectiveness. The PO is integrated into the quality assurance system; and a) The Maintenance supervisor will rep to the Continuous Quality Improvement committee on the findings of his month inspections quarterly during Quality Assurance Meetings.	etaff ins. is is is c o o o o o o o o o o o o	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055361	B. WING _			02/12/2024	
NAME OF PROVIDER OR SUPPLIER VISTA PACIFICA CONVALESCENT HOSPITAL				STREET ADDRESS, CITY, STATE, ZIP CO 3662 PACIFIC AVENUE JURUPA VALLEY, CA 92509	DDE		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG			(X5) COMPLETION DATE	
K 753	At 12:31 p.m., the cor Room/Day Room wer covered with plastic d in the form of a flat sh over the doors. Upon did not believe the ma	ridor doors to the Living re approximately 50 percent lecorations. The plastic was neet and was used to paper interview, the MA stated he aterial was fire-rated. ninistrator acknowledged the	K7	753			