## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/29/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  055361		IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A BUILDING 01  B. WING		(X3) DATE SURVEY COMPLETED 08/28/2012	
	ROVIDER OR SUPPLIE	SCENT HOSPITAL		REET ADDRESS, CITY, STATE. ZIP CO 3662 PACIFIC AVENUE RIVERSIDE, CA 92509	DDE	
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES ICY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE	(X5) COMPLETION DATE
K 000	STRUCTURE TY SPRINKLERED. The following ref Department of Pr Life Safety Code findings are in ac Federal Regulati (National Fire Pr Safety Code 200 Representing the Health: 27961	1	K 000	This plan of correction is surequired under Federal and regulations and statues apply Term Care providers. This Correction does not constitute of liability on the part of the such liability is herby specify The submission of the Plan constitute agreement by the surveyor's finding or conclusion accurate, that the findings of deficiency, or that the scope cited are correctly applied. Correction constitutes my wallegation of compliance for noted.	State licable to Long Plan of the an admission e facility and lically denied. does not facility that the asion are constitute a e or severity This plan of written credible the deficiencies	
K 018 SS=D	Doors protecting required enclosus hazardous areas those constructe wood, or capable minutes. Doors required to resist no impediment to are provided with the door closed, are permitted.  Roller latches are in all health care	corridor openings in other than res of vertical openings, exits, or are substantial doors, such as d of 1¾ inch solid-bonded core of resisting fire for at least 20 in sprinklered buildings are only the passage of smoke. There is the closing of the doors. Doors a means suitable for keeping Dutch doors meeting 19.3.6.3.6 19.3.6.3  The prohibited by CMS regulations facilities.	K 018	3	SEP 12	STATE DEPT OF

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program, participation.

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID GJNF21

Facility ID: CA240000154

If continuation sheet Page 1 of 5

PRINTED: USIZYIZUTZ DEPARTMENT OF HEALTH AND HUMAN SERVICES FORM APPROVED CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 (X3) DATE SURVEY (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES IDENTIFICATION NUMBER: COMPLETED AND PLAN OF CORRECTION A. BUILDING 01 B. WING 055361 08/28/2012 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 3662 PACIFIC AVENUE VISTA PACIFICA CONVALESCENT HOSPITAL RIVERSIDE, CA 92509 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION 10 (X5) COMPLETION (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX PREFIX CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) Continued From page 1 K 018 K 018 A. Specific actions to correct deficiency Maintenance assistant adjusted self closer and added a spring hinge to the clothing room 8/28/2012 door to ensure a positive latch upon closure This STANDARD is not met as evidenced by: B. Systems put in place to ensure deficient Based on observation, the facility failed to practice does not recur and person responsible maintain corridor doors to resist the passage of Maintenance Supervisor will conduct monthly smoke as evidenced by corridor doors that failed inspections to ensure corridor doors upon to positive latch. This affected 1 of 3 smoke closure have a positive latch. compartments, and had the potential to allow the migration of smoke causing harm to residents C. How facility plans to monitor corrective and staff. actions MS to report findings to administrator at Findings: quarterly Quality Assurance Committee. During the facility tour with the Maintenance Supervisor and the Housekeeping Supervisor on August 28, 2011, the corridor doors were observed. At 11:23 A.M., the door to the Clothing Room was equipped with a self closing device. The door was held open to the fullest extent and allowed to close, but failed to positive latch upon closure. NFPA 101 LIFE SAFETY CODE STANDARD K 029 K 029 SS=D One hour fire rated construction (with 3/4 hour

fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed

## DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 08/29/2012 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION				ULTIPLE LDING IG	ECONSTRUCTION 01	(X3) DATE SURVEY COMPLETED 38/28/2012	
	ROVIDER OR SUPPLIE	SCENT HOSPITAL		3662	T ADDRESS, CITY, STATE, ZIP COI 2 PACIFIC AVENUE ERSIDE, CA 92509		
(X4) ID PREFIX TAG	(EACH DEFICIEN	STATEMENT OF DEFICIENCIES NCY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF COR (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE
K 029	This STANDARD NFPA 101®, Lift 19.3.2.1 Hazards shall be safegua 1-hour fire resist with an automati accordance with extinguishing shaccordance with option is used, the other spaces by doors. The door automatic-closin but shall not be (1) Boiler and fu (2) Central/bulk m2) (3) Paint shops (4) Repair shops	D is not met as evidenced by: e Safety Code, 2000 Edition ous Areas. Any hazardous areas rded by a fire barrier having a ance rating or shall be provided c extinguishing system in 8.4.1. The automatic all be permitted to be in 19.3.5.4. Where the sprinkler ne areas shall be separated from smoke-resisting partitions and s shall be self-closing or g. Hazardous areas shall include, restricted to, the following: el-fired heater rooms laundries larger than 100 ft2 (9.3	K	029	DEFICIENCY)		
	(5) Soiled linen (6) Trash collect (7) Rooms or spincluding repair combustible supdeemed hazard jurisdiction (8) Laboratories combustible mathose that would exception: Door permitted to have	rooms tion rooms taces larger than 50 ft2 (4.6 m2), shops, used for storage of oplies and equipment in quantities ous by the authority having  employing flammable or terials in quantities less than d be considered a severe hazard. es in rated enclosures shall be			AMARO COUNTY		

ENTERS	FOR MEDICAR	H AND HUMAN SERVICES E & MEDICAID SERVICES	1		OMB NO.  (X3) DATE SU	
TATEMENT OF DEFICIENCIES ND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A BUILDING 01		COMPLE"	
		055361	B. WING _		08/28	3/2012
	OVIDER OR SUPPLIER	SCENT HOSPITAL	3	REET ADDRESS, CITY, STATE, ZIP C 8662 PACIFIC AVENUE RIVERSIDE, CA 92509	ODE	
(X4) ID PREFIX TAG	CACH DECICIEN	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTIO CROSS-REFERENCED TO TH DEFICIENCY)	N SHOULD BE E APPROPRIATE	(X5) COMPLETION DATE
	Based on observ hazardous areas evidenced by a h did not have a seallow the spread hazardous area to finjury to reside 3 smoke compartings:  During a tour of Supervisor and the August 28, 2012 observed.  At 12:50 P.M., the Room containing other medical ecapproximately 8 a self-closing den NFPA 101 LIFE.  Exit access is all accessible at all 7.1. 19.2.1	ation, the facility failed to protect with self-closing doors. This was azardous area with a door that elf closing device. This could of smoke and fire from one to another, and increase the risk ents and staff. This affected 1 of	K 029	A. Specific actions to corre Maintenance assistant added the storage room door in the floor pads kept in room mee fire retardant.  B. Systems put in place to practice does not recur an responsible Maintenance Supervisor wil inspections to ensure approp self closing doors.  C. How facility plans to m actions Maintenance Supervisor findings to administrator Quality Assurance Comm	l a spring hinge to dinning room. All tall regulations as ensure deficient d person I conduct monthly priate rooms have onitor corrective will report at quarterly	0/20/2012

CENTER	S FOR MEDICAR	H AND HUMAN SERVICES E & MEDICAID SERVICES	7			0938-0391
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01  B. WING		JRVEY TED 8/2012
	0.000.017.000.000		1	TREET ADDRESS, CITY, STATE, ZIP CO		0/12012
	ROVIDER OR SUPPLIER	SCENT HOSPITAL	3	3662 PACIFIC AVENUE RIVERSIDE, CA 92509		
(X4) ID PREFIX TAG	JEACH DESIGIEN	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL R LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE	(X5) COMPLETION DATE
K 038	corridor, exit discoshall be in accord 7.1.10 Means of 7.1.10.1* Means maintained free of impediments to for other emerger Based on observe maintain their extradily accessible evidenced by placoncrete walkwase emergency exit foculd result in a evacuation, and compartments.  Findings:  During the tour of Supervisor and August 28, 2012 At 11:35 A.M., the Dinning Roogrowing on it the wide, by 3 feet by wide, by 3 feet by 3 fe	Every aisle, passageway, harge, exit location, and access dance with Chapter 7.  Egress Reliability. of egress shall be continuously of all obstructions or ull instant use in the case of fire news.  Vation, the facility failed to it access so that exits were e at all times. This was ant growth that obstructed the sy that was used as an from the Dinning Room. This delay in egress in the event of an affected 1 of 3 smoke  of the facility with Maintenance the Housekeeping Supervisor on a the exit access was observed.  The concrete walkway leading from the the parking lot had plants at measured approximately 3 feet ong, by 2 feet high. The plants ted the concrete walkway, which	K 03	A. Specific actions to corre Maintenance assistant cut ba partially obstructing the door opening.  B. Systems put in place to opractice does not recur and responsible MS informed gardener all bu kept neat and trimmed MS will inspect monthly tha bushes from obstructing exit  C. How facility plans to me actions MS to report findings to adr quarterly Quality Assurance	ensure deficient diperson ashes need to be t gardener keeps doors.	