PRINTED: 02/07/2013 FORM APPROVED OMB NO. 0938-0391

	ATEMENT OF DEFICIENCIES D PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) M A. BU		PLE CONSTRUCTION  O1 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED	
		055873	B. WII	NG	· · · · · · · · · · · · · · · · · · ·	01/3	0/2013
	ROVIDER OR SUPPLIER	LA MESA, LP		86	EET ADDRESS, CITY, STATE, ZIP CODE 65 LA MESA BLVD. A MESA, CA 91942		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			PROVIDER'S PLAN OF CORRECTION PREFIX TAG  PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)			(X5) COMPLETION DATE
K 000 K 029 SS=D	STRUCTURE TYPE BASEMENT/GAR/SPRINKLERED.  The following reflect Department of Publifier Safety Code refindings are in accomplished Frederal Regulation (National Fire Protosafety Code 2000 Representing the CHealth: 29566.  Census: 106 NFPA 101 LIFE SA	AL: 1968 ER: 2000 EXISTING E: SINGLE STORY AND AGE, TYPE (V) (111), FULLY  ets the findings of the California dic Health, during an annual e-certification survey. The ordance with 42 CFR (Code of is) 483.70 (a) and NFPA ection Association) 101, Life edition, Existing codes.  California Department of Public		029	This Plan of Correction is submitted by the facility in accordance with the pertine terms and provisions of relatife and Safety Code regula and is intended to serve as credible allegation of our incorrect the isolated practice identified as deficient.  K 029 NFPA 101 LIFE SAFE CODE STANDARD  Scope & Severity: "D"- Isolated Specific Action and/or measure to correct the deficiency:  On 1/30/13, door closers for transition storage room and electroom were immediately instales.  Staff responsible for the conaction:  The Maintenance Supervisor designee and the Administrations.	ated tions tent to es TY ated sures the trical lled. errective	
	fire-rated doors) or extinguishing syste and/or 19.3.5.4 pro the approved auto- option is used, the other spaces by sr doors. Doors are field-applied protect	construction (with ¾ hour an approved automatic fire em in accordance with 8.4.1 stects hazardous areas. When matic fire extinguishing system areas are separated from noke resisting partitions and self-closing and non-rated or stive plates that do not exceed bottom of the door are 2.1			Systemic Change Impleme and Performance and Com Monitoring and POC Evaluation.  1. During daily maintenance rounds, the Maintenance Supervisor shall inspect hazardous area doors to that these doors are equivith appropriate door closed facilitate self-closing as a Any identified non-composhall be immediately cor	e e e e e e e e e e e e e e e e e e e	

other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 da following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 1 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) M A. BUI		PLE CONSTRUCTION  3 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED	
	055873		B. WING			01/30/2013	
	PROVIDER OR SUPPLIER	LA MESA, LP	1	86	EET ADDRESS, CITY, STATE, ZIP CODE 165 LA MESA BLVD. A MESA, CA 91942		
(X4) ID PREFIX TAG				ıx	TION ULD BE ROPRIATE	(X5) COMPLETION DATE	
K 029	This STANDARD is Based on observation the corridor from his by the janitor close equipped with selfof 3 smoke comparting spread of smokrisk of injury to resistevent of a fire.  National Fire Preves Safety Code 2000  19.3.2.1 Hazardous shall be safe guard shour fire resistance with an automatic eaccordance with 8.	s not met as evidenced by: tion, the facility failed to protect azardous areas as evidenced t and electrical room not closing device. This affected 2 tments. This could result in the and fire and increase the dents, visitors and staff in the	K	029	2. Compliance reports which include immediate corrective actions taken shall be reported the monthly Safety Committee for the recommendations and/or pertinent Quality Improvem actions.  Completion date: 2/30/13 and ongoing	rted to ttee / urther nent	
	accordance with 19 option is used, the other spaces by sn doors. The doors s automatic closing, shall not be restrict  (1) Boiler and fuel-(2) Cental/bulk laur (9.3 square m)  (3) Paint shops (4) Repair shops (5) Soiled linen roo (6) Trash collection (7) Rooms or space	a.3.5.4. Where the sprinkler areas shall be separated from noke -resisting partitions and hall be self-closing or Hazardous shall include, but ed to, the following:  fired heater rooms and hall be self-closing or Hazardous shall include, but ed to, the following:					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		1 '	LDING	PLE CONSTRUCTION  O1 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED		
		055873	B. WI	1G	_ <del></del>	01/3	0/2013
NAME OF PROVIDER OR SUPPLIER  COMMUNITY CONV HOSP OF LA MESA, LP				86	EET ADDRESS, CITY, STATE, ZIP CODE 65 LA MESA BLVD. A MESA, CA 91942		
(X4) ID PREFIX TAG			PREF	ID PROVIDER'S PLAN OF CORRECT PREFIX (EACH CORRECTIVE ACTION SHOTT CROSS-REFERENCED TO THE APPRICATION		ULD BE	(X5) COMPLETION DATE
K 029	storage of combus quantities deemed having jurisdiction. (8) Laboratories en combustible materithose that would be Exception: Doors i permitted to have rapplied protective than 48 in. (122 cm door.  Findings:	tible supplies and equipment in hazardous by the authority inploying flammable or itals in quantities less than a considered a severe hazard in rated enclosures shall be non-rated, factory-or field plates extending not more in above the bottom of the	K	029	K 048 NFPA 101 LIFE SAFE CODE STANDARD	ΤΥ	
		e facility with the Maintenance B, the hazardous areas doors			Scope & Severity: "D"- Isola	ated	
K 048 SS=C	equipped with a se storage room store and other combust 2. At 4:20 p.m., the 307(sub-acute) was elf-closing device NFPA 101 LIFE SATThere is a written patients and for the	e eletrical room by Rom s not equipped with a	ĸ	048	Specific Action and/or measto correct the deficiency:  On 1/30/12 and ongoing, affects staff were immediately re-educed regarding the sprinkler anti-tax system and its location, use, of purpose. Staff were re-education the event that the sprinkler buzzed, they are to immediate the Maintenance Supervisor/designee and/or the Administrator/designee.	cted cated mper or ted that system aly call	
	Based on observa failed to instruct the	is not met as evidenced by: tion and interview, the facility eir staff on their role to protect ne event of an emergency. This			Staff responsible for the conaction:  Director of Staff Development Maintenance Supervisor, and Administrator.		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDI	TIPLE CONSTRUCTION  NG 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED				
		055873	B. WING	<u> </u>	01/30/2013				
NAME OF PROVIDER OR SUPPLIER  COMMUNITY CONV HOSP OF LA MESA, LP			STREET ADDRESS, CITY, STATE, ZIP CODE  8665 LA MESA BLVD.  LA MESA, CA 91942						
(X4) ID PREFIX TAG	(EACH DEFICIENT	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPR DEFICIENCY)	ULD BE COMPLETION				
K 048	with their duties we tampered. This comaintenance of prosystem.  NFPA 101, Life Scale 19.7.1.3 Employes shall be instructed devices.  Findings:  During the facility Director on 1/30/1 sprinkler system the staff were intended of the staff were intended of Three staff mere action they were the was activated at the NFPA 101 LIFE Scale Required automatic condition and are periodically. 19.25, 9.7.5	the staff's lack of familiarity then the sprinkler system was ould result in failure to notify roblems with the sprinkler  afety Code, 2000 Edition as of health care occupancies in life safety procedures and  tour with the Maintenance 3, the facility automatic amper alarm was tested, and rviewed to determine their tamper alarm.  camper switch was activated and d at the Nurse's Station. Three mbers could not relate what to take when the tamper alarm	K 048	Monitoring and POC Evaluation  1. Quarterly during drills, the Maintenance Supervisor activate the tamper switch observe and ask staff or their roles are when the sounded. Any staff ident be unfamiliar with the spansystem shall receive immon-site re-education.  2. Compliance reports shall reported to the monthly. Committee and to the quality Assurance Committee recommendations pertinent Quality Improve actions.  Completion date: 2/30/13 a ongoing	ation:  ae shall ch and what alarm is iffied to rinkler mediate  I be Safety warterly mittee for s and/or ement				

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1, -,	IULTIP ILDING	PLE CONSTRUCTION  O1 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED		
	055873			NG		01/30/2013		
	ROVIDER OR SUPPLIER	LA MESA, LP	<b>'</b>	86	EET ADDRESS, CITY, STATE, ZIP CODE 65 LA MESA BLVD. A MESA, CA 91942			
(X4) ID PREFIX TAG				ix	PROVIDER'S PLAN OF CORRECTIVE ACTION SHO (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	DULD BE	(X5) COMPLETION DATE	
K 062	maintain their autorevidenced by Fire (FDC) failed to rot of 3 smoke compacause delay for fire due to the faulty sypossible harm to reof a fire.  NFPA 25, Inspection Water Based Fire I Edition  9-7.1 Fire Departminspected quarterly the following: (a) The fire department and accessible. (b) Couplings or syrotate smoothly. (c) Plugs or caps and (d) Gaskets are in (e) Identification signification signification signification perating properly.  Findings:  During a tour of the director on 1/30/13 lot was observed.  At 3:25 p.m., one parking lot of the failed to rotate.	matic sprinkler system as Department Connections ate smoothly. This affected 3 rtments. This could potentially e-fighters in extinguishing a fire vivels at the facility and esidents and staff, in the event on, Testing and Maintence of Protection System. 1998  The inspection shall be rent Connections are visible wivels are not damaged and are in place and undamaged. place and in good condition. gns are in place. e is not leaking. drain valve is in place and		062	K 062 NFPA 101 LIFE SAFE CODE STANDARD  Scope & Severity: "D"- Isol Specific Action and/or meato correct the deficiency:  On 1/30/13, the swivels for the parking lot FDC were replaced action:  Maintenance Supervisor or descriptions and Performance and Communitoring and POC Evaluations.  Monthly, the Maintenance Supervisor shall inspect and ensure that the coup swivels are rotating appropriately. Any identifications taken shall be immediate corrected.  Compliance reports which include immediate corrected.  Compliance for further recommendations and/or pertinent Quality Improve actions.  Completion date: 2/30/1313 ongoing	ated sures  ne ed.  orrective  designee  ntation pliance ation:  e the FDC olings or fied non- ediately  the trive ported to urance rement		
SS=D	1			1			1	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			CONSTRUCTION		(X3) DATE SURVEY COMPLETED	
A STORY COMMITTEE	J. COMILETION	i i i i i i i i i i i i i i i i i i i		LDING	01 - MAIN BUILDING 01			
		055873	B. WI	NG		<del></del>	01/30	0/2013
	PROVIDER OR SUPPLIER	LA MESA, LP		8665	T ADDRESS, CITY, STAT 5 LA MESA BLVD. MESA, CA 91942	E, ZIP CODE		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES  'MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		K 076 NFPA 10	E ACTION SHO D TO THE APPR CIENCY) I LIFE SAFI	ULD BE OPRIATE	(X5) COMPLETION DATE
K 076	Medical gas storage protected in accord Standards for Healt (a) Oxygen storage 3,000 cu.ft. are end separation.	e and administration areas are ance with NFPA 99,	K	076	Scope & Severi Specific Action to correct the d On 1/30/13, the cylinders were in accordance with (1). This would and delay if a full hurriedly. In additted with self-or	and/or meandformeand/or meandformeandf	en PTY" in 5.2.2 (b) fusion inceded por was	
	Based on observat maintain oxygen strevidenced by storin cylinders in the sam was not equipped vaffected 1 of 3 smocause a delay in an and could cause a residents in an emotional Fire Proter Facilities -99, 1998 Storage shall be pluse in the order in the supplier.  (2) If stored within 1 cylinders shall be sempty cylinders shall be sempty cylinders shall be sempty cylinders shall sempty	s not met as evidenced by: tion, the facility failed to orage area. This was ag of full and empty oxygen ne crate, oxygen storage room with a self-closure device. This ke compartments. This could nemergency for the resident potential risk of injury to ergency.  ction Association Health Care neglight Edition- 4-3.5.2.2 (b) (1) anned so that cylinders can be which they are received from the same enclosure, empty egregated from full cylinders. all be marked to avoid y if a full cylinder is needed			cylinders ar 2. During daily rounds, the Supervisor hazardous that these with appropriate facilitate se Any identifit shall be im 3. Compliance	Staff upervisor  Inge Implemente and Core I POC Evaluate POC Evaluate empty oxygore marked "Exymaintenance shall inspectate doors are adoors are doors are doors are doors are doors are doors are endoors are doors are endoors are endoo	entation npliance uation:  ff will ten EMPTY." ce te all to ensure quipped losers to required. pliance prected.	

PRINTED: 02/07/2013 FORM APPROVED OMB NO. 0938-0391

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) N A. BU		PLE CONSTRUCTION  G 01 - MAIN BUILDING 01	(X3) DATE SURVEY COMPLETED	
		055873	B. WI	√G		01/3	0/2013
	ROVIDER OR SUPPLIER	LA MESA, LP		86	EET ADDRESS, CITY, STATE, ZIP CODE 665 LA MESA BLVD. A MESA, CA 91942		_
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAC		PROVIDER'S PLAN OF CORRI (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE AP DEFICIENCY)	HOULD BE	(X5) COMPLETION DATE
K 076 K 141 SS=D	Findings:  During tour of facilit director on 1/30/13 observed.  At 3:59 p.m., Oxyg Room 312 had both oxygen cylinders material to equip the door to self-closure device.  NFPA 101 LIFE SA	ty with the maintenance, the oxygen room was gen room off the corridor by the empty and full E- sized hix together. The facility failed to the oxygen room with a AFETY CODE STANDARD the oxnoking signs in areas ared or stored are in accordance		141	actions taken shall be the monthly Safety Co and to the quarterly Qi Assurance Committee recommendations and pertinent Quality Impreactions.  Completion date: 2/30/11 ongoing	mmittee uality for further l/or ovement	
	Based on observa failed to ensure that including lighters we residents possessive respiratory therapy. The resident on oxygen lighter in his possess smoke compartment increased risk of firminity to the resident NFPA 99, Health Comparettes, lighters, form) shall be removed administration.	is not met as evidenced by: tion and interview, the facility at all smoking materials were removed from the on who are receiving This was evidenced by therapy who had a cigarette ssion. This affected 1 of 3 ants. This could result in the we and the potential risk of attraction in the materials (matches, lighter fluid, tobacco in any oved from patients receiving and from the area of			K 141 NFPA 101 LIFE SAF CODE STANDARD  Scope & Severity: "D"- Iso  Specific Action and/or me to correct the deficiency:  On 1/30/13, staff immediate removed and confiscated the affected resident's lighter. To resident was also reminded facility's smoking Policy and Procedure with emphasis of safety and those of other resident:  Staff responsible for the caction:  All staff	olated easures ely ne The i of the d n his esidents.	

Facility ID: CA080000041

NAME OF PROVIDER OR SUPPLIER  COMMUNITY CONV HOSP OF LA MESA, LP  STREET ADDRESS, CITY, STATE, ZIP CODE 8665 LA MESA BLVD. LA MESA, CA 91942	2013
NAME OF PROVIDER OR SUPPLIER  STREET ADDRESS, CITY, STATE, ZIP CODE  8665 LA MESA BLVD.	
(X4) ID SUMMARY STATEMENT OF DEFICIENCIES ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE CORRE	(X5) COMPLETION DATE
K 141 Continued From page 7 smoking areas, resident in room 306, who has a tracheostomy tube, an opening through the neck and into the trachea, was at the smoking area and produced his own cigarette lighter from his shirt pocket. The resident stated that the resident does not comply with policy and knew it is against regulation to have a lighter in his possession. When the resident was interviewed, he acknowledged that he had the lighter in his possession while on oxygen therapy.  K 147 SS=D  Electrical wiring and equipment is in accordance with NFPA 70, National Electrical Code. 9.1.2  This STANDARD is not met as evidenced by: Based on observation, the facility falled to maintain electrical safety as evidenced by electrical appliances plugged into multi-plug, surged protector power strips and not into wall outlets. This saffected 1 of 3 smoke compartments. This could potentially cause a fire and potential harm to residents and staff in the event of a fire emergency.  NFPA 70 Section 400-8 1999 Ed. Uses not permitted. Unless specifically permitted in section 400-7, flexible cords and cables shall not be used for the following:  (1) As a substitute for a fixed wiring of a structure (2) Where run through holes in walls, structural	

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (DENTIFICATION NUMBER:		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01 - MAIN BUILDING 01			(X3) DATÉ SURVEY COMPLETED	
	•	055873	B. WII	NG	· • <del></del>	01/3	0/2013
	ROVIDER OR SUPPLIER	F LA MESA, LP	1	866	EET ADDRESS, CITY, STATE, ZIP CODE 65 LA MESA BLVD. MESA, CA 91942		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETION DATE
K 147	ceilings, suspender floors.  (3) Where run throws imilar openings (4) Where attached (5) Where conceal structural ceilings, (6) Where installed otherwise permitted.  Findings:  During a tour of the Maintenance or system was observed.	d ceilings, dropped ceilings, or ugh doorways, windows, or to building surfaces ed behind building walls, suspended ceilings, or floors in raceways, except as d in this code	K	147	K 147 NFPA 101 LIFE SAFE CODE STANDARD  Scope & Severity: "D"- Isolate to correct the deficiency:  On 1/30/13, the refrigerators immediately plugged into the outlet.  Staff responsible for the control action:  All staff  Systemic Change Implementand Performance and Complementand Performance and Complementand Poc Evaluation of the Maintenance Supervisor will observe for use of multi-plugs and compliance shall be immediate corrected.  Daily during routine main rounds, the Maintenance Supervisor will observe for use of multi-plugs and compliance shall be immediate corrected.  Compliance reports which include immediate corrected.  Compliance for further recommendations and/or pertinent Quality Improve actions.  Completion date: 2/30/113 and completio	were wall  rective  rective  rective  rective  rection:  tenance  rect  rect	
				İ	ongoing	_ <del>_</del>	