PRINTED: 12/31/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDIN	PLE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED	
		056315	B. WING		12/18/2018
NAME OF PROVIDER OR SUPPLIER  CYPRESS GARDENS CARE CENTER			1	STREET ADDRESS, CITY, STATE, ZIP CODE 9025 COLORADO AVENUE RIVERSIDE, CA 92503	,
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE APP DEFICIENCY)	IOULD BE COMPLETION
E 000	Initial Comments		E 00	00	
	Emergency Prepared The findings are in a Federal Regulations for Long Term Care ( The facility is in subs CFR §483.73 for Long	nt of Public Health, during an diness recertification survey. ccordance with 42 Code of (CFR) 483.73, Requirement			
	Census: 115				
K 000	INITIAL COMMENTS	3	K 0	00	
	K3 BUILDING: 01 K6 PLAN APPROVA K7 SURVEY UNDER STRUCTURE TYPE: CONSTRUCTION TY SPRINKLERED.	R: 2012 EXISTING ONE STORY,			
	Department of Public Life Safety Code reco findings are in accord Federal Regulations National Fire Protect Life Safety Code, 20 Health Care Facilities	s the findings of the California c Health, during an annual ertification survey. The dance with 42 Code of (CFR) §483.90(a)(b)(c)(j), ion Association (NFPA) 101 - 12 Edition, and NFPA 99 - s Code, 2012 Edition.			
	Health: 40597	·			
	<u> </u>	substantial compliance with			
LABORATORY	DIRECTOR'S OR PROVIDER/	SUPPLIER REPRESENTATIVE'S SIGNATURE		TITLE	(X6) DATE

Electronically Signed 12/31/2018

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

Approved 12/31/18 per Jose Gonzalez

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTANT A. BUILDING <b>02</b>			(X3) DATE COMP	SURVEY			
		056315	B. WING			12/	18/2018
	ROVIDER OR SUPPLIER  GARDENS CARE CENT	ER	•	9	TREET ADDRESS, CITY, STATE, ZIP CODE 025 COLORADO AVENUE LIVERSIDE, CA 92503		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 000	Continued From page 42 CFR §483.90 for L	e 1 .ong Term Care Facilities.	К	000			
K 291 SS=D	Emergency Lighting CFR(s): NFPA 101		K	291			1/18/19
	is provided automatic 18.2.9.1, 19.2.9.1 This REQUIREMENT by: Based on document facility failed to maintevidenced by the failt 90 minutes annually. of the emergency light disaster. This affected compartments.  NFPA 101, Life Safetty 7.8.2.2 Battery-operated years of portable lampused for primary illum Battery-operated elect to be used as an emergermitted under Section 7.9.1 General. 7.9.1.1* Emergency liegress shall be provided Section 7.9 for the fol (1) Buildings or struct Chapters 11 through (2) Underground and addressed in Section (3) High-rise buildings sections of this Code	y Code, 2012 Edition ted electric lights and other os or lanterns shall not be ination of means of egress. stric lights shall be permitted ergency source to the extent on 7.9.  ghting facilities for means of ded in accordance with lowing: ures where required in 43 limited access structures as			This Plan of Correction constitutes Cypress Gardens Care Centers written credible allegation of compliance. Cypr Gardens Care Center (hereinafter CGC makes its best effort to operate in full compliance with both federal and state laws. Nothing included in this plan of correction is an admission otherwise. CGCC has submitted this plan of correction in order to comply with its regulatory obligation and does not wain any objections to the allegations contained herein. Please note that CG may contest the merits and/or from any deficiency findings alleged below and r take appropriate actions to appeal then  K 291  It is the practice of CGCC to maintain elights.  IMMEDIATE CORRECTIVE ACTION Under direction and supervision of the Administrator, the exit lights underwent	ress CC) /e GCC /may m.	

AND DIAN OF CORRECTION IDENTIFICATION NUMBER		(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>02</b>			(X3) DATE SURVEY COMPLETED		
		056315	B. WING		12/	18/2018	
NAME OF PROVIDER OR SUPPLIER  CYPRESS GARDENS CARE CENTER			9(	TREET ADDRESS, CITY, STATE, ZIP CODE			
				R	IVERSIDE, CA 92503		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 291	enclosures, for which (a) The stair shaft and permitted to include a installed for the smok mechanical ventilation (b) The standby gene be used for the stair s emergency lighting po (6) New access-contr accordance with 7.2.  Finding:  During a document re Maintenance Supervi for the emergency ex  At 12:07 p.m., the fact record for the annual During an interview w Supervisor at 12:08 p annually for 90 minute it was required. He c have a back up batter Cooking Facilities CFR(s): NFPA 101  Cooking Facilities Cooking equipment is with NFPA 96, Standa and Fire Protection of Operations, unless: * residential cooking e appliances such as m toasters) are used for cooking in accordance	estibules of smokeproof the following also apply: d vestibule shall be a standby generator that is eproof enclosure n equipment. rator shall be permitted to shaft and vestibule ower supply. olled egress doors in 1.6.2  eview and interview with the sor on 12/18/18, the records it lights were requested.  iility did not provide the emergency exit lights test. iith the Maintenance .m., he did not test the lights es because he did not know onfirmed that the exit lights ry.  s protected in accordance and for Ventilation Control of Commercial Cooking		324	90-minute testing.  RESIDENTS AFFECTED No other residents were affected by the alleged deficient conduct.  CORRECTIVE ACTION The Director of Maintenance was in-serviced by the Administrator on annually testing the exit signs for 90-minutes.  MONITORING OF CORRECTIVE ACTION At the direction of the QAPI Committee the Director of Maintenance will test the exit signs annually for 90-minutes.  The results of the test will be submitted the QAPI Committee on an annual bas for further monitoring and/or action planning as needed.	e e	1/18/19

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING <b>02</b>			(X3) DATE SURVEY COMPLETED	
		056315	B. WING _			12/	18/2018	
	ROVIDER OR SUPPLIER	ENTER		STREET ADDRE				
(X4) ID PREFIX TAG	(EACH DEFICI	Y STATEMENT OF DEFICIENCIES ENCY MUST BE PRECEDED BY FULL OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG		PROVIDER'S PLAN OF CORRECTIC FACH CORRECTIVE ACTION SHOULD DSS-REFERENCED TO THE APPROP DEFICIENCY)	D BE	(X5) COMPLETION DATE	
K 324	with the condition or  * cooking facilities 30 or fewer patier 18.3.2.5.4, 19.3.2 Cooking facilities per 9.2.3 are not in hazardous areas, corridor.	h 30 or fewer patients comply s under 18.3.2.5.3, 19.3.2.5.3, in smoke compartments with its comply with conditions under .5.4.  protected according to NFPA 96 required to be enclosed as but shall not be open to the	K	24				
	by: Based on observinterview, the faci cooking equipmer failure to provide documents at least equipment. This dequipment to mali in the kitchen. The compartments.  NFPA 101, Life Sa 19.3.2.5 Cooking 19.3.2.5.1 Cooking accordance with Spermitted by 19.3  9.2.3 Commercial Commercial cook accordance with Nentilation Control	ation, document review, and lity failed to maintain their nt. This was evidenced by the inspection and servicing st annually for the cooking ould result in cooking function and could cause a fire is affected one of four smoke afety Code, 2012 Edition Facilities.  If facilities shall be protected in 0.2.3, unless otherwise 2.2.5.2, 19.3.2.5.3, or 19.3.2.5.4.  Cooking Equipment.  Ing equipment shall be in NFPA 96, Standard for I and Fire Protection of cing Operations, unless such		IMMEDIA Under dir Administ servicing complete  RESIDEI No other alleged d  CORREC The facili requestir inspectio	practice of CGCC to maintain equipment.  ATE CORRECTIVE ACTION rection and supervision of the trator, the inspection and g of the cooking equipment were as required on 12/21/2015 NTS AFFECTED residents were affected by redicient conduct.  CTIVE ACTION ity will continue its practice of g and performing annual on and servicing of its cooking and servicing of its cooking and as required.	N ne vas 8. the		

	MENT OF DEFICIENCIES LAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:  (X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED				
		056315	B. WING _			12/	18/2018
NAME OF PROVIDER OR SUPPLIER  CYPRESS GARDENS CARE CENTER			90	TREET ADDRESS, CITY, STATE, ZIP CODE 025 COLORADO AVENUE IVERSIDE, CA 92503	•		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	<	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 324	which shall be permitt service.  NFPA 96, Standard for Fire Protection of Corroperations, 2011 Edit 11.7.1 Inspection and equipment shall be m properly trained and continuous trained	oved existing installations, and to be continued in a very ventilation Control and an a continued in a very ventilation Control and an a continued in a very ventilation control and an a very ventilation continued in a very ventilation continued in a ventilation co	KS		MONITORING OF CORRECTIVE ACTION At the direction of the QAPI Committee the Director of Maintenance will verify to cooking equipment and inspected and serviced annually as required.  The results of the inspections will be provided to the QAPI Committee on an annual basis for further monitoring and action planning as needed.	he	
K 345 SS=D		esting and Maintenance	K 3	345			1/18/19
	Fire Alarm System - T	esting and Maintenance					

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTI A. BUILDIN	PLE CONSTRUCTION G <b>02</b>		(X3) DATE SURVEY COMPLETED	
		056315	B. WING _	<del></del>	1	2/18/2018	
NAME OF P	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE			
CVDDESS	GARDENS CARE CENT	ED		9025 COLORADO AVENUE			
CIFRESS	GARDENS CARE CENT	ER		RIVERSIDE, CA 92503			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETION DATE	
K 345	Continued From page	e 5	K 3	45			
2 343	A fire alarm system is accordance with an awith the requirements Electric Code, and NI and Signaling Code. It acceptance, maintena available.  9.6.1.3, 9.6.1.5, NFP/This REQUIREMENT by: Based on document facility failed to maintate the fire alarm commonths. This could rest the fire alarm system shall be installed, test accordance with the analysis and approved existing permitted to be conting 9.6.1.5* To ensure opalarm system shall hamaintenance and test the applicable requires the applicable requir	tested and maintained in pproved program complying of NFPA 70, National FPA 72, National FPA 72, National FPA 72, National FPA 72 Fis not met as evidenced review and interview, the ain the fire alarm systems. By the failure to inspect and introl panel batteries every six esult in malfunction of the effice alarm control panel. This affected four of four stem required for life safety ted, and maintained in applicable requirements of ectrical Code, and NFPA 72, and Signaling Code, unless it in ginstallation, which shall be nued in use. Perational integrity, the fire ave an approved ting program complying with ements of NFPA 70, National NFPA 72, National Fire	K 3	It is the practice of CGCC to mair fire alarm systems.  IIMMEDIATE CORRECTIVE ACT Under the direction and supervisi Administrator, the Director of Mai inspected and tested the fire alar panel batteries.  RESIDENTS AFFECTED No residents were affected by the deficient conduct.  CORRECTIVE ACTION The Administrator in-serviced the of Maintenance beginning 12/18/inspecting and testing fire alarm opanel batteries every six months.  MONITORING OF CORRECTIVE ACTION At the direction of the QAPI Comthe Director of Maintenance will put the testing and inspection of fire a control panel batteries every six recontrol panel batteries every six reco	FION ion of the intenance in control e alleged e Director 2018 on control e mittee, perform alarm		
	shall be performed in			The results of these tests and ins	pections		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULT A. BUILDII		CONSTRUCTION 2	(X3) DATE COMF	SURVEY PLETED	
		056315	B. WING _			12/	18/2018
NAME OF PROVIDER OR SUPPLIER  CYPRESS GARDENS CARE CENTER			90	TREET ADDRESS, CITY, STATE, ZIP CODE 025 COLORADO AVENUE IVERSIDE, CA 92503			
	CH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI) TAG	×	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE
schedules required b  Finding:  During do Maintenar for the ser was requested an intervier 12:42 p.m.  K 353 SS=D  Sprinkler S Automatic inspected, with NFPA Testing, an Protection maintenar maintained available.  a) Date s  b) Who p  c) Water  Provide in any non-resystem. 9.7.5, 9.7.	cument revince Supervinice Supervinicannual finested.  I.m., the fact the semi-and to the fire sew with the semi-and to the fire sew with the sprinkler and Maintain System - May System - May System Superinkler systems. If the security in a security system supervinkler system system supervinkler system sy	iew and interview with the sor on 12/18/18, the records re alarm system inspection  fility did not provide the natural testing of the batteries alarm control panel. During Maintenance Supervisor at to know this was required. The aintenance and Testing and standpipe systems are domaintained in accordance and for the Inspection, ing of Water-based Fire Records of system design, ion and testing are re location and readily stem last checked		345	will be presented to the QAPI Committ on a minimum quarterly basis for further monitoring and/or action planning as needed.		1/18/19

PRINTED: 12/31/2018 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY **IDENTIFICATION NUMBER:** AND PLAN OF CORRECTION COMPLETED A. BUILDING 02 056315 B. WING 12/18/2018 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 9025 COLORADO AVENUE CYPRESS GARDENS CARE CENTER RIVERSIDE, CA 92503 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION ΙD (X5) COMPLETION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE PREFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) K 353 Continued From page 7 K 353 by: K 353 Based on observation and interview, the facility failed to maintain the sprinkler system free of physical damage. This was evidenced by the It is the practice of CGCC to maintain the failure to secure the cover on the Post Indicator sprinkler system free of damage. Valve (PIV) due to missing hardware. This could IMMEDIATE CORRECTIVE ACTION result in malfunction of the valve cover during an emergency event. This affected four of four Under direction and supervision of the smoke compartments. Administrator, the Director of Maintenance replaced the missing hex-nut screw. NFPA 101, Life Safety Code, 2012 Edition 9.7.5 Maintenance and Testing. All automatic RESIDENTS AFFECTED sprinkler and standpipe systems required by this No residents were affected by the alleged Code shall be inspected, tested, and maintained deficient conduct. in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintenance of CORRECTIVE ACTION Water-Based Fire Protection Systems. The Administrator in-serviced the Director of Maintenance beginning 12/18/2018 on NFPA 25, Standard for the Inspection, Testing, maintaining the sprinkler system free of and Maintenance of Water-Based Fire Protection physical damage. Systems, 2011 Edition 13.4.1 Inspection of Alarm Valves. Alarm vales MONITORING OF CORRECTIVE shall be inspected as described in 13.4.1.1 and **ACTION** At the direction of the QAPI Committee, 13.4.1.2. 13.4.1.1\* Alarm valves and stem risers check the Director of Maintenance will continue valves shall be externally inspected monthly and to complete the monthly inspection of the shall verify the following: sprinkler system. The Administrator or his (1) The gauges indicate normal supply water designee will verify the inspection was pressure is being maintained. completed and the sprinkler system is (2) The valve is free of physical damage. free of physical damage. (3) All valves are in the appropriate open or closed position. The results of these inspections will be (4) The retarding chamber or alarm drains are not presented to the QAPI Committee on a leaking. minimum quarterly basis for further monitoring and/or action planning as Finding: needed. During a tour and interview with the Maintenance Supervisor on 12/18/18, the PIV was observed.

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION  (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED		
		056315	B. WING _			12/	18/2018
NAME OF PROVIDER OR SUPPLIER  CYPRESS GARDENS CARE CENTER		ER		STREET ADDRESS, CITY, STATE, ZIP CODE 9025 COLORADO AVENUE RIVERSIDE, CA 92503			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	PROVIDER'S PLAN OF CORF (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE AI DEFICIENCY)	SHOULD BE	Έ	(X5) COMPLETION DATE
K 920 SS=D	It was missing one of p.m., the locking wrer to a closed position. as the operating nut winterview with the Ma p.m., he stated the schis last monthly inspecient in the schis last monthly in the schief in the schi	In the PIV was not secured. The hex nut screws. At 3:01 Inch was used to turn the PIV The valve cover was loose was turned. During an intenance Supervisor at 3:02 Irrew was not missing during rection. In Power Cords and Extens In the patient care vicinity are only of movable Idectrical equipment Ithat have been assembled Ithat h		DEFICIENCY)  353			1/18/19
	by:						

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		, ,	(X2) MULTIF A. BUILDING	PLE CONSTRUCTION G <b>02</b>		(X3) DATE SURVEY COMPLETED	
		056315	B. WING	<del></del>	1	2/18/2018	
NAME OF P	ROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE			
0./55500				9025 COLORADO AVENUE			
CYPRESS	GARDENS CARE CENT	EK		RIVERSIDE, CA 92503			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORF (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE AI DEFICIENCY)	SHOULD BE	(X5) COMPLETION DATE	
K 920	Continued From page	9	K 92	20			
	Based on observatio	n and interview, the facility		K 920			
		electrical equipment. This					
	was evidenced by the	use of a power tap in a		It is the practice of CGCC to ma	aintain		
	resident care vicinity.	This could result in an		electrical equipment.			
	electrical fire. This at	fected one of four smoke					
	compartments.			IMMEDIATE CORRECTIVE AC			
	 			Under the direction and supervi			
	NFPA 101, Life Safety	y Code, 2012 Edition		Administrator, the Director of M	aintenance		
	19.5.1 Utilities.	and the second second		removed the power tap.			
	of Section 9 .1.	comply with the provisions		RESIDENTS AFFECTED			
		ms. Electrical wiring and		No other power strips were ider	ntified		
	-	accordance with NFPA 70,		Therefore, no other residents w			
		ode, unless such installations		affected by the alleged deficien			
		installations, which shall be					
	permitted to be contin			CORRECTIVE ACTION			
				The Administrator in-serviced the	ne Director		
	NFPA 70, National El	ectrical Code, 2011 Edition		of Maintenance beginning 12/1	8/2018 on		
		itted. Unless specifically		unapproved power taps.			
	•	exible cords and cables shall					
	not be used for the fo	•		MONITORING OF CORRECTI	VE		
	(1) As a substitute for	the fixed wiring of a		ACTION			
	structure			At the direction of the QAPI Co			
		h holes in walls, structural ceilings, or		the Director of Maintenance wil daily room rounds to verify una			
	floors	centings, dropped centings, or		power taps are removed from fa			
		h doorways, windows, or		premises.	acinty		
	similar openings	Tudorwayo, Willadwo, Or		premiece.			
	(4) Where attached to	building surfaces		The results of these rounds will	be		
		ible cord and cable shall be		reported to the QAPI Committe			
	permitted to be attach	ned to building surfaces in		minimum quarterly basis for fur	ther		
		provisions of 368.56(8)		monitoring and/or action planni	ng as		
		by walls, floors, or ceilings		needed.			
		pended or dropped ceilings					
	(6) Where installed in						
	otherwise permitted in						
		physical damage 400.10					
		minals. Flexible cords and ected to devices and to					
	i capies shall be conn	ecieu io devices and io	1	1		1	

STATEMENT OF DEFICIENCIES  (X1) PROVIDER/SUPPLIER/CLIA  IDENTIFICATION NUMBER:		A. BUILDII	TIPLE CONSTRUCTION NG <b>02</b>	(X	(X3) DATE SURVEY COMPLETED			
		056315	B. WING _			12/18/2018		
NAME OF PROVIDER OR SUPPLIER  CYPRESS GARDENS CARE CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 9025 COLORADO AVENUE RIVERSIDE, CA 92503			, .2.10.2010		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI TAG	(EACH CORRECTI CROSS-REFERENCI	LAN OF CORRECTION VE ACTION SHOULD BE ED TO THE APPROPRIATE FICIENCY)	(X5) COMPLETION DATE		
K 920	fittings so that tension or terminals. Exception: Listed por that are intended to a at their terminals shal with single-conductor Finding: During a tour and inte Supervisor on 12/18/was observed. At 3:31 p.m., a person to a power tap in Roowas not compliant.	table single-pole devices ccommodate such tension Il be permitted to be used	K	920				