PRINTED: 02/21/2018 FORM APPROVED OMB NO. 0938-0391

OLIVILI	CO I OI WILLDIOM CE	C WILDIONID OCITATOLO				WID INC.	1920-028	
	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		CONSTRUCTION 2	(X3) DATE SURVEY COMPLETED		
		555252	B. WING			02/1	5/2018	
	PROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP CODE 8777 SKYWAY PARADISE, CA 95969					
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAC		PROVIOER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROI DEFICIENCY)	DBE	(X5) COMPLETIO DATE	N
E 000	Initial Comments Surveyor: 37135			000	DISCLAIMER STATEMENT Preparation, submission and			
	Department of Put Emergency Prepa The findings are in	cts the findings of the California olic Health, during an redness recertification survey. a accordance with 42 Code of ns (CFR) 483.73, Requirement e (LTC) Facilities.		Andrew Green Christian Strategick and Green Christian Strategics Commencer	implementation of this Plan of Correction does not constitute admission of or agreement wit facts and conclusions set forth survey report. Our Plan of Con-	an th the on the rection		
	Health: 37135	California Department of Public			is prepared and executed as a to continuously improve the q care and to comply with all ap state and federal regulatory	uality of		
	Census: 86 Plan Based on All CFR(s): 483.73(a)	Hazards Risk Assessment)(1)-(2)	E	006	requirements.			
	and maintain an e that must be revie	lan. The [facility] must develop emergency preparedness plan ewed, and updated at least n must do the following:]			This Plan of Correction is sub- the facility's credible allegation compliance.			
	facility-based and	and include a documented, community-based risk ting an all-hazards approach.*			,	野.		
	on and include a community-based	s at §483.73(a)(1):] (1) Be baser documented, facility-based and d risk assessment, utilizing an ach, including missing residents						
	and include a doc	§483.475(a)(1):] (1) Be based or cumented, facility-based and d risk assessment, utilizing an each, including missing clients.	n			, I = TUERAI		
LABOR	(2) Ipoludo etrate	neilos fo a neldana alto - como	4		A TUPLE '	<u> </u>	(X6) CAT	: 1
Any de					Ition may be excused from correcting provon nursing homes, the findings stated abort		2/ etermined t	that
foliowin	wing the date these docu	ments are made available to the facility	. If defic	iencie	omes, the above findings and plans of cors are cited, an approved plan of correction	rection are d	disclosable	14

3 5 18

program participation.

Approved my

CENTERS FOR MEDICARE & MEDICAID SERVICES		G MILDIONIO OLIVAIOLO				OND NO. 0930-0391		
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDI		CONSTRUCTION	(X3) DATE SUR COMPLETE	VEY	
		555252	B. WING			02/15/20	18	
	ROVIDER OR SUPPLIER W CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 8777 SKYWAY PARADISE, CA 95969				
(X4) ID PREFIX TAG	(EACH DEFICIENC)	STEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SCIDENTIFYING INFORMATION)	PREFIX TAG	×	PROVIDER'S PLAN DF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROV DEFICIENCY)	D BE COM	(X5) IPLETION DATE	
E 006	Continued From pa	om page 1 E 006		i				
	* [For Hospices at §418.113(a)(2):] (2) Include strategies for addressing emergency events identified by the risk assessment, including the management of the consequences of power failures, natural disasters, and other emergencies that would affect the hospice's ability to provide care. This REQUIREMENT is not met as evidenced by: Surveyor: 37135 Based on document review and interview, the facility failed to base the emergency plan on a risk assessment. This was evidenced by the failure to identify potential natural, man-made, and facility specific hazards based on risk assessment unique to the facility, community, and geographic location. This affected three of three smoke compartments and could result in the facility being inadequately prepared for hazards that could be identified by a risk assessment.		To come the control of the control o		 Upon detailed review of the Emergency Preparedness Hazards Risk assessment completed for Pine View 10/10/2017. 	ss Plan the nt was		
				nada jaya mahada da	2) All residents have the popular be affected by this deficit practice. Facility Administrative and the Emergency preparedness plan on 2 printed out all pages and the Emergency Plan Bir at both nursing stations easily identify the facility plan prepared for the ce	ent istrator y /15/2018 d placed in ider located so staff car / individual		
		and interview with the 1/15/18, the risk assessment	and the state of t	The state of the s	on the Hazard Risk Ass			
	1. At 12:41 p.m., the facility failed to provide a risk assessment to identify potential hazards for the facility. Upon interview, Administrator confirmed the finding and stated they did not remember seeing a risk assessment. EP Testing Requirements CFR(s): 483.73(d)(2) (2) Testing. The [facility, except for LTC facilities, RNHCIs and OPOs] must conduct exercises to		And the second s	039	 Administrator will re-in-son 3/9/2018 with the former person and the identified Natural Disour facility and be awar steps to take to ensure provided at all times to residents. 	cus on ess Hazard n address isaster for e of what safety is		

AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 02	TE SURVEY MPLETED 2/15/2018
NAME OF PROVIDER OR SUPPLIER PINE VIEW CENTER STREET ADDRESS, CITY, STATE, ZIP CODE 8777 SKYWAY PARADISE, CA 95969 (X4) ID PREFIX TAG SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) E 039 Continued From page 2 test the emergency plan at least annually. The E 039 Continued From Page 2 test the emergency plan at least annually. The E 039 Continued From Page 2 test the emergency plan at least annually. The E 039 Continued From Page 2 test the emergency plan at least annually. The E 039 E 039 Continued From Page 2 test the emergency plan at least annually. The E 039 E 039 Continued From Page 2 test the emergency plan at least annually. The	2/15/2018
PINE VIEW CENTER STIT SKYWAY PARADISE, CA 95969	
PINE VIEW CENTER (X4) ID SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) E 039 Continued From page 2 (E039 4) Administrator/Designee will test the emergency plan at least annually. The Evaluate and update Emergency	İ
PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) E 039 Continued From page 2 test the emergency plan at least annually. The regulate and update Emergence in the state of the state o	
test the emergency plan at least annually. The evaluate and update Emergency	(X5) COMPLETION DATE
all of the following: *[For LTC Facilities at §483.73(d):] (2) Testing. The LTC facility must conduct exercises to test the emergency plan at least annually, including unannounced staff drills using the emergency procedures. The LTC facility must do all of the following:] (i) Participate in a full-scale exercise that is community-based or when a community-based exercise is not accessible, an individual, facility-based. If the [facility] experiences an actual natural or man-made emergency plan, the [facility] is exempt from engaging in a community-based or individual, facility-based full-scale exercise that may include, but is not limited to the following: (A) A second full-scale exercise that is community-based or individual, facility-based. (B) A tabletop exercise that includes a group discussion led by a facilitator, using a narrated, clinically-relevant emergency scenario, and a set of problem statements, directed messages, or prepared questions designed to challenge an emergency plan. (iii) Analyze the [facility's] response to and maintain documentation of all drills, tabletop exercises, and emergency plan, as needed. *[For RNHCIs at §403.748 and OPOs at §486.360] (d)(2) Testing. The [RNHCI and OPO]	plan vill

CENTER	S FOR MEDICARE	& MEDICAID SERVICES			<u> </u>	MB NO.	0938-0391
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER;	(X2) MUL A. BUILD		CONSTRUCTION 2	(X3) DATE SURVEY COMPLETED	
		555252	B. WING			02/15/2018	
NAME OF F	PROVIDER OR SUPPLIER			ST	REET ADDRESS, CITY, STATE, ZIP CODE		
PINE VIE	W CENTER				77 SKYWAY RADISE, CA 95969		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC (DENTIFYING INFORMATION)	IO PREF TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULI CROSS-REFERENCED TO THE APPROP DEFICIENCY)	DBE	(X5) COMPLETION DATE
E 039	must conduct exerplan. The [RNHCI following: (i) Conduct a papeleast annually. A tadiscussion led by a clinically relevant of problem statem prepared question emergency plan. (ii) Analyze the [R to and maintain do exercises; and em [RNHCI's and OP needed. This REQUIREME by: Surveyor: 37135 Based on docume facility failed to pathat was community that was community that the failure provindicated they had community-based efforts made to id full-scale community wide of the failures of the could result in a document of the failures.	cises to test the emergency and OPO) must do the er-based, tabletop exercise at abletop exercise at abletop exercise is a group a facilitator, using a narrated, emergency scenario, and a set ents, directed messages, or a designed to challenge an entermentation of all tabletop ergency events, and revise the O's] emergency plan, as entermentation of all tabletop ergency events, and revise the O's] emergency plan, as entermentation that it participate in a full-scale exercise or demonstrate the entify the availability of a nity-based exercise. This hree smoke compartments and elayed response to a full-scale		039	 Facility Administrator cont BUTTE county Emergency center on 3/1/2018 to sign 2018 table top community drill. All residents have the pot be affected by this deficie practice. Facility Maintens Director (MD) and Admin attend the next table top disaster drill to ensure the staff are knowledgeable is community wide emerger MD will in-service staff in after attending tabletop of to educate staff on emergence and a plan to assist community or community assistance for facility in the plans from the community exercise to the monthly or controlled. 	ential to ential ence facility fancy occurrent ency occurrent	will nity urs. ely 018
	2/15/18, records of emergency preparedness training drills were requested.				meeting for further review	w.and	
	that indicated that	nere were no records provided t there was a community-based nunity entities were contacted to			3/1/2018		

CENTERS FOR MEDICARE & MEDICALD SERVICES					ONB NO. 0938-0391		
	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPI A. BUILDING	LE CONSTRUCTION 02	(X3) DATE SURVEY COMPLETED		
		555252	B. WING		02/1	02/15/2018	
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE B777 SKYWAY PARADISE, CA 95969			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SCIDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	DBE	(X5) COMPLETION DATE	
E 039	attempt a full-scale exercise drill. Upo stated the former of contact someone of drill being held in Maintenance Superfrom them that ind community entities 5:00 p.m. on 2/15/1 indicating an attembased drill to the Other of the office of the other	e community-based emergency in interview, the Administrator Maintenance Supervisor did regarding community-based May 2018. The Administrator need to contact the former ervisor to get correspondence icated they made contact with s. The facility was given until 18 to provide documentation and to be part of a community California Department of Public 15/18, CDPH did not receive on the facility indicating an of a community based drill.	E 039				
	Surveyor: 37135 K3 BUILDING: 01 K6 PLAN APPRO K7 SURVEY UND STRUCTURE TY PARTIAL BASEM V, FULLY SPRIN The following refl Department of Pu Life Safety Code findings are in ac Federal Regulatio National Fire Pro Life Safety Code, Health Care Faci	VAL: 1987 DER: 2012 EXISTING PE: ONE STORY WITH BENT, CONSTRUCTION TYPE	a				

OLIVILLI	COT OTTIMEDION ITTE	A MEDIONID OLIVATORO			MD 140, 0930-0391
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE A. BUILDING C	ECONSTRUCTION 12	(X3) DATE SURVEY COMPLETED
		555252	B. WING		02/15/2018
	ROVIDER OR SUPPLIER W CENTER		87	REET ADDRESS, CITY, STATE, ZIP CODE 177 SKYWAY ARADISE, CA 95969	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	D BE COMPLETION
К 000	Continued From pa Health: 37135	age 5	K 000	K 161	
K 161 SS=D	42 CFR §483.90 for Census: 86 Building Construct CFR(s): NFPA 10 Building Construct 2012 EXISTING Building construct	tion Type and Height	K 161	1) Room 12 & 49 were immorepaired/replaced on 2/1 and no longer have any openetrations that would a smoke departments in ar fire.	5/2018 visible offect
	Table 19.1.6.1, unless otherwise permitted by 19.1.6.2 through 19.1.6.7 19.1.6.4, 19.1.6.5 Construction Type 1 I (442), I (332), II (222) Any number of stories non-sprinklered and sprinklered			2) All residents have the populates and smoke detected by this deficition practice. Facility Mainter Director will inspect cabe plates and smoke detect to ensure there are no populate.	ent nance le cover tors monthly
	2 II (111) non-sprinklered sprinklered 3 II (000) non-sprinklered 4 III (211) sprinklered 5 IV (2HH) 6 V (111) 7 III (200) non-sprinklered	Not allowed		 3) Facility Maintenance Di in-serviced by facility A on 3/1/2018 on the important sealing all visible penet would affect smoke de within the facility per residentified issues to the QA&A meeting for furth and discussions. 	dministrator portance of trations that partment egulations. ill bring any monthly
	8 V (000) sprinklered	Maximum 1 story	t desprisances a management	3/15/2018	

CENTERS FOR MEDICARE & MEDICAID SERVICES			OMB NO. 0938-03					
	IT OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		PLE CONSTRUCTION G 02	(X3) DATE SURVE COMPLETED		
		555252	B. WING			02/15/2018		
NAME OF	PROVIDER OR SUPPLIER			l	STREET ADDRESS, CITY, STATE, ZIP CODE			
PINE VI	PINE VIEW CENTER			1	PARADISE, CA 95969			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES YMUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG	ŀΧ	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPRODEFICIENCY)	D BE		(X5) PLETION OATE
K 16	Sprinklered stories throughout by an a system in accorda 19.3.5) Give a brief descriconstruction, the number basements, floors location of smoke approval. Complete plan of the building This REQUIREME by: Surveyor: 37135 Based on observation failed to maintain was evidenced by walls and ceiling.	must be sprinklered automatic proved, supervised automatic nee with section 9.7. (See ption, in REMARKS, of the umber of stories, including on which patients are located, or fire barriers and dates of e sketch or attach small floor	K	16	51			
	Maintenance Teck Keeping Manager ceilings were observed. There is behind Bed B that The cover plate han approximately Upon interview, Maconfirmed the find 2. At 11:21 a.m., observed. The strom the ceiling, of the strom the strom the ceiling, of the strom the strong the stron	the Resident Room 12 was was a cable cover plate located t was missing the bottom screw ad shifted to the side, creating 1-1/2 inch by 1 inch penetration faintenance Technician 1				TO LEAD TO LEAD TROSKAN		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02				(X3) DATE SURVEY COMPLETED				
		555252	B. WING				02/15/2018			
	PROVIDER OR SUPPLIER			87	77 Si	ADDRESS, CITY, STATE, ZIP CODE KYWAY DISE, CA 95969				
(X4) ID PREFIX TAG				(EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION						
K 345	Maintenance Tech Keeping Manager Fire Alarm System CFR(s): NFPA 10 Fire Alarm System A fire alarm system accordance with a with the requiremed Electric Code, and and Signaling Cod acceptance, main available. 9.6.1.3, 9.6.1.5, N This REQUIREMI by: Surveyor: 37135 Based on observatalled to maintain was evidenced by	9.6.1.3, 9.6.1.5, NFPA 70, NFPA 72 This REQUIREMENT is not met as evidenced by:		3345	15 1) Decorative tree was removed from in from emergency wall pull near the entrance of 2/15/2018. 2) All residents have the beaffected by this depractice. Facility Management Director will inspect weekly to ensure the obstructions prevent case of an emergent.		t of the station located the facility on e potential to eficient intenance oull stations re are no ing usage in cy.			
	was evidenced by one the manual alarm box that was obstructed and obscured from view. This affected one of three smoke compartments and could result in the inability to locate and/or obtain the manual alarm box in the event of a fire. NFPA 101, Life Safety Code, 2012 Edition. 19.3.4.2.2 Manual fire alarm boxes in patient sleeping areas shall not be required at exits if located at all nurses' control stations or other continuously attended staff location, provided that both of the following criteria are met: (1) Such manual fire alarm boxes are visible and continuously accessible. (2) Travel distances required by 9.6.2.5 are not exceeded. Findings:				4)	in-serviced by facility Administrator on 3/1/2018 on the importance of having nothing obstructing any of the facilities emergency pull stations which could have a negative effect on the facility if an emergency was to occur. Facility Maintenance will bring any identified issues to the monthly QA&A meeting for further review and discussions.				

STATEMENT OF DEFICIENCIES (X1) PROVIOER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:			(X2) MULTIPL A. BUILDING	CDNSTRUCTION	(X3) DATE SURVEY COMPLETED		
		555252	B. WING		02/15/2018		
	PROVIDER OR SUPPLIER W CENTER		8	TREET ADDRESS, CITY, STATE, ZIP CODE 1777 SKYWAY ARADISE, CA 95969			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	DBE COMPLETION		
K 345		e facility and interview with nician 1 on 2/15/18, the the	K 345		7. 1. 2. 2. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4. 4.		
K 353 SS=D	in the Entry Lobby decorative tree pla manual alarm box not visible. Upon Technician 1 confi Sprinkler System	- Maintenance and Testing	K 353	K 353	THE STATE OF THE S		
	Automatic sprinkle inspected, tested, with NFPA 25, Sta Testing, and Main Protection System maintenance, inspection and the second system available.	Maintenance and Testing er and standpipe systems are and maintained in accordance undard for the Inspection, taining of Water-based Fire as. Records of system design, pection and testing are ecure location and readily system last checked system test	· · · · · · · · · · · · · · · · · · ·	1) Maintenance Director (Minmediately repaired all sprinkler head plates and no signs of escutcheon. MD created a log to visu the pressure valve gaug system and will continue them on a monthly basis 2/15/2018.	identified d now has In addition ally inspect e and riser to inspect		
	any non-required system. 9.7.5, 9.7.7, 9.7.8 This REQUIREM by: Surveyor: 37135 Based on docum facility failed to m	RKS information on coverage for or partial automatic sprinkler , and NFPA 25		2) All residents have the population practice. Facility Mainter Director will continue to sprinkler heads, risers' pressure valves to ensure not tapered with and are working order per facility regulations.	ient enance inspect valves and, ire they are e in proper		

CENTERS FOR MEDICARE & MEDICAID SERVICES			& MEDICAID SERVICES			OMB NO. 0938-0391		
		OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		LE CONSTRUCTION (X3) DATE SURVEY COMPLETED		
			555252	B. WING		02/15/2018		
	NAME OF P	ROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP CODE				
	PINE VIE	W CENTER				PARADISE, CA 95969		
	(X4) ID PREFIX TAG	REFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (X5) (EACH CORRECTIVE ACTION SHOULD BE COMPLETION CROSS-REFERENCED TO THE APPROPRIATE DATE DEFICIENCY)		
	K 353	inspections and or escutcheon plate to ceiling. This affect compartments and of the automatic street. NFPA 101, Life Satistical Sat	9 of 12 complete monthly ne sprinkler head that had an that had separated from the ted three of three smoke d could result in the malfunction prinkler system in the event of a stety Code, 2012 Edition. In scontaining nursing homes throughout by an approved, atic sprinkler system in Section 9.7, unless otherwise 5.5. In the systems required by the pected, tested, and maintained th NFPA 25, Standard for the lig, and Maintenance of the Protection Systems. In the Inspection, Testing, of Water-Based Fire Protection dition. In the system and its shall be made available to the lurisdiction upon request. Iters shall not show signs of three of corrosion, foreign and physical damage; and shall the correct orientation (e.g.,		353	3) Maintenance Director was inserviced by facility Administrator on 3/1/2018. Focus was on having logs to provide proof of inspections per regulations and to ensure all are in properly working order to prevent a negative effect on the facility if not functioning properly if an emergency event was to occur. 4) Facility Maintenance will bring any identified issues to the monthly QA&A meeting for further review and discussions. 3/15/2018		

OCIVILLI	10 I OIL MITOIOULE	& MEDICAID SERVICES			MB NO. U	1930-0391	
	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPL A. BUILDING	LE CONSTRUCTION 02	(XJ) DATE SURVEY COMPLETED		
		555252	B. WING		02/1	5/2018	
.,	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE 3777 SKYWAY PARADISE, CA 95969	1 Vari	512010	
(X4) ID PREFIX TAG	(EACH OEFICIENC	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL. SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	DBE	(X5) COMPLETION DATE	
K 353	13.4.1.1* Alarm valves shall be ext shall verify the folio (1) The gauges indepressure is being to (2) The valve is free (3) All valves are inclosed position. (4) The retarding of leaking. 13.6.1.1.1 Valves electrically supervapplicable NFPAs monthly. Findings: During document Administrator, Malautomatic sprinkle requested. 1. At 11:26 a.m., the monthly insperved were reviewed. That indicated that the alarm and system following months May, June, Augus November of 201 interview, Mainte Administrator cordinarea out observed. The signal of	lves and system riser check ernally inspected monthly and owing: dicate normal supply water	The same that the same and the				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MUL A. BUILD		CONSTRUCTION 2		E SURVEY PLETED
		555252	B. WING			02/	15/2018
	PROVIDER OR SUPPLIER			87	REET ADDRESS, CITY, STATE, ZIP CODE 77 SKYWAY ARADISE, CA 95969		
(X4) ID PREFIX TAG				x	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE API DEFICIENCY)	(X5) COMPLETION DATE	
	approximately 2 in interview, Maintend House Keeping Ma Corridor - Doors CFR(s): NFPA 101 Corridor - Doors Doors protecting or required enclosure hazardous areas of and are made of 1 wood or other maintend at least 20 minutes moke compartments do not contain materials have possible latches are prohibing requirements do not contain flat Clearance between covering is not excomplying with 7, with a device cap when a force of 5 impediment to the devices that release pulled are permitted funlimited heigh meeting 19.3.6.3, shall be labeled a materials in compartment window assemblis sprinklered compartment of compartme	ch diameter penetration. Upon ance Technician 1 and the anager confirmed the finding. corridor openings in other than as of vertical openings, exits, or resist the passage of smoke a 3/4 inch solid-bonded core terial capable of resisting fire for s. Doors in fully sprinklered ents are only required to resist moke. Corridor doors and doors not apply to auxiliary spaces that mable or combustible sitive latching hardware. Roller of the sprinklered ents apply to auxiliary spaces that mable or combustible material en bottom of door and floor ceeding 1 inch. Powered doors 2.1.9 are permissible if provided able of keeping the door closed lbf is applied. There is no elosing of the doors. Hold open see when the door is pushed or ted. Nonrated protective plates at are permitted. Dutch doors 6 are permitted. Door frames and made of steel or other oliance with 8.3, unless the next is sprinklered. Fixed fire es are allowed per 8.3. In partments there are no ea or fire resistance of glass or	K	363	 K 363 Maintenance Director immediately repaired closet and now is in forder. Beds were pla correct positions in eroom, hangers were all rooms identified a obstructed and all dowithout any obstructive 2/15/2018. All residents have the beaffected by this depractice. Facility Made Director will inspect facility rounds all resensure they are not any beds and or othe prevent closure per and regulations. 	the clean unctional ced in the ach identification in the ach identification in the ach identification in the ach identification in the ach idents' do obstructed ach idents the ach idents idents the ach idents idents the ach idents the ach identification identification in the ach iden	ied rom I to ors to d with
	tremice th window	a apparitories.				= -	

CENTER	(2 LOK MEDICAKE	& MEDICAID SERVICES	0			MB NO. 0938-0391	
	ATEMENT OF DEFICIENCIES AD PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MUL A. BUILD		CONSTRUCTION 12	(X3) DATE SURVEY COMPLETED	
		555252	B, WING			02/15/2018	
NAME OF F	ROVIDER OR SUPPLIER		STREET ADDRESS, CITY, STATE, ZIP CODE				
PINE VIE	PINE VIEW CENTER				777 SKYWAY ARADISE, CA 95969		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SCIDENTIFYING INFORMATION)	PREF TAG		PROVIDER'S PLAN OF CORRECTIC (EACH CORRECTIVE ACTION SHOUL) CROSS-REFERENCED TO THE APPROF DEFICIENCY)	D BE	(X5) COMPLETION DATE
K 363	19.3.6.3, 42 CFR Fand 485 Show in REMARK protection ratings, etc. This REQUIREME by: Surveyor: 37135 Based on observate falled to maintain evidenced by one when tested and tobstructed from of three smoke compute inability to confroom. NFPA 101, Life Sa 19.3.6.3.10* Door devices other the door is pushed or Findings: During a tour of the Maintenance Teckeeping Manage were observed. 1. At 10:35 a.m., Linen Closet by Fwhen tested. The closing device. 2. At 10:48 a.m., Resident Room 2	Parts 403, 418, 460, 482, 483, Sidetails of doors such as fire automatics closing devices, and interview, the facility the corridor doors. This was comid or door that did not latch hree corridor doors that were osing. This affected two of partments and could result in tain smoke and/or fire to a shall not be held open be not those that release when the pulled. The facility and interview with thinking 1 and the House on 2/15/18, the corridor doors the corridor door to the Clean Resident Room 3 did not latch a door was equipped with a self the corridor door to the 24 was obstructed from closing thing hangers that were hanging thing the parts of the corridor to th		363	serviced by facility Admin 3/1/2018. Focus was to a doors are in properly work to prevent a negative effet facility if not functioning p an emergency event was 4) Facility Maintenance will identified issues to the m QA&A meeting for furthe and discussions. 3/15/2018	istrator ensure king order on the roperly to occubring a onthly review	all ler ne if ur.

	TATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MUL A. BUILO		CONSTRUCTION	(X3) DATE	938-0391 SURVEY LETED
		555252	B. WING			02/15/2018	
	ROVIDER OR SUPPLIER			87	REET ADDRESS, CITY, STATE, ZIP CODE 77 SKYWAY ARADISE, CA 95969		
(X4) ID PREFIX TAG	(EACH DEFICIENC	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROF DEFICIENCY)	DBE	(X5) COMPLETION DATE
K741	Resident Room 27 by the foot of Bed 4. At 10:58 a.m., t Resident Room 47 by the bed comfor the House Keepin was vacant and th staff regarding this These findings we	the corridor door to the was obstructed from closing A. The corridor door to the was obstructed from closing ter of Bed A. Upon interview, and Manager stated that Bed A ey would talk to house keeping issue. The all confirmed by inclaim 1 and the House work.		741	K 741	SBMAR-5 MICES	
	include not less the (1) Smoking shall ward, or compartic combustible gase and in any other harea shall be possible. SMOKING or shall international symbolished and signation of the care prohibited and signation of the care (3) Smoking by presponsible shall (4) The requirem where the patien (5) Ashtrays of new comparished shall (4) The requirem where the patien (5) Ashtrays of new comparished shall (4) The requirem where the patien (5) Ashtrays of new comparished shall (4) The requirem where the patien (5) Ashtrays of new comparished shall (4) The requirem where the patien (5) Ashtrays of new comparished shall (4) The requirem where the patien (5) Ashtrays of new comparished shall (5) Ashtrays of new comparished shall (6) Ashtrays of new compari	ans shall be adopted and shall an the following provisions: be prohibited in any room, ment where flammable liquids, s, or oxygen is used or stored reazardous location, and such ted with signs that read NO all be posted with the pol for no smoking, occupancies where smoking is generally secondary signs with language oking shall not be required, attents classified as not be prohibited, ent of 18.7.4(3) shall not apply it is under direct supervision, oncombustible material and safe rovided in all areas where	2) All residents have the potential to be affected by this deficient practice. Facility Maintenance Director will inspect during daily facility rounds employee smoking			nere	

	ATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		l ' '	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			E SURVEY IPLETED
		555252	B. WING			02/	15/2018
	PROVIDER OR SUPPLIER			8777	ET ADDRESS, CITY, STATE, ZIP CODE SKYWAY ADISE, CA 95969		
(X4) ID PREFIX TAG	REFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL			x	PROVIDER'S PLAN OF CORRECTIVE ACTION SHO (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	(X5) COMPLETION DATE	
K 741	(6) Metal contained devices into which be readily available permitted. 18.7.4, 19.7.4 This REQUIREM by: Surveyor: 37135 Based on documinterview, the factorial service of the could result in the service with Mathouse Keeping Inon-smoking are smoking policy with a	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) Continued From page 14 (6) Metal containers with self-closing cover devices into which ashtrays can be emptied shall be readily available to all areas where smoking is permitted. 18.7.4, 19.7.4 This REQUIREMENT is not met as evidenced by: Surveyor: 37135 Based on document review, observation, and interview, the facility failed to maintain the smoking regulations. This was evidenced by cigarette butts that were found at locations that were designated as non-smoking areas. This affected one of three smoke compartments and could result in the ignition of fire. Findings: During a tour of the facility, document review, and interview with Maintenance Technician 1 and the House Keeping Manager on 2/15/18, the non-smoking areas were observed and the smoking policy was reviewed. 1. At 11:28 a.m., the area outside the exit of Nurse Station 2 was observed. To the left of the exit was the 30 kilowatt diesel generator and to the right was the emply oxygen storage with 13 empty oxygen E tanks. There was a no smoking sign posted on the wall above the generator and on the generator itself and on the wall above the oxygen tanks. There were seven cigarette butts on the ground approximately 10 feet from the generator and empty oxygen storage. Upon interview, Maintenance Technician 1 and the		From page 14 ontainers with self-closing cover o which ashtrays can be emptied shall available to all areas where smoking is 7.4 JIREMENT is not met as evidenced 37135 document review, observation, and the facility failed to maintain the egulations. This was evidenced by butts that were found at locations that gnated as non-smoking areas. This not of three smoke compartments and lit in the lignilition of fire. We are a outside the exit of ation 2 was observed. To the left of the ha 30 kilowatt diesel generator and to was the empty oxygen storage with 13 yeen E tanks. There was a no smoking are on the properties of the finding approximately 10 feet from the rand empty oxygen storage. Upon Maintenance Technician 1 and the eaping Manager confirmed the finding se Keeping Manager staled that staff		sinistrator on continu ds on eas to staff that the re designated and than here staff y of all will bring a memorphy ther revieu	hey ated t are

		WINDOWS SEED OF SEED O			MD 140. 0936-0391			
	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/GLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE A. BUILDING D	CONSTRUCTION 2	(X3) DATE SURVEY COMPLETED			
	555252 B. WING			WING 02/15/2018				
	NAME OF PROVIDER OR SUPPLIER PINE VIEW CENTER			STREET ADDRESS, CITY, STATE; ZIP CODE 8777 SKYWAY PARADISE, CA 95969				
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIC (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROF DEFICIENCY)	D BE COMPLETION			
K 741	Continued From p	age 15	K 741					
	that smoking is on smoking areas. Electrical Systems		K 914	K 914				
	Smoking areas. Electrical Systems - Maintenance and Testing CFR(s): NFPA 101 Electrical Systems - Maintenance and Testing Hospital-grade receptacles at patient bed locations and where deep sedation or general anesthesia is administered, are tested after initial installation, replacement or servicing. Additional testing is performed at intervals defined by documented performance data. Receptacles not listed as hospital-grade at these locations are tested at intervals not exceeding 12 months. Line isolation monitors (LIM), if installed, are tested at intervals of less than or equal to 1 month by actuating the LIM test switch per 6.3.2.6.3.6, which activates both visual and audible alarm. For LIM circuits with automated self-testing, this manual test is performed at intervals less than or equal to 12 months. LIM circuits are tested per 6.3.3.3.2 after any repair or renovation to the electric distribution system. Records are maintained of required tests and associated repairs or modifications, containing date, room or area tested, and results. 6.3.4 (NFPA 99) This REQUIREMENT is not met as evidenced by: Surveyor: 37135 Based on document review, observation, and interview, the facility failed to maintain the electrical system and its components. This was evidenced by the absence of an annual electrical receptacle test for all non-hospital grade receptacles located in patient bed locations. This			1) Maintenance Director (M 2/17/2018) after further rable to locate the logs for inspections on the Hospitand non-hospital grade radio Binder is now assessable agency request. 2) All residents have the probe affected by this deficing practice. Facility Maintenance Director will maintain all immediate retrieval upon requests, will continue to hospital grade and nongrade receptacles mont facility policy and regular	review was r ital grade receptacles. e upon ptential to ient enance binders for n agency o inspect hospital hly per			

	TATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER;		(X2) MULTIF	PLE CONSTRUCTION IG 02		E SURVEY PLETED			
		555252	B. WING		02/	15/2018			
	PROVIDER OR SUPPLIER W CENTER								
(X4) ID PREFIX TAG	(EACH DEFICIENCY MUST BE PRECEDED BY FULL			X (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE				SHOULD BE	(X5) COMPLETION DATE
K 914	Continued From page 16 affected two of three smoke compartments, and could result in an increased risk of an electrical fire. NFPA 99, Health Care Facilities Code, 2012 Edition. 6.3.4.1.3 Receptacles not listed as hospital-grade, at patient bed locations and in locations where deep sedation or general anesthesia is administered, shall be tested at intervals not exceeding 12 months. 6.3.4.2.1.1 A record shall be maintained of the tests required by this chapter and associated repairs or modification. 6.3.4.2.1.2 At a minimum, the record shall contain the date, the rooms or areas tested, and an indication of which items have met, or have failed to meet, the performance requirements of this chapter. Findings: During document review, a tour of the facility, and interview with Maintenance Technician 1 on 2/15/18, the electrical receptacle records were requested. 1. At 9:55 a.m., no annual receptacle test for all non-hospital grade receptacles located in patient bed locations had been completed. Upon				dministrator as on s pertaining non-hospital receptacles now proof of tions per factors.	to I s, so cility			
	interview, Mainte were not sure if the receptacles in parcheck their recorn At 10:39 a.m., Re	nance Technician 1 stated they hey had non-hospital grade tient bed locations, but would							
	At 10:55 a.m., R	esident Room 47 was observed	<u>.</u>						

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MUL A. BUILD		CONSTRUCTION 2	(X3) DATE SURVEY COMPLETED		
		555252	B. WING			02/15/2018		
,	NAME OF PROVIDER OR SUPPLIER PINE VIEW CENTER			87	reet address, city, state, zip code 77 skyway ARADISE, GA 95969			
(X4) ID PRÉFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTIVE ACTION SHO (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETION DATE	
	Technician 1 states records for annual receptacles locate. This issue was als Safety Code annual completed on 1/24 Electrical Systems CFR(s): NFPA 101 Electrical Systems Maintenance and The generator or and associated exprosonability for the location is not me process shall be process shall be process shall be process shall be process within 10. Generator sets and transfer switches with NFPA 110. Generator sets arounder load 30 min day intervals, and months for 4 confunder load conditions simulated cold statement of all Estephician competent persons stored energy posaccordance with circuit breakers a program for period components is estephicial components.	g an interview, Maintenance d they were not able to find any testing on non-hospital grade d in patient bed locations. o found during last year's Life al re-certification survey 1/17. - Essential Electric Syste	K	914:	1) Maintenance Director contacted facility gene on 2/17/2018. MD revendor that per regula in the generator must test annually. Per MD agreed and upon next for generator inspection the fuel will be taken a be made available on records upon agency 2) Residents have the paffected by this deficit Facility Maintenance maintain records for regulation and have available per agency	erator ve equested tions, the have a contential tent practor fuel quaresults	I from e fuel quality date nple of ilts will to be ctice. will lity per	

AND STATE CATION INCIDENT		(X2) MULTIPI A. BUILDING	LE CONSTRUCTION 02	(X3) DATE SURVEY COMPLETED			
	555252 B. WING				02/15/2018		
NAME OF PROVIDER OR SUPPLIER PINE VIEW CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 8777 SKYWAY PARADISE, CA 95969				
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIV (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	DBE COMPLETION		
K 918	maintenance and to readily available. Ecircuits are marked separate from norm the possibility of da source is a design installations. 6.4.4, 6.5.4, 6.6.4 (111, 700.10 (NFPA This REQUIREMED by: Surveyor: 37135 Based on docume facility failed to masystem. This was annual fuel quality generator. This are compartments and the generator in the NFPA 99, Health CEdition. 6.4.4.1.1,3 Maintenaccordance with NEmergency and SChapter 8. NFPA 110, Standar Power Systems, 28.3.8 A fuel quality least annually using standards. Findings: During document Maintenance Technology.	esting are maintained and ES electrical panels and it, readily identifiable, and mal power circuits. Minimizing image of the emergency power consideration for new (NFPA 99), NFPA 110, NFPA 170) entries and interview, the circuit in the emergency power evidenced by the absence of test for the 30 KW dieself fected three of three smoked could result in the failure of the event of a power outage. Care Facilities Code, 2012 mance shall be preformed in IFPA 110, Standard for tandby Power Systems,		serviced by facility Admir 3/1/2018. Focus was to documentation on the ge fuel quality and to have available so they can be upon request of agency policy and regulations. 4) Facility Maintenance will identified issues to the n QA&A meeting for further and discussions. 3/15/2018	nistrator on maintain maintain the records presented per facility		

IDENTIFICATION NOTES		(X2) MULTI A. BUILDIN	IPLE CONSTRUCTION NG 02	(X3) DAT COM	E SURVEY IPLETED	
		555252				15/2018
	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP C 8777 SKYWAY PARADISE, CA 95969		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES ID PROVIDER'S PLAN OF CORRECTION (EACH OFFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)				(XS) COMPLETION DATE	
K 918	1. At 9:43 a.m., the	ere was no records indicating est had been completed for the nterview, Maintenance	К9	18		
					ALLER AT AT AT A ROCKAR	