PRINTED: 07/11/2024 FORM APPROVED OMB NO. 0938-0391

	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILDING	LE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED
		055557	B. WING		06/20/2024
	ROVIDER OR SUPPLIER DE POST ACUTE			STREET ADDRESS, CITY, STATE, ZIP CODE 35253 AVENUE H YUCAIPA, CA 92399	·
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE COMPLETION
E 000	Initial Comments		E 00	00	
E 007 SS=D	Department of Public Emergency Prepared The findings are in a Federal Regulations for Long Term Care Representing the Carlealth: 43035 The facility is not in a 42 CFR 483.73 for Legalities. Census = 47 EP Program Patient CFR(s): 483.73(a)(3) §403.748(a)(3), §416 §441.184(a)(3), §446 §441.184(a)(3), §485.68(a)(3), §485.727(a)(3), §485.727(a)(3), §485.727(a)(3). [(a) Emergency Planand maintain an emethat must be reviewed 2 years. The plan must but not limited to, peservices the [facility] an emergency; and contact the services the facility and the services the facility	dness recertification survey. ccordance with 42 Code of (CFR) 483.73, Requirement (LTC) Facilities. differnia Department of Public substantial compliance with ong Term Care (LTC) Population 3.54(a)(3), §418.113(a)(3), 30.84(a)(3), §482.15(a)(3), 475(a)(3), §484.102(a)(3), 542(a)(3), §485.625(a)(3), 5.920(a)(3), §491.12(a)(3), The [facility] must develop ergency preparedness planed, and updated at least every	E 00	77	6/26/24
ADODATORY		/SUPPLIER REPRESENTATIVE'S SIGNATUR		TITI F	(X6) DATE

Electronically Signed 07/10/2024

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

PRINTED: 07/11/2024 FORM APPROVED OMB NO. 0938-0391 (X3) DATE SURVEY

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED		
		055557	B. WING _			06/2	20/2024
	ROVIDER OR SUPPLIER DE POST ACUTE			3	TREET ADDRESS, CITY, STATE, ZIP CODE 5253 AVENUE H UCAIPA, CA 92399		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG	х	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
E 007	Plan. The LTC facility an emergency prepar reviewed, and update plan must do all of the (3) Address resident plimited to, persons at-LTC facility has the all emergency; and contincluding delegations plans. *NOTE: ["Persons at hospice, PACE, HHA RHC/FQHC, or ESRE This REQUIREMENT by: Surveyor: 43035 Based on record reviefailed to maintain an I (EOP). This was evid information addressin population that would emergency event. Th residents and could rereact during an emergency event and could record the population during an erequested. At 1:59 p.m., the facility and the population during an erequested.	§483.73(a):] Emergency must develop and maintain redness plan that must be red at least annually. The re following: copulation, including, but not risk; the type of services the colity to provide in an inuity of operations, of authority and succession risk" does not apply to: ASC, CORF, CMCH, of facilities.] is not met as evidenced rew and interview, the facility mergency Operations Plan enced by missing go the facility's patient be at risk during an is affected 47 of 47 result in the failure to properly gency. rew and interview with the sor on 6/20/24, refacility's at risk patient remergency event was rity failed to include ressed the facility's resident	E	007	How corrective action(s) will be accomplished for those residents found have been affected by the deficient practice No residents were affected by the deficient finding. How the facility will identify other reside having the potential to be affected by the same deficient practice and what corrective action will be taken No other residents were affected by the deficient finding. A resident population mix matrix will be created and added to the EPP so that the facility will be informed & prepared to handle the resident population according during an emergency What measures will be put into place of what systemic changes will the facility make to ensure that the deficient practic does not recur	ents ne he ngly	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED		
		055557	B. WING _			06/	/20/2024
	ROVIDER OR SUPPLIER DE POST ACUTE		,	35	TREET ADDRESS, CITY, STATE, ZIP CODE 5253 AVENUE H UCAIPA, CA 92399		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
E 007	Continued From page	e 2	E	007			
	Continued From page 2 emergency. Upon interview, the Maintenance Supervisor confirmed the finding and stated that they did not have the information.			The facility will review the EPP progrannually in the safety committee more to facilitate changes, implement recommendations, and report to the committee annually for review. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must deviplan for ensuring that correction is achieved and sustained. This plan be implemented, and the corrective evaluated for its effectiveness. The must be integrated into the Quality Assurance system. A special QAPI meeting was converthe Administrator/Designee and DC 06/26/24 to present the results of the standard Recertification survey and POC. The Administrator/ Designee and More present results of the updated policing Resident Population Matrix to the Commonthly committee meeting for reviand recommendations. Corrective Action Compliance Date		ngs API ns p a st tion PC I by on	
E 013 SS=D	•	Policies and Procedures	E	013	06/26/24		6/26/24
	§483.475(b), §484.10 §485.542(b), §485.62 §485.920(b), §486.36 §494.62(b).	4(b), §482.15(b), §483.73(b), 02(b), §485.68(b), 25(b), §485.727(b),					

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		1	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055557	B. WING			06/	20/2024
	ROVIDER OR SUPPLIER DE POST ACUTE		•	35	REET ADDRESS, CITY, STATE, ZIP CODE 1253 AVENUE H JCAIPA, CA 92399	•	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD E CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE
E 013	policies and procedu plan set forth in paragand the communicati this section. The pol be reviewed and upd *[For LTC facilities at procedures. The LTC implement emergency procedures, based of forth in paragraph (a) assessment at paragand the communicati this section. The pol be reviewed and upd *Additional Requirem Facilities: *[For PACE at §460.8 procedures. The PACE at procedures. The PACE at procedures. The pol develop and implement policies and procedure policies and procedures and the communicati this section. The pol address management at paragand the communicati this section. The pol address management emergencies, includic equipment, power, or emergencies; and nathreaten the health o staff, or the public. To must be reviewed anyears.	res, based on the emergency graph (a) of this section, risk raph (a)(1) of this section, on plan at paragraph (c) of icies and procedures must ated at least every 2 years. §483.73(b):] Policies and facility must develop and y preparedness policies and in the emergency plan set of this section, risk raph (a)(1) of this section, on plan at paragraph (c) of icies and procedures must ated at least annually.	E	013			

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTI A. BUILDIN	IPLE CONSTRUCTION IG 02	(X3) DATE SURVEY COMPLETED				
		055557	B. WING _		06/20/2024			
	ROVIDER OR SUPPLIER DE POST ACUTE			STREET ADDRESS, CITY, STATE, ZIP CODE 35253 AVENUE H YUCAIPA, CA 92399				
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROFIDEFICIENCY)	D BE COMPLETION			
E 013	procedures. The dia and implement emer and procedures, bas set forth in paragraph assessment at paragrand the communicat this section. The policy be reviewed and upon These emergencies to, fire, equipment or emergencies, water natural disasters like geographic area. This REQUIREMENT by: Surveyor: 43035 Based on record review failed to maintain an (EOP). This was evic This affected the 47 result in the failure to Findings: During record review Maintenance Supervisor documentation elopement risk. Upon Supervisor confirmed	lysis facility must develop gency preparedness policies ed on the emergency plan (a) of this section, risk graph (a)(1) of this section, ion plan at paragraph (c) of icies and procedures must lated at least every 2 years. include, but are not limited power failures, care-related supply interruption, and ly to occur in the facility's T is not met as evidenced T is not met as evidenced	EO	How corrective action(s) will be accomplished for those residents for have been affected by the deficient practice No residents were affected by the deficient finding. How the facility will identify other reshaving the potential to be affected by same deficient practice and what corrective action will be taken No other residents were affected by deficient finding. The facility policy for missing resident/elopement will be added to EPP binder for staff to review and be ready for emergencies regarding this concern. What measures will be put into place what systemic changes will the facili make to ensure that the deficient pradoes not recur The Administrator/Designee and MD present the policy and procedure to Safety Committee for review of	idents y the the the es or ty actice			

	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055557	B. WING _			06/20/2024	
	ROVIDER OR SUPPLIER DE POST ACUTE		STREET ADDRESS, CITY, STATE, ZIP CODE 35253 AVENUE H YUCAIPA, CA 92399		5253 AVENUE H		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	x	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
	Methods for Sharing I CFR(s): 483.73(c)(4)- §403.748(c)(4)-(6), §4 (4)-(6), §441.184(c)(4) §441.184(c)(4)-(6), §4 (4)-(6), §483.73(c)(4)- §484.102(c)(4)-(5), §4 (4)-(6), §485.625(c)(4	nformation (6) 116.54(c)(4)-(6), §418.113(c))-(6), §460.84(c)(4)-(6), 160.84(c)(4)-(6), §482.15(c) -(6), §483.475(c)(4)-(6), 185.68(c)(4), §485.542(c)		013	compliance. The safety committee will review the EPP and policies annually a update accordingly to changing regulations. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must develop plan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective act evaluated for its effectiveness. The PO must be integrated into the Quality Assurance system. A special QAPI meeting was convened the Administrator/Designee and DON of 06/26/24 to present the results of the standard Recertification survey and the POC. The Administrator/ Designee and MD we present results of the monthly Safety Committee meeting to the QAPI month committee meeting for monitoring and recommendations. Corrective Action Compliance Date: 06/26/24	nd s o a t ion C by n	6/26/24
	(6).	develop and maintain an					

PRINTED: 07/11/2024 FORM APPROVED OMB NO. 0938-0391 (X3) DATE SURVEY

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055557	B. WING _			06/	20/2024
	ROVIDER OR SUPPLIER DE POST ACUTE		STREET ADDRESS, CITY, STATE, ZIP CODE 35253 AVENUE H YUCAIPA, CA 92399		5253 AVENUE H		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	x	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
E 033	that complies with Feand must be reviewed 2 years [annually for I communication plan refollowing: (4) A method for shard documentation for pacare, as necessary, with maintain the continuit (5) A means, in the expelease patient inform CFR 164.510(b)(1)(ii) required for HHAs ununder §485.68(c)] (6) [(4) or (5)]A means about the general compatients under the [faunder 45 CFR 164.51] *[For RNHCIs at §403 sharing information and patients under the RN with care providers to care, based on the with made by the patient of the condition and location facility's care as permit 164.510(b)(4).	ness communication plan deral, State and local laws d and updated at least every LTC facilities]. The must include all of the nust include all of the ing information and medical tients under the [facility's] with other health providers to y of care. Went of an evacuation, to nation as permitted under 45. [This provision is not der §484.102(c), CORFs s of providing information and location of cility's] care as permitted 0(b)(4). 8.748(c):] (4) A method for and care documentation for IHCl's care, as necessary, maintain the continuity of citten election statement or his or her legal tt §491.12(c):] (4) A means on about the general of patients under the	E	0333	How corrective action(s) will be		

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055557	B. WING _			06/	/20/2024
	ROVIDER OR SUPPLIER DE POST ACUTE			35	REET ADDRESS, CITY, STATE, ZIP CODE 5253 AVENUE H UCAIPA, CA 92399		
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFII TAG				(X5) COMPLETION DATE
E 033	Based on record revifailed to maintain the (EOP). This was evid for sharing documen facility's care with oth communication plan. residents and could recommunication in the Findings: During record review Maintenance Supervicements communication plan reviewed. At 2:40 p.m., the faci communication plan sharing information afor residents under the necessary, with othe the continuity of care Maintenance Supervicements.	lew and interview, the facility Emergency Operations Plan denced by missing a method tation for residents under the her health providers in the This affected the 47 of 47 result in the delay of event of an emergency. If and interview with the isor on 6/20/24, the was requested and lity was unable to provide a that outlined a means for and medical documentation he facility's care, as relating the finding did have a policy and would	E	0333	accomplished for those residents found have been affected by the deficient practice No residents were affected by the deficient finding. How the facility will identify other reside having the potential to be affected by the same deficient practice and what corrective action will be taken No other residents were affected by the deficient finding. The facility policy for communication outlining the means for sharing information & medical documentation of facility residents will be reviewed & add to the facility EPP. What measures will be put into place of what systemic changes will the facility make to ensure that the deficient practic does not recur The Administrator/Designee and MD we present the policy and procedure to the Safety Committee for review of compliance. The safety committee will review the EPP and policies annually a update accordingly to changing regulations. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must developlan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective act evaluated for its effectiveness. The PC must be integrated into the Quality Assurance system. A special QAPI meeting was convened the Administrator/Designee and DON 06/26/24 to present the results of the	ents ne or ded r iice iill e and	

	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED		
		055557	B. WING _			06/	20/2024
	ROVIDER OR SUPPLIER DE POST ACUTE			35	TREET ADDRESS, CITY, STATE, ZIP CODE 5253 AVENUE H UCAIPA, CA 92399		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD TAG CROSS-REFERENCED TO THE APPROPE DEFICIENCY)			(X5) COMPLETION DATE	
E 033	Continued From page	÷ 8	E	033	standard Recertification survey and the POC. The Administrator/ Designee and MD w present results of the monthly Safety Committee meeting to the QAPI month committee meeting for monitoring and recommendations. Corrective Action Compliance Date: 06/26/24	vill	
E 034 SS=D	' '		E	034			6/26/24

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILDING	PLE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED		
	055557	B. WING	 	06/20/2024		
NAME OF PROVIDER OR SUPPLIER CREEKSIDE POST ACUTE			STREET ADDRESS, CITY, STATE, ZIP CODE 35253 AVENUE H YUCAIPA, CA 92399			
PREFIX (EACH DEFICIENCY MU	MENT OF DEFICIENCIES JST BE PRECEDED BY FULL IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	D BE COMPLETION		
*[For Inpatient Hospice a means of providing inform hospice's inpatient occup ability to provide assistant having jurisdiction, the Incenter, or designee. This REQUIREMENT is by: Surveyor: 43035 Based on record review failed to maintain their EPlan (EOP). This was even providing information about occupancy and needs mocommunication plan. This residents and could resucommunication in the even Findings: During record review and Maintenance Supervisor communication plan was reviewed. At 2:45 p.m., the facility's was missing a means of about the facility's occup ability to provide assistant having jurisdiction, the Incenter, or designee. Upo Maintenance Supervisor and stated that they did twas provided.	mation about the bancy, needs, and its nee, to the authority neident Command not met as evidenced and interview, the facility mergency Operations idenced by a means of but the facility's issing from the saffected 47 of 47 lt in the delay of ent of an emergency. It in the delay of ent of an emergency. It in the delay of ent of an emergency.	E 03	How corrective action(s) will be accomplished for those residents for have been affected by the deficient practice No residents were affected by the deficient finding. How the facility will identify other reshaving the potential to be affected by same deficient practice and what corrective action will be taken No other residents were affected by deficient finding. The facility policy for communication outlining the means for sharing our occupancy, needs and our ability to provide assistance will be reviewed added to the facility EPP. □RediNetom Department of the appropriate agent What measures will be put into place what systemic changes will the facil make to ensure that the deficient prodoes not recur The Administrator/Designee and MI present the policy and procedure to Safety Committee for review of compliance. The safety committee review the EPP and policies annual	sidents by the the and the our of the cy(s). e or ity actice D will the will		

AND PLAN OF	F DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055557	B. WING			06/20/2024	
NAME OF PR	OVIDER OR SUPPLIER			S ⁻	TREET ADDRESS, CITY, STATE, ZIP CODE		
CREEKSID	E POST ACUTE				5253 AVENUE H UCAIPA, CA 92399		
()(1) ID	SHMMADV ST/	ATEMENT OF DEFICIENCIES	ID	1	PROVIDER'S PLAN OF CORRECTION		(VE)
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		(EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
E 041 SS=D	hospital must impleme power systems based forth in paragraph (a) policies and procedur paragraphs (b)(1)(i) a §483.73(e), §485.625 (e) Emergency and st [LTC facility CAH and	C Emergency Power for Participation: andby power systems. The ent emergency and standby I on the emergency plan set of this section and in the es plan set forth in nd (ii) of this section.		034	update accordingly to changing regulations. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must develop plan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective act evaluated for its effectiveness. The PO must be integrated into the Quality Assurance system. A special QAPI meeting was convened the Administrator/Designee and DON of 06/26/24 to present the results of the standard Recertification survey and the POC. The Administrator/ Designee and MD was present results of the monthly Safety Committee meeting to the QAPI month committee meeting for monitoring and recommendations. Corrective Action Compliance Date: 06/26/24	o a it ion C by in	6/26/24

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		A. BUILDIN	IPLE CONSTRUCTION NG 02	(C	(X3) DATE SURVEY COMPLETED	
		055557	B. WING _			06/20/2024
	ROVIDER OR SUPPLIER DE POST ACUTE					
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	((EACH CORRECTI) CROSS-REFERENCE	AN OF CORRECTION VE ACTION SHOULD BE ED TO THE APPROPRIATI FICIENCY)	(X5) COMPLETION DATE
E 041	this section. §482.15(e)(1), §483. §485.625(e)(1) Emergency generate must be located in acrequirements found i Code (NFPA 99 and Amendments TIA 12 12-5, and TIA 12-6), and Tentative Interim 12-2, TIA 12-3, and when a new structure structure or building 482.15(e)(2), §483.7 §485.542(e)(2) Emergency generate [hospital, CAH and L the emergency power and [maintenance] re Health Care Facilities Safety Code. 482.15(e)(3), §483.7 (3),§485.542(e)(2) Emergency generate LTC facilities] that mato power emergency for how it will keep en	set forth in paragraph (a) of 73(e)(1), §485.542(e)(1), or location. The generator coordance with the location in the Health Care Facilities Tentative Interim -2, TIA 12-3, TIA 12-4, TIA Life Safety Code (NFPA 101 Amendments TIA 12-1, TIA TIA 12-4), and NFPA 110, er is built or when an existing is renovated. 3(e)(2), §485.625(e)(2), or inspection and testing. The TC facility] must implement er system inspection, testing, equirements found in the scode, NFPA 110, and Life	E			
	REHs at §485.542(g §485.625(g):]	32.15(h), LTC at §483.73(g),), and and CAHs porated by reference in this				

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055557	B. WING _	B. WING			20/2024
	ROVIDER OR SUPPLIER DE POST ACUTE			35	REET ADDRESS, CITY, STATE, ZIP CODE 253 AVENUE H JCAIPA, CA 92399	•	
(X4) ID PREFIX TAG			I	ID PROVIDER'S PLAN OF CORRECT PREFIX (EACH CORRECTIVE ACTION SHOUT TAG CROSS-REFERENCED TO THE APPRIDENCE)			(X5) COMPLETION DATE
E 041	Federal Register in at 552(a) and 1 CFR paramaterial from the sour inspect a copy at the Center, 7500 Security or at the National Arc Administration (NARA availability of this mat 202-741-6030, or goon http://www.archives.gg_federal_regulations/lf any changes in this incorporated by refere document in the Federal the changes. (1) National Fire Prote Batterymarch Park, Quincy, MA 02169, who 1.617.770.3000. (i) NFPA 99, Health Condition, issued August (ii) Technical interim at NFPA 99, issued August (iii) TIA 12-3 to NFPA (vi) TIA 12-5 to NFPA (vi) TIA 12-6 to NFPA (vii) NFPA 101, Life Sissued August 11, 2011. (ix) TIA 12-2 to NFPA 2011.	for incorporation by ctor of the Office of the Coordance with 5 U.S.C. rt 51. You may obtain the rees listed below. You may CMS Information Resource of Boulevard, Baltimore, MD chives and Records (A). For information on the rerial at NARA, call to: ov/federal_register/code_of libr_locations.html. edition of the Code are rence, CMS will publish a reral Register to announce rection Association, 1 www.nfpa.org, fare Facilities Code, 2012 to 11, 2011. amendment (TIA) 12-2 to 11, 2011. gg, issued August 9, 2012. gg, issued August 9, 2013. gg, issued March 7, 2013. gg, issued March 3, 2014. afety Code, 2012 edition,	E	041			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		A. BUILDING (E CONSTRUCTION D2	(X3) DATE SURVEY COMPLETED			
		055557	B. WING		06/20/2024		
	ROVIDER OR SUPPLIER DE POST ACUTE	,	3	STREET ADDRESS, CITY, STATE, ZIP CODE 35253 AVENUE H YUCAIPA, CA 92399			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD E CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)			
E 041	Standby Power Syste TIAs to chapter 7, iss This REQUIREMENT by: Surveyor: 43035 Based on record revifailed to maintain an (EOP). This was evidinformation in the emsystem policy and pred 47 residents and couproperly react during Findings: During record review Maintenance Superv was requested. At 2:58 p.m., the faciand specified policy amaintaining emergent such as, how back up how long back up fue power. Upon intervier	dard for Emergency and ems, 2010 edition, including sued August 6, 2009 T is not met as evidenced ew and interview, the facility Emergency Operations Plan lenced by missing ergency power supply ocedure. This affected 47 of ld result in the failure to an emergency. and interview with the isor on 6/20/24, the EOP lity was missing a written and procedure for cy power during an outage of fuel would be acquired and el could sustain emergency w, the Maintenance I the finding and stated that	E 041	How corrective action(s) will be accomplished for those residents foun have been affected by the deficient practice No residents were affected by the deficient finding. How the facility will identify other resid having the potential to be affected by the same deficient practice and what corrective action will be taken No other residents were affected by the deficient finding. The facility policy for managing a power outage and procedures for maintaining the generator during the power outage along with the fuel delivery agreement be reviewed and added to the facility. What measures will be put into place of what systemic changes will the facility make to ensure that the deficient practices not recur. The Administrator/Designee and MD we present the policy and procedure to the Safety Committee for review of compliance. The safety committee will review the EPP and policies annually a update accordingly to changing regulations. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must developlan for ensuring that correction is achieved and sustained. This plan must	ents he e er y will EPP. or ice vill e I and		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED			
		055557	B. WING		06/20/2024		
	ROVIDER OR SUPPLIER DE POST ACUTE			35	TREET ADDRESS, CITY, STATE, ZIP CODE 5253 AVENUE H UCAIPA, CA 92399		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PROVIDER'S PLAN OF CORRECTION PREFIX (EACH CORRECTIVE ACTION SHOULD I TAG CROSS-REFERENCED TO THE APPROPR DEFICIENCY)			(X5) COMPLETION DATE	
E 041	Continued From page 14		EO		be implemented, and the corrective ac evaluated for its effectiveness. The PC must be integrated into the Quality Assurance system. A special QAPI meeting was convened the Administrator/Designee and DON of 06/26/24 to present the results of the standard Recertification survey and the POC. The Administrator/ Designee and MD of present results of the monthly Safety Committee meeting to the QAPI month committee meeting for monitoring and recommendations. Corrective Action Compliance Date: 06/26/24		
K 000	Surveyor: 43035 K3 BUILDING: 01 K6 PLAN APPROVAL: 1966 K7 SURVEY UNDER: 2012 EXISTING STRUCTURE TYPE: ONE STORY, CONSTRUCTION TYPE V (1111), FULLY SPRINKLERED. Resident Certified Beds: 59 Resident Census: 47 The following reflects the findings of the California Department of Public Health, during an annual Life Safety Code recertification survey. The findings are in accordance with 42 Code of Federal Regulations (CFR) §483.90(a)(b)(c)(j), National Fire Protection Association (NFPA) 101 - Life Safety Code, 2012 Edition, and NFPA 99 -		K	000			

	AND DLAN OF CORRECTION IDENTIFICATION NUMBER		1 ' '	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED	
		055557	B. WING		06/20/2024		
	ROVIDER OR SUPPLIER DE POST ACUTE			3	TREET ADDRESS, CITY, STATE, ZIP CODE 5253 AVENUE H UCAIPA, CA 92399	-	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		Х	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 000	Health Care Facilities Representing the Call Health: 43035 The facility is not in so		K	000			
K 345 SS=D	Fire Alarm System - TCFR(s): NFPA 101 Fire Alarm System - TA fire alarm system is accordance with an awith the requirements Electric Code, and NF and Signaling Code. If acceptance, maintend available. 9.6.1.3, 9.6.1.5, NFPA This REQUIREMENT by: Surveyor: 43035 Based on document refacility failed to maintate This was evidenced by documentation of sen inspections, including battery testing. This accompartments, 47 of could result in the fail occupants and exting emergency.	Testing and Maintenance Testing and Maintenance Tested and maintained in pproved program complying of NFPA 70, National FPA 72, National Fire Alarm Records of system ance and testing are readily A 70, NFPA 72 Tis not met as evidenced Review and interview, the ain the fire alarm system. The system fire alarm control panel ffected four of four smoke A 7 active residents, and aure to notify and evacuate auish fire in the event of an Ty Code, 2012 Edition alth care occupancies shall a alarm system in	K:	345	How corrective action(s) will be accomplished for those residents found have been affected by the deficient practice No residents were affected by the deficient finding. How the facility will identify other reside having the potential to be affected by the same deficient practice and what corrective action will be taken No other residents were affected by the deficient finding. (1) As part of the Semi-Annual Fire Alarm System Inspections performed be Quick Response, it will be requested the their documentation be provided in a timely manner after each inspection.	ents ne e y nat	6/26/24

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055557	B. WING _	B. WING			06/20/2024	
NAME OF P	ROVIDER OR SUPPLIER		<u> </u>	ST	TREET ADDRESS, CITY, STATE, ZIP CODE	,		
				35	5253 AVENUE H			
CREEKSII	DE POST ACUTE				UCAIPA, CA 92399			
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI) TAG	PREFIX (EACH CORRECTIVE ACTION SHOULD			(X5) COMPLETION DATE	
K 345	345 Continued From page 16		K 3	345				
K 343	9.6.1.3 A fire alarm syshall be installed, test accordance with the a NFPA 70, National Ele National Fire Alarm aris an approved existing permitted to be conting 9.6.1.5* To ensure opalarm system shall hamaintenance and test the applicable require Electrical Code, and Nalarm and Signaling ONFPA 72 - National Ficode, 2010 Edition 14.3 Inspection. 14.3.1 * Unless other visual inspections sha accordance with the smore often if required jurisdiction. Table 14.3.1 3. Batteries (d) Sealed lead-acid guirisdiction. Table 14.3.1 3. Batteries (d) Sealed lead-acid guirisdiction. Table 14.3.1 5. Batteries (i) Supervisory signal 14.4.2.2* Systems and shall be tested accorded to the state of the sta	existem required for life safety ed, and maintained in applicable requirements of ectrical Code, and NFPA 72, and Signaling Code, unless it ag installation, which shall be used in use. Berational integrity, the fire are an approved ing program complying with ments of NFPA 70, National NFPA 72, National Fire Code. Breather and Signaling wise permitted by 14.3.2 all be performed in schedules in Table 14.3.1 or by the authority having Semiannually Bemiannually Bemiannually Besemiannually Besmiannually B		345	check list of the last performed inspect and documentation received will be ad to the life and safety binder of logs. (2) As part of the semi-annual fire alar control panel inspection and testing. Quick Response will add battery load testing to their reports. What measures will be put into place of what systemic changes will the facility make to ensure that the deficient pract does not recur. Quick Response will perform their semi-annual fire alarm system inspections if it's an annual inspection to meet the requirements. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must developlan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective active active and sustained. The Quality Assurance system. A special QAPI meeting was be converted by the Administrator/Designee and DO on 06/26/24 to present the results of the standard Recertification survey and the Plan of Correction (POC). The Maintenance Director (MD) will present the results of the Semi-Annual Fire Alarm System Inspection at the Quanthly meeting. Corrective Action Completion Date: 06/26/24	ded rm r r r r r r r r r r r r r r r r r r		

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDING	LE CONSTRUCTION 5 02	(X3) DATE SURVEY COMPLETED			
		055557	B. WING			6/20/2024	
	ROVIDER OR SUPPLIER DE POST ACUTE			STREET ADDRESS, CITY, STATE, ZIP CODE 35253 AVENUE H YUCAIPA, CA 92399	•		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE	(X5) COMPLETION DATE	
K 345	necessary, battery to be cleaned and coar lead-acid batteries is (b) Battery replacem replaced in accorda recommendations of manufacturer or who voltage or current farecommendations. (e) Load voltage test disconnected, the test measured while suprequired by its applied not fall below the level type of battery. If the specified, corrective batteries shall be repload equal to the full the battery shall be conducting this test. 14.4.5 * Unless other sections of this Cod in accordance with the or more often if requipired in the sections of the cod in accordance with the composition. Table 14.4.5 for accordance with the sections of the cod in accordance with the composition of the cod in accordance with the	e checked and ensured. If the erminals or connections shall ted. Electrolyte level in shall be visually inspected. The energy of	K 34	5			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED		
		055557	B. WING		06/20/2024		
	ROVIDER OR SUPPLIER DE POST ACUTE			35	REET ADDRESS, CITY, STATE, ZIP CODE 1253 AVENUE H JCAIPA, CA 92399		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFIZ TAG	x	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 345 K 353 SS=D	Upon interview, the M confirmed the finding was not completing the 2. At 1:28 p.m., the fadocumentation of fire semi-annual load volt the Maintenance Sup and stated that the vethe semi-annual inspection.	e alarm system inspections. Ilaintenance Supervisor and stated that the vendor ne inspections. Icility was unable to provide alarm control panel battery age testing. Upon interview, ervisor confirmed the finding		345			6/26/24
	Automatic sprinkler at inspected, tested, and with NFPA 25, Standa Testing, and Maintain Protection Systems. If maintenance, inspect maintained in a secur available. a) Date sprinkler system support of the system support of the system. Provide in REMARKS any non-required or paystem. 9.7.5, 9.7.7, 9.7.8, and This REQUIREMENT by: Surveyor: 43035 Based on document residue.	ing of Water-based Fire Records of system design, ion and testing are re location and readily stem last checked stem test oply source 6 information on coverage for reartial automatic sprinkler d NFPA 25 is not met as evidenced review and interview, the			K353 How corrective action(s) will be		
	Surveyor: 43035 Based on document r	review and interview, the ain the sprinkler system.				I to	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02				TE SURVEY MPLETED	
		055557	B. WING _	B. WING		0	06/20/2024	
NAME OF P	ROVIDER OR SUPPLIER			STREET AL	DDRESS, CITY, STATE, ZIP CODE	•		
CDEEKSII	DE POST ACUTE			35253 AVE	ENUE H			
CKEEKSII	DE POSTACUTE			YUCAIPA	A, CA 92399			
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	UST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE			(X5) COMPLETION DATE		
K 353	inspection records. T smoke compartments malfunction of the au the event of a fire. NFPA 101 Life Safety 19.3.5 Extinguishment 19.3.5.1 Buildings con be protected through supervised automatic accordance with Secon permitted by 19.3.5.5 19.3.5.4 * The sprink 19.3.5.1 or 19.3.5.3 son accordance with 9.7. 9.7 Automatic Sprink Equipment. 9.7.1 Automatic Sprink Equipment. 9.7.1.1 * Each automatic sprinkler Systems (2) NFPA 13D, Standa Sprinkler Systems in Dwellings and Manuf (3) NFPA 13R, Standa Sprinkler Systems in Dwellings and Manuf (3) NFPA 13R, Standa Sprinkler Systems in to and Including Four 9.7.5 All automatic sprinkler Systems required by tested, and maintaine 25, Standard for the Maintenance of Water Systems. 9.7.7 All required doc	by missing quarterly sprinkler this affected four of four and could result in the atomatic sprinkler system in the Accordance with NFPA Inspection, Testing, and ear-Based Fire Protection of the store of the following and standpipe this Code shall be inspection.	K3	have practi No re defici How havin same corre No of defici The Mathematical What what make does A che Admi quart testin docur quick for life The s repor Design recorrect How perfo are s plant achie be im evalu must Assu	esidents were affected by the ient finding. the facility will identify other read the potential to be affected as deficient practice and what ective action will be taken ther residents were affected be ient finding. Maintenance Staff was educate egulation and deficient finding inistrator/Designee on 04/16/2 to measures will be put into place to ensure that the deficient part of the certain the process of the inistrator/Designee to include terly fire sprinkler inspection and mentation received. To be about the certain the deficient part of the certain the desire and safety has been received and safety has been received the part of this checklist will be read by the MD to the Administ gene monthly for further action mendations. The facility plans to monitor its extended to make sure that solution the facility plans to monitor its extended. The facility must define the facility must define the facility of the correction is eved and sustained. This plan inplemented, and the corrective that the correction that the correction that the correction that the correction that	esidents by the y the ed on by the 024. ce or ility ractice nd le to entation ed. rator/ as or utions velop a must e action e POC		
design of the fire protection system and the				ecial QAPI Meeting will be con				

PRINTED: 07/11/2024 FORM APPROVED OMB NO. 0938-0391 (X3) DATE SURVEY

	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	l ` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED	
		055557	B. WING		06/20/2024		
NAME OF P	ROVIDER OR SUPPLIER			S	TREET ADDRESS, CITY, STATE, ZIP CODE		
CDEEKSII	DE POST ACUTE			3	5253 AVENUE H		
CKLLKOII	DE FOST ACOIL			Υ	UCAIPA, CA 92399		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI TAG	х	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 353	testing of the fire protomaintained at an apport the life of the fire protogorous and maintained at an apport the life of the fire protogorous and maintenance of Volume of Volu	ection system shall be roved, secured location for ection system. Internance records required d for the Inspection, Testing, Vater-Based Fire Protection intained at an approved, In the Installation of Sprinkler of the Installation	K	353	Director of Nursing on 06/26/24 to presthe results of the standard Recertification survey and the POC. The MD will present the results of the checklist in the monthly QAPI meeting then quarterly moving forward. Corrective Action Completion Date: 06/26/24	on	

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDIN	PLE CONSTRUCTION IG 02		(X3) DATE SURVEY COMPLETED	
		055557	B. WING _			06/20/2024
	ROVIDER OR SUPPLIER DE POST ACUTE			STREET ADDRESS, CITY, STATE, 35253 AVENUE H YUCAIPA, CA 92399	, ZIP CODE	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI) TAG	PREFIX (EACH CORRECTIVE ACTION SHO		DATE
K 353 K 511 SS=D	of 4 quarterly sprinkler interview, the Mainter the finding and stated completing the inspect Utilities - Gas and Electrical with NFPA 5 electrical wiring and entire NFPA 70, National Eleinstallations can continued the Mainterview of the Mai	ity was unable to provide 2 ir inspections. Upon nance Supervisor confirmed I that the vendor was not ctions. ectric ectric or related gas piping 64, National Fuel Gas Code, equipment complies with	K S			6/26/24
	by: Surveyor: 43035 Based on observatior failed to maintain the was evidenced by an the weatherproof cov four smoke compartm and could result in the NFPA 101 Life Safety 19.5 Building Service 19.5.1 Utilities. 19.5.1.1 Utilities shall of Section 9.1. 9.1.2 Electrical wiring	is not met as evidenced and interview, the facility electrical receptacles. This outdoor receptacle missing ering. This affected one of nents, 47 of 47 residents, e ignition and spread of fire.		K511 How corrective action(accomplished for those have been affected by practice No residents were affedeficient finding. How the facility will ide having the potential to same deficient practice corrective action will be No other residents were deficient finding. The tension and polari updated to monitor we	e residents found the deficient ected by the entify other reside be affected by the e and what e taken re affected by the ity log will be	ents ne

` /		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
055557 B. WING			06/20/2024				
	ROVIDER OR SUPPLIER DE POST ACUTE	,		STREET ADDRESS, CITY, STATE, ZIP CODE 35253 AVENUE H YUCAIPA, CA 92399			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 511	Code, unless such in existing installations, be continued in service NFPA 70 National Elea 406.6 Receptacle fact as to completely cover against the mounting faceplates mounted in recess-mounted recest the opening and seat surface. 406.9(A) A receptacle location protected frood damp locations shall receptacle that is wear receptacle is covered inserted and receptacle from the face and receptacle in the face outside in the pation observed missing a vinterview, the Maintenance in service in the pation observed missing a vinterview, the Maintenance in the pation observed missing a vinterview, the Maintenance in the pation observed missing a vinterview, the Maintenance in the pation of the face of the pation observed missing a vinterview, the Maintenance in the pation of the pation observed missing a vinterview, the Maintenance in the pation of the pation observed missing a vinterview, the Maintenance in the pation of the pation o	stallations are approved which shall be permitted to ce. ectrical Code, 2011 Edition seplates shall be installed so er the opening and seat surface. Receptacle inside a box having a sptacle shall effectively close against the mounting entire installed outdoors in a similar the weather or in other have an enclosure for the atherproof when the did (attachment plug cap not cle covers closed). eacility and interview with the sisor on 6/20/24, the electrical served. extrical receptacle located ext to the smoking area was weatherproof covering. Upon mance Supervisor confirmed of that there was usually a	K	511	on all outside receptacles. What measures will be put into place of what systemic changes will the facility make to ensure that the deficient practic does not recur. The tension and polarity inspection repeated will be presented at the monthly safety committee meeting to ensure we composite weatherproof protection on exterior receptacles. How the facility plans to monitor its performance to make sure that solution are sustained. The facility must develop plan for ensuring that correction is achieved and sustained. This plan must be implemented, and the corrective act evaluated for its effectiveness. The PO must be integrated into the Quality Assurance system The Administrator/Designee and DON convened a special QAPI meeting on 06/26/24 to present the results of the standard Recertification survey and the POC. Any concerns from the monthly safety committee meeting will be presented at the quarterly QAPI meeting by the Maintenance Director (MD). Corrective Action Completion Date: 06/26/24	ort ly r as o a st cion C	