append 128/2018

PRINTED: 08/07/2018 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01			(X3) DATE SURVEY COMPLETED	
		055760	B. WING			07/13/2018	
	SUMMARY STA	WELLNESS CENTRE, LP TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)		STREET ADDRESS, CITY, STATE, ZIP CODE 415 SOUTH GARFIELD ALHAMBRA, CA 91801 ID PROVIDER'S PLAN OF CORRECTION SHOULD CROSS-REFERENCED TO THE APPROVIDER'S PLAN OF C			(X5) COMPLETION DATE
E 030 SS=C	California Departme Emergency Prepare The findins are in a Federal Regulation for Long Term Care Representing the C Health: Federal ID Number The facility is not in 42 CFR 483.73 for Facilities. S/S: C Names and Contac CFR(s): 483.73(c)([(c) The [facility, ex transplant centers, maintain an emerge communication pla State and local law updated at least an plan must include a (1) Names and con following: (i) Staff. (ii) Entities providin (iii) Patients' physic (iv) Other [facilities] (v) Volunteers. *[For RNHCIs at §4 communication pla	california department of Public 2: 14041 substantial compliance with Long Term Care (LTC) ct Information 1) cept RNHCIs, hospices, and HHAs] must develop and ency preparedness n that complies with Federal, s and must be reviewed and inually. The communication all of the following:] ctact information for the g services under arrangement. cians [. 403.748(c):] The n must include all of the	Εú	0000	agents, officers, directors, or shareholders. The provider reserves the right to challenge the cited findings if at any time the provider determines that the disputed findings are relied upon in a manner adverse to the interests of the provider either by the governmental agencies or third party.	on 2010 AUG 17 AM 8: 0	HEALTH FACILITY
ARORATOR	MURHATORIS OR PROVID	DER/SUPPLIER REPRESENTATIVE'S SIGN	VATURE	^	, TITLE	. ((X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

	T OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01			(X3) DATE SURVEY COMPLETED	
		055760	B. WING			07/13/2018	
	PROVIDER OR SUPPLIER BRA HEALTHCARE &	WELLNESS CENTRE, LP		415 \$	EET ADDRESS, CITY, STATE, ZIP CODE SOUTH GARFIELD IAMBRA, CA 91801		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)) BE	(X5) COMPLETION DATE
E 030	following: (1) Names and confollowing: (i) Staff. (ii) Entities providing: (ii) Next of kin, gualion (iv) Other RNHCIs. (v) Volunteers. *[For ASCs at §416 plan must include at (1) Names and confollowing: (i) Staff. (ii) Entities providing: (ii) Patients' physice (iv) Volunteers. *[For Hospices at § communication plant following: (1) Names and confollowing: (1) Names and confollowing: (i) Hospice employed: (ii) Entities providing: (iii) Patients' physice (iv) Other hospices *[For OPOs at §486 plan must include at (1) Names and confollowing: (i) Staff. (ii) Entities providing: (iii) Volunteers. (iv) Other OPOs.	g services under arrangement. additional arra	E	030	On July 16, 2018 The Facility Administrator contacted area volunteers to include in the Facility's Emergency Preparedness plan. In case of a prolonged emergency situation the volunteers will provide extra assistance. On July 16, 2018 the Facility Administrator reviewed the Emergency Preparedness Plan and all other areas of the communication plan were fulfilled. Administrator will review the Emergency Preparedness plan every 6 months to ensure compliance. Any negative findings will be communicated to the Quality Assurance Committee monthly for review and further plan of action.	1	8/17/18

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MUL' A. BUILDI	OATE SURVEY OMPLETED			
		055760	B. WING		o	7/13/2018
	PROVIDER OR SUPPLIER BRA HEALTHCARE &	WELLNESS CENTRE, LP		STREET ADDRESS, CITY, STATE, ZIP 415 SOUTH GARFIELD ALHAMBRA, CA 91801	CODE	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG		ON SHOULD BE IE APPROPRIATE	(X5) COMPLETION DATE
E 030	by: Based on record refailed to develop a communication plain case there is a pfrom non-licensed needed. The deficiand services to the emergency. Finding: On July 13, 2018, a conducted a review Preparedness plan communication plain physicians, other Little The evaluator held administrator and it of the survey, the content of the survey.	NT is not met as evidenced eview and interview, the facility	ΕO)30		
	and make available would include the sother LTC facility, a prolong emergency assistance from lic EP Testing Require CFR(s): 483.73(d)(2) Testing. The [faRNHCIs and OPOstest the emergency		ΕC	On July 17, 2018 facility administrator scheduled scale emergency exercis Sept 13, 2018. Shakeou scenario planned.	d a full se for	8/17/18

	STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MUL A. BUILD		LE CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED	
		055760	B. WING	_		07/	13/2018
NAME OF	PROVIDER OR SUPPLIER			s	STREET ADDRESS, CITY, STATE, ZIP CODE		
ALHAME	BRA HEALTHCARE &	WELLNESS CENTRE, LP			15 SOUTH GARFIELD		
				A	ALHAMBRA, CA 91801		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	BE	(X5) COMPLETION DATE
E 039	all of the following: *[For LTC Facilities The LTC facility must the emergency plan unannounced staff procedures. The LT following:] (i) Participate in a fucommunity-based of exercise is not accessacility-based. If the actual natural or marequires activation of [facility] is exempt for community-based of full-scale exercise for the actual event. (ii) Conduct an additional exercise is not lined (A) A second full-community-based of (B) A tabletop exercise for the actual event. (iii) Conduct an additional exercise is not accessate activation of full-community-based of the actual event. (iii) Conduct an additional exercise is not accessate activation of full-community-based of the actual event. (iii) Analyze the [factual exercises, and emergency plan. *[For RNHCIs at §4 §486.360] (d)(2) Temust conduct exercises.	at §483.73(d):] (2) Testing. st conduct exercises to test at least annually, including drills using the emergency. C facility must do all of the all-scale exercise that is at when a community-based essible, an individual, and facility experiences an en-made emergency that for the emergency plan, the form engaging in a far individual, facility-based for 1 year following the onset of the exercise that may mitted to the following: scale exercise that is ar individual, facility-based. Sercise that includes a group facilitator, using a narrated, mergency scenario, and a set ints, directed messages, or designed to challenge an ility's] response to and ation of all drills, tabletop or gency events, and revise the	E	039	On July 17, 2018 Administrator looked over the Facility Emergency Plan to ensure all testing requirements were met No other areas were noncompliant. Facility Administrator will review Emergency Preparedness Plan annually to ensure all areas are up to date and compliant. Any negative findings will be communicated to the Quality Assurance Committee monthly for review and further plan of action.	•	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MUI A. BUILE		NSTRUCTION	(X3) DATE SURVEY COMPLETED		
		055760	B. WING				7/13/2018
	PROVIDER OR SUPPLIER BRA HEALTHCARE &	WELLNESS CENTRE, LP		415 SC	T ADDRESS, CITY, STATE, ZIP CODE DUTH GARFIELD IMBRA, CA 91801		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPL DEFICIENCY)	OULD BE	(X5) COMPLETION DATE
	following: (i) Conduct a pape least annually. A tal discussion led by a clinically relevant er of problem stateme prepared questions emergency plan. (ii) Analyze the [RN to and maintain doc exercises, and eme [RNHCl's and OPO needed. This REQUIREMEN by: Based on interview failed to develop an policy for emergency procedu emergency procedu emergency procedu emergency policy are care and services to emergency. Findings: On July 13, 2018, at facility's emergency was conducted. It we documentation to inconducted any emergency event, needed to conducted and been conducted and bee	r-based, tabletop exercise at oletop exercise is a group facilitator, using a narrated, mergency scenario, and a set onts, directed messages, or designed to challenge an although the interpretation of all tabletop ergency events, and revise the regency events, and revise the regency events, and revise the regency plan, as and record review, the facility emergency preparedness testing. The a policy to conduct full scale dness exercises using the res. The lack of this and excercise(s) could delay the residents, during an as noticed that there was no dicate the facility had regency preparedness ty had no documentation to exercise, an actual or a second full-scale conducted.	E	039			
	administrator regard	ling the facility's emergency		1			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE A. BUILDING 0	(X3) DATE SURVEY COMPLETED		
		055760	B. WING		07/13/2018
	PROVIDER OR SUPPLIER BRA HEALTHCARE &	WELLNESS CENTRE, LP	41	REET ADDRESS, CITY, STATE, ZIP CODE 5 SOUTH GARFIELD _HAMBRA, CA 91801	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES LY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROP DEFICIENCY)	D BE COMPLETION
E 039	preparedness docu emergency prepare administrator state scheduled to condu preparedness full-s	umentation, specifically for edness testing. The data the facility was	E 039	•	
K 000	This facility was su Code NFPA 101, 2 Existing Health Ca applicable codes. Representing the D 14041 The following representation of Pub Code Survey.	urveyed under the Life Safety 2012 Edition, Chapter 19, are Occupancies, and other Department of Public Health: esents the findings of the olic Health during a Life Safety	K 000		
	accordance with 7. also served by the 19.2.10.1 (Indicate N/A in on with less than 30 otravel is obvious.)	al signs are displayed in .10 with continuous illumination emergency lighting system. ne-story existing occupancies occupants where the line of exit	K 293	On July 11, 2018 Maintenance Supervisor contacted Five Star Fire Protection to relocate and replace exit signs. All exit signs will maintain an obvious and clear fire exit direction to the nearest approved fire exit door at all times.	1 1 1 1 1 1 1 1 1 1

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MUI A. BUILD		LE CONSTRUCTION 6 01	(X3) DATE SURVEY COMPLETED		
		055760	B. WING	·		07/	13/2018
	PROVIDER OR SUPPLIER BRA HEALTHCARE &	WELLNESS CENTRE, LP	STREET ADDRESS, CITY, STATE, ZIP CODE 415 SOUTH GARFIELD ALHAMBRA, CA 91801				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 293	7.10.1.2.1* Exits, of doors that obviously exits, shall be mark readily visible from 7.10.1.5 Exit Access 7.10.1.5.1 Access to approved, readily visible exit or way to reapparent to the occ 7.10.1.8* Visibility. If 7.10 shall be locate color, and design the provide contrast with or other signs. No dequipment that import that import that import that import the line of vision of could detract attention permitted. Based on observation failed to maintain and irrection to the near all times. In case of emergency, a fire eximperative for an efficial times. In case of emergency, a fire eximperative for an efficial of the occupants from an official Life 8/8/2016. Findings: On July 11, 2018, as conducted a tour of most of the fire exit black arrows.	ther than main exterior exity and clearly are identifiable as ed by an approved sign that is any direction of exit access. s. o exits shall be marked by sible signs in all cases where each the exit is not readily	Ka	293	On July 11, 2018 Maintenance Supervisor did another walk through of all exit signs in the facility and found no other exit signs noncompliant. Maintenance Supervisor will conduct monthly walk through of all exit signs to ensure they are all compliant and visible. All trends and negative finding will be communicated monthly to the Quality Assurance committee for review and further plan of action.	s	

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MUL A. BUILD	TIPLE CONSTRUCTION DING 01		(X3) DATE SURVEY COMPLETED		
		055760	B. WING		07	07/13/2018	
	PROVIDER OR SUPPLIER BRA HEALTHCARE &	WELLNESS CENTRE, LP		STREET ADDRESS, CITY, STATE, ZIP (415 SOUTH GARFIELD ALHAMBRA, CA 91801	CODE		
(X4) ID PREFIX TAG				PROVIDER'S PLAN OF CO X (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE E APPROPRIATE	(X5) COMPLETION DATE	
K 293	dining room and Nu observed two exits activity/dining room saw the yellow arrowhite and the arrowbuilding supervisor room was one of thimmediate area. The evaluator inspends observed approximality stood in the area and did not see that would lead to the control of two doors as a kitchen set up and Magnolia Dining Room of two doors are and did not see that would lead to the control of two doors are a kitchen set up and Magnolia Dining Room of two doors are a kitchen set up and Magnolia Dining Room of two doors are a kitchen set up and Magnolia Dining Room of two doors are a kitchen set up and Magnolia Dining Room of two doors are and the second of the control of two doors are a kitchen set up and Magnolia Dining Room of the control of the control of two doors are a kitchen set up and Magnolia Dining Room of the control	age 7 urse Station 1. The evaluator igns over the resident door and upon closer look, w. The word "exit" was in a pale yellow. The confirmed that the dining e fire exits out of the ected the interior patio and ately 12-residents' room the interior patio. The he center of the interior patio he fire exit access corridor. It is any signs over the doors he fire exit access corridor. It is any signs over the doors he fire exit access corridor. It is an interview with the building stated he would correct the fire ange for addition of 2-fire exit	К 2				
K 321 SS=D	In case of a fire, sn emergency the fire shall be available, of point to the nearest times. Hazardous Areas - CFR(s): NFPA 101 Hazardous Areas - Hazardous areas a having 1-hour fire r fire rated doors) or system in accordar		Κ3	On July 12, 2018 Main Supervisor installed a on the door in the air area.	doorknob	8 17 18	

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01			(X3) DATE SURVEY COMPLETED	
		055760	B. WING			07/13/2018	
	SUMMARY STA	WELLNESS CENTRE, LP TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL	ID PREFI	41 Al	REET ADDRESS, CITY, STATE, ZIP CODE 15 SOUTH GARFIELD LHAMBRA, CA 91801 PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD	ON (X5)	
TAG	REGULATORY OR L	SC IDENTIFYING INFORMATION)	TAG		CROSS-REFERENCED TO THE APPROP DEFICIENCY)	RIATE	DATE
K 321	system option is us separated from oth partitions and doors Doors shall be self-and permitted to ha protective plates the from the bottom of Describe the floor a hazardous areas th 19.3.2.1, 19.3.5.9 Area Separation N//a. Boiler and Fuel-Fb. Laundries (larger c. Repair, Maintenad. Soiled Linen Roce. Trash Collection (exceeding 64 gallof. Combustible Stor. (over 50 square feeg. Laboratories (if chazard - see K322) This REQUIREMEN by: Based on observate failed to ensure the basement are main partitions at all time smoke compartmer condenser held in a This deficient praction of smoke during a feriodings: On July 11, 2018, acconducted an inspecial content of the second of the sec	ed, the areas shall be er spaces by smoke resisting in accordance with 8.4. closing or automatic-closing we nonrated or field-applied at do not exceed 48 inches the door. Ind zone locations of at are deficient in REMARKS. Automatic Sprinkler Automatic Sprinkler Aired Heater Rooms I than 100 square feet) Ince, and Paint Shops Ims (exceeding 64 gallons) Rooms Ins) I age Rooms/Spaces It) I assified as Severe I is not met as evidenced I ion and interview, the facility hazardous area located in the tained with a smoke resisting is. The basement is one int with the air handler and separate room and door. I ce could result in the spread	КЗ	321	On July 12, 2018 Maintenance Supervisor checked all doors in the facility to ensure that they all had doorknobs. No other doors were found to have no doorknob. Maintenance Supervisor will check all doors monthly to ensure all doors have doorknobs. All trends and negative findings will be communicated monthly to the Quality Assurance committee for review and further plan of action.		

OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X3) DATE SURVEY COMPLETED		
	055760	B. WING		07/13/2018		
PROVIDER OR SUPPLIER BRA HEALTHCARE &	WELLNESS CENTRE, LP	STREET ADDRESS, CITY, STATE, ZIP CODE 415 SOUTH GARFIELD				
(EACH DEFICIENC)	Y MUST BE PRECEDED BY FULL		X (EACH CORRECTIVE ACTION SHOUL	D BE COMPLÉTION		
area which stores to supplies, the air duck handler/condenser. The evaluator insperair handler area via door handle and left measuring approximation diameter. The evaluator held supervisor at the tire stated he would reproson as possible. Subdivision of Build Construction 2012 EXISTING Smoke barriers shafter resistance rating be permitted to term Smoke dampers and penetrations in fully an approved sprink smoke compartme barrier. 19.3.7.3, 8.6.7.1(1) Describe any mechanic REMARKS. This REQUIREMED by: NFPA 101, 2012 E 8.3.5 Penetrations. govern the materia	the medical records, building ct system, and the air (in a separate area). The door had no fit a large hole in the door mately three inches in an interview with the building me of the observation, and he blace the missing doorknob as ding Spaces - Smoke Barrier all be constructed to a 1/2-houring per 8.5. Smoke barriers shall minate at an atrium wall. The not required in duct of ducted HVAC systems where all series installed for antical smoke control system. Note that is not met as evidenced addition. The provisions of 8.3.5 shall and methods of construction.	К3	On July 18, 2018 the Maintenance Supervisor replaced the white substance found in the smoke barrier wa with fire barrier sealant. On July 18, 2018 Maintenance Supervisor checked all the oth smoke barrier walls and no other wall was found to be noncompliant. Maintenance Supervisor will check all smoke barrier walls annually to make sure fire barrier walls are compliant. Any negative findings will be communicated to the Quality Assurance Committee for			
			review and further plan of action.			
	PROVIDER OR SUPPLIER BRA HEALTHCARE & SUMMARY STA (EACH DEFICIENCY REGULATORY OR L Continued From pa area which stores to supplies, the air duch handler/condenser The evaluator inspecair handler area via door handle and left measuring approxint diameter. The evaluator held supervisor at the tire stated he would rep soon as possible. Subdivision of Build CFR(s): NFPA 101 Subdivision of Build Construction 2012 EXISTING Smoke barriers shafter resistance ratin be permitted to term Smoke dampers ar penetrations in fully an approved sprink smoke compartment barrier. 19.3.7.3, 8.6.7.1(1) Describe any mech in REMARKS. This REQUIREMENT by: NFPA 101, 2012 E 8.3.5 Penetrations. govern the material used to protect through	STANDER CORRECTION DENOVIDER OR SUPPLIER BRA HEALTHCARE & WELLNESS CENTRE, LP SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) Continued From page 9 area which stores the medical records, building supplies, the air duct system, and the air handler/condenser (in a separate area). The evaluator inspected the area and entered the air handler area via a door. The door had no door handle and left a large hole in the door measuring approximately three inches in diameter. The evaluator held an interview with the building supervisor at the time of the observation, and he stated he would replace the missing doorknob as soon as possible. Subdivision of Building Spaces - Smoke Barrier CFR(s): NFPA 101 Subdivision of Building Spaces - Smoke Barrier Construction 2012 EXISTING Smoke barriers shall be constructed to a 1/2-hour fire resistance rating per 8.5. Smoke barriers shall be permitted to terminate at an atrium wall. Smoke dampers are not required in duct penetrations in fully ducted HVAC systems where an approved sprinkler system is installed for smoke compartments adjacent to the smoke barrier. 19.3.7.3, 8.6.7.1(1) Describe any mechanical smoke control system in REMARKS. This REQUIREMENT is not met as evidenced	PROVIDER OR SUPPLIER SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) Continued From page 9 area which stores the medical records, building supplies, the air duct system, and the air handler/condenser (in a separate area). The evaluator inspected the area and entered the air handler area via a door. The door handle and left a large hole in the door measuring approximately three inches in diameter. The evaluator held an interview with the building supervisor at the time of the observation, and he stated he would replace the missing doorknob as soon as possible. Subdivision of Building Spaces - Smoke Barrier CFR(s): NFPA 101 Subdivision of Building Spaces - Smoke Barrier Construction 2012 EXISTING Smoke barriers shall be constructed to a 1/2-hour fire resistance rating per 8.5. Smoke barriers shall be permitted to terminate at an atrium wall. Smoke dampers are not required in duct penetrations in fully ducted HVAC systems where an approved sprinkler system is installed for smoke compartments adjacent to the smoke barrier. 19.3.7.3, 8.6.7.1(1) Describe any mechanical smoke control system in REMARKS. This REQUIREMENT is not met as evidenced by: NFPA 101, 2012 Edition 8.3.5 Penetrations. The provisions of 8.3.5 shall govern the materials and methods of construction used to protect through-penetrations and	The evaluator held an interview with the building supervisor at the time of the observation adiameter. Subdivision of Building Spaces - Smoke Barrier CFR(s): NFPA 101 Subdivision of Building Spaces - Smoke Barrier Censtruction in REMARKS. Sound Spaces and space and and space at a trium wall. Sound in duct penetrations in fully ducted HVAC systems where an approved sprinkler system in REMARKS. NFPA 101, 2012 Edition 8.3.5 Penetrations. The provisions of 8.3.5 shall govern the materials and methods of construction used to protect through-penetrations and		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MUI A. BUILD		E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED		
		055760	B. WING			07/	13/2018
NAME OF I	PROVIDER OR SUPPLIER				TREET ADDRESS, CITY, STATE, ZIP CODE		
ALHAME	BRA HEALTHCARE &	WELLNESS CENTRE, LP			115 SOUTH GARFIELD		
				Α.	ALHAMBRA, CA 91801	·	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTIC (EACH CORRECTIVE ACTION SHOUL) CROSS-REFERENCED TO THE APPROF DEFICIENCY)) BE	(X5) COMPLETION DATE
K 372	Continued From pa	ge 10	K	372			
K 372	walls, and fire resis assemblies. The prapply to approved e of construction use through-penetrations in fire resistance-rated ho otherwise required 8.3.5.1* Firestop Sy Penetrations for capipes, tubes, combivents, wires, and si electrical, mechanic communications sy wall, floor, or floor/cas a fire barrier sha system or device. The firestop system accordance with ASM ethod for Fire Tes Stops, or ANSI/UL of Through-Penetra positive pressure dicolumn (2.5 N/m2) unexposed surface NFPA 101, 2012 Ec 8.3.5 Penetrations. govern the material used to protect thromembrane penetra walls, and fire resis	tance-rated horizontal ovisions of 8.3.5 shall not existing materials and methods of to protect existing is and existing membrane walls, fire barrier walls, or fire rizontal assemblies, unless by Chapters 11 through 43. In through expand through a see that pass through a see through a s	K	372			
	of construction use through-penetration penetrations in fire	existing materials and methods d to protect existing as and existing membrane walls, fire barrier walls, or fire					
	resistance-rated ho	rizontal assemblies, unless			1		:

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01			(X3) DATE SURVEY COMPLETED		
		055760	B. WING		_	07/13/2018	
	PROVIDER OR SUPPLIER BRA HEALTHCARE &	WELLNESS CENTRE, LP		STREET ADDRESS, CITY, S 415 SOUTH GARFIELD ALHAMBRA, CA 9180			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	X (EACH CORRECT CROSS-REFERENC	AN OF CORRECTION VE ACTION SHOULD ED TO THE APPROPORTICIENCY)	BE	(X5) COMPLETION DATE
K 372	otherwise required Based on observatifailed to maintain a least one-half hour through the smoke smoke barrier walls of the smoke compartments duri deficiency affected compartments. Findings: On July 12, 2018, transpection of the smoke compartments. Findings: The evaluator requirements the smoke compartments. The evaluator requirements the smoke compartments are the smoke compartments. The evaluator requirements the smoke compartments the smoke compartments are the smoke compartments. The evaluator requirements the smoke compartments the smoke compartments are the smoke of anyon over the smoke barrobserved that this value to check or inspect the condition and the infully intact at all time or penetrations into	by Chapters 11 through 43. ion and interview, the facility fire resistance rating of at by having penetrations barrier wall. Penetrations on a may compromise the integrity bartments, thereby, allowing sily between smoke ng a fire emergency. The two of three smoke the evaluator conducted an noke barrier wall located over tment doors near Room 14. ested a ladder to be set up mpartment double doors. The three electrical conduits oke barrier wall and white	K	372			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01			(X3) DATE SURVEY COMPLETED	
055760			B. WING		07	07/13/2018	
		WELLNESS CENTRE, LP		415	REET ADDRESS, CITY, STATE, ZIP CODE 5 SOUTH GARFIELD .HAMBRA, CA 91801		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROFICIENCY)	D BE	(X5) COMPLETION DATE
K 372 K 900 SS=D	authority having jurithealth Care Facilitic CFR(s): NFPA 101 Health Care Facilitic List in the REMARK requirements (excluthat are not address but are deficient. The applicable Health Costandard citation, so CMS-2567. This REQUIREMENT of Spaces About Access and working maintained about a permit ready and so of such equipment. (A) Working Space equipment operating to ground and likely adjustment, servicing energized shall continued to the less than the continue	isdiction at all times. es Code - Other es Code - Other (S section any NFPA 99 uding Chapter 7, 8, 12, and 13) sed by the provided K-Tags, his information, along with the care Facilities Code or NFPA hould be included on Form NT is not met as evidenced ition nal, or Less out Electrical Equipment. g space shall be provided and ill electrical equipment to afe operation and maintenance . Working space for ng at 600 volts, nominal, or less of to require examination, ng, or maintenance while nply with the dimensions of), and (A)(3) or as required or	KS	İ	On July 11, 2018 the Maintenance Supervisor removed the 16 intravenous immediately. On July 11, 2018 Maintenance Supervisor did a walk through of entire facility and found no other electrical panels were affected by deficient practice. On July 12, 2018 Administrator in-serviced maintenance department to keep all electrical panels free of any medical equipment. In case of an emergency immediate access to the electrical panels ir required at all times.		8/17/18

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		ONSTRUCTION	(X3) DATE SURVEY COMPLETED	
0:		055760	B. WING			07	/13/2018
NAME OF PROVIDER OR SUPPLIER ALHAMBRA HEALTHCARE & WELLNESS CENTRE, LP			STREET ADDRESS, CITY, STATE, ZIP CODE 415 SOUTH GARFIELD ALHAMBRA, CA 91801				
(X4) ID PREFIX TAG	(EACH DEFICIENCY MUST BE PRECEDED BY FULL			(PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	(X5) COMPLETION DATE	
K 900	failed to ensure the basement main elected medical equipment affected the basement findings: On July 11, 2018, at conducted an inspective evaluator observable.	Working Spaces, Ground tance Condition 2 914 mm (3 ft) 914 mm (3 ft) on and interview, the facility area directly adjacent to the ctrical panel was free of storage at all times. This	K 9	00	During daily morning rounds Maintenance Supervisor will make sure all electrical panels are free from any equipment. Any noncompliance will be corrected immediately. Any negative findings will be reported monthly to the Quali Assurance Committee for review and further plan of action.		
	supervisor and he s remove the poles as In case of an emerg the electrical panels Electrical Systems - CFR(s): NFPA 101	an interview with the building tated he would have the staff is soon as possible. ency, immediate access to are required at all times. Essential Electric Syste	K 91	16			
				1			

NAME OF PROVIDER OR SUPPLIER ALHAMBRA HEALTHCARE & WELLNESS CENTRE, LP (A) D (SAND) (EACH DEFICIENCE PROVIDER OR SUPPLIER ALTHOUSES ALTHOUSES ALTHOUSES ALTHOUSES (EACH DEFICIENCY MUST BE PRECEDED BY PULL REGULATORY OR LSC IDENTIFYING INFORMATION) K 918 (Continued From page 14 Aremote annunciator that is storage battery powered is provided to operate outside of the generating room in a location readily observed by operating system (e.g., building information system) is not to be substituted for the alarm annunciator. 6.4.1.1.17. 6.4.1.1.17. 6.1 (NFPA 99) This REQUIREMENT is not met as evidenced by: N FPA 99, 2012 Edition, 6.4.1.1.17 Alarm Annunciator. A remote annunciator that is storage battery powered shall be provided to operate outside of the generating room in a location readily observed by operating personnel at regular work station (see 700.12 of NFPA 70, National Electrical Code). The annunciator shall indicate the following: (a) When the battery charge is malfunctioning (2) Individual visual signals shall indicate the following: (a) When the battery charger is malfunctioning (2) Individual visual signals plus a common audible signal to warm of an engine-generator alarm conditions shall indicate the following: (a) Low fuel when the main fuel storage tank contains less than a 4-hour operating supply			(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	' ') MULTIPLE CONSTRUCTION BUILDING 01			(X3) DATE SURVEY COMPLETED	
ALHAMBRA HEALTHCARE & WELLNESS CENTRE, LP X3 D			055760	B. WING			07/	13/2018	
ALHAMBRA HEALTHCARE & WELLNESS CENTRE, LP (X4) ID SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) K 916 Continued From page 14 A remote annunciator that is storage battery powered is provided to operate outside of the generating prom in a location readily observed by operating personnel. The annunciator is hard-wired to indicate alarm conditions of the emergency power source. A centralized computer system (e.g., building information system) is not to be substituted for the alarm annunciator. 6.4.1.1.17, 6.4.1.1.17, 6.1.1.17 (NFPA 99) This REQUIREMENT is not met as evidenced by: NFFA 99, 2012 Edition, 6.4.1.1.17 (A 1.1.17 Airm Annunciator. A remote annunciator that is storage battery powered shall be provided to operate outside of the generating personnel at a regular work station (see 700.12 of NFPA 70, National Electrical Code). The annunciator shall be hard-wired to indicate alarm conditions of the emergency or auxiliary power source as follows: (1) Individual visual signals shall indicate the following: (2) Individual visual signals blus a common audible signal to warn of an engine-generator alarm condition shall indicate the following: (a) Low lubricating oil pressure (b) Low water temperature (below that required in 6.4.1.1.11) (c) Excessive water temperature (d) Low fuel when the main fuel storage tank	NAME OF PROVIDER OR SUPPLIER				8	STREET ADDRESS, CITY, STATE, ZIP CODE			
CX4-10 SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG PREFIX TAG PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG PREFIX TAG PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE COMMETION) DEFICIENCY) K 916 Continued From page 14 A remote annunciator that is storage battery powered is provided to operate outside of the generating proom in a location readily observed by operating personnel. The annunciator is hard-wired to indicate alarm conditions of the emergency power source. A centralized computer system (e.g., building information system) is not to be substituted for the alarm annunciator. 6.4.1.1.17, 6.4.1.1.17. S (NFPA 99) This REQUIREMENT is not met as evidenced by: NFPA 99, 2012 Edition, 6.4.1.1.17 Alarm Annunciator. A remote annunciator that is storage battery powered shall be provided to operate outside of the generating personnel at a regular work station (see 700.12 of NFPA 70, National Electrical Code). The annunciator shall be hard-wired to indicate alarm conditions of the emergency or auxiliary power source as follows: (1) Individual visual signals shall indicate the following: (a) When the emergency or auxiliary power source is operating to supply power to load (b) When the battery charger is malfunctioning (2) Individual visual signals plus a common audible signal to warn of an engine-generator alarm condition shall indicate the following: (a) Low hubricating oil pressure (b) Low water temperature (d) Low weter temperature (d) Low weter temperature (d) Low full when the main fuel storage tank	ALLIAME	DA HEALTHCADE S	WELLNESS CENTRE LD		4	115 SOUTH GARFIELD			
REGULATORY OR LSC IDENTIFYING INFORMATION) K 916 Continued From page 14 A remote annunciator that is storage battery powered is provided to operate outside of the generating room in a location readily observed by operating personnel. The annunciator is hard-wired to indicate alarm conditions of the emergency power source. A centralized computer system (e.g., building information system) is not to be substituted for the alarm annunciator. 6.4.1.1.17, 6.4.1.1.17.5 (NFPA 99) This REQUIREMENT is not met as evidenced by: NFPA 99, 2012 Edition, 6.4.1.1.17 Alarm Annunciator. A remote annunciator that is storage battery powered shall be provided to operate outside of the generating room in a location readily observed by operating personnel at a regular work station (see 700.12 of NFPA 70, National Electrical Code). The annunciator shall be hard-wired to indicate alarm conditions of the emergency or auxiliary power source as follows: (1) Individual visual signals shall indicate the following: (a) When the emergency or auxiliary power source is operating to supply power to load (b) When the battery charger is malfunctioning (2) Individual visual signals plus a common audible signal to warm of an engine-generator alarm condition shall indicate the following: (a) Low lubricating oil pressure (b) Low water temperature (c) Low with the memergency or auxiliary power source is operating to supply power to load (b) When the battery charger is malfunctioning (2) Individual visual signals plus a common audible signal to warm of an engine-generator alarm condition shall indicate the following: (a) Low lubricating oil pressure (b) Low water temperature (c) Low weter temperature (c) Low weter temperature (d) Low full when the main fuel storage tank	ALHAME	OKA NEALI NCAKE &	WELLINESS CENTRE, EF		1	ALHAMBRA, CA 91801			
A remote annunciator that is storage battery powered is provided to operate outside of the generating room in a location readily observed by operating personnel. The annunciator is hard-wired to indicate alarm conditions of the emergency power source. A centralized computer system (e.g., building information system) is not to be substituted for the alarm annunciator. 6, 4, 1.1.17, 6, 1/1.17, 6, 1/1.117, 6, 1/1.	PRÉFIX	(EACH DEFICIENCY MUST BE PRECEDED BY FULL			PREFIX (EACH CORRECTIVE ACTION SHOUL TAG CROSS-REFERENCED TO THE APPRO			COMPLETION	
(e) Overcrank (failed to start) (f) Overspeed Based on observation and interview, the facility	K 916	A remote annuncial powered is provided generating room in operating personne hard-wired to indical emergency powers system (e.g., building to be substituted for 6.4.1.1.17, 6.4.1.1. This REQUIREMED by: NFPA 99, 2012 Ec. 6.4.1.1.17 Alarm Arannunciator that is be provided to oper room in a location represonnel at a regular NFPA 70, National annunciator shall be conditions of the ersource as follows: (1) Individual visual following: (a) When the emergource is operating (b) When the batter (2) Individual visual audible signal to war alarm condition shall (a) Low lubricating (b) Low water temposition of the error condition shall (a) Low lubricating (b) Low water temposition shall (b) Low fuel when the contains less than all (c) Overspeed	tor that is storage battery d to operate outside of the a location readily observed by al. The annunciator is ate alarm conditions of the source. A centralized computering information system) is not in the alarm annunciator. 17.5 (NFPA 99) NT is not met as evidenced dition, innunciator. A remote storage battery powered shall rate outside of the generating lear work station (see 700.12 of Electrical Code). The enhard-wired to indicate alarm mergency or auxiliary power asignals shall indicate the gency or auxiliary power to supply power to load by charger is malfunctioning a signals plus a common arm of an engine-generator all indicate the following: oil pressure perature (below that required in the remperature the main fuel storage tank a 4-hour operating supply ed to start)	KS	916	Supervisor contacted James Gollner Services, Inc to install annunicator for the generator at the nursing station. A contract was provided on 8/16/18. Installation will be done within 30 days. On Aug 16, James Gollner Services, Inc checked other components of alarm system and found no other areas to be noncompliant. During the monthly load test Maintenance Supervisor will check that remote annunciato is functioning correctly. Any negative findings will be communicated to the Quality Assurance Committee for review and further plan of	e	8/17/14	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:					(X3) DATE SURVEY COMPLETED		
	055760 B. WING					07	07/13/2018		
NAME OF PROVIDER OR SUPPLIER ALHAMBRA HEALTHCARE & WELLNESS CENTRE, LP				STREET ADDRESS, CITY, STATE, ZIP CODE 415 SOUTH GARFIELD ALHAMBRA, CA 91801					
(X4) ID PREFIX TAG				(EA	PROVIDER'S PLAN OF CORRECTIVE ACTION SHO SS-REFERENCED TO THE APPI DEFICIENCY)	OULD BE	(X5) COMPLETION DATE		
K 916	equipped with an a deficient practice he not to be aware of emergency power potentially dangerd could affect the entermination. The every generator of the entermination of the entermination of the every generator of the every gen	e emergency generator was larm annunciator. The ad the potential for the staff the alarm condition of the generator, allowing a sus situation to happen that tire facility. at 9:15 a.m., the evaluator ection of the facility and its aluator asked to see the annunciator. The evaluator with the building staff and he or generator remote ole at the time of the survey.	К9	16					

California Department of Public Health (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY STATEMENT OF DEFICIENCIES COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING: 01 B. WING CA950000101 07/13/2018 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **415 SOUTH GARFIELD** ALHAMBRA HEALTHCARE & WELLNESS CEN ALHAMBRA, CA 91801 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X5) COMPLETE (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX **PRÉFIX** CROSS-REFERENCED TO THE APPROPRIATE DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG **DEFICIENCY**) B5680 B5680 T22 DIV5 CH3 ART6-72601(a) Alterations to During weekly testing on June Existing Buildings or New Cons 22, 2018 facility generator did not turn on. Maintenance (a) Alterations to existing buildings licensed as skilled nursing facilities or new construction shall Supervisor contacted vendor be in conformance with Chapter 1, Division 17, Sweinhart Electric Company. Part 6, Title 24, California Administrative Code Within 2 hours vendor had and requirements of the State Fire Marshal. back-up generator on site. Back up generator tested This Statute is not met as evidenced by: weekly and monthly per NFC Based on observation, interview, and document review, the facility failed to contact the Office of Code. Documentation available Statewide Health Planning and Development onsite. (OSHPD), the authority having jurisdiction (AHJ) for alteration and construction work in healthcare Maintenance Supervisor will facilities regarding a replacement of back up source of power, the generator. The deficient continue to perform weekly practice placed the residents at risk to their health testing and monthly load test of and safety if the unauthorized alterations were faulty. the generator. Findings: Any negative findings will be communicated to the Quality On July 12, 2018, at 11:30 a.m., the evaluator **Assurance Committee monthly** conducted an inspection of the Life Safety Code system. The evaluator was going over the for review and further plan of emergency back-up generator monthly test action. documentation and noted that on June 22, 2018, the generator hour meter reading was .8 hours. However, the generator hour meter reading was 292.7 hours on May 31, 2018. The building supervisor was interviewed on the discrepancy of the reading and he stated that the generator overheated and did not start on June 22, 2018. The building supervisor contacted the generator service company who removed the existing generator and installed a temporary generator.

Licensing and Certification Division

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

California Department of Public Health

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPL A. BUILDING:	E CONSTRUCTION 01		(X3) DATE SURVEY COMPLETED			
CA950000101			B. WING		07/1	07/13/2018			
	NAME OF PROVIDER OR SUPPLIER ALHAMBRA HEALTHCARE & WELLNESS CEN ALHAMBRA, CA 91801								
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORREC (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPR DEFICIENCY)	ULD BE	(X5) COMPLETE DATE			
B5680	At the time of the exp.m., the evaluator contacted the AHJ failure and the instagenerator. The admecessary because removed and the rereplaced in no more	xit, on July 12, 2018, at 3:00 asked the administrator if she regarding the generator's allation of a temporary ministrator stated it was not a the old generator was eplacement generator was	-B5680						

Licensing and Certification Division

Q6W721