DEPARTMENT OF HEALTH AND HUMAN SERVICES PRINTED: 05/26/2015 CENTERS FOR MEDICARE & MEDICAID SERVICES FORM APPROVED OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION DENTIFICATION NUMBER (X3) DATE SURVEY A. BUILDING 01 COMPLETED 056110 B. WING NAME OF PROVIDER OR SUPPLIER 05/20/2015 STREET ADDRESS, CITY, STATE, ZIP CODE LAGUNA HILLS HEALTH AND REHABILITATION CENTER 24452 HEALTH CENTER DRIVE LAGUNA HILLS, CA 92653 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX COMPLETION DATE PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY K 000 INITIAL COMMENTS K 000 K3 BUILDING: 01 K6 PLAN APPROVAL: 1971 K7 SURVEY UNDER: 2000 EXISTING STRUCTURE TYPE: ONE STORY, CONSTRUCTION TYPE (V) (111), FULLY SPRINKLERED. The following reflects the findings of the California Department of Public Health, during an annual Life Safety Code recertification survey. The findings are in accordance with 42 CFR (Code of Federal Regulations) 483.70 (a) and NFPA (National Fire Protection Association) 101, Life Safety Code 2000 edition, Existing codes. Representing the California Department of Public Health: 26387 The facility is not in substantial compliance with 42 CFR 483.70 (a) for Long Term Care Facilities. Census = 140 K 012 NFPA 101 LIFE SAFETY CODE STANDARD K 012 SS=D Building construction type and height meets one of the following. 19.1.6.2, 19.1.6.3, 19.1.6.4, 19.3.5.1 This STANDARD is not met as evidenced by: Based on observation, the facility failed to maintain the integrity of their building construction. This was evidenced by an unsealed LABORATORY DIRECTOR'S O

Any deficiency statement en ncy which the institut other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

S SIGNATURE

PRINTED: 05/26/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

NAME OF PROVIDER OR SUPPLIER

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION A. BUILDING 01

(X3) DATE SURVEY COMPLETED

056110

B. WING

05/20/2015

LAGUNA HILLS HEALTH AND REHABILITATION CENTER

STREET ADDRESS, CITY, STATE, ZIP GODE 24452 HEALTH CENTER DRIVE

LAGUNA HILLS, CA 92653

(X4) ID PREFIX TAG

SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)

PREFIX TAG PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)

(X5) COMPLETION DATE

6/11/15

K 012 Continued From page 1

penetration in the facility wall. This could result in the spread of smoke or fire to other locations in the facility. This affected 1 of 6 smoke compartments.

NFPA 101, Life Safety Code, 2000 Edition 19.1.6.4 Each exterior wall of frame construction and all interior stud partitions shall be firestopped to cut off all concealed draft openings, both horizontal and vertical, between any cellar or basement and the first floor. Such firestopping shall consist of wood not less than 2 in. (5 cm) (nominal) thick or shall be of noncombustible material:

8.3.1* General. Where required by Chapters 12 through 42, smoke barriers shall be provided to subdivide building spaces for the purpose of restricting the movement of smoke.

B.3.2*Continuity: Smoke barriers required by this Code shall be continuous from an outside wall to an outside wall, from a floor to a floor, or from a smoke barrier to a smoke barrier or a combination thereof. Such barriers shall be continuous through all concealed spaces, such as those found above a ceiling, including interstitial spaces.

Exception: A smoke barrier required for an occupied space below an interstitial space shall not be required to extend through the interstitial space, provided that the construction assembly forming the bottom of the interstitial space provides resistance to the passage of smoke equal to that provided by the smoke barrier.

Findings:

During a tour of the facility with the Director of Environmental Services on 5/20/15, the building construction was observed.

K 012 NFPA 101 Life Safety Code Standard

It is the policy of the facility to maintain the integrity of our building, to prevent the spread of smoke or fire to other locations in the facility.

Corrective action for Residents found to have been affected by this deficiency:

It was found that one room had been affected by this deficiency.

On 5/20/15, the Director of Environmental -Services sealed the penetration in the wall behind the door in room 314.

Identification of other Residents having the potential to be affected by the same deficient practice and corrective action that will be taken:

All Resident rooms have the potential to be affected by this deficiency.

On 5/29/15, the Director of Environmental Services completed a sweep of all 107 facility rooms and found no other rooms with same deficiency.

(X2) MULTIPLE CONSTRUCTION

FORM APPROVED OMB NO. 0938-0391 (X3) DATE SURVEY

PRINTED: 05/26/2015

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER

056110

A. BUILDING 01

COMPLETED

NAME OF PROVIDER OR SUPPLIER

B. WING

05/20/2015

-	A HILLS HEALTH AND REHABILITATION CENTER	AGUNA HILLS, CA 92653 BY STATEMENT OF DEFICIENCIES FINANCY MUST BE PRECEDED BY FULL FOR LSC IDENTIFYING INFORMATION) TAG PREFIX TAG PREFIX TAG PREFIX TAG PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) TO PREFIX TAG Measures/Corrective action that will be put into place to ensure that this same deficiency does not recur: On 6/11/15 the Administrator in-serviced The		
(X4) IO PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE	(X5) COMPLETION DATE
	At 9:02 a.m. there was an approximately 5 inch by 1/4 inch unsealed penetration in the wall behind the door of Room 314. NFPA 101 LIFE SAFETY CODE STANDARD Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as those constructed of 1½ inch solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors in sprinklered buildings are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Doors are provided with a means suitable for keeping the door closed. Dutch doors meeting 19.3,6,3,6 are permitted. 19.3,6,3.3 Roller latches are prohibited by CMS regulations in all health care facilities.		into place to ensure that this same deficiency does not recur: On 6/11/15 the Administrator in-serviced The	

This STANDARD is not met as evidenced by: Based on observation, the facility falled to maintain corridor their doors. This was evidenced by corridor doors that failed to latch, and by corridor doors that were impeded from closing. This could result in a delay to contain smoke or fire to a room. This affected 3 of 6 smoke compartments.

On 6/11/15 the Director of Environmental Services in-serviced facility Environmental Service staff on maintaining the facility building integrity, including; all interior stud partitions shall be fire stopped to cut off all concealed draft openings, both horizontal and vertical, between any cellar or basement on the first floor. Such fire stopping shall

consist of wood not less than 2". (5cm) thick

combination thereof. Such barriers shall be continuous through all concealed spaces, such as those found above a celling, including

FORM CMS-2567(02-99) Previous Versions Obsolete

Event ID: SGJ621

Facility ID; CA060000042

interstitial spaces.

If continuation sheet Page 3 of 13

NAME OF PROVIDER OR SUPPLIER

DEPARTMENT OF HEALTH AND HUMAN	SERVICES
ACTION OF THE PARTY OF THE PART	ALLIAIOLA
CENTERS FOR MEDICARE & MEDICAID :	SERVICES

PRINTED: 05/26/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION A. BUILDING 01

(X3) DATE SURVEY COMPLETED

056110

B. WING

05/20/2015

LAGUNA HILLS HEALTH AND REHABILITATION CENTER

STREET ADDRESS, CITY, STATE, ZIP CODE

24452 HEALTH CENTER DRIVE LAGUNA HILLS, CA 92653

(X4) ID	SUMMARY STATEMENT OF DE
PREFIX	(EACH DEFICIENCY MUST BE PREC
TAG	REGULATORY OR LSC IDENTIFYING

FICIENCIES CEDED BY FULL G INFORMATION)

PREFIX TAG

PROVIDER'S PLAN OF CORRECTION TEACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)

(XS) COMPLETION DATE

K 018 | Continued From page 3

NFPA 101, Life Safety Code, 2000 Edition 19.3.6.3.1* Doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas shall be substantial doors, such as those constructed of 13/4-in. (4.4-cm) thick, solid-bonded core wood or of construction that resists fire for not less than 20 minutes and shall be constructed to resist the passage of smoke. Compliance with NFPA 80, Standard for Fire Doors and Fire Windows, shall not be required. Clearance between the bottom of the door and the floor covering not exceeding 1 in. (2.5 cm) shall be permitted for corridor doors. Exception No. 1: Doors to tollet rooms, bathrooms, shower rooms, sink closets, and similar auxiliary spaces that do not contain flammable or combustible materials. Exception No. 2: In smoke compartments protected throughout by an approved, supervised automatic sprinkler system in accordance with 19.3.5.2, the door construction requirements of 19.3.6.3.1 shall not be mandatory, but the doors shall be constructed to resist the passage of smoke.

19.3.6.3.3* Hold-open devices that release when the door is pushed or pulled shall be permitted.

A.19.3.6.3.3 Doors should not be blocked open by furniture, door stops, chocks, tie backs, drop down or plunger type devices, or other devices that necessitate manual unlatching or releasing action to close. Examples of hold-open devices that release when the door is pushed or pulled are friction catches or magnetic catches.

NFPA 80, Standard for Fire Doors and Fire Windows, 1999 Edition 2-4.1.4. All closing mechanisms shall be adjusted K 018

or shall be noncombustible. Smoke barriers shall be provided to subdivide building spaces for the purpose of restricting the movement of smoke. Smoke barriers are required shall be continuous from an outside wall to an outside wall, from the floor to a floor, or from a smoke barrier to a smoke barrier, or a combination thereof. Such barriers shall be continuous through all concealed spaces, such as those found above a ceiling, including interstitial spaces.

Measures that will be implemented to ensure that solutions are sustained;

The Environmental Services Director and/or his/her designee will perform visual Inspections of all 107 facility rooms weekly X 12 weeks to ensure compliance of building integrity, and document results of the weekly inspections on the Continuous Quality Improvement audit tool. Results of the documented visual inspections will be forwarded to the QA+A Committee monthly X 3 months for further monitoring and action planning as indicated or until the QA+A Committee determines compliance.

K 018 NFPA 101 Life Safety Code Standard

It is the policy of the facility that doors

6/11/15

PRINTED: 05/26/2015 FORM APPROVED

OMB NO 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION (X3) DATE SURVEY IDENTIFICATION NUMBER A BUILDING 01 COMPLETED 056110 B. WING NAME OF PROVIDER OR SUPPLIER 05/20/2015 STREET ADDRESS, CITY, STATE, ZIP CODE LAGUNA HILLS HEALTH AND REHABILITATION CENTER 24452 HEALTH CENTER DRIVE LAGUNA HILLS, CA 92653 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL COMPLETION DATE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) (EACH CORRECTIVE ACTION SHOULD BE TAG CHOSS-REFERENCED TO THE APPROPRIATE TAG DEFICIENCY) K 018 Continued From page 4 required enclosures of vertical openings, K 018 to overcome the resistance of the latch exits, or hazardous areas are substantial mechanism so that positive latching is achieved doors, such as those constructed of 13/4" on each door operation. solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors Findings: and sprinklers buildings are only required to During a tour of the facility with the Director of resist the passage of smoke. There is no Environmental Services on 5/20/15, the doors in Impediment to the closing of the doors. the facility were observed. Doors are provided with a means suitable for 1. At 8:37 a.m., the Director of Staff keeping the door closed. Development Office door, was impeded from closing with a rubber wedge under the door. Corrective action for Residents found to have been affected by this deficiency: 2. At 8:44 a.m., the Director of Staff Development Office door latching mechanism, It was found that 5 doors were affected by was not latching when tested. The latch was this deficiency. stuck inward. On 5/20/15 the Environmental Services 3. At 8:52 a.m., the self-closing Physical Therapy corridor door near Room 301, was not latching Director removed the rubber wedge from when tested underneath the DSD office door. 4. At 10:07 a.m., the self-closing corridor door to On 5/20/15 the Environmental Services the Feeding Supply Room, was not latching when Director replaced the latching mechanism for tested. The room was near Room 335. the DSD office door. 5. At 10:14 a.m., the self-closing corridor door to Nursing Station 2 Office, was impeded from On 5/20/15 the Environmental Services closing with a rubber wedge under the door. Director repaired the Physical Therapy NFPA 101 LIFE SAFETY CODE STANDARD K 046 corridor door near room 301 latching K 046 SS=D mechanism. Emergency lighting of at least 11/2 hour duration is provided in accordance with 7.9. 19.2.9.1. On 5/20/15 the Environmental Services Director repaired the latching mechanism for the Feeding Supply Room near 335. This STANDARD is not met as evidenced by:

DEPARTMENT OF HEALTH AND HUMAN SERVICES PRINTED: 05/26/2015 CENTERS FOR MEDICARE & MEDICAID SERVICES FORM APPROVED OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION (X3) DATE SURVEY IDENTIFICATION NUMBER: A. BUILDING 01 COMPLETED 056110 B. WING NAME OF PROVIDER OF SUPPLIER 05/20/2015 STREET ADDRESS, CITY, STATE, ZIP CODE LAGUNA HILLS HEALTH AND REHABILITATION CENTER 24452 HEALTH CENTER DRIVE LAGUNA HILLS, CA 92653 (X4) ID SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (X5) COMPLETION PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG CROSS-REFERENCED TO THE APPROPRIATE TAG DATE DEFICIENCY K 046 Continued From page 5 On 5/20/15 the Environmental Services K 046 Based on observation, document review, and Director removed the rubber wedge from interview, the facility failed to maintain their underneath the Nursing Station 2 Office. emergency lighting units. This was evidenced by 3 of 3 emergency lights that failed to illuminate Identification of other Residents having the when tested and by the facility failure to perform potential to be affected by the same monthly and annual testing on the emergency lighting units. This could result in a delay in deficient practice and corrective action that accessing items in the kitchen during a power will be taken: failure. This affected 1 of 6 smoke compartments. All Resident rooms have the potential to be NFPA 101, Life Safety Code, 2000 Edition affected by this deficiency. 7.9.3 Periodic Testing of Emergency Lighting Equipment. On 5/22/15, the Director of Environmental A Functional test shall be conducted on every Services completed a sweep of all facility required emergency lighting system at 30-day intervals for not less than 30 seconds. An annual doors and found 2 rooms with the same test-shall be conducted on every required deficiency; a rubber wedge was impeding the battery-powered emergency lighting system for door to the dining room near Activities Office; not less than 1.5 hours. Equipment shall be fully a rubber wedge was impeding the door to the operational for the duration of the test. Written records of visual inspections and tests shall be living room entrance. kept by the owner for inspection by the authority having jurisdiction. On 5/22/15 the Environmental Services Director removed the rubber wedge from Findings: underneath the door to the dining room (near Activities Office) allowing the door to During a tour of the facility with the Director of Environmental Services (DOES) on 5/20/15, the close freely. facility emergency lighting units in the kitchen were tested, testing documents were reviewed, On 5/22/15 the Environmental Services and a staff person was interviewed. Director removed the rubber wedge from underneath the door to the living room 1. At 9:38 a.m., the emergency light near the entrance, allowing the door to close freely. Emergency Food in the kitchen, was not

illuminating when tested.

2. At 9:41 a.m., the emergency light near the sink

in the kitchen, was not illuminating when tested.

Measures/Corrective action that will be put

into place to ensure that this same

deficiency does not recur:

PRINTED: 05/26/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF GORRECTION

(X4) ID

PREFIX

K 047

SS=C

NAME OF PROVIDER OR SUPPLIER

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION A. BUILDING 01

(X3) DATE SURVEY COMPLETED

056110

B. WING

PREFIX

TAG

K 047

05/20/2015

COMPLETION DATE

LAGUNA HILLS HEALTH AND REHABILITATION CENTER

STREET ADDRESS, CITY, STATE, ZIP CODE 24452 HEALTH CENTER DRIVE

LAGUNA HILLS, CA 92653

(EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) TAG K 046 | Continued From page 6 3. At 9:44 a.m., the emergency light near the dish machine in the kitchen, was not illuminating when tested. 4. At 11:04 a.m., the facility provided a testing

SUMMARY STATEMENT OF DEFICIENCIES

document for the emergency that indicated that the lights were tested every three months and there was no documented evidence of an annual

At 11:06 a.m., the DOES said during an interview, that he tested the emergency lights every three months and did not test them annually. NFPA 101 LIFE SAFETY CODE STANDARD

Exit and directional signs are displayed in accordance with section 7.10 with continuous illumination also served by the emergency lighting system. 19.2.10.1

This STANDARD is not met as evidenced by: Based on document review, and interview, the facility failed to maintain their exit signs. This was evidenced by the failure to perform monthly and an annual tests on the 32 exit signs with a battery back-up. This could result in a delay in evacuation if the exit signs failed to illuminate during a power failure. This affected 6 of 6 smoke compartments.

NFPA 101, Life Safety Code, 2000 Edition 7.10.9.2 Exit signs connected to or provided with a battery-operated emergency illumination source, where required in 7.10.4, shall be tested and maintained in accordance with 7.9.3.

On 6/8/15 the Administrator in-serviced the K 046 Director of Environmental Services on the

facility's policy and procedure regarding doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as those constructed of 13/4" solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors and sprinklers buildings are only required to resist the passage of smoke. There is no impediment to the closing of the doors.

Doors are provided with a means suitable for

keeping the door closed.

PROVIDER'S PLAN OF CORRECTION

(EACH CORRECTIVE ACTION SHOULD BE

CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)

On 6/8/15, 6/9/15, 6/10/15, 6/11/15 the DSD in-serviced all facility staff on the facility's policy and procedure regarding doors protecting corridor openings in other than required enclosures of vertical openings, exits, or hazardous areas are substantial doors, such as those constructed of 13/4" solid-bonded core wood, or capable of resisting fire for at least 20 minutes. Doors and sprinklers buildings are only required to resist the passage of smoke. There is no impediment to the closing of the doors. Doors are provided with a means suitable for

Measures that will be implemented to ensure that solutions are sustained:

keeping the door closed.

TATEMEN	NT OF DEFICIENCIES I OF CORRECTION	E & MEDICAID SERVICES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIF	LE CONSTRUCTION (X3)	NO. 0938-039 DATE SURVEY
		056110		3.01	COMPLETED
NAME OF	PROVIDER OR SUPPLIER		B. WING	STREET ADDRESS, CITY, STATE, ZIP CODE	05/20/2015
		REHABILITATION CENTER	1 3	24452 HEALTH CENTER DRIVE LAGUNA HILLS, CA 92653	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSG IDENTIFYING INFORMATION)	PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	GOMPLETIO DATE
K 064 SS=D	7.9.3 Periodic Test Equipment. A Functional test strequired emergence intervals for not less test shall be conducted battery-powered emot less than 1.5 he operational for the records of visual inskept by the owner for having jurisdiction. Findings: During a tour of the Environmental Servitesting documentation person was intervied. 1. At 11:02 a.m., the document for the exigns were tested even as no documented. 2. At 11:06 a.m., the interview, that he test months and did not NFPA 101 LIFE SAF	ting of Emergency Lighting hall be conducted on every by lighting system at 30-day s than 30 seconds. An annual cted on every required mergency lighting system for ours. Equipment shall be fully duration of the test. Written spections and tests shall be or Inspection by the authority facility with the Director of fices on 5/20/15, the exit sign on was reviewed, and a staff wed. e facility provided a testing dit signs that indicated that the every three months and there if evidence of an annual test. E DOES said during an sted the exit signs every three test them annually. ETY CODE STANDARD lishers are provided in all cies in accordance with	K 047	The Environmental Services Director and/ohis/her designee will perform visual inspections of all facility rooms/doors week X 12 weeks to ensure compliance of proper door hold open devices, and document the results of the weekly inspections on the Continuous Quality Improvement audit too Results of the documented visual inspection will be forwarded to the QA+A Committee monthly X 3 months for further monitoring and action planning as indicated or until the QA+A Committee determines compliance. K 046 NFPA 101 Life Safety Code Standard It is the policy of the facility that emergency lighting of at least 1 ½ hour duration is provided. Corrective action for Residents found to have been affected by this deficiency: It was found that 3 emergency lights were affected by this deficiency. On 5/29/15 the DOES replaced the emergency light near the emergency food in the kitchen.	6)9(15
				On 5/29/15 the DOES replaced the emergency light near the sink in the kitchen.	

DEPARTMENT OF HEALTH AND HUMAN	SERVICES
CENTEDO FOO MEDIOLDES	CELLINOLO
CENTERS FOR MEDICARE & MEDICAID	SERVICES

PRINTED: 05/26/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

NAME OF PROVIDER OR SUPPLIER

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION A. BUILDING 01

(X3) DATE SURVEY COMPLETED

056110

B. WING

05/20/2015

STREET ADDRESS, CITY, STATE, ZIP CODE

LAGUNA HILLS HEALTH AND REHABILITATION CENTER

24452 HEALTH CENTER DRIVE

Beilin	auditions		LAGUNA HILLS, CA 92653	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE
	Continued From page 8 This STANDARD is not met as evidenced by:	K 064	On 5/29/15 the DOES replaced the	

Based on observation and interview, the facility failed to maintain its portable fire extinguishers. This was evidenced by a portable fire extinguisher that was obstructed from access. This could delay extinguishing a fire in the event of a fire. This affected 1 of 6 smoke compartments.

NFPA 101, Life Safety Code, 2000 Edition 9.7.4.1* Where required by the provisions of another section of this Code, portable fire extinguishers shall be installed, inspected, and maintained in accordance with NFPA 10, Standard for Portable Fire Extinguishers.

NFPA 10, Standard for Portable Fire Extinguishers, 1998 Edition 1-6.3 Fire extinguishers shall be conspicuously located where they will be readily accessible and immediately available in the event of fire. Preferably they shall be located along normal paths of travel, including exits from areas.

Findings:

During a tour of the facility with the Director of Environmental Services (DOES)on 5/20/15, the portable fire extinguishers were observed, and staff was interviewed.

- 1. At 9:14 a.m. the Kitchen K-class portable fire extinguisher was impeded from access with a metal cart in front of the device.
- 2. At 9:15 a.m., the DOES said during an interview that nothing should be in front of the fire extinguishers.

rgency light near the dish machine in the kitchen.

On 5/29/15 the DOES updated the testing log for emergency lights to be carried out monthly, not quarterly starting 6/15/15.

Identification of other Residents having the potential to be affected by the same deficient practice and corrective action that will be taken:

All Resident rooms have the potential to be affected by this deficiency.

On 5/29/15 the DOES completed a sweep of all facility emergency lights and found that no other emergency lights have been found to be affected by the same deficiency.

Measures/Corrective action that will be put into place to ensure that this same deficiency does not recur:

On 6/8/18 the Administrator in-serviced the DOES on the facility's policy and procedures regarding emergency lighting of at least 1 % hour duration is provided.

On 6/8/15 the Administrator in-serviced the DOES on functional emergency lighting. testing; a functional test shall be conducted on every required emergency lighting system at 30-day intervals for not less than 30

PRINTED: 05/26/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION

(X4) ID

PREFIX

TAG

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:

(X2) MULTIPLE CONSTRUCTION A. BUILDING 01

(X3) DATE SURVEY COMPLETED

056110

B. WING

PREFIX

TAG

K 147

K 147

05/20/2015

COMPLETION

DATE

NAME OF PROVIDER OR SUPPLIER

LAGUNA HILLS HEALTH AND REHABILITATION CENTER

STREET ADDRESS, CITY, STATE, ZIP CODE 24452 HEALTH CENTER DRIVE

LAGUNA HILLS, CA 92653

REGULATORY OR LSC IDENTIFYING INFORMATION) K 147 Continued From page 9 K 147 NFPA 101 LIFE SAFETY CODE STANDARD SS=E Electrical wiring and equipment is in accordance

> This STANDARD is not met as evidenced by: Based on observation and interview, the facility

with NFPA 70, National Electrical Code, 9.1.2

SUMMARY STATEMENT OF DEFICIENCIES

(EACH DEFICIENCY MUST BE PRECEDED BY FULL

failed to maintain their electrical equipment and utilities. This was evidenced by appliances that were plugged into multi-outlet extension cords, by utilizing extension cords as permanent wiring, by multi-outlet extension cords plugged into another multi-outlet extension cords, by an electrical outlet that was missing a cover plate, by an impeded electrical panel, and by medical equipment plugged into a six plug adapter. This could result in an electrical fire. This affected 3 of 6 smoke compartments.

NFPA 101, Life Safety Code, 2000 Edition SECTION 9.1 UTILITIES

9.1.2 Electric. Electrical wiring and equipment shall be in accordance with NFPA 70, National Electrical Code, unless existing installations, which shall be permitted to be continued in service, subject to approval by the authority having jurisdiction.

NFPA 70, National Electrical Code, 1999 Edition 240-4 Flexible cord, including tinsel cord and extension cords, and fixture wires shall be protected against overcurrent by either (a) or (b). (a) Ampacities. Flexible cord shall be protected by an overcurrent device in accordance with its ampacity as specified in Tables 400-5(A) and (B). Fixture wire shall be protected against overcurrent in accordance with its ampacity as

seconds. An annual test shall be conducted on every required battery powered emergency lighting system for no less than 1.5 hours. Equipment shall be fully operational for the duration of the test. Written records of visual Inspections and tests shall be kept by the DOES.

PROVIDER'S PLAN OF CORRECTION

(EACH CORRECTIVE ACTION SHOULD BE

CROSS-REFERENCED TO THE APPROPRIATE

DEFICIENCY)

Measures that will be implemented to ensure that solutions are sustained:

The Environmental Services Director and/or his/her designee shall preform functional emergency lighting testing; a functional test shall be conducted on every required emergency lighting system at 30-day intervals for not less than 30 seconds. An annual test shall be conducted on every required battery powered emergency lighting system for no less than 1.5 hours. Equipment shall be fully operational for the duration of the test; and document the results of the monthly emergency lighting test on the Continuous Quality Improvement audit tool. Results of the documented emergency lighting test will be forwarded to the QA+A Committee monthly X 4 months for further monitoring and action planning as indicated or until the QA+A Committee determines compliance.

K 047 NFPA Life Safety Code Standard

6/8/15

CENTERS FOR MEDICARE & MEDICAID SERVICES ATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01		FORM APPROV OMB NO. 0938-03 (X3) DATE SURVEY COMPLETED	
056110		B. WING		12.50	
NAME OF PROVIDER OR SUPPLIER		1 3	STREET ADDRESS, CITY, STATE, ZIP CODE	05/20/2015	
LAGUNA HILLS HEALTH AND		4	24452 HEALTH CENTER DRIVE LAGUNA HILLS, CA 92653		
PHEFIX (EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)	COMPLETION TE DATE	
overcurrent protect be permitted to be providing this prote 400-8 Unless speci 400-7, flexible cord for the following: (1) As a substitute structure (2) Where run thro ceillings, suspended floors (3) Where run thro similar openings (4) Where attached (5) Where conceals structural ceillings, since ceillings, or floors (6) Where installed otherwise permitted NFPA 70, National E 370-25. Covers and installations, each b faceplate, or fixture Article 110-26(a)(2) The width of the wore electric equipment is equipment or 30 in. greater. In all cases at least a 90 degree or hinged panels. Article 110-26(3)(b)	ion, as in Section 240-10, shall an acceptable means for ction. ifically permitted in Section and cables shall not be used for the fixed wiring of a ugh holes in walls, structural ceilings, dropped cellings, or ugh doorways, windows, or to building surfaces ed behind building walls, suspended ceilings, dropped in raceways, except as in this Code Electrical Code, 1999 Edition Canopies. In completed ox shall have a cover.	K 147	It is the policy of the facility that all exit a directional signs are displayed in accorda with section 7.10 with continuous also set by the emergency lighting system. Corrective action for Residents found to have been affected by this deficiency: It was found that 32 emergency exit signs were affected by this deficiency. On 5/20/15 the DOES performed a month test on the 32 exit signs. Identification of other Residents having to potential to be affected by the same deficient practice and corrective action the will be taken: No Residents and exit signs have the potential be to be affected by this deficiency. Measures/Corrective action that will be into place to ensure that this same deficiency does not recur: On 6/8/18 the Administrator in-serviced the DOES on the facility's policy and procedure regarding periodic testing of emergency lighting equipment, including; a functional test should be conducted on every required emergency lighting system at 30-day interfor not less than 30 seconds. An annual ships conducted on every required battery powered emergency lighting system for not less than 30 seconds. An annual ships conducted on every required battery powered emergency lighting system for not less than 30 seconds. An annual ships conducted on every required battery powered emergency lighting system for not less than 30 seconds. An annual ships conducted on every required battery powered emergency lighting system for not less than 30 seconds.	nce rved the hat ntial out	

PRINTED: 05/26/2015 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF GORRECTION

(X4) ID

NAME OF PROVIDER OR SUPPLIER

(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER

(X2) MULTIPLE CONSTRUCTION A BUILDING 01

(X3) DATE SURVEY COMPLETED

056110

B. WING

05/20/2015

LAGUNA HILLS HEALTH AND REHABILITATION CENTER

STREET ADDRESS, CITY, STATE, ZIP CODE 24452 HEALTH CENTER DRIVE

LAGUNA HILLS, CA 92653

SUMMARY STATEMENT OF DEFICIENCIES PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL TAG REGULATORY OR LSC IDENTIFYING INFORMATION)

PREFIX TAG

PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)

COMPLETION DATE

K 147 Continued From page 11

During a tour of the facility with the Director of Environmental Services on 5/20/15, the electrical equipment and wiring were observed.

- 1. At 8:39 a.m., there was an orange extension cord in use in the Staff Development office.
- 2. At 8:48 a.m., there was a multi-outlet extension cord that was plugged into another multi-outlet extension cord in the Admission Office.
- 3. At 8:49 a.m., the refrigerator in the Admission Office was plugged into a multi-outlet extension cord.
- 4. At 8:55 a.m., there was a multi-outlet extension cord that was plugged into another multi-outlet extension cord in the Payroll office in the Business office.
- 5. At 8:57 a.m., Bed A and the oxygen machine near Bed A in Room 312 were plugged into a six plug adapter.

At 8:59 a.m., the DOES said during an interview, that the facility did not have any electrical waivers and he thought that the six plug adapter was okay.

- 6. At 9:00 a.m., the electrical outlet behind Bed A in Room 312, was missing a cover plate.
- 7. At 9:05 a.m., the Activities Office microwave was plugged into an orange extension cord that was plugged into a multi-outlet extension cord.
- 8. At 9:56 a.m., there was an orange extension

K 147

less than 1.5 hours. Equipment shall be fully operational for the duration of the test. Written records of visual inspections and tests shall be kept by the DOES.

Measures that will be implemented to ensure that solutions are sustained:

The Environmental Services Director and/or his/her designee shall preform periodic testing of emergency lighting equipment including; a functional test should be conducted on every required emergency lighting system at 30-day intervals for not less than 30 seconds. An annual shall be conducted on every required battery powered emergency lighting system for not less than 1.5 hours. Equipment shall be fully operational for the duration of the test and document the results of the monthly emergency lighting system test on the Continuous Quality Improvement audit tool. Results of the documented emergency lighting test will be forwarded to the QA+A Committee monthly X 4 months for further monitoring and action planning as indicated or until the QA+A Committee determines compliance.

K 064 NFPA 101 Life Safety Code Standard

6/8/15

CENTERS FOR MEDICARE & MEDICAID SERVICES TATEMENT OF DEFICIENCIES ND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER		(X2) MULTIPLE CONSTRUCTION		FORM APPROVE MB NO. 0938-039 (X3) DATE SURVEY COMPLETED	
		056110	B. WING		
NAME OF	PROVIDER OR SUPPLIER				05/20/2015
		REHABILITATION CENTER	1 2	STREET ADDRESS, CITY, STATE, ZIP CODE 24452 HEALTH CENTER DRIVE AGUNA HILLS, CA 92653	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIAT DEFICIENCY)	COMPLETION DATE
K 147	9. At 10:01 a.m., E. office, was impeded cabinet and two box	entral Supply Office. The plugged into the refrigerator. Rectrical Panel MI in the MDS of from access with a storage ses in front of the panel. There was an orange ged into the outside light near			he eat ted of er

regarding fire extinguishers, including;

AND PLAN O	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 056110	A. BUILDE	IPLE CONSTRUCTION	(X3) DAT	. 0938-03 TE SURVEY MPLETED
NAME OF PROVIDER OR SUPPLIER LAGUNA HILLS HEALTH AND REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 24482 NEALTH CENTER DRIVE LAGUNA HILLS, CA 92663		20/2015	
(X4) ID PREFIX TAG	CEAGH DEFICIEN	TATEMENT OF DEFICIENCIES CY MUST BE PARCEDED BY FULL LSC IDENTIFYING INPORMATIONS	PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPRIES (CROSS-REFERENCED)	N FOR	COMPLETION DATE
				maintaining its portable fire extinguisher fire extinguishers shall be conspicuously located where they will be readily access and immediately available in the event. On 6/8/18 the DSD in-serviced all facility on the facility's policy and procedures regarding fire extinguishers, including; maintaining its portable fire extinguisher fire extinguishers shall be conspicuously located where they will be readily access and immediately available in the event. Measures that will be implemented to ensure that solutions are sustained: The DOES and/or his/her designee shall preform weekly facility sweeps on maintaining its portable fire extinguisher fire extinguishers shall be conspicuously located where they will be readily access and immediately available in the event of the documented results of the weekly fire extinguisher sweep will be reported on the Quality Improvement audit tool. Results the documented fire extinguisher sweep be forwarded to the QA+A Committee monthly X 4 months for further monitoriand action planning as indicated or until QA+A Committee determines compliance.	y stable of fire. y staff ers, sible of fire. rs; sible of fire. re the of will ng the	

DEPARTMENT OF HEALTH AND HUMAN SERVICES PRINTED: 05/26/2015 CENTERS FOR MEDICARE & MEDICAID SERVICES FORM APPROVED STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: OMB NO. 0938-0391 (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY A. BUILDING 01 COMPLETED 055110 B. WING NAME OF PROVIDER OR SUPPLIER 05/20/2015 STREET ADDRESS, CITY, STATE, ZIP CODE LAGUNA HILLS HEALTH AND REHABILITATION CENTER 24452 HEALTH CENTER DRIVE LAGUNA HILLS, CA 92653 (X4) 10 SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PROVIDER'S PLAN OF CORRECTION REGULATORY OR LSC IDENTIFYING INFORMATION) (XB) DOMPLETION DATE TAG PREFIX (EACH CORRECTIVE ACTION SHOULD BE TAG CHOSS-REFERENCED TO THE APPROPRIATE **DEFICIENCY**) K 147 101 Electrical wiring and 6/30/15 equipment is in accordance with NFPA 70, National Electrical Code 9.1.2 It is the policy of the facility that all electrical equipment and utilities be maintained in accordance with NFPA 70. Corrective action for Residents found to have been affected by this deficiency: It was found that 10 electrical outlets were affected by this deficiency. 1. On 5/20/15 the DOES initiated corrective action, a replacement extension cord (Leviton medical grade plug strips), compliant with NFPA 70, will be ordered and will be delivered by 6/30/15. 2. On 5/20/15 the DOES removed the extension cord in the Admission Office. 3. On 5/20/15 the DOES removed the multioutlet extension cord that the refrigerator In the Admissions Office was plugged into. 4. On 5/20/15 the DOES Initiated corrective action for the multi-outlet extension cord that was plugged into another multi-outlet extension cord in the payroll office in the business office. A replacement extension cord (Leviton medical grade plug strips), compliant with NFPA 70, will be ordered and will be delivered by 6/30/15.

DEPARTMENT OF HEALTH AND HUMAN SERVICES PRINTED: 05/26/2015 CENTERS FOR MEDICARE & MEDICAID SERVICES FORM APPROVED STATEMENT OF DEFICIENCIES OMB NO. 0938-0391 (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION (X2) MULTIPLE CONSTRUCTION IDENTIFICATION NUMBER: O(3) DATE SURVEY A. BUILDING 01 COMPLETED 056110 B. WING NAME OF PROVIDER OR SUPPLIER 05/20/2015 STREET ADDRESS, CITY, STATE, ZIP CODE LAGUNA HILLS HEALTH AND REHABILITATION CENTER 24452 HEALTH CENTER DRIVE LAGUNA HILLS, CA 92653 (X4) ID SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX 0(5) REACH CORRECTIVE ACTION SHOULD BE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) COMPLETION TAG CROSS REFERENCED TO THE APPROPRIATE DEFICIENCY 5. On 5/20/15 the DOES removed the six plug adapter from 312A. 5. On 5/20/15 the DOES provided an electrical outlet cover plate for 312A. 7. On 5/20/15 the DOES removed the orange extension cord in the activities office. 8. On 5/20/15 the DOES removed the orange extension cord in the Central Supply Office. 9, 5/20/15 the DOES removed the storage cabinet and two boxes that were impeding access to the electrical panel MI in the MDS office. 10. On 5/20/15 the DOES removed the orange extension cord from outside the laundry room. Identification of other Residents having the potential to be affected by the same deficient practice and corrective action that will be taken: All residents have the potential to be affected by this deficiency. On 6/3/15 the DOES did a facility sweep of all facility resident rooms and offices, and found that 116 resident rooms and/or offices were affected by the same deficiency. On 6/3/15 the DOES initiated corrective action for all 116 resident rooms/offices to

421

GENTERS FOR MEDICARE & MEDICAID SERVICES STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION OSCI 10		CON MUNTIPLE CONDITIONS		FORM APPROVI IB NO. 0938-03 X3) DATE SURVEY COMPLETED	
NAME OF PROVIDER OR SUPPLIER LAGUNA HILLS HEALTH AND REHABILITATION CENTER				05/20/2015	
(X4) ID PREFIX TAG	USPOUNT CHEP KARNE	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD E CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	BE COMPLETION DATE
				remove multi-outlet extension cords and replace them with Leviton medical grade strips that are compliant with NFPA 70, the will be completed by 6/30/15. Measures that will be implemented to ensure that solutions are sustained: The DOES and/or his/her designee shall preform weekly facility sweeps on maintaining electrical equipment and utilitien accordance with NFPA 70. The documented results of the weekly electrical equipment and utilities sweep will be reported on the Quality Improvement Aud Tool. Results of the documented electrical equipment and utilities sweep will be forwarded to the QA+A Committee month 4 months for further monitoring and action planning as indicated or until the QA+A Committee determines compliance.	plug nis ties al dit