PRINTED: 03/11/2024 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		555838	B. WING _			02/08/2024	
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC			STREET ADDRESS, CITY, STATE, ZIP CODE 1331 CAMDEN AVENUE CAMPBELL, CA 95008			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF COF ((EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE A DEFICIENCY)	SHOULD BE		(X5) COMPLETION DATE
	Initial Comments Surveyor: 43035 The following reflects Department of Public Emergency Prepared The findings are in ac Federal Regulations (for Long Term Care (I Representing the Cal Health: 43035 The facility is not in si 42 CFR 483.73 for Lo Facilities. Census = 51 Hospital CAH and LTC CFR(s): 483.73(e) §482.15(e) Condition (e) Emergency and si hospital must implem power systems based	the findings of the California Health, during an ness recertification survey. cordance with 42 Code of (CFR) 483.73, Requirement LTC) Facilities. ifornia Department of Public ubstantial compliance with ong Term Care (LTC) C Emergency Power for Participation: tandby power systems. The ent emergency and standby d on the emergency plan set of this section and in the tes plan set forth in	1	CROSS-REFERENCED TO THE A DEFICIENCY)			2/29/24
	[LTC facility CAH and emergency and stand	(e), §485.542(e) tandby power systems. The REH] must implement lby power systems based on the forth in paragraph (a) of					
	§485.625(e)(1)	73(e)(1), §485.542(e)(1), r location. The generator					
_ABORATORY I	DIRECTOR'S OR PROVIDER/S	SUPPLIER REPRESENTATIVE'S SIGNATURE	1	TITLE			(X6) DATE

Electronically Signed 02/23/2024

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDII	TIPLE CONSTRUCTION NG 02	(X3)	(X3) DATE SURVEY COMPLETED		
		555838	B. WING _			02/08/2024	
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC			STREET ADDRESS, CITY, STATE, ZIP CO 1331 CAMDEN AVENUE CAMPBELL, CA 95008	,DE		
(X4) ID PREFIX TAG	(-, -, -, -, -, -, -, -, -, -, -, -, -, -		ID PREFI TAG	PROVIDER'S PLAN OF C X (EACH CORRECTIVE ACTIC CROSS-REFERENCED TO TH DEFICIENCY	ON SHOULD BE HE APPROPRIATE	(X5) COMPLETION DATE	
E 041	requirements found in Code (NFPA 99 and Amendments TIA 12-12-5, and TIA 12-6), I and Tentative Interim 12-2, TIA 12-3, and T when a new structure structure or building is 482.15(e)(2), §483.73 §485.542(e)(2) Emergency generato [hospital, CAH and L the emergency powe and [maintenance] re Health Care Facilities Safety Code. 482.15(e)(3), §483.73 (3),§485.542(e)(2) Emergency generato LTC facilities] that mato power emergency for how it will keep er operational during the evacuates. *[For hospitals at §48 REHs at §485.542(g) §485.625(g):] The standards incorp section are approved reference by the Dire Federal Register in a 552(a) and 1 CFR paramaterial from the sou	cordance with the location in the Health Care Facilities Fentative Interim 2, TIA 12-3, TIA 12-4, TIA Life Safety Code (NFPA 101 Amendments TIA 12-1, TIA IA 12-4), and NFPA 110, is built or when an existing is renovated. B(e)(2), §485.625(e)(2), in the TC facility] must implement in system inspection, testing, quirements found in the TC Code, NFPA 110, and Life EC (S), §485.625(e) If fuel. [Hospitals, CAHs and dintain an onsite fuel source generators must have a plan mergency power systems in emergency, unless it 2.15(h), LTC at §483.73(g), and and CAHs orated by reference in this	E	041			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		555838	B. WING _			02/	08/2024
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC			13	REET ADDRESS, CITY, STATE, ZIP CODE 31 CAMDEN AVENUE AMPBELL, CA 95008		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	×	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
E 041	or at the National Arc Administration (NARA availability of this mat 202-741-6030, or go in http://www.archives.g _federal_regulations/if If any changes in this incorporated by refered document in the Federal the changes. (1) National Fire Prote Batterymarch Park, Quincy, MA 02169, w 1.617.770.3000. (i) NFPA 99, Health Cedition, issued Augus (ii) Technical interim a NFPA 99, issued Augus (iii) TIA 12-3 to NFPA (vi) TIA 12-4 to NFPA (vi) TIA 12-5 to NFPA (vii) NFPA 101, Life Sissued August 11, 201 (viii) TIA 12-1 to NFPA 2011. (ix) TIA 12-2 to NFPA 2012. (x) TIA 12-3 to NFPA 2013. (xii) NFPA 110, Stand Standby Power Syste TIAs to chapter 7, iss	A Boulevard, Baltimore, MD hives and Records A). For information on the erial at NARA, call to: ov/federal_register/code_of obr_locations.html. edition of the Code are ence, CMS will publish a eral Register to announce ection Association, 1 ww.nfpa.org, are Facilities Code, 2012 to 11, 2011. mendment (TIA) 12-2 to 11, 2011. 99, issued August 9, 2012. 99, issued August 9, 2013. 99, issued March 7, 2013. 99, issued March 3, 2014. afety Code, 2012 edition, 11. A 101, issued August 11, 101, issued October 30, 101, issued October 22, 101, issued October 22, 101, issued October 22, 101, issued October 22, 101 edition, including	E	041			
	Surveyor: 43035				Camden PostAcute Care submits this		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULT A. BUILDI		PLE CONSTRUCTION G 02		(X3) DATE SURVEY COMPLETED	
		555838	B. WING			02	/08/2024
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC	;		STREET ADDRESS, CITY, STATE, ZIP CODE 1331 CAMDEN AVENUE CAMPBELL, CA 95008			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE
E 041		e 3 ew and interview, the facility Emergency Preparedness	E	041	response and plan of correction as par the requirements under State and Fed		
	Program (EPP). This information in the em system policy and proof 51 residents and oproperly react during Findings: During record review Administrator on 2/8/ At 3:44 p.m., the faci and specified policy a maintaining emergen such as, how long bas	was evidenced by missing lergency power supply ocedure. This affected the 51 could result in the failure to an emergency. and interview with the 24, the EPP was requested.			law. The Plan of Correction is submitted accordance with specific regulatory requirements. It shall not be construed admission of any alleged deficiency citor any liability. The provider submits the plan of correction with the intention that is inadmissible by any third party in any civil, criminal action or proceedings against the provider of its employees, agents, officer so directors or shareholders. The provider reserves the right to challenge the cited findings if a any time the provider determines that the disputed findings are relied upon in a manner adverse to the interest of the governmental agencies or third party for the submitted in the content of the governmental agencies or third party for the submitted in the content of the governmental agencies or third party for the governmental agencies or the governmental age	ad in as ed is t it y ne t	
	generator type. Upor	n interview, the Administrator apdate the information.			evaluation and appropriate treatment modalities. The emergency operations plan was updated by the administrator to include policy and procedure for maintaining emergency power during an outage including how long back up fuel could sustain emergency power as well as generator specific information, includin generator type. This was completed or 02/08/2024. The updated policy and procedure was shared with CDPH. All residents have the potential to be affected by this deficient practice. The director of staff development will provide an inservice to facility staff on the staff of the	g n	

	ATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED			
		555838	B. WING			02/08/2024	
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC		•	STREET ADDRESS, CITY, STATE, ZIP COD 1331 CAMDEN AVENUE CAMPBELL, CA 95008	PE		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES ID PROVIDER'S PLAN OF CO (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION TAG CROSS-REFERENCED TO THE DEFICIENCY)			N SHOULD BE		(X5) COMPLETION DATE	
E 041	Continued From page	÷ 4	E	facility policy and procedure finaintaining emergency power outage including how long bare could sustain emergency power generator specific information generator type. This inservice completed by 02/29/2024. The administrator will update policy and procedure for main emergency power during an expectation of the policy and procedure for main emergency power as generator specific information generator type, upon any charemergency generator or resessupply. Monthly the administrator and will audit the facility policy and for maintaining emergency power an outage including how long could sustain emergency power information on the generator ensure information is present Any findings will be immediat. The administrator and/or desireport their audit findings to the committee for further review a up. The QAPI committee will effectiveness of the plan mon measuring the number of san occurrences. The QAPI Committee for areas or issues ident recurring or trending negative implement a new and more ended to action. The QAPI committee of action.	er during and ck up fuel over as well on, including and the facility of taining outage uel could well on, including outage uel could well on, including outage uel could well on, including outages in rive fuel of the facility of the facili	neee re g uel l as	

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED		
		555838	B. WING _			02/	08/2024
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC			13	TREET ADDRESS, CITY, STATE, ZIP CODE 331 CAMDEN AVENUE AMPBELL, CA 95008		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PREFIX (EACH CORRECTIVE ACTION SHOUL			(X5) COMPLETION DATE
E 041	Continued From page	5	E	041	reassess the need for further monitorin quarterly. This Plan of Correction will be complete by 02/29/2024.		
K 000	Department of Public Life Safety Code rece findings are in accord Federal Regulations (National Fire Protection Life Safety Code, 201 Health Care Facilities Representing the Call Health: 43035	:: 1974 :: 2012 EXISTING ONE STORY, 'PE V (111), FULLY ds: 60 the findings of the California Health, during an annual ertification survey. The ance with 42 Code of (CFR) §483.90(a)(b)(c)(j), on Association (NFPA) 101 - 2 Edition, and NFPA 99 -	K	000			
K 324 SS=D		ong Term Care Facilities.	K	324			2/29/24

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDIN	IPLE CONSTRUCTION NG 02		(X3) DATE SURVEY COMPLETED		
		555838	B. WING _			02/08/2024	
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC		1	STREET ADDRESS, CITY, STATE, ZIP COI 1331 CAMDEN AVENUE CAMPBELL, CA 95008	•		
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO ((EACH CORRECTIVE ACTIO CROSS-REFERENCED TO THI DEFICIENCY)	N SHOULD BE E APPROPRIATE	(X5) COMPLETION DATE	
K 324	with NFPA 96, Stand and Fire Protection of Operations, unless: * residential cooking appliances such as represented to cooking in accordance to cooking in accordance to cooking facilities operate the cooking facilities operate to cooking facilities in 30 or fewer patients of 18.3.2.5.4, 19.3.2.5.4 Cooking facilities proper 9.2.3 are not required hazardous areas, but corridor.	s protected in accordance and for Ventilation Control of Commercial Cooking equipment (i.e., small nicrowaves, hot plates, or food warming or limited be with 18.3.2.5.2, 19.3.2.5.2 when to the corridor in smoke 0 or fewer patients comply onder 18.3.2.5.3, 19.3.2.5.3, smoke compartments with comply with conditions under 1. tected according to NFPA 96 wired to be enclosed as the shall not be open to the 3.3.2.5.4, 19.3.2.5.1 through	K3	324			
	This REQUIREMENT is not met as evidenced by: Surveyor: 43035 Based on observation, document review, and interview, the facility failed to maintain the kitchen cooking equipment. This was evidenced by missing records of annual kitchen appliance inspections and by dirty nozzles for the ANSUL fire suppression system. This affected one of three smoke compartments, 22 of 51 residents, and could result in a failure of the fuel-fired kitchen cooking equipment or an inability to extinguish a fire in the kitchen.			The kitchen ANSUL nozzles griddle were cleaned on 02/0 An annual inspection of kitch equipment was completed by agency on 03/02/2023. Recorequested and maintained. Noted. All residents have the potent affected by this deficient practice.	08/2024. Ten y an outside ord was lo findings		

PRINTED: 03/11/2024 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY IDENTIFICATION NUMBER-AND PLAN OF CORRECTION COMPLETED A. BUILDING 02 555838 B. WING 02/08/2024 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **1331 CAMDEN AVENUE CAMDEN POSTACUTE CARE, INC** CAMPBELL, CA 95008 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X5) COMPLETION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE PREFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) Continued From page 7 K 324 NFPA 101, Life Safety Code, 2012 Edition. The administrator and/or designee will 19.3.2.5 Cooking Facilities. inservice the kitchen and 19.3.2.5.1 Cooking facilities shall be protected in housekeeping/maintenance staff on the accordance with 9.2.3, unless otherwise necessity of routine weekly cleaning of the permitted by 19.3.2.5.2, 19.3.2.5.3, or 19.3.2.5.4. kitchen ANSUL nozzles over the griddle. 9.2.3 Commercial Cooking Equipment. This inservice will be completed by Commercial cooking equipment shall be in 02/29/2024. accordance with NFPA 96, Standard for Ventilation Control and Fire Protection of The administrator provided an inservice to Commercial Cooking Operations, unless such the Housekeeping/maintenance installations are approved existing installations, Supervisor on the need for kitchen which shall be permitted to be continued in equipment to be inspected annually and for the records to be requested and 19.3.2.5.3* Within a smoke compartment, where maintained. This inservice was completed residential or commercial cooking equipment is on 02/19/2024. used to prepare meals for 30 or fewer persons, one cooking facility shall be permitted to be open The kitchen ANSUL nozzles over the to the corridor, provided that all of the following griddle will be cleaned by the kitchen staff conditions are met: weekly and as needed. (10) Procedures for the use, inspection, testing, The kitchen supervisor and/or designee and maintenance of the cooking equipment are in will perform a weekly check on the kitchen accordance with Chapter 11 of NFPA 96 and the ANSUL nozzles over the griddle to ensure the kitchen ANSUL nozzles over the manufacturer's instructions and are followed. griddle are free from grease. The kitchen NFPA 96, Standard for Ventilation Control and supervisor and/or designee will report Fire Protection of Commercial Cooking audit findings to the administrator and/or Operations. director of nursing in the daily stand-up 10.2.6 Automatic fire-extinguishing systems shall meeting. Any findings will be immediately be installed in accordance with the terms of their resolved. listing, the manufacturer's instructions, and the following standards where applicable: Annually the housekeeping/maintenance (1) NFPA 12 Supervisor and/or designee will contact an (2) NFPA 13 outside agency to inspect kitchen (3) NFPA 17 equipment, and as needed. The results of (4) NFPA 17A the kitchen equipment inspection will be recorded and maintained. 10.2.7.3 The addition of obstructions to spray patterns from the cooking appliance nozzle(s) such as baffle plates, shelves, or any modification Annually the administrator and/or shall not be permitted. designee will audit the kitchen equipment

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED		
		555838	B. WING			02	/08/2024	
NAME OF P	ROVIDER OR SUPPLIER			S	TREET ADDRESS, CITY, STATE, ZIP CODE			
CAMDEN	DOSTACUTE CADE INC			1	331 CAMDEN AVENUE			
CAMDEN	POSTACUTE CARE, INC			C	AMPBELL, CA 95008			
(X4) ID	SUMMARY ST	ATEMENT OF DEFICIENCIES	ID		PROVIDER'S PLAN OF CORRECTION		(X5)	
PREFIX TAG	`	Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	PREF TAG		(EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI, DEFICIENCY)		COMPLETION DATE	
K 324			К	324				
	11.7 Cooking Equipm	ent Maintenance.			inspection records to ensure all kitcher	1		
	11.7.1 Inspection and	servicing of the cooking			equipment has been inspected at least	İ		
	equipment shall be m	ade at least annually by			annually. The administrator and/or			
	properly trained and o	qualified persons.			designee will report their audit findings the administrator and/or director of	to		
	NFPA 17A, Standard	for Wet Chemical			nursing in the daily stand-up meeting.	Anv		
	Extinguishing System				findings will be immediately resolved.	,		
		s. All discharge nozzles			,			
	shall be located to mi				The kitchen supervisor and/or designe	е		
		within the limitations and			will report their audit findings to the QA			
	constraints of the mai				committee for further review and follow			
	installation and maint	enance manual.			up. The QAPI committee will review the	е		
	5.6.4 Movable cookin	g equipment shall be			effectiveness of the plan monthly by			
	provided with a mean	s to ensure that it is			measuring the number of same			
	correctly positioned in	relation to the appliance			occurrences. The QAPI Committee wil	l		
	discharge nozzle duri	ng cooking operations.			develop a Performance Improvement			
	7.3.2* A service techr	nician who has the			Plan for areas or issues identified as			
	applicable manufactu	rer ' s design, installation,			recurring or trending negatively and			
		nual and service bulletins			implement a new and more effective p	an		
		chemical fire-extinguishing			of action. The QAPI committee will			
	•	no more than 6 months as			reassess the need for further monitoring	ıg		
	outlined in 7.3.3.				quarterly.			
		nnually and after any system						
		ce shall be conducted in			The Administrator and/or designee will			
		nanufacturer's design,			report their audit findings to the QAPI			
	installation, and main				committee for further review and follow			
		shall include the following:			up. The QAPI committee will review the	е		
	(1) A check to see tha	at the hazard has not			effectiveness of the plan annually by			
	changed	fall data atoms the server allows			measuring the number of same			
		f all detectors, the expellant			occurrences. The QAPI Committee wil			
		agent container(s), releasing			develop a Performance Improvement			
	devices, piping, hose				Plan for areas or issues identified as			
	signais, all auxiliary e level of all nonpressu	quipment, and the liquid			recurring or trending negatively and	an		
	containers	nzed wet chemical			implement a new and more effective plot of action. The QAPI committee will	all		
		he agent distribution piping			reassess the need for further monitoring	na		
	is not obstructed	ne agent distribution piping			annually.	y		
	is not obstitucted				This Plan of Correction will be complet	ed		
	Findings:				by 02/29/2024.	cu		

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDI	TIPLE CONSTRUCTION NG 02		(X3) DATE SURVEY COMPLETED	
		555838	B. WING _			02/	08/2024
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC			STREET ADDRESS, CITY, STATE, ZIP CO 1331 CAMDEN AVENUE CAMPBELL, CA 95008	ODE		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		ON SHOULD BI HE APPROPRIA		(X5) COMPLETION DATE
K 324	interview with the Mai Staff 2 on 2/8/24, the maintenance records 1. At 9:53 a.m., the ki the griddle were obse grease. Upon intervie finding and stated that 2. At 2:13 p.m., the fadocumentation for the inspection. Upon interview of the could not find the Alcohol Based Hand CFR(s): NFPA 101 Alcohol Based Hand ABHRs are protected unless all conditions at Corridor is at least 6 maximum individual gallons (0.53 gallons ounces of Level 1 aer bispensers shall ha horizontal spacing Not more than an activity of the compartment of the compartmen	acility, document review, and intenance Supervisor and kitchen and associated were inspected. Itchen ANSUL nozzles over erved to be covered in w, Staff 2 confirmed the intention they did not notice. Incility was unable to provide every annual kitchen equipment review, the Maintenance the finding and stated that every documentation. Rub Dispenser (ABHR) In accordance with 8.7.3.1, are met: In feet wide dispenser capacity is 0.32 in suites) of fluid and 18 rosols we a minimum of 4-foot aggregate of 10 gallons of the erosol are used in a single poutside a storage cabinet, and dispenser per room semoke compartment greater the es with NFPA 30 installed within 1 inch of an installed within		325			2/29/24
	* Dispensers over car sprinklered smoke co						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIF A. BUILDING	PLE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED
		555838	B. WING		02/08/2024
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC			STREET ADDRESS, CITY, STATE, ZIP CODE 1331 CAMDEN AVENUE CAMPBELL, CA 95008	,
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROF	D BE COMPLETION
K 325	* Operation of the dis Section 18.3.2.6(11) of * ABHR is protected at 18.3.2.6, 19.3.2.6, 42 482, 483, and 485 This REQUIREMENT by: Surveyor: 43035 Based on observation failed to maintain the dispensers. This was near an ignition source smoke compartments could result in the ign emergency. Findings: During a tour of the familiar mance Supervial alcohol-based hand-robserved. At 10:11 a.m., the autilocated in the outdoor mounted directly about Upon interview, the Maintenance with the mounted of the second process.	eed 95 percent alcohol penser shall comply with or 19.3.2.6(11) against inappropriate access CFR Parts 403, 418, 460, is not met as evidenced and interview, the facility alcohol-based hand-rub evidenced by installation are. This affected one of three as, 15 of 51 residents, and aition of fire in the event of an accility and interview with the sor on 2/8/24, the able (ABHR) dispensers	K 32	The alcohol based hand rub dispen located on the outdoor patio was immediately removed by the housekeeping/maintenance supervis 02/08/2024. All residents have the potential to be affected by this deficient practice. The administrator audited automatic alcohol based hand rub dispensers throughout the facility to ensure eac proper placement and none were at electrical receptacles. This audit wa completed on 02/08/2024. No findin noted. The administrator provided an insert the housekeeping/maintenance supervisor on the proper placement alcohol based hand rub dispensers an emphasis on not placing automa alcohol based hand rub dispensers electrical receptacles. This inservice completed on 02/19/2024. The housekeeping/maintenance supervisor and/or designee will place alcohol based hand rub dispensers appropriate locations as needed.	sor on e c ch had bove s gs vice to of with tic above e was

	STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULT A. BUILDII	LTIPLE CONSTRUCTION DING 02			(X3) DATE SURVEY COMPLETED	
		555838	B. WING _			02/	/08/2024	
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC		STREET ADDRESS, CITY, STATE, ZIP CODE 1331 CAMDEN AVENUE CAMPBELL, CA 95008					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PREFIX (EACH CORRECTIVE ACTION SHOULD			(X5) COMPLETION DATE	
K 325	Continued From page	• 11	K	325	Monthly the Administrator and/or design will audit placement of automatic alcoh based hand rub dispensers to ensure the are not placed above electrical receptacles. The administrator and/or designee will report their audit findings the administrator and/or director of nursing in the daily stand-up meeting. If findings will be immediately resolved. The administrator and/or designee will report their audit findings to the QAPI committee for further review and follow up. The QAPI committee will review the effectiveness of the plan monthly by measuring the number of same occurrences. The QAPI Committee will develop a Performance Improvement Plan for areas or issues identified as recurring or trending negatively and implement a new and more effective plof action. The QAPI committee will reassess the need for further monitorin quarterly. This Plan of Correction will be complete.	ol hey to Any		
K 347 SS=E	Smoke Detection CFR(s): NFPA 101		K	347	by 02/29/2024.		2/29/24	
	open to corridors as r 19.3.4.5.2	ems are provided in spaces equired by 19.3.6.1. is not met as evidenced			Smoke detector sensitivity tests were			

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILDI	ULTIPLE CONSTRUCTION LDING 02			(X3) DATE SURVEY COMPLETED	
		555838	B. WING _			02	/08/2024	
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC		STREET ADDRESS, CITY, STATE, ZIP CODE 1331 CAMDEN AVENUE CAMPBELL, CA 95008		331 CAMDEN AVENUE			
(X4) ID PREFIX TAG	(EACH DEFICIENC	Y STATEMENT OF DEFICIENCIES ID ENCY MUST BE PRECEDED BY FULL PREFOR LSC IDENTIFYING INFORMATION)			PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE	
K 347	Based on record revirfailed to maintain the evidenced by missing records. This affected compartments, 51 of result in the failure or fire. NFPA 101 Life Safety 19.3.4 Detection, Ala Systems. 19.3.4.1 General. Health care occupantire alarm system in a 9.6.2.10.1.1 Where rethis Code, single-stat smoke alarms shall b 72, National Fire Alar unless otherwise prov 9.6.10.1.3, or 9.6.2.10 NFPA 72, National Fic Code, 2010 Edition 14.4.5.3.1 Sensitivity year after installation 14.4.5.3.2 Sensitivity alternate year therear permitted by complian 14.4.5.3.3 After the stest, if sensitivity tests	ew and interview, the facility smoke detectors. This was a smoke detector testing three of three smoke 51 residents, and could delay of notification during a code, 2012 Edition rm, and Communications cless shall be provided with a accordance with Section 9.6 required by another section of ion and multiple-station in accordance with NFPA rm and Signaling Code, vided in 9.6.2.10.1.2, 0.1.4. The Alarm and Signaling shall be checked within 1 shall be checked every fter unless otherwise	K	347	conducted by an outside agency on facts smoke detectors on 02/14/2024. No findings noted. The smoke detector sensitivity test report was maintained. All residents have the potential to be affected by this deficient practice. The administrator provided an inservice the housekeeping/maintenance supervisor on the need for sensitivity to for smoke detectors to be conducted every two years and records are to be maintained. This inservice was complet on 02/19/2024. The housekeeping/maintenance supervisor will contact an outside agent to conduct smoke detector sensitivity to every two years, and as needed. Every two years the administrator and/designee will audit the smoke detector sensitivity test reports to ensure smoke detectors have had sensitivity testing a least every two years. Any findings will immediately resolved. The Administrator and/or designee will report their audit findings to the QAPI committee for further review and follow	e to ests ted cy ests or et		
	if not marked), the let calibration tests shall to a maximum of 5 ye	be permitted to be extended			up. The QAPI committee will review the effectiveness of the plan every two year by measuring the number of same occurrences. The QAPI Committee will develop a Performance Improvement	ırs		
	Findings: During record review	and interview with the			Plan for areas or issues identified as recurring or trending negatively and implement a new and more effective plants.	an		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED		
		555838	B. WING			02/08/2024	
NAME OF PROVIDER OR SUPPLIER CAMDEN POSTACUTE CARE, INC				13	TREET ADDRESS, CITY, STATE, ZIP CODE 331 CAMDEN AVENUE AMPBELL, CA 95008		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 347	At 2:26 p.m., the facilismoke detector sensi interview, the Mainter the finding and stated send the documentati	sor on 2/8/24, the smoke requested. Ity was unable to provide tivity testing records. Upon nance Supervisor confirmed that it was done and will	K:	347	of action. The QAPI committee will reassess the need for further monitorin every two years. This Plan of Correction will be complete by 02/29/2024.		
K 353 SS=E	, ,		K	353	The housekeeping/maintenance supervisor contacted an outside agenc perform sprinkler inspection and testing on 02/22/2024. All records maintained.	9	2/29/24

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		` '	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
	555838		B. WING _	B. WING			/08/2024
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC		•	13	TREET ADDRESS, CITY, STATE, ZIP CODE 331 CAMDEN AVENUE AMPBELL, CA 95008		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	x	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE
K 353	of three smoke compresidents, and could extinguish and suppreemergency. NFPA 101, Life Safet 19.3.5 Extinguishmer 19.3.5.1 Buildings cobe protected through supervised automatic accordance with Section permitted by 19.3.5.5 9.7.1.1* Each automate in accordance with or (1) NFPA 13, Standar Sprinkler Systems (2) NFPA 13D, Stand Sprinkler Systems in Dwellings and Manuf (3) NFPA 13R, Stand Sprinkler Systems in to and Including Four 9.7.5 All automatic sprinkler Systems in to and Including Four 9.7.5 All automatic sprinkler Systems required by tested, and maintaine 25, Standard for the I Maintenance of Water Systems. NFPA 25 Standard for Systems, 2011 Edition 5.2.1.1* Sprinkler shallow for level annually. 5.2.2* Sprinkler pipe inspected annually from the standard for systems and sprinkler pipe inspected annually from the systems.	artments, 51 of 51 result in the failure to result in the event of an A Code, 2012 Edition result Requirements. That an approved, requirements. That an approved, reprinkler system in rection 9.7, unless otherwise rection of this Code shall be rection of this Code shall be rection of the Installation of rection of the Installation of rection of the Installation of residential Occupancies up results of the Installation of residential Occupancies up residential Occupancies up residential Decupancies up residential be inspected, rection of the Installation of residential of Sprinkler rection of	K	353	All residents have the potential to be affected by this deficient practice. The administrator provided an inservice the housekeeping/maintenance supervisor on the need for annual sprinkler inspection, semi-annual sprin testing, and quarterly sprinkler inspection. This inservice was completed on 02/22/2024. The housekeeping/maintenance supervisor and/or designee will contact outside agency to perform an annual sprinkler inspection, semi-annual sprintesting, and quarterly sprinkler inspection. Records of inspection and testing will be maintained. Quarterly the administrator and/or designee will audit facility sprinkler inspection records to ensure that annual sprintesting, and quarterly sprinkler inspection testing, and quarterly sprinkler inspection thave been conducted. The administrate and/or designee will report audit finding to the administrator and/or director of nursing in the daily stand-up meeting. Indings will be immediately resolved. The Administrator and/or designee will report their audit findings to the QAPI committee for further review and follow up. The QAPI committee will review the effectiveness of the plan monthly by measuring the number of same	kler on. t an kler on. be al kler ons or gs Any	
	hydraulically designe	design information sign for discreted systems shall be inspected tit is attached securely to			occurrences. The QAPI Committee wil develop a Performance Improvement Plan for areas or issues identified as		

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	I ` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		555838	B. WING	B. WING		02/	08/2024	
NAME OF PROVIDER OR SUPPLIER CAMDEN POSTACUTE CARE, INC			1:	TREET ADDRESS, CITY, STATE, ZIP CODE 331 CAMDEN AVENUE AMPBELL, CA 95008				
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE	
	to verify that it is secuted to verify that it is secuted 5.3.3 Waterflow Alarm 5.3.3.2* Vane-type and waterflow alarm device semiannually. 13.3.2.2* The valve in valves are in the follow (1) In the normal oper (2)* Sealed, locked, of (3) Accessible (4) Provided with correction (5) Free from externation (6) Provided with app 13.7 Fire Department 13.7.1 Fire department 13.7.1 Fire department (1) The fire department and accessible. (2) Couplings or swive rotate smoothly. (3) Plugs or caps are (4) Gaskets are in place (5) Identification signs (6) The check valve is (7) The automatic drapperating properly. (8) The fire department of the place and operating 13.7.4 Any obstruction removed.	d is legible. ign. shall be inspected annually urely attached and is legible. In Devices. In Devices. Ind pressure switch-type ces shall be tested Inspection shall verify that the wing condition: In or closed position or supervised I leaks Ilicable identification I Connections. Int connections shall be overify the following: Int connections are visible In place and undamaged. In place and undamaged. In place and undamaged. In place and in good condition. Is are in place. Is not leaking. In valve is in place and Int connection clapper(s) is	K	353	recurring or trending negatively and implement a new and more effective plus of action. The QAPI committee will reassess the need for further monitorin quarterly. This Plan of Correction will be complete by 02/29/2024.	9		
	Findings:	acility, record review, and						

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED	
		555838	B. WING		02/08/2024	
NAME OF PROVIDER OR SUPPLIER CAMDEN POSTACUTE CARE, INC				STREET ADDRESS, CITY, STATE, ZIP CODE 1331 CAMDEN AVENUE CAMPBELL, CA 95008	•	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 353 K 355 SS=D	interview with the Mai Staff 1 on 2/8/24, the records were requested. 1. At 2:48 p.m., the fathe annual sprinkler in known inspection recoupon interview, the Modern of the annual sprinkler in known inspection recoupon interview, the Modern of the documentation. 2. At 2:52 p.m., the fasemi-annual sprinkler interview, the Mainter the finding and stated the documentation. 3. At 2:55 p.m., the faquarterly sprinkler insinterview, the Mainter the finding and stated the documentation. Portable Fire Extinguic CFR(s): NFPA 101 Portable Fire Extinguic Portable fire extinguis inspected, and mainta NFPA 10, Standard for Extinguishers. 18.3.5.12, 19.3.5.12, This REQUIREMENT by: Surveyor: 43035 Based on observation failed to maintain the This was evidenced by	automatic sprinkler system ed and reviewed. cility was unable to provide aspection records. The last ord was dated 1/23/23. Iaintenance Supervisor and stated that they could entation. cility was unable to provide testing records. Upon ance Supervisor confirmed that they could not locate cility was unable to provide pection records. Upon ance Supervisor confirmed that they could not locate shers shers shers shers shers shers are selected, installed, ained in accordance with or Portable Fire	K 3			2/29/24

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
	555838 B. WING			02	/08/2024		
NAME OF PROVIDER OR SUPPLIER CAMDEN POSTACUTE CARE, INC			STREET ADDRESS, CITY, STATE, ZIP CODE 1331 CAMDEN AVENUE CAMPBELL, CA 95008				
PREFIX (EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	<	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		(X5) COMPLETION DATE	
and could result in the the event of an emerging NFPA 101 Life Safety 19.3.5.12 Portable fire provided in all health accordance with 9.7.4 9.7.4.1* Where require another section of this extinguishers shall be inspected, and mainta NFPA 10, Standard for Extinguishers. NFPA 10 Standard for Extinguishers, 2010 E 7.2.1.2* Fire extinguishers either manually or by monitoring device/systintervals. 7.2.2 Periodic inspect of fire extinguishers in least the following iter (1) Location in design (2) No obstruction to a (3) Pressure gauge responsible range or pos (4) Fullness determiniself-expelling-type excartridge-operated ex (5) Condition of tires, nozzle for wheeled ex (6) Indicator for nonresusing push-to-test pre 7.2.2.1 In addition to	ments, 22 of 51 residents, a delay to extinguish a fire in gency. Code, 2012 Edition extinguishers shall be care occupancies in I.1. ed by the provisions of a Code, portable fire exelected, installed, ained in accordance with or Portable Fire The Portable Fire extinguishers shall be inspected means of an electronic extern at a minimum of 30-day ained include a check of at ms: ated place access or visibility exading or indicator in the sition ed by weighing or hefting for tinguishers, and pump tanks wheels, carriage, hose, and ctinguishers extangeable extinguishers extangeable extinguishers shall in accordance with 7.2.2.2 if	К3	355	All residents have the potential to be affected by this deficient practice. The administrator audited all fire extinguisher inspection tags to ensure monthly inspection was completed. Au was completed on 02/09/2024. No findings noted. The administrator provided an inservice the housekeeping/maintenance supervisor on the need for fire extinguishers inspections to be conducted for inspection tags to be updated following inspection and for inspection records to be maintained. This inservice was completed on 02/19/2024. Monthly the Housekeeping/maintenance supervisor and/or designee will inspectifie extinguishers and record the inspection on the fire extinguisher inspection tag. Records of inspection was to emaintained. Monthly the Administrator and/or designee will report to ensure a monthly inspection of each fire extinguisher was completed. The administrator and/or designee will report their audit findings to the administrator and/or director of nursing in the daily stand-up meeting. Any findings will be immediately resolved. The Administrator and/or designee will report their audit findings to the QAPI committee for further review and follows.	dit e to eted n, eted vill nee gs		

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			PLETED	
		555838	B. WING _			02/	08/2024
	ROVIDER OR SUPPLIER POSTACUTE CARE, INC			STREET ADDRESS, CITY, STATE, ZIP COD 1331 CAMDEN AVENUE CAMPBELL, CA 95008			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFIX TAG	<	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 355	damage (4) Exposure to abno corrosive atmosphere 7.2.4.1 Personnel mashall keep records of inspected, including the corrective action. 7.2.4.3 Where at least inspections are condinspection was perforperson performing the recorded. 7.2.4.4 Where manual records for manual intag or label attached an inspection checklican electronic method 7.2.4.5 Records shall at least the last 12 meperformed. Findings: During a tour of the fastaff 2 on 2/8/24, the were observed. At 9:42 a.m., the Clast extinguisher located in with monthly inspection.	ke fire extinguishers nical injury or physical rmal temperatures or es king manual inspections all fire extinguishers hose found to require at monthly manual ucted, the date the manual med and the initials of the e inspections are conducted, spections shall be al inspections are conducted, spections shall be kept on a to the fire extinguisher, on st maintained on file, or by be kept to demonstrate that bothly inspections have been acility and interview with portable fire extinguishers as K portable fire in the kitchen was observed on records missing on the interview, Staff 2 confirmed	К3	355	effectiveness of the plan monthly by measuring the number of same occurrences. The QAPI Committee will develop a Performance Improvement Plan for areas or issues identified as recurring or trending negatively and implement a new and more effective plof action. The QAPI committee will reassess the need for further monitorin quarterly. This Plan of Correction will be complete by 02/29/2024.	an g	
K 511 SS=D	Utilities - Gas and Ele CFR(s): NFPA 101		K 5	511			2/29/24

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		555838	B. WING			02/08/2024	
NAME OF PROVIDER OR SUPPLIER CAMDEN POSTACUTE CARE, INC			•	13	TREET ADDRESS, CITY, STATE, ZIP CODE 331 CAMDEN AVENUE AMPBELL, CA 95008	,	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	х	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 511	electrical wiring and e NFPA 70, National El	ectric or related gas piping 64, National Fuel Gas Code, equipment complies with ectric Code. Existing nue in service provided no	к	5511			
	by: Surveyor: 43035 Based on observatior failed to maintain the was evidenced by an weatherproof covering smoke compartments could result in the ign NFPA 101 Life Safety 19.5 Building Service 19.5.1 Utilities. 19.5.1.1 Utilities shall of Section 9.1. 9.1.2 Electrical wiring accordance with NFP Code, unless such insexisting installations, be continued in service NFPA 70 National Ele 406.9(A) A receptacle location protected fro	comply with the provisions and equipment shall be in A 70 National Electrical stallations are approved which shall be permitted to be. extrical Code, 2011 Edition a installed outdoors in a m the weather or in other have an enclosure for the			Weatherproof coverings were applied electrical receptacles located outside in the patio on 02/09/2024. All residents have the potential to be affected by this deficient practice. The administrator inspected all external electrical receptacles to ensure they have weatherproof covering. This audit was completed on 02/09/2024. No findings noted. The administrator provided an inservice the housekeeping/maintenance supervisor on the need for external electrical receptacles to have a weatherproof covering. This inservice is completed on 02/19/2024. Monthly the housekeeping/maintenance supervisor and/or designee will audit external electrical receptacles to ensurt they have a weatherproof covering. The	l ad a e to vas e	

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		' '	(X3) DATE SURVEY COMPLETED	
		555838	B. WING _	B. WING		08/2024	
NAME OF PROVIDER OR SUPPLIER CAMDEN POSTACUTE CARE, INC				STREET ADDRESS, CITY, STATE, ZIP CODE 1331 CAMDEN AVENUE CAMPBELL, CA 95008			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO X (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	BE	(X5) COMPLETION DATE	
K 511	inserted and receptace An installation suitable be considered suitable be considered suitable. A receptacle shall be location protected from located under roofed marquees, and the like to a beating rain or we 20-ampere, 125- and receptacles shall be at type. Informational Note: The covered by this require	(attachment plug cap not ble covers closed). e for wet locations shall also e for damp locations. considered to be in a methe weather where open porches, canopies, e.e, and will not be subjected atter runoff. All 15- and 250-volt nonlocking a listed weather-resistant the types of receptacles ement are identified as 6-20 in ANSI/NEMA WD attrical Manufacturers for Dimensions of	K	housekeeping/maintenance supervis and/or designee will report audit findi to the administrator and/or director of nursing in the daily stand-up meeting findings will be immediately resolved. The housekeeping/maintenance supervisor and/or designee will report their audit findings to the QAPI comm for further review and follow up. The committee will review the effectivene the plan monthly by measuring the number of same occurrences. The Q Committee will develop a Performance Improvement Plan for areas or issued identified as recurring or trending negatively and implement a new and effective plan of action. The QAPI committee will reassess the need for further monitoring quarterly.	Any ittee QAPI ss of API e		
K 918 SS=D	Maintenance Supervireceptacles were obs At 8:56 a.m., the electoutside in the patio was weatherproof covering Maintenance Supervirent and stated that it was patio. Electrical Systems - ECFR(s): NFPA 101 Electrical Systems - EMaintenance and Teston The generator or other	trical receptacle located as observed missing g. Upon interview, the sor confirmed the finding because it was under the Essential Electric Syste	ΚS	This Plan of Correction will be completely 02/29/2024.	ted	2/29/24	

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 555838		, ,	(X2) MULTIPLI A. BUILDING (E CONSTRUCTION D2	(X3) DATE SURVEY COMPLETED
		B. WING		02/08/2024	
NAME OF PROVIDER OR SUPPLIER CAMDEN POSTACUTE CARE, INC		1	STREET ADDRESS, CITY, STATE, ZIP CODE 1331 CAMDEN AVENUE CAMPBELL, CA 95008		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD I CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	BE COMPLÉTION
K 918	criterion is not met du process shall be prove capability for the life is Maintenance and tes transfer switches are with NFPA 110. Generator sets are in under load 30 minuted day intervals, and exemonths for 4 continuounder load conditions simulated cold start at transfer of all EES load competent personnel stored energy power accordance with NFF circuit breakers are in program for periodical components is estable manufacturer require maintenance and tes readily available. EES circuits are marked, in separate from normathe possibility of dam source is a design constallations. 6.4.4, 6.5.4, 6.6.4 (NI 111, 700.10 (NFPA 70 This REQUIREMENT by: Surveyor: 43035 Based on document if facility failed to maint supply. This was evic conduct the monthly generator batteries at	ands. If the 10-second bring the monthly test, a ided to annually confirm this safety and critical branches. Iting of the generator and performed in accordance aspected weekly, exercised as 12 times a year in 20-40 ercised once every 36 bus hours. Scheduled test include a complete and automatic or manual ads, and are conducted by and are conducted by and testing of sources (Type 3 EES) are in A 111. Main and feeder aspected annually, and a ally exercising the ished according to ments. Written records of ting are maintained and a leadily identifiable, and a power circuits. Minimizing age of the emergency power insideration for new	K 918	Emergency generator battery conductance testing was completed o 02/08/2024. Emergency generator battery inspection was completed on 02/08/2024.	

PRINTED: 03/11/2024 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY **IDENTIFICATION NUMBER:** AND PLAN OF CORRECTION COMPLETED A. BUILDING 02 555838 B. WING 02/08/2024 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE **1331 CAMDEN AVENUE CAMDEN POSTACUTE CARE, INC** CAMPBELL, CA 95008 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE PREFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) Continued From page 22 K 918 three smoke compartments, 51 of 51 residents, All residents have the potential to be and could result in the failure to provide affected by this deficient practice. emergency power during the loss of normal utility power. The administrator reviewed the emergency generator monthly emergency NFPA 101. Life Safety Code, 2012 Edition generator battery conductance testing and 19.5.1 Utilities, Utilities shall comply with the weekly emergency generator battery provisions of section 9.1 inspection for the last 3 months. Audit was 19.5.1.1 Utilities shall comply with the provisions completed on 02/12/2024. No findings of section 9.1 noted. 9.1.3.1 Emergency Generators and standby power systems shall be installed, tested, and The administrator provided an inservice to maintained in accordance with NFPA 110, the housekeeping/maintenance Standard for Emergency and Standby Power supervisor on the need for monthly Systems. emergency generator battery conductance testing and weekly emergency generator NFPA 110, Standard for Emergency and Standby battery inspection. This inservice was Power Systems, 2010 Edition completed on 02/19/2024. 8.3.2.1 The operational test shall be initiated at an ATS and shall include testing of each EPSS Monthly the housekeeping/maintenance component on which maintenance or repair has supervisor and/or designee will test the been performed, including the transfer of each emergency generator battery automatic and manual transfer switch to the conductance. alternate power source, for a period of not less than 30 minutes under operating temperature. Weekly the housekeeping/maintenance 8.3.7 * Storage batteries, including electrolyte supervisor and/or designee will inspect levels or battery voltage, used in connection with the emergency generator battery. systems shall be inspected weekly and maintained in full compliance with manufacturer's Monthly the administrator and/or designee specifications. will audit the emergency generator battery 8.3.7.1 Maintenance of lead-acid batteries shall conductance testing and emergency include the monthly testing and recording of generator battery inspection logs to electrolyte specific gravity. Battery conductance ensure that the emergency generator testing shall be permitted in lieu of the testing of battery conductance testing was specific gravity when applicable or warranted. performed monthly and the emergency 8.4.1 * EPSSs, including all appurtenant generator battery inspection was components, shall be inspected weekly and performed weekly. The Administrator exercised under load at least monthly. and/or designee will report audit findings 8.4.9* Level 1 EPSS shall be tested at least once to the administrator and/or director of

	TATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULT A. BUILDI		CONSTRUCTION 2	(X3) DATE SURVEY COMPLETED	
		555838	B. WING _	B. WING			/08/2024
NAME OF PROVIDER OR SUPPLIER CAMDEN POSTACUTE CARE, INC		,	13	TREET ADDRESS, CITY, STATE, ZIP CODE 331 CAMDEN AVENUE AMPBELL, CA 95008			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	×	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 918	within every 36 month Findings: During document revi Maintenance Supervis testing records were r 1. At 1:26 a.m., the far required monthly eme conductance testing fr has a 7 kW gasoline pr interview, Maintenance stated it was done but documentation. 2. At 1:28 a.m., the far required weekly emer inspection for January Maintenance confirmed	ew and interview with the sor on 2/8/24, the generator requested and reviewed. cility failed to conduct the ergency generator battery or January 2024. The facility powered generator. Upon see confirmed the finding and	K	918	nursing in the daily stand-up meeting A findings will be immediately resolved. The administrator and/or designee will report their audit findings to the QAPI committee for further review and follow up. The QAPI committee will review the effectiveness of the plan monthly by measuring the number of same occurrences. The QAPI Committee will develop a Performance Improvement Plan for areas or issues identified as recurring or trending negatively and implement a new and more effective plof action. The QAPI committee will reassess the need for further monitoring quarterly. This Plan of Correction will be complete by 02/29/2024.	an g	