PRINTED: 12/29/2016 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/GLIA (DENTIFICATION NUMBER:	(X2) MULTII A. BUILDIN	1 60	E SURVEY IPLETED
		056300	8. WING		22/2016
7	PROVIDER OR SUPPLIER	& WELLNESS CENTER, LP		STREET ADDRESS, CITY, STATE, ZIP CODE 2885 HARRIS STREET, EUREKA, CA 95503	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PHEFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	COMPLETION DATE
K 000	STRUCTURE TYPE CONSTRUCTION, The following reflect Department of Publifier Safety Code refindings are in accordance of the Protection Assets Telegraphics (Protection Assets)	AL: 7/10/1973 ER: 2012 EXISTING E: ONE STORY, TYPE V (111) FULLY SPRINKLERED.  cts the findings of the California blic Health, during an annual ecertification survey. The ordance with 42 CFR (Code of is) 483.70 (a), NFPA (National sociation) 101, Life Safety Code NFPA 99 Health Care Facilities	K 00	Preparation, submission and/or execution of this plan of Correction does not constitute admission or agreement by the Provider of the truth of the facts alleged or conclusions set forth in this statement od deficiencies. The Plan of Correction is prepared submitted and/or executed solei because it is required by the provision of federal and state law.  CALISTY A DEPARTMENT OF PUBLIC HEALTMENT OF PUBLIC	
K 161 SS∞D	Health: Federal ID Numbe The facility is not in 42 CFR 483.70 (a) Census: 82 NFPA 101 Building Building Construct 2012 EXISTING Building construct Table 19.1.6.1, unl 19.1.6.2 through 1 19.1.6.4, 19.1.6.5  Constructi 1 I (442), I (3 stories	r substantial compliance with for Long Term Care Facilities.  Construction Type and Height ion Type and Height on type and stories meets ess otherwise permitted by 9.1.6.7		LIFE SAFETY CODE UNIT SAN BERNARDINO  K161 Maintenance Director repaired the two by three inches penetration in the Director of Nursing Office located in the bottom center area of the wall on December, 2016. Maintenance Director and Administrator will monitor walls and ceiling to ensure the integrity of the building construction. Results will be acted upon immediately. Any trends identified will be brought to the monthly Safety meeting.  Completion date:1/23/2017	1/23/2017

Any deficiency statement ending with an asterisk (\*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-98) Previous Versions Obsolete

Event ID: XOJE

Facility ID: CA010000024

If continuation sheet Page 1 of 24

119/17 - Por Acceptable Per Robert Compton

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDENSUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIF A. BUILDING	LE CONSTRUCTION 5 01	(X3) DATE SURVEY COMPLETED		
		056300	B, WING		12/22/2016	<b>6</b>	
	PROVIDER OR SUPPLIER A REHABILITATION	& WELLNESS CENTER, LP	STREET ADDRESS, CITY, STATE, ZIP CODE 2885 HARRIS STREET EUREKA, CA 95503				
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	BE COMPLE		
K 161	throughout by an a system in accordated 19.3.5) Give a brief description, the numbrasements, floors location of smoke approval. Completed plan of the building This STANDARD Based on observations in the integrit	One story  Maximum 3 stories  Not allowed  Maximum 2 stories  Not allowed  Maximum 1 story  must be sprinklered  upproved, supervised automatic nce with section 9.7. (See  ption, in REMARKS, of the umber of stories, including on which patients are located, or fire barriers and dates of e sketch or attach small floor	K 16	CALIFORNIA DEPARTMENT OF PUBL LICENSING & CERTIFICATION OF JAN 17 2017 LIFE SAFETY CODE UNIT SAN BERNARDINO	COGRAM		
	penetration. This a compartments, and	ffected one of four smoke d could result in the passage of eas in the event of a fire.					

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIP A. BUILDING	LE CONSTRUCTION	(X3) DATE COMP	OMPLETED	
	,	056300	B. WING	and the same of th	12/2	2/2016	
	PROVIDER OR SUPPLIER  DA REHABILITATION	& WELLNESS CENTER, LP	;	STREET ADDRESS, CITY, STATE, ZIP CODE 2895 HARRIS STREET EUREKA, CA 95503			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES  MUST BE PRECEDED BY FULL  SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPIDE DEFICIENCY)	D SE	(X5) COMPLETION DATE	
K 211 SS=D	During a tour of the the walls and ceilin At 11:45 a.m., the \ Nursing (DON) Off approximately two was located in the NFPA 101 Means of Egress - Aisles, passageway exit locations, and with Chapter 7, and continuously maintfull use in case of a 18/19.2.2 through 18.2.1, 19.2.1, 7.1. This STANDARD I Based on observationations in corridors maintain the means evidenced by obstrictions in corridors moke compartment delayed evacuation NFPA 101, Life Saf 19.2.1 General. Eviconidor, exit dischashall be in accordant otherwise modified 7.1.2 Definitions. 7.1.2.1 General. For Definitions. 3.3.170* Means of unobstructed way of the safe and the sa	refacility with staff on 12/22/16, gs were observed.  West Wall in the Director of one was observed. An object on center area of the wall, of Egress - General  General ys, corridors, exit discharges, accesses are in accordance if the means of egress is ained free of all obstructions to emergency, unless modified by 18/19,2.11.	K 211		the back The d to the ance nitor to Results y trends nthly	1/23/2017	

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDII		(X3) DATE SURVEY COMPLETED		
		056300	a, WING			12/	22/2016
	PROVIDER OR SUPPLIER  DA REHABILITATION	& WELLNESS CENTER, LP		281	REET ADDRESS, CITY, STATE, ZIP CODE 85 HARRIS STREET IREKA, CA 95503		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	<	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	) BE	(X5) COMPLETION DATE
K 211	access, (2) the exit  3.3.170.1 Accessible of egress that prove area of refuge, a high result of egress that prove area of refuge, a high result of the end of the end of the egress of the egress of the egress therefrom, the egress therefrom the egress therefrom, the egress therefrom the egress therefrom the egress therefrom, the egress therefrom the egress therefrom the egress the egress the egress the egress the egress th	distinct parts: (1) the exit it, and (3) the exit discharge.  It was an accessible route to an orizontal exit, or a public way.  It is gress shall be continuously all obstructions or instant use in the case of fire y.  It is and Decorations in Means of shings, decorations, or other act exits, access thereto, or visibility thereof.  Indicate the continuously all obstructions or other act exits, access thereto, or visibility thereof.  Indicate the continuously all obstructions of egress from an 48 in. (1220 mm) in clear g as means of egress from oms, unless otherwise following:  In an an adjunct areas a housing, treatment, or use of not less than 44 in. (1120 mm) tructed width.  In width is at least 6 ft (1830 as projections not more than 6 and be permitted.  In a room or suite of rooms requirements of 19.2.5 shall the required width shall be led equipment, provided that	K 2	111	CALIFORNIA DEPARTMENT OF PUBLIC LICENSOIG & CERTIFICATION TENOS JAN 17 2 2017 LIFE SAFETY CODE UNIT SAN BERNANDINO	BCALTH RVAN	
	permitted for wheel all of the following of	the required width shall be led equipment, provided that conditions are met: quipment does not reduce the					

STATEMENT	OF DEFICIENCIES	(X1) PROVIDER/BUPPLIER/CLIA	(X2) MULTIPLE CONSTRUCTION (X3)			(X3) DATE	SURVEY
	F CORRECTION	IDENTIFICATION NUMBER:	A. BUILD				PLETED
		056300	B. WING			12/2	22/2016
NAME OF I	PROVIDER OR SUPPLIER			' -	TREET ADDRESS, CITY, STATE, ZIP CODE		
GRANAD	A REHABILITATION	& WELLNESS CENTER, LP		ı	885 HARRIS STREET		
		A CONTRACTOR OF THE CONTRACTOR		E	UREKA, CA 95503		
(X4) ID PREFIX		ITEMENT OF DEFICIENCIES I MUST BE PRECEDED BY FULL	ID PREF	ΙX	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD		(X5) COMPLETION
TAG		SCIDENTIFYING INFORMATION)	TAG		CROSS-REFERENCED TO THE APPROP DEFICIENCY)		DATE
					DEFIDIENCY)		
K 211	Continued From pa	one 4	. بر	211	;		
11/4/11	clear unobstructed	uje 4	1	ZII.		,	
		ss than 60 in.(1525 mm).	ì				
		occupancy fire safety plan					
ĺ	and training	occupancy me salety plan				ı	
		ne relocation of the wheeled					
		i fire or similar emergency.	•				
İ		quipment is limited to the				i	
	following:		j				
l	i. Equipment in use						
		ncy equipment not in use					
		ansport equipment					
		idor width is at least 8 ft (2440	ĺ				
		to the required width shall be	1		,		
]	the following condi-	furniture, provided that all of					
		ure is securely attached to the					
1	floor or to the wall.	are is secondly attached to the	1				ĺ
		ure does not reduce the clear					
1		for width to less than 6 ft (1830					
İ	mm), except as pe	rmitted by 19.2.3.4(2).	1		Ĺ		ĺ
İ	(c) The fixed furniti	ure is located only on one side					İ
1	of the corridor.						
ĺ		ure is grouped such that each					
		exceed an area of 50 ft2 (4.6			PALIFORNIA DEPARTMENT OF PUBLIC H		}
	m2).	ura arausinas addragadia	ļ		LICENSING & CERTIFICATION PROGR	AM	
		ure groupings addressed in separated from each other by a	1				
		: 10 ft (3050 mm).					
	(f)*The fixed furnit	ire is located so as to not	1		JAN 3 7 1217		
		building service and fire	(				
	protection equipme		1		1157 0157		ĺ
	(g) Corridors through	ghout the smoke compartment			LIFE SAFETY CODE UNIT		
1		electrically supervised			SAN BERNARDINO		
i	automatic smoke o	letection system in accordance			1		
1		fixed furniture spaces are					
l		ed to allow direct supervision	1				
		from a nurses 'station or			[		
	similar space.	granden and la super-start					
į.	TOD THE SHICKE CON	rpartment is protected			I		l l

<u> </u>		X MEDIONID CENTRICE		_		A1177 LA 675 -	0000 0001
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		CONSTRUCTION	(X3) DATE SURVEY COMPLETED	
		056300	B. WING		il to the second	12/2	22/2016
NAME OF F	ROVIDER OR SUPPLIER				REET ADDRESS, CITY, STATE, ZIP CODE		
GRANAD	A REHABILITATION	& WELLNESS CENTER, LP	,		UREKA, CA 95503		
(X4) iD PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECÉDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	×	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	BE	(%) COMPLETION DATE
K 211	throughout by an a	ge 5 pproved, supervised automatic accordance with 19.3.5.8.	Κź	211			
		facility with staff on 12/22/16, s was observed.					
	by Laundry was ob- measured 8 feet. O (ABHR) dispenser side of the corridor unsecured to either dispenser stand pro- inches into the corr width reduced to as inches. Smoke alai	e Back Exit Corridor, directly served. The corridor width one alcohol based hand rub stand, was stationed on one in front of the handrail, the floor or wall. The ABHR ojected approximately 17 idor, with the corridor clear oppoximately six feet seven rms were installed in the dispenser was not in an area rision.					
K 324 SS=D	Director of Nursing The corridor width a wooden storage ca side of the corridor unsecured to either projected approximation dis- with the corridor dis- approximately eight	e Exit Corridor, directly by (DON) Office was observed. measured 10 feet. One binet was stationed on one in front of the handrail, the floor or wall. The cabinet sately two feet into the corridor, ear width reduced to t feet. The cabinet was in an upervision of office staff.	Ks	324	CALIFORNIA DEPARTMENT OF PUBLIC II LICENSING & CERTIFICATION PROGR  JAN 1 / J17  LIFE SAFETY CODE UNIT SAIL BERNARDINO		
55=0	with NFPA 96, Stan	t is protected in accordance dard for Ventilation Control of Commercial Cooking					

	TO TOT INCIDIONALE	A MEDICAID SERVICES				Air inc.	<u> </u>
	T OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01			(X3) DATE SURVEY COMPLETED	
		056300	B. WING			12/2	2/2016
	PROVIDER OR SUPPLIER  DA REHABILITATION	& Wellness Center, LP		2	FREET ADDRESS, CITY, STATE, ZIP CODE 985 HARRIS STREET UREKA, CA 95503		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC (DENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(XS) COMPLETION DATE
K 324	Operations, unless * residential cookin appliances such as toasters) are used cooking in accorda * cooking facilities compartments with with the conditions or * cooking facilities 30 or fewer patient 18.3.2.5.4, 19.3.2.5 Cooking facilities p per 9.2.3 are not re hazardous areas, t corridor.	ig equipment (i.e., small is microwaves, hot plates, for food warming or limited ince with 18.3.2.5.2, 19.3.2.5.2 open to the corridor in smoke is 30 or fewer patients comply under 18.3.2.5.3, 19.3.2.5.3, in smoke compartments with a comply with conditions under 5.4. In ordected according to NFPA 96 equired to be enclosed as put shall not be open to the	K	324	K 324 Maintenance Director ordered identification sign that the fire protect system shall be activated prior to using fire extinguisher in the dietary cook? The Maintenance Director will equip Ansul hood fire suppression system identification sign when receive. Administrator will ensure the work is completed. Maintenance Director at Administrator will monitor to ensure are no issues with the sign. Results acted upon immediately. Any trends identified will be brought to the more Safety Committee.  Completion date: 1/23/2017	etion ing the ing area. of the with the s ind ethere will be	1/23/2017
	Based on observa maintain the kitche This was evidence located with the K-This affected one cand could result in grease fire in the d NFPA 101. Life Sai 19.3.2.5 Cooking F 19.3.2.5.1 Cooking accordance with 9.9.2.3 Commercial cooking accordance with N	fety Code, 2012 Edition facilities.			CALIFORNIA DEPARTMENT OF PUBLIC LICENSING & GEREFICATION PROS JAN 1 1 2017 LIFE SAFETY CODE UNIT SAN BERNARDINO	HEALTH BRAW	-

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDI		E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED	
		056300	B, WING			12/2	2/2016
,	PROVIDER OR SUPPLIER	& WELLNESS CENTER, LP		28	TREET ADDRESS, CITY, STATE, ZIP CODE 885 HARRIS STREET UREKA, CA 95503.	· · · · · · · · · · · · · · · · · · ·	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES / MUST BE PRÉCEDED BY FULL SC IDENTIFYING INFORMATION)	PREFI TAG	x	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	SE	(75) COMPLETION DATE
K 324	Commercial Cookir installations are ap	ge 7 ng Operations, unless such proved existing installations, nitted to be continued in	K 3	24			
	Fire Protection of C Operations, 2011 E 10.2 Types of Equip 10.2.1 Fire-extingu- both automatic fire-extinguishing st and portable fire extinguis 10.2.2* A placard s near each extinguis that states that the activated prior to us 10.2.2.1 The languis placard shall be	oment. shing equipment shall include ystems as primary protection uishers as secondary backup. hall be conspicuously placed					
	Findings: During a facility tou	r with staff on 12/22/16, the			CALIFORNIA DEPARTMENT OF PUBLIC		
	observed.  At 11:32 a.m., the E equipped with an Ar system, and K-Clas No sign was posted K-Class extinguishes suppression system prior to using the firm	Dietary Cooking Area was used hood fire suppression is portable back-extinguisher, it along with the portable are to indicate the fire a should be activated first, a extinguisher.			JAN 1 1 1 17  LIFE SAFETY CODE UNIT  SAN BERNARDINO	FkAw!	
K 325 SS=D	NFPA101 Alcohol (ABHR)	Based Hand Rub Dispenser	KЗ	25			

TATEMENT	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01			(X3) DATE SURVEY COMPLETED	
		056300	B. WING			12/2	22/2016
	A REHABILITATION	& WELLNESS CENTER, LP		28	TREET AODRESS, CITY, STATE, ZIP CODE 385 HARRIS STREET UREKA, CA 95503	And the second s	
(X4) ID PREFIX TAG	(EACH DEFICIENC	TEMENT OF DEFICIENCIES  MUST BE PRECEDED BY FULL  SCIDENTIFYING INFORMATION)	PREFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 325	ABHRs are protect unless all condition * Corridor is at leas * Maximum individe gallons (0.59 gallor ounces of Level 1 a * Dispensers shall horizontal spacing * Not more than an fluid or 135 ounces smoke compartme excluding one indiv * Storage in a single than 5 gallons com * Dispensers are mignition source * Dispensers are mignition source * Dispensers over 6 sprinklered smoke * ABHR does not 6 * Operation of the 6 Section 18.3.2.6(11 * ABHR is protecte 18.3.2.6, 19.3.2.6, 482, 483; and 485 This STANDARD in Based on observatinterview, the facility based hand rub (All evidenced by the all testing for dispense four of four smoke	d Rub Dispenser (ABHR) ad in accordance with 8.7.3.1, s are met: t 6 feet wide val dispenser capacity is 0.32 us in suites) of fluid and 18 derosols have a minimum of 4-foot aggregate of 10 gallons of aerosol are used in a single nt outside a storage cabinet, idual dispenser per room e smoke compartment greater plies with NFPA 30 of installed within 1 inch of an carpeted floors are in compartments exceed 95 percent alcohol fispenser shall comply with	K	325	K 325 Housekeeping staff was in sent to maintain the alcohol based hand-ru dispensers using the new QA form. T QA form was implemented to inspect test the dispenser when refills were in to meet the new regulation. The Main Director, and/or Housekeeping Super will monitor staff for effectiveness of training. Results will be acted upon immediately. Any trends identified w brought to the monthly Safety Committee Completion date: 1/23/2017  CALIFORNIA DEPARTMENT OF PUBLIC LICENSING & GERRISIDATION 25000 JAN 17 2017  LIFE SAFETY CODE UNIT	b The new and stalled tenance visor facility vill be ittee.	1/23/201
	NFPA 101. Life Saf 19.3.2.6Alcohol-Ba Alcohol-based hand	ety Code, 2012 Edition sed Hand-Rub Dispensers. I-rub dispensers shall be ance with 8.7.3.1, unless all of			SAN BERNARDINO		

C2 104 1 1 144	THE PARTY OF THE P						
	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		CONSTRUCTION		SURVEY
		056300	a. WING			12/2	22/2016
NAME OF	PROVIDER OR SUPPLIER			ST	REET ADDRESS, CITY, STATE, ZIP CODE		
CDANAL	A REHABILITATION :	& WELLNESS CENTER, LP			85 HARRIS STREET		
GRAMAL	Anchabichanon	X III ELINCOO VEIVIEN, EI		E	JREKA, CA 95503		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	BE	(X5) COMPLETION DATE
K 325	(1)Where dispense the corridor shall had (1830 mm). (2)The maximum in capacity shall be as (a)0.32 gal (1.2 L) corridors, and area (b)0.53 gal (2.0 L) rooms (3)Where aerosol of maximum capacity be 18 oz. (0.51 kg) aerosols as defined Manufacture and S (4)Dispensers shall by horizontal spacimm). (5)Not more than a alcohol-based hand kg) of Level 1 aero flquids and Level 1 total, the equivalen (32.2 kg), shall be cabinet in a single as otherwise provid (6) One dispenser (3) per room and lo included in the agg 19.3.2.6(5). (7)Storage of quant L) in a single smok requirements of NF Combustible Liquid (8)Dispensers shall following locations: (a)Above an ignitio horizontal distance source	ers are installed in a corridor, ave a minimum width of 6 ft andividual dispenser fluid is follows: for dispensers in rooms, as open to corridors for dispensers in suites of containers are used, the containers are used, the containers are used, the containers are used, the containers are used, the containers are used, the containers are used, the containers are used, the containers are used, the containers are used, the containers are used, the containers are used, the corage of Aerosol Products. If the separated from each other and of not less than 48 in. (1220 in aggregate 10 gai (37.8 L) of drub solution or 1135 oz (32.2 sols, or a combination of aerosols not to exceed, in it of 10 gai (37.8 L) or 1195 oz in use outside of a storage smoke compartment, except died in 19.3.2.6(6) complying with 19.3.2.6 (2) or coated in that room shall not be regated quantity addressed in titles greater than 5 gal (18.9 in compartment shall meet the FPA 30, Flammable and its Code.	K	325	CALIFORNIA DEPARTMENT OF PUBLIC LICENSING & CERTIFICATION, PROD JAN 17 1817 LIFE SAFETY CODE UNIT SAN BERNARDINO	PHEALTH GRAW	

NAME OF PROVIDER OR BUPPLIER  GRANADA REHABILITATION & WELLNESS CENTER, LP.  SUMMAY STATEMENT OF DEPOCACIONS  SUMMAY STATEMENT OF DEPOCACIONS  RESULTATION ON LIST ON LIST OF DEPOCACIONS  RESULTATION ON LIST ON		OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01				(X3) DATE SURVEY COMPLETED	
GRANADA REHABILITATION & WELLNESS CENTER, LP  SUMMARY STATEMENT OF DEPICIENCY, LP  RESULATORY OR ISO CONTRY WIST BE PRECEDED BY FULL RESULATORY OR ISO CONTRY WIST BY FULL RESULATORY OR ISO CONTRY WIST BE PRECEDED BY FULL RESULATORY OR ISO CONTRY WIST BE PRECEDED BY FULL RESULATORY OR ISO CONTRY WIST BE PRECEDED BY FULL RESULATORY OR ISO CONTRY WIST BE PRECEDED BY FULL RESULATORY OR ISO CONTRY WIST BE PRECEDED BY FULL RESULATORY OR ISO CONTRY WIST BE PRECEDED BY FULL RESULATORY OR ISO CONTRY WIST BE PRECEDED BY FULL RESULATORY OR ISO CONTRY WIST BE PRECEDED BY FULL RESULT OF CONTRY WIST BE PRECEDED BY FULL RESULT OF CONTRY WIST BE PRECEDED BY FULL RESULT OF CONTRY WIST BE PRECEDED BY FULL RESULT OF CONTRY WIST BE PRECEDED BY FULL RESULT OF CONTRY WIST BE PRECEDED BY FULL RESULT OF CONTRY WIST BY FULL RESULT OF CONTRY WIST BE RESULT OF CONTRY WIST BY FULL RESULT OF CONTRY WIST BE RESUL			056300	B. WING			12/2	22/2016	
FREST TAG RESULATORY OR LSC IDENTIFYING INFORMATION)  K 325  Continued From page 10 (Z5 mm) horizontal distance from the ignition source (c) Beneath an ignition source within a 1 in. (25 mm) vortical distance from the ignition source (9) Dispensers installed directly over carpeted floors shall be permitted only in sprinklered smoke compartments. (10) The allochol-based hand-rub solution shall not exceed 95 percent alcohol content by volume. (11) Operation of the dispenser shall comply with the following criteria: (a) The dispenser shall not release its contents except when the dispenser is activated, either manually or automatically by touch-free activation. (b) Any activation of the dispenser shall occur only when an object is placed within 4 in. (100 mm) of the sensing device. (c) An object placed within the activation zone and left in place shall not dispense more solution than the amount required for hand hygiene consistent with label instructions. (s) The dispenser shall be designed, constructed, and operated in a manner that ensures that accidental or malicious activation of the dispensing device is minimized. (f) The dispenser shall be tested in accordance with the manufacturer's care and use instructions each time a new refill is installed. 8.7.3.1 The storage and handling of flammable liquids or gases shall be in accordance with the following applicable standards: (f) NFPA 50 (1), Flammable and Combustible Liquids Code (g) NFPA 50, National Fuel Gas Code					288	S HARRIS STREET			
(25 mm) horizontal distance from the ignition source (c)Beneath an ignition source (d)Beneath an ignition source within a 1 in. (25 mm) vertical distance from the Ignition source (9) Dispensers installed directly over carpeted floors shall be permitted only in sprinklered smoke compartments.  (10) The alcohol-based hand-rub solution shall not exceed 95 percent atcohol content by volume.  (11) Operation of the dispenser shall comply with the following or piceria:  (a) The dispenser shall not release its contents except when the dispenser is activated, either manually or automatically by touch-free activation.  (b) Any activation of the dispenser shall occur only when an object is placed within 4 in. (100 mm) of the sensing device.  (c) An object placed within the activation zone and left in place shall not cause more than one activation.  (d) The dispenser shall be designed, constructed, and operated in a manner that ensures that accidental or malicious activation of the dispensing device is minimized.  (f) The dispenser shall be tested in accordance with the manufacturer 's care and use instructions each time a new refill is installed.  8.7.3.1 The storage and handling of flammable liquids or gases shall be in accordance with the following applicable standards:  (1) NFPA 30(1), Flammable and Combustible Liquids Code  (2) NFPA 54, National Fuel Gas Code	PREFIX	X (EACH DEFICIENCY MUST BE PRECEDED BY FULL PRE				(EACH CORRECTIVE ACTION SHOW CROSS-REFERENCED TO THE APPR			
	K 325	(25 mm) horizontal source (c) Beneath an ign mm) vertical distal (9) Dispensers instal floors shall be persmoke compartmed (10) The alcohol-bexceed 95 percend (11) Operation of the following criterial (a) The dispenser except when the comanually or automactivation. (b) Any activation when an object is the sensing device (c) An object place left in place shall in activation. (d) The dispenser solution than the anactivation operated in a accidental or mall dispensing device (f) The dispenser swith the manufact instructions each instructions each instructions each instructions applicabed (1) NFPA 30(1), Fuguids Code (2) NFPA 54, National part in the sensitive code (2) NFPA 54, National code (2) NFPA 54, National code (2) NFPA 54, National code (2) NFPA 54, National code (2) NFPA 54, National code (2) NFPA 54, National code (2) NFPA 54, National code (2) NFPA 54, National code (3) NFPA 54, National code (4) NFPA 54, National code (5) NFPA 54, National code (6) NFPA 54, National code (7) NFPA 54, National code	Ition source within a 1 in. (25 ince from the ignition source stalled directly over carpeted mitted only in sprinklered ents. ased hand-rub solution shall not it alcohol content by volume, the dispenser shall comply with ria: shall not release its contents dispenser is activated, either natically by touch-free of the dispenser shall occur only placed within 4 in. (100 mm) of e. of within the activation zone and not cause more than one shall not dispense more amount required for hand it with label instructions, shall be designed, constructed, manner that ensures that clous activation of the is minimized. Is minimized, when a new refill is installed, we and handling of flammable thall be in accordance with the le standards: lammable and Combustible onal Fuel Gas Code	K	325	LICENSHIS & CERTIFICATION  JAN 1 7 2017  LIFE SAFETY CODE UN	PROGRAM		

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENT:FICATION NUMBER:	(X2) MULTIPI A, BUILDING	E CONSTRUCTION 01	(X3) DATE COME	SUAVEY LETED
		056300	B. WING	NAME OF THE PARTY	12/2	2/2016
	PROVIDER OR SUPPLIER  DA REHABILITATION	& WELLNESS CENTER, LP	2	TREET ADDRESS, CITY, STATE, ZIP CODE 1885 HARRIS STREET EUREKA, CA 95503		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES I MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	SE	(X5) COMPLETION DATE
K 355 SS=D	During observation review with staff on dispensers were of requested.  At 10:50 a.m., the fabric and corridors. No had been performed on were installed. Staff stated "they were used testing require refilling."  NFPA 101 Portable Portable Fire Exting inspected, and main NFPA 10, Standard Extinguishers.  18.3.5.12, 19.3.5.1  This STANDARD is Based on observal maintain the portable evidenced by a fire view and access. To compartments, and staff to readily acceevent of a fire.  NFPA 101 Life Saff 19.3.5.12 Portable provided in all health care occupal 9.7.4.1.	interview, and document 12/22/16, the refillable ABHR deserved and documentation racility was observed with ocated throughout the facility respection and/or testing had the units when new refills if 3 confirmed this finding and reware of the new inspection ments for ABHR dispensers for instance in accordance with if or Portable Fire  2, NFPA 10 s not met as evidenced by: tion, the facility failed to alle fire extinguishers. This was extinguisher obstructed from this affected one of four smoke if could result in the inability of east the fire extinguisher in the eaty Code, 2012 edition fire extinguishers shall be uncles in accordance with	K 325	K 355 Dietary staff was in-serviced December 12, 2016 on the importance blocking the portable K – class fire extinguisher located in Dietary by a ficart. The Maintenance Director and E Supervisor will monitor staff for effectiveness of facility training. Resulted be acted upon immediately. Any trest identified will be brought to the mont Safety Committee.  Completion date: 1/23/2017  CALIFORNIA DEPARTMENT OF PUBLIC LICENSING & CERTIFICATION PROCESSING ood Dietary ults will ids thly	1/23/2017	
	9.7.4.1* Where req	uired by the provisions of		SAN BERNARDINO		

<u>OLIVILI</u>	IO LOUI MEDIONIE	O MEDIONID GENVIOLO			(167 : 167 , 1	1000-0031
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPL A. BUILDING	(X3) DATE SURVEY COMPLETED		
		056300	B. WING		12/22/2016	
	PROVIDER OR SUPPLIER	& WELLNESS CENTER, LP	. S 2. . E	1 12 / 22		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	BE	(XG) COMPLETION DATE
K 355	Continued From position of this Code, portal selected, Installed, inspected, and man NFPA 10, Standard Extinguishers.  NFPA 10, Standard Extinguishers, 2016.1.3.3 Visual Obs 6.1.3.3.1 Fire extinobstructed or observated or observated or observated or observated or observated from view.  Findings:  During a tour of the extinguisher located from view and acceptinguisher was lead to the extinguisher was lead to the extingu	age 12  ble fire extinguishers shall be intained in accordance with a for Portable Fire  d for Portable Fire 0, edition. tructions. guishers shall not be ured  e facility with staff on 12/22/16, tinguishers were observed.  portable K-class fire and in Dietary, was obstructed ess by a food cart. The ocated only after asking a location.	K 355	DEFICIENCY)	iately if be y when ance tor the ing.	
	passage of smoke means suitable for	Doors shall be provided with a keeping the door closed. ment to the closing of the		Completion date: 1/23/2017		<b>1/23</b> /2017

### DEPARTMENT OF HEALTH AND HUMAN SERVICES

CENTER	13 FOR MEDICARE	& MEDICAID SERVICES				IVED IVED.	0999-0991
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		E CONSTRUCTION .	(X3) DATE SURVEY COMPLETED	
		056300	B. WING			12/2	2/2016
NAME OF F	ROVIDER OR SUPPLIER			\$	TREET ADDRESS, CITY, STATE, ZIP CODE		
CEANAD	A REPARKITATION	& WELLNESS CENTER, LP	j	2	995 HARRIS STREET	•	
CHIPAINA	ייָיסויאָרוישוטרוושון אין	a weekless selven, ar		_ E	UREKA, CA 95503		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES  Y MUST BE PRECEDED BY FULL  SCIDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULE CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
K 363	doors. Clearance be floor covering is not latches are prohibit corridor doors and or combustible mat complying with 7.2, devices that releast pulled are permitted of unlimited height meeting 19.3.6.3.6. Door frames shall the smoke company window assemblies sprinklered company restrictions in area frames in window assemblies sprinklered company restrictions in area frames in window as 19.3.6.3, 42 CFR Fland 485. Show in REMARKS protection ratings, and the smoke and seed on observational maintain the doors corridor door obstructions. This affect compartments, and contain smoke and NFPA 101, Life Saf 19.3.6.3.10* Doors devices other than door is pushed or prindings:	etween bottom of door and texceeding 1 inch. Roller red by CMS regulations on rooms containing flammable terials. Powered doors 1.9 are permissible. Hold open e when the door is pushed or d. Nonrated protective plates are permitted. Dutch doors are permitted. Dutch doors are permitted. Dutch doors are permitted. The labeled and made of steel in compliance with 8.3, unless than is sprinklered. Fixed fire is are allowed per 8.3. In the intensistence of glass or is semblies. Parts 403, 418, 460, 482, 483, and details of doors such as fire automatics closing devices, is not met as evidenced by a licted from closing and ted one of four smoke if could result in the Inability to for fire to a room.  The code, 2012 Edition shall not be held open by those that release when the	К.	363	CALIFORNIA DEPARTMENT OF PUBLICIONSING & CERTIFICATION PRO JAN T. 1.717 LIFE SAFETY CODE UNIT SAN BERNARDINO		
	the doors were obs	erved.					

	STEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		A. BUILDII (X2) MULT	(X3) DATE SURVEY COMPLETED	
		056300	B. WING		12/22/2016
	PROVIDER OR SUPPLIER  DA REHABILITATION	& WELLNESS CENTER, LP		STREET ADDRESS, CITY, STATE, ZIP CODE 2965 HARRIS STREET EUREKA, CA 95503	The second secon
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI ( (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE COMPLÉTION
K 363	At 11:35 a.m., the of Room was observe with a self-closing open, obstructed fr floor-standing trastroom at the time.	corridor door to the Class ad. The door was equipped device. The door was held om closing and latching by a barrel. No staff were in the	K3		Section
K 918 SS=D	Electrical Systems Maintenance and I The generator or o and associated equivalences within 10 statements of the process shall be process shall be process shall be process shall be process shall be process shall be process shall be process shall be process shall be process shall be process shall be processed in the statement of	- Essential Electric System esting ther alternate power source lipment is capable of supplying econds. If the 10-second during the monthly test, a ovided to annually confirm this esting of the generator and re performed in accordance inspected weekly, exercised ites 12 times a year in 20-40 exercised once every 36 euous hours. Scheduled test ins include a complete it and automatic or manual loads, and are conducted by iel. Maintenance and testing of er sources (Type 3 EES) are in EPA 111. Main and feeder inspected annually, and a cally exercising the solished according to rements. Written records of esting are maintained and ES electrical panels and and readily identifiable.	K9	K 918 In accordance NFPA 110, 8-4, Emergency power system (To Generator and Transfer Switch) shi inspected weekly and exercised unavailable load every other week. Temporary generator and existing switch, as installed, have been according to the temporary EPS for this facility OSHPD under #S153014-12-00-B expiration date 9/30/2017.  The Administrator submitted a war December 9, 2016, requesting a 12 waiver extension because we are a complete this project within the time. Attached to the POC is the invoice generator testing.  Completion date: 1/23/2017  CALIFORMIA DEPARTMENT OF PLOUDINGENSING & CERCIFICATION PLOUDI	emporary all be der full  transfer epted as by T01  iver, on 2 month mable to me frame.  for the

<u> </u>		24 141 22 22 1451 11 22 23 1451 11 25 25 1451 11 25 25 1451 11 25 25 1451 11 25 25 1451 11 25 25 1451 11 25 25					
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUE A. BUILD		ECCNSTRUCTION 11	(X3) DATE SURVEY COMPLETED	
		056300	B, WING			12/2	22/2016
	ROVIDER OR SUPPLIER	& WELLNESS CENTER, LP		28	REET ADDRESS, CITY, STATE, ZIP GODE 885 HARRIS STREET UREKA, CA 95503		
(X4) ID PREFIX TAG	. (EACH DEFICIENC)	TEMENT OF DEFICIENCIES  Y MUST BE PRECEDED BY FULL  SC IDENTIFYING INFORMATION)	ID PREFIX TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPRIED DEFICIENCY)	BE	(X5) COMPLETION DATE
K 918	emergency power sconsideration for no consideration for no 6.4.4, 6.5.4, 6.6.4 (111, 700.10 (NFPA This STANDARD is Based on observa Interview, the facilities are gency power sevidenced by the fapermanent EPS in 2010 Edition, and presting on a tempor four smoke compalloss of power due to during an emergent NFPA 101 Life Safe 19.5.1 Utilities, Utiliprovisions of section 9.1 9.1.3.1 Emergency power systems shall maintained in acco Standard for Emerg Systems.  NFPA 99, Health C Edition. 6.4.4.1.1.4 Inspectic conditions, and per requirements shall 6.4.4.1.1.4(A) through 6.4.4.1.1.4 (A)* Test Criteria. Conditions a	sibility of damage of the source is a design ew installations.  NFPA 99), NFPA 110, NFPA 70) is not met as evidenced by: tion, document review, and y falled to maintain the system (EPS). This was allure to install and provide a accordance with NFPA 110, perform minimal required load rary EPS. This affected four of riments, and could result in a to a generator malfunction cy power outage.  Ety Code, 2012 edition ties shall comply with the en 9.1 all comply with the provisions.  Generators and standby all be installed, tested, and ridance with NFPA 110, gency and Standby Power are Facilities Code, 2012 on and Testing. Criteria, sonnel be in accordance with (C). Senerator sets shall be tested	K	918	CALIFORNIA DEPARTMENT OF POLY LICENSING A CERTIFICATION  JAN 1 1 107  LIFE SAFETY CODE UNIT SAN BERNARDINO	อนิเลย์	i i
	year, with testing in days nor more	tervals of not less than 20					

		& MEDICAID SERVICES			The state of the s	7112	<u> </u>	
	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA (DENTIFICATION NUMBER:	(X2) MUL A BUILD		CONSTRUCTION	(X3) DATE COME	SURVEY LETED	
		056300	e, wing			12/22/2016		
NAME OF	PROVIDER OR SUPPLIER			STF	EET ADDRESS, CITY, STATE, ZIP CODE	i de la companya de l		
				288	5 HARRIS STREET			
GRANAI	DA REHABILITATION	& WELLNESS CENTER, LP		EU	REKA, CA 95503			
(X4) ID PREFIX TAG	(EACH DEFIGIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC (DENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION SHOULD CROSS-REFERENCED TO THE APPRODEFICIENCY)	DBE	(X5) COMPLETION DATE	
K 918	than 40 days. Gene electrical systems shall be tested in a Standard for Emery and Standby Powe (B) Test Conditions load conditions shall include a comappropriate automatic and mare electrical system loads. (C) Test Personnel conducted by competent personand, in addition, semalfunction and to train person NFPA 110, Standal Power Systems, 204.4.2* Level 2 systems fallure of the EPSS to perform is safety. 4.4.3 All equipment installed. 7.4 Mounting. 7.4.1 Rotating enerinstalled on solid foundations to profor lubricating oil piping and damage at joints. 7.4.1.1 Such found raise the	coordance with NFPA 110, gency r Systems, Chapter B. The scheduled test under replete simulated cold start and rual transfer of all essential.  The scheduled tests shall be connel to keep the machines rive to detect causes of mel in operating procedures, rd for Emergency and Standby		918	CALIFORNIA DEPARTMENT OF PUS LICENSING S CERTIFICATION OF JAN 1 117	.dunan		

Contract Prof.	101 OTT MEDION IL	C III. C III. C III.	<u> </u>				
	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILD		E CONSTRUCTION 01	(X3) DATE SURVEY COMPLETED	
		056300	B. WING			12/2	22/2016
NAME OF	PROVIDER OR SUPPLIER			{	TREET ADDRESS, CITY, STATE, ZIP CODE		
GRANAD	A REHABILITATION	& WELLNESS CENTER, LP		! -	985 Harris Street Jureka, ca 95503		
()(1) (0)	SI MUADV STA	ATEMENT OF DEFICIENCIES	10		PROVIDER'S PLAN OF CORRECTIO	NI I	5.00
(X4) ID PREFIX TAG	(ÉACH DÉFICIENC)	Y MUST BE PRECEDED BY FULL SCIDENTIFYING INFORMATION)	PREF TAG		(EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(XS) COMPLETION CATE
K 918	Continued From pa	age 17	· K	918			
}		-	'`'	- 10			
1	lubricating-oil drain		1				
1	and ease of mainte		1				
1		shall be of the size (mass) and					
1	type recommended		!			-	
1	by the energy conv	erter manufacturer.					ĺ
	7.4.3 Where requir	ed to prevent transmission of					
	vibration during						
		dation shall be isolated from					
	the surrounding						
1		lations, or both, in accordance					
	with						
1		s recommendations and	!				
)	accepted structural		ľ				
	engineering practic		1			ļ	
}						1	l
		Il be mounted on a fabricated					
1	metal skid				'	ſ	}
	shipping and	at shall resist damage during					
i		allation, the base shall	İ				
	maintain alignment						
1	of the unit during o	peration.				i	
1	7.5* Vibration. Vibra	ation isolators, as	}				)
	recommended by t						]
		EPS, shall be installed either				1	1
	between the	•	ĺ		,		!
	rotating aquipment	and its skid base or between			CALIFORNIA DEPARTMENT OF PUBL.	المروجية وا	
	the skid base		!		1		
1	and the foundation	or inertia base.	ĺ		LICENSING & CERTIFICATION TO	Jan Wilei	
		edule for routine maintenance					
		ting of the EPSS shall be				-	ĺ
1	established.	A STATE OF LINES			JAN 1 7 47	1	[
1		record of the EPSS					
]		exercising, operation, and				i	i
	ranaire chall ha ma	intelled and seedily evelleble			LIFE SAFETY CODE UNIT		
		intained and readily available.	ĺ				
	a.s.4.1 the permar	nent record shall include the			SAN BERNARDINO		
	Tollowing: (1) he da	ate of the maintenance report					
	(2)Identification of t	the servicing personnel			·	j	[
	(3)Notation of any t	insatisfactory condition and				Ì	
	the corrective actio	n taken, including parts				j	

	19 LOUGHT MICHIONIE	& MEDICAID SERVICES			CIMIR NO.	0900-0091		
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CUA IDENTIFICATION NUMBER:	(X2) MULTI A, BUILDIN	PLE CONSTRUCTION IG 01	(X3) DATE COMP	(X3) DATE SURVEY COMPLETED		
		056300	B, WING_		12/2	2/2016		
		& WELLNESS CENTER, LP	STREET ADDRESS, CITY, STATE, ZIP CODE 2885 HARRIS STREET EUREKA, CA 95503					
(X4) ID PREFIX TAG	(EACH DEFICIENC)	Y MUST BE PRECEDED BY FULL	F BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE A		DULD BE	(X5) COMPLETION DATE		
K 918	PROVIDER OR SUPPLIER  DA REHABILITATION & WELLINESS CENTER, LP  SUMMARY STATEMENT OF DEFICIENCIES  (EACH DEFICIENCY MUST BE PRECEDED BY FULL  REGULATORY OR LSC IDENTIFYING INFORMATION)		K 91	CALIFORNIA DEPARTMENT OF PLICENSING & CERTIFICATION  JAN 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Hudthald /			
			<u> </u>					

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENT/FICATION NUMBER:	(X2) MULT A. BUILDI	(XS) DATE SURVEY COMPLETED	
	-	056300	B. WING		12/22/2016
	PROVIDER OR SUPPLIER  PAREHABILITATION	& WELLNESS CENTER, LP		STREET ADDRESS, CITY, STATE, ZIP CODE 2885 HARRIS STREET EUREKA, CA 96503	
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES  Y MUST BE PRECEDED BY FULL  SC IDENTIFYING INFORMATION)	ID PREFI) TAG	PREFIX (EACH CORRECTIVE ACTION SHOULD BE	
K 918	During a facility tou	r, document review, and on 12/22/16, the EPS was	К9	818	
	temporary trailer m with seismle bracin building by Laundry installed under Offil Planning and Deve \$153014-12-00-BP expiration date 9/30 OSHPD documents that indicated a per issued on 10/28/16 EPS, with expiratio Indicated in an Inter 12/9/16, they reque extension, and are receiving bids, and project will start. No at the time of surve	facility was observed with a cunted 13 kilowatt diesel EPS, g, located outside behind the v. The temporary EPS was ce of Statewide Health lopment (OSHPD) permit # 2T01, Issued 11/24/15, 0/2017. The facility submitted ation titled "Building Permit" mit BP # S161020-12-00 was for installation of a permanent in date 9/30/2017. Staff 1 rview at the time that on ested a 12 month waiver now in the process of once the bid is accepted the courrent waiver was in place by. No current signed contract ring and installation was			
K 923 88=D	testing did not indic nameplate kilowatt temporary diesel Ei dated 11/21/16, was at 60 minutes, not 1 3 confirmed the find stating "he thought and would fax the r 9:00 a.m." No fax w	eview of bi-monthly load sate 30 percent of the rating was achieved for the PS. Annual load bank testing is performed per run flow sheet the required 90 minutes." Staff ding in an interview at the time it was done for 90 minutes, eport if available by 12/2716 at as received.	К9	CALIFORNIA DEPARTMENT OF PUBLICENSING & CERTIFICATION OF JAN 12 227  LIFE SAFETY CODE UNIT SAN BERNARDINO	CHEALTH DGRAM

	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION  A. BUILDING 01				(X3) DATE SURVEY COMPLETED	
		056300	B. WING			12/2	2/2016	
	PROVIDER OR SUPPLIER  OA REHABILITATION	& WELLNESS CENTER, LP		28	TREET ADDRESS, CITY, STATE, ZIP CODE 185 HARRIS STREET UREKA, CA 95503			
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES  Y MUST BE PRECEDED BY FULL  SC   DENTIFYING INFORMATION)	ID PAEFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	) <b>B</b> E	COMPLETION DATE	
K 923	Gas Equipment - O Greater than or eq Storage locations a ventilated in accord 5.1.3.3.3. >300 but <3,000 ct Storage locations a within an enclosed limited- combustible gates outdoors) tha gases are not stora separated from con sprinklered) or enc noncombustible con 1/2 hr. fire protection Less than or equal in a single smoke of cylinders available care areas with an or equal to 300 cut stored in an enclos handled with preca A precautionary sig each door or gate of where the sign incl minimum "CAUTIC STORED WITHIN Storage is planned of which they are re Empty cylinders ar cylinders. When fa integral pressure g considered empty are marked to avoi in the open are pro 11.3.1, 11.3.2, 11.3 This STANDARD Based on observa	bylinder and Container Storage that to 3,000 cubic feet are designed, constructed, and dance with 5.1.3.3.2 and libic feet are outdoors in an enclosure or interior space of non- or e construction, with door (or at can be secured. Oxidizing ad with flammables, and are inbustibles by 20 feet (5 feet if losed in a cabinet of instruction having a minimum on rating. to 300 cubic feet compartment, individual for immediate use in patient aggregate volume of less than bic feet are not required to be sure. Cylinders must be utlons as specified in 11.6.2. In readable from 5 feet is on of a cylinder storage room, udes the wording as a DN: OXIDIZING GAS(ES)	K			c, and/or ness of ed upon will be ng.	1/23/2017	

	ATEMENT OF DEPICIENCIES (X1) PROVIDER/SUPPLIER/GLIA IDENTIFICATION NUMBER:		(X2) MUL A. BUILD		1	(X3) DATE SURVEY COMPLETED		
	PROVIDER OR SUPPLIER DA REHABILITATION	056300 & WELLNESS CENTER, LP	STREET ADDRESS, GITY, STATE, ZIP CODE 2885 HARRIS STREET EUREKA, CA 95503					
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES  Y MUST BE PRECEDED BY FULL  SCIDENTIFYING INFORMATION)	ID PŘEŘI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X3) COMPLETION DATE	
K 923	evidenced by the fa empty cylinders in t	ailure to segregate full and the same enclosure. This r smoke compartments, and	KS	923				
	Edition. 11.6.5 Special Predand Containers. 11.6.5.1 Storage she cylinders can be used in the order in the supplier. 11.6.5.2 If empty as within the	are Facilities Code, 2012 cautions - Storage of Cylinders nall be planned so that which they are received from and full cylinders are stored impty cylinders shall be			CALIFORNIA DEPARTMENT OF PUBLIC H LICENSINA & CERTIFICATION LAGGR	SAIN AM		
K 926 SS≃D	portable oxygen sto At 2:45 p.m., the O observed. Two full with six empty in th NFPA 101 Gas Equ Training Gas Equipment - C Personnel Personnel concern- maintenance and h cylinders are traine provide continuing of guidelines and usag	r, with staff on 12/22/16, the brage was observed.  xygen Storage Room was tanks were stored together e same rack.  sipment - Qualifications and ualifications and Training of ed with the application, andling of medical gases and d on the risk. Facilities education, including safety ge requirements. Equipment is reconnel trained in the	KS	926	LIFE SAFETY CODE UNIT SAN BERNARDING  K 926 The staff will be inservice yearly handling and use of oxygen by the Respiratory Therapist. The Administrate Respiratory Therapist, and/or DSD will monitor staff for effectiveness of Facility training. Results will be acted upon immediately. Any trends identified will brought to the monthly Safety meeting.  Completion date: 1/23/2017	r, be	/23/2017	

	STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLI AND PLAN OF CORRECTION DENTIFICATION NO		(X2) MUL A, BUILD			(X3) DATE SURVEY COMPLETED	
		058300	B. WING			12/2	22/2016
}	PROVIDER OR SUPPLIER	& WELLNESS CENTER, LP		2	TREET ADDRESS, CITY, STATE, ZIP CODE 885 HARRIS STREET UREKA, CA 95503		
(X4) (D PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES  / MUST BE PRECEDED BY FULL  BC IDENTIFYING INFORMATION)	PREF		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	BE	(XG) COMPLETION DATE
K 926	11.5.2.1 (NFPA 99) This STANDARD i Based on observarinterview, the facilit safety. This was ever continuing in-service risks associated with gases. This affects compartments, and handling and use of equipment.  NFPA 99, Health Continuers. 11.5.2.1 Qualification of the continuers. 11.5.2.1.1* Personal gases and the cyling gases shall be trained on the risks and use. 11.5.2.1.2 Health or programs of continuers and use. 11.5.2.1.3 Continuers include periodic review of safety guirequirements for medical gases and Findings:	peration of equipment.  s not met as evidenced by: tion, document review, and y failed to maintain oxygen idenced by the absence of a se and training program for th handling and use of medical d four of four smoke I could result in the unsafe of oxygen and oxygen delivery  are Facilities Code, 2012  linders and Liquefied Gases in on and Training of Personnel, nel concerned with the adical gases and others who ders that contain the medical associated with their handling are facilities shall provide uling education for their ng education programs shall delines and usage	K	926	CALIFORNIA DEPARTMENT OF PUBLIC LICENSING & CERTIFICATION 1000 JAN 1 1 8017 LIFE SAFETY CODE UNIT SAN BERNARDINO	HEACT of ARAIL	
	review with staff on	12/22/16, the oxygen delivery				}	

	OF DEFICIENCIÉS F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		CONSTRUCTION	(X3) DATE SURVEY COMPLETED	
		056300	B. WING		The state of the s	12/2	22/2016
	PROVIDER OR SUPPLIER	& Wellness Center, LP	STREET ADDRESS, CITY, STATE, ZIP CODE 2885 HARRIS STREET EUREKA, CA 95503				
(X4) ID PRĒFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SO IDENTIFYING INFORMATION)		PROVIDER'S PLAN OF CORRECTION PREFIX TAG CROSS-REFERENCED TO THE APPROP DEFICIENCY)		BĘ	(XG) COMPLETION DATE
K 926	equipment was obstrequested.  At 10:55 a.m., the football portable oxygen sudocumentation was education of personanding and use of finding in an intervi	age 23 served, and training records facility was observed with a apply tank delivery system. No a available for continuing nnel associated with the of oxygen. Staff 3 confirmed the ew at the time stating "that of the new requirement."		926			
					CALIFORNIA DEPARTMENT OF PUBL LICENSING & CERTIFICATION IN JAN 17 1517		
					LIFE SAFETY CODE UNIT SAN BERNARDINO		