PRINTED: 09/12/2022 FORM APPROVED OMB NO. 0938-0391

AND DLAN OF CORRECTION IDENTIFICATION NUMBER		A. BUILDIN	PLE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED	
		055213	B. WING _		01/04/2022
	ROVIDER OR SUPPLIER OST ACUTE CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376	·
(X4) ID PREFIX TAG	(EACH DEFICIENC	TATEMENT OF DEFICIENCIES BY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRE (EACH CORRECTIVE ACTION SH CROSS-REFERENCED TO THE APP DEFICIENCY)	OULD BE COMPLETION
E 000	Initial Comments		E 0	00	
K 000	Department of Public Emergency Prepared The findings are in a Federal Regulations Participation for Inter Individuals with Intell Representing the Carlealth: 43035 The facility is in subs CFR 483.475, Conditional Control	dness recertification survey. ccordance with 42 Code of (CFR) 483.475, Condition of mediate Care Facilities for ectual Disabilities (ICF/IID). lifornia Department of Public stantial compliance with 42 tion of Participation for acilities for Individuals with es (ICF/IID).	К 0	00	
	Department of Public Life Safety Code reco findings are in accord Federal Regulations	R: 2012 EXISTING CONE STORY, YPE I (111), FULLY So the findings of the California Control Health, during an annual Control Health, during annual Co			
ARODATORY		ion Association (NFPA) 101 -		TITLE	(X6) DATE

Electronically Signed

01/14/2022

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		1 ' '	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED	
		055213	B. WING		01/	/04/2022
	ROVIDER OR SUPPLIER OST ACUTE CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL) CROSS-REFERENCED TO THE APPROF	D BE	(X5) COMPLETION DATE
K 161 SS=D	Health Care Facilities Representing the Cal Health: 43035 The facility is not in statement of the fac	12 Edition, and NFPA 99 - 5 Code, 2012 Edition. ifornia Department of Public ubstantial compliance with long Term Care Facilities Type and Height type and stories meets s otherwise permitted by .6.7	K 16			1/17/22

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPI A. BUILDING	LE CONSTRUCTION 02	(X3) DATE SURVEY COMPLETED
		055213	B. WING		01/04/2022
	ROVIDER OR SUPPLIER OST ACUTE CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULE CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE COMPLETION
K 161	system in accordance 19.3.5) Give a brief description construction, the numbasements, floors on location of smoke or approval. Complete splan of the building as This REQUIREMENT by: Surveyor: 43035 Based on observation failed to maintain the was evidenced by a vaffected one of seven could result in the pasthroughout the facility NFPA 101 - Life Safe 8.5.6 Penetrations. 8.5.6.2 Penetrations. 8.5.6.2 Penetrations to conduits, pipes, tubes items to accommodate plumbing, and commodate plumbing, and commodate plumbing as through a wall, for a smoke barrier as	Maximum 1 story ust be sprinklered roved, supervised automatic with section 9.7. (See on, in REMARKS, of the ober of stories, including which patients are located, fire barriers and dates of ketch or attach small floor appropriate. It is not met as evidenced on and interview, the facility building construction. This wall penetration. This is smoke compartments and assage of smoke and/or fire of cables, cable trays, so, vents, wires, and similar the electrical, mechanical, unications systems that	K 16	Corrective action: Fire retardant can was put in the hole around the wiring in-service was given to the maintena department. Potential problems: No other wall was found to have a circular penetration. Systemic changes: All holes in walls where the wires enter will be visually checked and resolved if required by maintenance department. Monitoring: A log will be filled out moby the maintenance department for vinspection of all holes in walls and cowhere wires enter. Results of the monitoring will be brought to QA for oversight and recommendations.	. An nce as

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED		
		055213	B. WING _			01/	04/2022
	ROVIDER OR SUPPLIER DST ACUTE CENTER			14	TREET ADDRESS, CITY, STATE, ZIP CODE 471 S RIVERSIDE AVE LIALTO, CA 92376		-
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	x	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 161 K 223 SS=D	Administrator on 1/4/2 was observed. At 11:58 a.m., the East Waste Storage room penetration measured inches in diameter. Up Administrator confirm	acility and interview with the 22, the building construction st wall of the Infectious was observed with a circular I at approximately 1/2 con interview, the ed the finding.		161			1/17/22
	or horizontal exit, smoore area enclosure are second position, unless device complying with closes all such doors compartment or entire * Required manual fire* Local smoke detector smoke passing throug smoke detection syste * Automatic sprinkler * Loss of power. 18.2.2.2.7, 18.2.2.2.8 This REQUIREMENT by: Surveyor: 43035 Based on observation failed to maintain the by a self-closing exit of latch. This affected or	ageway, stairway enclosure, oke barrier, or hazardous elf-closing and kept in the sheld open by a release a 7.2.1.8.2 that automatically throughout the smoke a facility upon activation of: a alarm system; and ors designed to detect gh the opening or a required em; and system, if installed; and and interview, the facility doors. This was evidenced door failing to close and the of seven smoke uld result in the spread of			Corrective action: The self-closing exidoor located between rooms 37 and 39 was repaired to allow it to fully close ar latch by the maintenance department. Potential problems: Other exit doors we inspected and no other door was found not to be fully closing and latching.) nd ere	

NAME OF PROVIDER OR SUPPLIER RIALTO POST ACUTE CENTER (XA) ID PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) K 223 Continued From page 4 Findings: During a tour of the facility and interview with the Administrator on 1/4/22, the doors and exits were observed. At 11:11 a.m., a self-closing exit door located between Room 37 and 39 was observed being unable to fully close and latch. Upon interview, the Administrator confirmed the finding. K 353 Sprinkler System - Maintenance and Testing Automatic sprinkler and standpipe systems are STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376 PREFIX (EACH CORRECTIVE ACTION SHOULD BE (EACH CORRECTIVE ACTION SHOULD BE (CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) PREFIX (EACH CORRECTIVE ACTION SHOULD BE (CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) In-services were provided to staff. Systemic changes: All exit doors will be inspected for proper closing and latching by the maintenance department. Monitoring: A log will be filled out monthly by the maintenance department to verify proper closing and latching of each exterior self-closing door. Result of such monitoring will be brought to the QAA committee for over sight and recommendation as needed. K 353 Sprinkler System - Maintenance and Testing Automatic sprinkler and standpipe systems are			(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
NAME OF PROVIDER OR SUPPLIER RIALTO POST ACUTE CENTER (X4) ID SUMMARY STATEMENT OF DEFICIENCIES PREFIX TAG (X4) ID SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) K 223 Continued From page 4 Findings: During a tour of the facility and interview with the Administrator on 1/4/22, the doors and exits were observed. At 11:11 a.m., a self-closing exit door located between Room 37 and 39 was observed being unable to fully close and latch. Upon interview, the Administrator confirmed the finding. K 353 SS=D K 353 SS=D Sprinkler System - Maintenance and Testing SUMMARY STATEMENT OF DEFICIENCY ID PREFIX TAG PROVIDER SUM RIALTO, CA 92376 PREFIX TAG PREFIX TAG PRACH TA			055213	B. WING _			01/	04/2022
REGULATORY OR LSC IDENTIFYING INFORMATION PREFIX TAG CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY					1471 S RIVERSIDE AVE			
Findings: During a tour of the facility and interview with the Administrator on 1/4/22, the doors and exits were observed. At 11:11 a.m., a self-closing exit door located between Room 37 and 39 was observed being unable to fully close and latch. Upon interview, the Administrator confirmed the finding. K 353 SS=D K 353 SS=D Sprinkler System - Maintenance and Testing Findings: In-services were provided to staff. Systemic changes: All exit doors will be inspected for proper closing and latching by the maintenance department. Monitoring: A log will be filled out monthly by the maintenance department to verify proper closing and latching of each exterior self-closing door. Result of such monitoring will be brought to the QAA committee for over sight and recommendation as needed. K 353 Sprinkler System - Maintenance and Testing Sprinkler System - Maintenance and Testing	PREFIX	(EACH DEFICIENC)	Y MUST BE PRECEDED BY FULL	PREFI	х	(EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA		COMPLETION
inspected, tested, and maintained in accordance with NFPA 25, Standard for the Inspection, Testing, and Maintaining of Water-based Fire Protection Systems. Records of system design, maintenance, inspection and testing are maintained in a secure location and readily available. a) Date sprinkler system last checked b) Who provided system test c) Water system supply source Provide in REMARKS information on coverage for any non-required or partial automatic sprinkler system. 9.7.5, 9.7.7, 9.7.8, and NFPA 25 This REQUIREMENT is not met as evidenced by: Surveyor: 43035 Corrective action: A new sign was	K 353	Findings: During a tour of the fath Administrator on 1/4/2 observed. At 11:11 a.m., a self-obetween Room 37 and unable to fully close at the Administrator confider System - MacCFR(s): NFPA 101 Sprinkler System - MacCFR(s): NFPA 101 Sprinkler System - MacAutomatic sprinkler and inspected, tested, and with NFPA 25, Standar Testing, and Maintain Protection Systems. Findintenance, inspecting maintenance, inspecting maintenance, inspecting maintained in a securiavailable. a) Date sprinkler system support of the system of the system. Provide in REMARKS and the system support of the system. 9.7.5, 9.7.7, 9.7.8, and This REQUIREMENT by:	acility and interview with the 22, the doors and exits were closing exit door located d 39 was observed being and latch. Upon interview, firmed the finding. aintenance and Testing and standpipe systems are d maintained in accordance and for the Inspection, ing of Water-based Fire Records of system design, ion and testing are e location and readily stem last checked attem test apply source a information on coverage for artial automatic sprinkler			Systemic changes: All exit doors will be inspected for proper closing and latchin by the maintenance department. Monitoring: A log will be filled out monto by the maintenance department to verify proper closing and latching of each exterior self-closing door. Result of such monitoring will be brought to the QAA committee for over sight and recommendation as needed.	ng thly fy	1/17/22

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` ′	2) MULTIPLE CONSTRUCTION BUILDING 02		(X3) DATE SURVEY COMPLETED	
		055213	B. WING _				01/04/2022
NAME OF P	ROVIDER OR SUPPLIER		,	S	TREET ADDRESS, CITY, STATE, ZIP CODE		
DIALTO D	OCT ACUTE CENTED			14	471 S RIVERSIDE AVE		
RIALIUP	OST ACUTE CENTER			R	IALTO, CA 92376		
(X4) ID PREFIX TAG	(EACH DEFICIEN	TATEMENT OF DEFICIENCIES CY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI TAG	х	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	BE	(X5) COMPLETION DATE
K 353	Continued From pag	Continued From page 5			ordered from Majestic Fire company.		
	failed to maintain the This was evidenced missing escutcheon	on and interview, the facility e automatic sprinkler system. by illegible signage and a plate on a sprinkler head.			Potential problems: No other contro were without signage.		
	This affected seven of seven smoke compartments and could result in the failure to extinguish and suppress fire in the event of an emergency. NEPA 101 Life Safety Code, 2012 Edition				Systemic changes: There will be a vi inspection of each of the fire stations the property for proper and legible signage by the maintenance departm every week.	on	
	NFPA 101 Life Safety Code, 2012 Edition 19.3.5.1 Buildings containing nursing homes shall be protected throughout by an approved, supervised automatic sprinkler system in accordance with Section 9.7, unless otherwise permitted by 19.3.5.5.				Every automatic fire sprinkler head w visually inspected every week by the maintenance director and/or designed Monitoring: A log will be filled out mo	Э.	
9.7.1.1 * Each automatic required by another sec in accordance with one (1) NFPA 13, Standard f Sprinkler Systems		section of this Code shall be one of the following: and for the Installation of anintenance records required			by the maintenance department to vis inspect each of the fire stations on the property for proper and legible signag Result of such monitoring will be brou to the QAA for oversight and recommendation monthly and as nee	e je. ight	
	and Maintenance of	rd for the Inspection, Testing, Water-Based Fire Protection aintained at an approved,			Corrective action: Escutcheon plate replaced by the maintenance departn		
	Systems, 2011 Edition	or the Installation of Sprinkler on hall be inspected from the			Potential problems: No other automate sprinkler system was found to be with an escutcheon plate.		
	floor level annually. 5.2.1.1.1* Sprinklers leakage; shall be fre materials, paint, and	shall not show signs of e of corrosion, foreign physical damage; and shall prrect orientation (e.g.,			Systemic changes: All sprinkler head were inspected for proper placement the escutcheon plate throughout the facility by the maintenance department	of	
	upright, pendent, or 5.2.8 * Information S The information sign	sidewall).			Monitoring: A log will be kept by the maintenance department to visually inspect the presence of escutcheon paround each sprinkler head. Result or		

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULT A. BUILDIN		CONSTRUCTION 2	(X3) DATE SURVEY COMPLETED	
		055213	B. WING _			01/	04/2022
	OST ACUTE CENTER			14	TREET ADDRESS, CITY, STATE, ZIP CODE 171 S RIVERSIDE AVE IALTO, CA 92376		-
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES / MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	<	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 353	Systems, 2010 Editio 6.2.7 Escutcheons and 6.2.7.1 Plates, escutoused to cover the anni sprinkler shall be met around a sprinkler. 6.2.7.2 * Escutcheons flush-type, or conceal a listed sprinkler asse 6.2.7.3 Cover plates a sprinklers shall be parassembly. Findings: During observation ar Administrator on 1/4/2 system was observed 1. At 10:40 a.m., the asprinkler rise located was observed with a finding security of the sprinkler rise located was observed with a finding security of the secu	or the Installation of Sprinkler of d Cover Plates. Heons, or other devices ular space around a fallic or shall be listed for use a used with recessed, for ed sprinklers shall be part of mbly. It is used with concealed at of the listed sprinkler. In the listed sprinkler is control valve of the South at the front of the facility faded control valve sign le. Upon interview, the	KS	353	such monitoring will be brought to the QAA for oversight and recommendation monthly and as needed.	1	
K 355 SS=D	located outside of the observed missing an interview, the Adminis Portable Fire Extingui CFR(s): NFPA 101 Portable Fire Extingui	shers	K3	355			1/17/22
		hers are selected, installed, ained in accordance with or Portable Fire					

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDING	E CONSTRUCTION 02	(X3) DATE SURVEY COMPLETED		
	055213	B. WING		01/04/2022		
NAME OF PROVIDER OR SUPPLIER RIALTO POST ACUTE CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376	,		
PREFIX (EACH DEFICIENC	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		(EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX		PROVIDER'S PLAN OF CORRECTIC (EACH CORRECTIVE ACTION SHOULI CROSS-REFERENCED TO THE APPROF DEFICIENCY)	O BE COMPLETION
by: Surveyor: 43035 Based on observation failed to maintain the This is evidenced by missing the required affected one of sever could result in the deevent of an emergent NFPA 101 Life Safety 19.3.5.12 Portable file provided in all health accordance with 9.7.9.7.4.1* Where require another section of the extinguishers shall be inspected, and maintain NFPA 10, Standard for Extinguishers. NFPA 10 Standard for Extinguishers, 2010 7.2.1.2* Fire extinguishers with the extinguishers of fire extinguishers in the extinguishers in the extinguishers in the extinguishers in the following ite (1) Location in design (2) No obstruction to	n and interview, the facility portable fire extinguishers a portable fire extinguisher monthly inspections. This in smoke compartments and play to extinguish a fire in the cy. y Code, 2012 Edition re extinguishers shall be care occupancies in 4.1. red by the provisions of its Code, portable fire e selected, installed, tained in accordance with for Portable Fire or Portable Fire Edition shers shall be inspected or means of an electronic stem at a minimum of 30-day extinguishers in access or visibility reading or indicator in the	K 355	Corrective action: The fire extinguis was inspected and signed off on the by the maintenance department. Potential problems: No other fire extingusiher was noted not to be sig off after inspection of all fire extinguis in the building by the maintenance director. Systemic changes: A list of location each fire extinguisher will be identified a checklist by the maintenance department to verify each month that are being checked. Monitoring: A log will be kept for the monthly check with locations identified the maintenance department. Results such monitoring will be brought to the QAA committee for over sight and recommendation on a monthly basis as needed	ned shers s of ed on they ed by c of e		

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055213	B. WING _			01/04/2022
	ROVIDER OR SUPPLIER OST ACUTE CENTER		1	STREET ADDRESS, CITY, STATE, ZIP CO 1471 S RIVERSIDE AVE RIALTO, CA 92376	DDE	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI) TAG	PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTIVE CROSS-REFERENCED TO THE DEFICIENCY	ON SHOULD BE HE APPROPRIATE	(X5) COMPLETION DATE
K 355	self-expelling-type excartridge-operated ex (5) Condition of tires, nozzle for wheeled ex (6) Indicator for nonrousing push-to-test pro 7.2.4.1 Personnel mashall keep records of inspected, including the corrective action. 7.2.4.3 Where at least inspections are condinspection was perforperson performing the recorded. 7.2.4.4 Where manual records for manual intag or label attached an inspection checklican electronic method 7.2.4.5 Records shall at least the last 12 minute performed. Findings: During a tour of the fainterview with the Adaportable fire extinguisinspection records were selected.	tinguishers, and pump tanks wheels, carriage, hose, and attinguishers echargeable extinguishers essure indicators alting manual inspections all fire extinguishers hose found to require at monthly manual functed, the date the manual functed, the date the manual functed and the initials of the ele inspections are conducted, spections shall be all inspections are conducted, spections shall be kept on a fire extinguisher, on st maintained on file, or by the bekept to demonstrate that conthly inspections have been sacility, record review, and ministrator on 1/4/22, the shers were observed, and	KS	355		
K 363 SS=D	in front of the Directo observed with month on the inspection tag	r of Nursing office was ly inspection record missing . Upon interview, the led the finding and stated	K	363		1/17/22

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIF A. BUILDING	PLE CONSTRUCTION G 02	, ,	(X3) DATE SURVEY COMPLETED		
		055213	B. WING			01/04/2022	
	ROVIDER OR SUPPLIER OST ACUTE CENTER			STREET ADDRESS, CITY, STATE, ZIP COD 1471 S RIVERSIDE AVE RIALTO, CA 92376	•		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	N SHOULD BE	(X5) COMPLETION DATE	
K 363	required enclosures of hazardous areas resi and are made of 1 3/4 wood or other materia at least 20 minutes. It is smoke compartments the passage of smoke to rooms containing for materials have positive latches are prohibited requirements do not ado not contain flamm Clearance between be covering is not exceed complying with 7.2.1. with a device capable when a force of 5 lbf impediment to the cloadevices that release to pulled are permitted. Of unlimited height are meeting 19.3.6.3.6 are shall be labeled and materials in compliant smoke compartment window assemblies as sprinklered compartment restrictions in area or frames in window assembles as 19.3.6.3, 42 CFR Parand 485 Show in REMARKS of	idor openings in other than of vertical openings, exits, or st the passage of smoke 4 inch solid-bonded core al capable of resisting fire for Doors in fully sprinklered are only required to resist e. Corridor doors and doors lammable or combustible we latching hardware. Roller to by CMS regulation. These apply to auxiliary spaces that able or combustible material. For the door solding 1 inch. Powered doors 9 are permissible if provided to of keeping the door closed is applied. There is no using of the doors. Hold open when the door is pushed or Nonrated protective plates to permitted. Dutch doors to permitted. Dutch doors to permitted. Dutch doors to permitted. Door frames made of steel or other ce with 8.3, unless the is sprinklered. Fixed fire allowed per 8.3. In ments there are no fire resistance of glass or	K 36				

	OF DEFICIENCIES CORRECTION			(X3) DATE SURVEY COMPLETED			
		055213	B. WING _			01/	04/2022
	ROVIDER OR SUPPLIER OST ACUTE CENTER			14	TREET ADDRESS, CITY, STATE, ZIP CODE 171 S RIVERSIDE AVE IALTO, CA 92376		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	х	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 363	etc. This REQUIREMENT by: Surveyor: 43035 Based on observation failed to maintain the evidenced by a self-cheld open. This affect compartments and cofire in the event of an NFPA 101 Life Safety 19.3.6.3.10 * Doors s devices other than the door is pushed or pull Findings: During a tour of the fa Administrator on 1/4/2 observed. At 12:13 p.m., the sel Activities room was o a propped up folding door from being close Administrator confirm Subdivision of Buildin CFR(s): NFPA 101 Subdivision of Buildin Doors 2012 EXISTING Doors in smoke barrie bonded wood-core do resists fire for 20 mine	is not met as evidenced and interview, the facility corridor doors. This was losing corridor door being ted one of seven smoke ould result in the spread of emergency. Code, 2012 Edition hall not be held open by ose that release when the ed. acility and interview with the 22, the corridor doors were f-closing corridor door of the bserved being held open by chair which obstructed the ed. Upon interview, the		363	Corrective action: A magnet has been installed to keep door open with ability close during fire or fire drill. An in-servi was given to all staff to not prop any doopen. Potential problems: No other door was found to held open by devices other that those that will release when the door is pushed or pulled. Systemic changes: All doors will be identified and checked for full closure without obstruction. Monitoring: All doors will be visually checked for obstructions on a weekly basis and logged by the maintenance department. Result of such will brought the QAA for oversight and recommendation on a monthly basis are as needed.	to ice icor an	1/17/22

	DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTI A. BUILDIN	IPLE CONSTRUCTION IG 02		TE SURVEY MPLETED
		055213	B. WING _			01/04/2022
	OST ACUTE CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORF ((EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE AI DEFICIENCY)	HOULD BE	(X5) COMPLETION DATE
K 374	Continued From page	e 11	K 3	.74		
	are permitted to have assemblies per 8.5. Dautomatic-closing, do are not required to swegress travel. Door of clear width of 32 inch doors. 19.3.7.6, 19.3.7.8, 19 This REQUIREMENT by: Surveyor: 43035 Based on observation failed to maintain the was evidenced by an closing smoke barrier seven smoke compart the spread of fire in the Findings: During a tour of the fand Administrator on 1/4/2 were observed. At 11:11 a.m., an autodoor located adjacemand 6 was observed in ursing cart preventir when activated by the	fixed fire window poors are self-closing or not require latching, and ving in the direction of pening provides a minimum es for swinging or horizontal 3.7.9 is not met as evidenced and interview, the facility smoke barrier doors. This obstructed automatic door. This affected two of trents and could result in the event of an emergency. acility and interview with the 22, the smoke barrier doors omatic closing smoke barrier the lobby next to Room 5		Corrective action: The medica was moved to allow the full clos fire door. An in-service was given ursing staff to ensure the medicarts are not parked over the year closer to the door. Potential problems: No other macert was found to be obstructined door. Systemic changes: A yellow tabe placed 3 feet away from the position of the fire door and extended feet away from the wall by the maintenance department. Monitoring: Tape will be visuall monthly for integrity and need for replacement due to wear and the maintenance department. Resumentioning will be brought to the committee for oversight and recommendation monthly and a	sure of the ven to the ication ellow line nedication g the fire pe line will full closure ending 3	
K 511 SS=D	Utilities - Gas and Ele CFR(s): NFPA 101	ectric	K 5		is needed.	1/17/22
	Utilities - Gas and Ele	ectric				

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDING	LE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED			
		055213	B. WING		01/04/2022		
NAME OF PROVIDER OR SUPPLIER RIALTO POST ACUTE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIOI (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	BE COMPLETION		
K 511	Equipment using gas complies with NFPA selectrical wiring and e NFPA 70, National El	or related gas piping 54, National Fuel Gas Code, equipment complies with ectric Code. Existing inue in service provided no	K 51				
	by: Surveyor: 43035 Based on observation failed to maintain the electrical receptacles obstructions to the el weatherproof facepla receptacles. This affecompartments and cospread of fire. NFPA 101 Life Safety 19.5.1.1 Utilities shal of Section 9.1. 9.1.2 Electrical wiring accordance with NFF Code, unless such in existing installations, be continued in service NFPA 70 National Electrocation protected frod damp locations shall receptacle that is weather the surveyor	and equipment shall be in PA 70 National Electrical stallations are approved which shall be permitted to ce. ectrical Code, 2011 Edition e installed outdoors in a m the weather or in other have an enclosure for the		Corrective action: Weather proof corplates were placed by the maintenant department. Potential problems: all other electrical receptacle and panel were inspected the maintenance director, none was found without weather proofing. Systemic changes: All outdoor electrical plugs have been visually inspected for proper weatherproofing by the maintenance director. Monitoring: A monthly log will be kep inspection of outdoor electrical plugs the maintenance department. Result such monitoring will be brought to the QAA for recommendation and oversig on a monthly basis and as needed. Corrective action: Both closets have lall items on the floor removed immediately. Potential problems: No other electrical problems: No other	ce I by rical or It for by of explore and the control of the co		

PRINTED: 09/12/2022 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY **IDENTIFICATION NUMBER:** AND PLAN OF CORRECTION COMPLETED A. BUILDING 02 055213 B. WING 01/04/2022 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE **RIALTO POST ACUTE CENTER RIALTO, CA 92376** SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETION (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL **PREFIX** (EACH CORRECTIVE ACTION SHOULD BE PREFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) Continued From page 13 K 511 inserted and receptacle covers closed). panel was observed to have any boxes or An installation suitable for wet locations shall also soiled linen bins obstructing access to be considered suitable for damp locations. them. A receptacle shall be considered to be in a location protected from the weather where Systemic changes: All electrical panels located under roofed open porches, canopies. will be inspected weekly by the marquees, and the like, and will not be subjected maintenance director and/or designee to to a beating rain or water runoff. All 15- and verify that there are no boxes and/or linen 20-ampere, 125- and 250-volt nonlocking bins obstructing its access. The receptacles shall be a listed weather-resistant maintenance director/designee will ensure that there is at least 3 feet of clutter free type. Informational Note: The types of receptacles perimeter. covered by this requirement are identified as 5-15, 5-20, 6-15, and 6-20 in ANSI/NEMA WD Monitoring: A weekly log will be kept by 6-2002, National Electrical Manufacturers the maintenance department to verify all Association Standard for Dimensions of electrical panels have at least a 3 foot Attachment Plugs and Receptacles. clutter free perimeter. 408.18 Clearances. Results of such monitoring will be brought 408.18(B) Around Switchboards. to the QA committee by the maintenance Clearances around switchboards shall comply director and/or designee for oversight, with the provisions of 110.26. review and recommendation on a monthly 110.26 Spaces About Electrical Equipment. basis and as needed. Access and working space shall be provided and maintained about all electrical equipment to permit ready and safe operation and maintenance of such equipment. 110.26(A) Working Space. Working space for equipment operating at 600 volts, nominal, or less to ground and likely to require examination, adjustment, servicing, or maintenance while energized shall comply with the dimensions of 110.26(A)(1), (A)(2), and (A)(3) or as required or permitted elsewhere in this Code. 110.26(A)(1) Depth of Working Space. The depth of the working space in the direction of live parts shall not be less than that specified in Table 110.26(A)(1) unless the requirements of 110.26(A)(1)(a), (A)(1)(b), or (A)(1)(c) are met.

	STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDING	LE CONSTRUCTION 02	(X3) DATE SURVEY COMPLETED	
		055213	B. WING		01/04/	2022
NAME OF PROVIDER OR SUPPLIER RIALTO POST ACUTE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376		-
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPI DEFICIENCY)	BE C	(X5) COMPLETION DATE
K 511	Distances shall be m live parts or from the live parts are enclosed. Table 110.26(A)(1) W 0-150 Nominal Voltage Minimum Clear Distances. During a tour of the factor Administrator on 1/4/electrical receptacles. 1. At 10:54 a.m., and on the West exterior observed missing a w Upon interview, the Affinding. 2. At 11:14 a.m., and on the North exterior observed missing a w Upon interview, the Affinding. 3. At 11:39 a.m., the located in the Utility robstructed by storage inability to access the Administrator confirm. 4. At 12:33 p.m., the south panel" located was observed being bin resulting in the indupon interview, the Affinding in the indupon interview in the Aff	easured from the exposed enclosure or opening if the ed. forking Spaces ge to Ground, 3-feet nice acility and interview with the 22, the electrical panels and were observed. electrical receptacle located side of the facility was veatherproof cover plate. Idministrator confirmed the electrical panel labeled "L" oom was observed being e boxes resulting in the e panel. Upon interview, the	K 51	1		
K 911 SS=D	finding. Electrical Systems - 0	Other	K 91	1	1/	17/22

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED		
		055213	B. WING _			01/	04/2022
NAME OF PROVIDER OR SUPPLIER RIALTO POST ACUTE CENTER				14	TREET ADDRESS, CITY, STATE, ZIP CODE 171 S RIVERSIDE AVE IALTO, CA 92376		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL .SC IDENTIFYING INFORMATION)	ID PREFI TAG	×	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 911	Chapter 6 Electrical Sare not addressed by are deficient. This info applicable Life Safety citation, should be inc Chapter 6 (NFPA 99) This REQUIREMENT by: Surveyor: 43035 Based on observation failed to maintain the evidenced by missing switches in an electric seven of seven smok result in the failure of for life and safety in the NFPA 101 - Life Safet 19.5.1.1 Utilities shall of Section 9.1. 9.1.2 Electrical wiring accordance with NFP Code, unless such insexisting installations, be continued in service NFPA 70 - National E 408.4 Field Identificate 408.4(A) Circuit Direct Every circuit and circulegibly identified as to specific purpose or us include sufficient details	Other section any NFPA 99 Systems requirements that the provided K-Tags, but ormation, along with the Code or NFPA standard cluded on Form CMS-2567. It is not met as evidenced in and interview, the facility electrical system. This was a identification of the cal panel. This affected e compartments and could electrical systems essential the event of an emergency. It Code, 2012 Edition comply with the provisions and equipment shall be in A 70 National Electrical stallations are approved which shall be permitted to be.	K	911	Corrective action: All 18 circuits have been labeled on the electrical panel (E-LS). Potential problems: No other panel was found not to be labeled. Systemic changes: Maintenance direct and/or designee will visually inspect ear electrical panel to ensure that all circuit are labeled. Monitoring: A log will be kept to identify that the inspection has been done by the maintenance department. Result of such monitoring will be brought to the QAA foversight and recommendation monthly and as needed.	or ich is y ne ch or	

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		, ,	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED	
		055213	B. WING		01/04/2022	
	ROVIDER OR SUPPLIER OST ACUTE CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPR DEFICIENCY)	BE.	(X5) COMPLETION DATE
K 911	shall be described ac shall be included in a located on the face of the case of a panelbo switch or circuit break circuit shall be descrit depends on transient. Findings: During a tour of the far Maintenance Assistant panels were observed. At 12:33 p.m., the ele located in the Housek observed without ider circuits that were in the elements that the circuits that the circuits that the circuits that were in the elements that the circuits that the circuits t	urrent devices or switches cordingly. The identification circuit directory that is inside of the panel door in ard, and located at each ter in a switchboard. No bed in a manner that conditions of occupancy. Acility and interview with the at on 1/4/22, the electrical direction for 18 of 18 the ON position. The uits supplied were unable to of the missing identification. Idaintenance Assistant and stated that he was not circuits supplied. Essential Electric System		911		1/17/22

OLIVILIV	O T OTT MEDIO, TILE &	WEDIO/ ND CEITVICE				CIVID ITC	7. 0000 000 I	
, ,		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED	
		055213	B. WING			01/	04/2022	
NAME OF P	ROVIDER OR SUPPLIER			S	TREET ADDRESS, CITY, STATE, ZIP CODE			
DIALTO D	OST ACUTE CENTER			1	471 S RIVERSIDE AVE			
RIALIUP	USI ACUIE CENTER			R	IALTO, CA 92376			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE	
K 918	under load 30 minuted day intervals, and exemonths for 4 continuounder load conditions simulated cold start at transfer of all EES load competent personnel stored energy power accordance with NFP circuit breakers are in program for periodical components is estable manufacturer requires maintenance and test readily available. EES circuits are marked, reseparate from normat the possibility of dam source is a design constallations. 6.4.4, 6.5.4, 6.6.4 (NI 111, 700.10 (NFPA 70 This REQUIREMENT by: Surveyor: 43035 Based on document in facility failed to maint supply. This was evide conduct the monthly get and the 4-hour longenerator. This affect compartments and conductions in the compartments and conductions.	spected weekly, exercised s 12 times a year in 20-40 ercised once every 36 ous hours. Scheduled test include a complete and automatic or manual ads, and are conducted by . Maintenance and testing of sources (Type 3 EES) are in PA 111. Main and feeder aspected annually, and a sully exercising the ished according to ments. Written records of ting are maintained and seedetrical panels and eadily identifiable, and I power circuits. Minimizing age of the emergency power insideration for new	K	918	Corrective action: The 4-hour load test for the emergency generator has been scheduled for 1/13/22. The monthly lot testing log was located for the months January, February, and March from the previous Plant manager. Systemic changes: The monthly testin log will be kept up to date and the 4-ho load test will be scheduled every 3 year.	ad of e g ur rs.		
	NFPA 101, Life Safet 19.5.1 Utilities, Utilitie	y Code, 2012 Edition es shall comply with the			Monitoring: The log book will be looked by the maintenance department each month to verify that the monthly load te			

	TATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA ND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULT A. BUILDII	LTIPLE CONSTRUCTION DING 02			(X3) DATE SURVEY COMPLETED	
		055213	B. WING _			01/	04/2022	
NAME OF PROVIDER OR SUPPLIER RIALTO POST ACUTE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFI TAG	•			(X5) COMPLETION DATE	
K 918	provisions of section 19.5.1.1 Utilities shal of section 9.1 9.1.3.1 Emergency of power systems shall maintained in accord Standard for Emerge Systems. NFPA 110, Standard Power Systems, 2018.3.2.1 The operation ATS and shall include component on which been performed, include automatic and manual alternate power sound than 30 minutes under 8.4.1 * EPSSs, include components, shall be exercised under load 8.4.9* Level 1 EPSS within every 36 mont 8.4.9.1 Level 1 EPSS for the duration of its 4.2). 8.4.9.2 Where the as 4 hours, it shall be pafter 4 continuous hours, it shall be pafter 5 being the test fun or initiated by opening supplying normal power of the EPSS being the test fun or initiated by opening supplying normal power functions.	9.1 I comply with the provisions Generators and standby be installed, tested, and ance with NFPA 110, ncy and Standby Power for Emergency and Standby 0 Edition nal test shall be initiated at an extesting of each EPSS maintenance or repair has uding the transfer of each al transfer switch to the ce, for a period of not less er operating temperature. ding all appurtenant exinspected weekly and at least monthly. shall be tested at least once hs. Shall be tested continuously assigned class (see Section signed class is greater than exmitted to terminate the test urs. be initiated by operating at itch test function and then by action of all remaining ATSs, g all switches or breakers wer to all ATSs that are part	K	918	was completed.			
	Findings:							
	During document rev	iew and interview with the						

	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED		
		055213	B. WING			01/	04/2022
	ROVIDER OR SUPPLIER OST ACUTE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BI CROSS-REFERENCED TO THE APPROPRIA DEFICIENCY)		(X5) COMPLETION DATE
K 918 K 923 SS=D	Administrator on 1/4/2 records were requested. 1. At 3:57 p.m., the farequired monthly load generator for the month March of 2021. The farequired generator. Under the confirm of 2021. The farequired generator confirm of 2. At 4:06 p.m., the farequired 4-hour load by generator every 3-year a 4-hour load bank terinterview, the Administrator confirm of 2. At 4:06 p.m., the farequired 4-hour load by generator every 3-year a 4-hour load bank terinterview, the Administrator confirm of 3-4 confirmed	ed and reviewed. cility failed to conduct the latesting of the emergency of the of January through acility had a 30 kW diesel don interview, the led the finding. cility failed to conduct the boank test of the emergency ars. The facility did not have set documented. Upon strator confirmed the finding. Inder and Container Storage to 3,000 cubic feet designed, constructed, and once with 5.1.3.3.2 and of feet loutdoors in an enclosure or construction, with door (or can be secured. Oxidizing with flammables, and are lustibles by 20 feet (5 feet if led in a cabinet of truction having a minimum rating. 300 cubic feet		918			1/17/22

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIF A. BUILDING	PLE CONSTRUCTION G 02	(X3) DATE SURVEY COMPLETED	
	055213				01/04/2022	
NAME OF PROVIDER OR SUPPLIER RIALTO POST ACUTE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 1471 S RIVERSIDE AVE RIALTO, CA 92376	•	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROI DEFICIENCY)	D BE COMPLETION	
K 923	A precautionary sign each door or gate of a where the sign included minimum "CAUTION: STORED WITHIN NO Storage is planned so of which they are recomptionally considered empty is a remarked to avoid on the open are protect in the open are protect	e. Cylinders must be ions as specified in 11.6.2. readable from 5 feet is on a cylinder storage room, es the wording as a OXIDIZING GAS(ES) OSMOKING." of cylinders are used in order elived from the supplier. Segregated from full lity employs cylinders with ge, a threshold pressure established. Empty cylinders stored cted from weather. 11.3.4, 11.6.5 (NFPA 99) To is not met as evidenced is was evidenced by the cull and empty oxygen ed one of seven smoke ould result in harm during the cylinders are stored osure, empty cylinders shall	K 92	Corrective action: The 2 empty oxy tanks were removed from the full ox storage room. All staff in-servicing or Potential problems: No other oxygen was identified to have both empty at oxygen tanks. Systemic changes: QA and/or design will verify that every oxygen storage rooms has the appropriate full or entanks. Monitoring: Weekly visual inspection oxygen tanks for appropriate placen by QA and/or designee will done. The of such monitoring will be brought to QAA for oversight and recommendations.	ygen done. n room nd full gnee npty n of nent esults o the	

STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		A. BUILDI	TIPLE CONSTRUCTION NG 02	(X	(X3) DATE SURVEY COMPLETED	
		055213	B. WING			01/04/2022
	ROVIDER OR SUPPLIER OST ACUTE CENTER	,	•	STREET ADDRESS, CITY, STAT 1471 S RIVERSIDE AVE RIALTO, CA 92376	E, ZIP CODE	
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFI TAG	X (EACH CORRECT) CROSS-REFERENC	LAN OF CORRECTION IVE ACTION SHOULD BE ED TO THE APPROPRIATE FICIENCY)	(X5) COMPLETION DATE
K 923	During a tour of the fa Administrator on 1/4/ room was observed. At 12:41 p.m., the Fu observed with nine fu	acility and interview with the 22, the Full Oxygen Storage Ill Oxygen Storage room was ull and two empty oxygen d together. The cylinders Upon interview, the	K	923		