STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X3) DATE SURVEY COMPLETED D. WING 056495 04/23/2018

NAME OF PROVIDER OR SUPPLIER

CASA COLOMA HEALTH CARE CENTER

STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RD RANCHO CORDOVA, CA 95670

			HF	ancho Cohuova, ca 95670	
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	DAT		PROVIDER'S PLAN OF CORRECTION (PG) (EACH CORRECTIVE ACTION SHOULD BE CROSS-REPERENCED TO THE APPROPRIATE DEFICIENCY)	N.
E 000	(EACH DEFICIENCY MUST BE PRECEDED BY FULL	PREFF TAG		E 013 Temporary and Permanent Correction It is the policy of this facility to develop and implement emergency preparedness policies and procedures, based on the emergency plan set forth in paragraph (a)(1) of this section, and the communication plan at paragraph (c) of this section. The policies and procedures must be reviewed and updated at least annually. This facility will update policies and procedures regarding providing care and treatment at an alternate site, including policy and procedures indicating the facility's role in providing	TO THE PUBLISH
	*(For PACE at \$460.84(b):) Policies and procedures. The PACE organization must develop and implement emergency preparedness policies and procedures, based on the emergency plan set forth in paragraph (a) of this section, risk assessment at paragraph (a)(1) of this section, and the communication plan at paragraph (c) of this section. The policies and procedures must			treatment and care under an 1135 walver at an alternate care site in the event of an emergency. 05/23/201	18

LABC

Any.

Institution may be accused from correcting providing it is peterprined that other control of the control 18 101 Cynthia Approved

FORM CMS-2507(02-98) Provious Votalons Obsolete

Event ID: Z01L21

Facility ID: CA030000021

If continuation sheet Page 1 of 30

(A6) DATE

CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY COMPLETED IDENTIFICATION NUMBER: A. BURDING 02 058495 04/23/2018 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RD CASA COLOMA HEALTH CARE CENTER RANCHO CORDOVA, CA 85670 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (K4) COMPLETION DATE ID PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LOC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) Continued From page 1 E 013 E 013 Continued emergencies, including, but not limited to: Fire; equipment, power, or water failure; care-related The Policies and Procedures will be emorgencies; and natural disasters likely to updated to address all provisions threaten the health or safety of the participants, staff, or the public. The policles and procedures including: must be reviewed and updated at least annually. (1) The provision of subsistence needs *iFor ESRD Facilities at \$494.62(b):1 Policies and procedures. The dialysis facility must develop and for staff and residents, whether implement emergency preparedness policies and they evacuate or shelter in place. procedures, based on the emergency plan set forth in paragraph (a) of this section, risk (2) A system to track the location of assessment at paragraph (a)(1) of this section, on-duty staff and sheltered and the communication plan at paragraph (c) of residents in the LTC facility's care this section. The policies and procedures must be raviewed and updated at least annually. These during and after an emergency. If emergencies include, but are not limited to, fire, on-duty staff and sheltered equipment or power failures, care-related emergencies, water supply interruption, and residents are relocated during the natural disasters likely to occur in the facility's emergency, the LTC facility will geographic area. This REQUIREMENT is not met as evidenced document the specific name and by: location of the receiving facility or Surveyor: 32973 Based on record review and interview, the facility other location. falled to provide policies and procedures to provide care and treatment at an alternate site. (3) Safe evacuation from the LTC This was evidenced by no policy and procedure facility, which includes indicating the facility's role in providing treatment consideration of care and end care under an 1135 walver at an alternate care site in the event of an emergency. This treatment needs of evacuees; staff affected 117 residents and staff, and could result responsibilities; transportation: in the facility being inadequately prepared to provide care at an alternate location. identification of evacuation 05/23/2018 location(s); and primary and (b) Policies and procedures. The LTC facility must develop and implement emergency preparedness alternate means of communication policies and procedures, based on the with external sources of assistance. emergency plan set forth in paragraph (a) of this

FUHM APPROVED

CENTER	S FOR MEDICARE	& MEDICAID SERV	/ICES			0	OMB NO. 0938-0391		
STATEMENT OF DEFICIENCIES (XI) PROVI		(X1) PROVIDER/SUPPLIE IDENTIFICATION NU	RVCLIA	(X2) MUL A. BUILD		CONSTRUCTION 2	COMPI		
		050495		B.WING			04/23	3/2018	
	ROVIDER OR SUPPLIER DLOMA HEALTH CAR	E CENTER			10	REET ADDRESS, CITY, STATE, ZIP CODE 410 COLOMA RD ANCHO CORDOVA, CA 95670			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIE MUST BE PRECEDED BY SCHOENTIFYING INFORM	/ FULL	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X6) COMPLETION DATE	
	this section, and the paragraph (c) of this procedures must be least annually. At a procedures must a consideration of and residents, when place, include, but (i) Food, water, me supplies. (ii) Alternate source (A) Temperatures is safety and for the inprovisions; (B) Emergency light (C) Fire detection, systems; and (D) Sawage and we consider and sheltered residently and after an and sheltered residently and shelter	sment at paragraph e communication plate is section. The policite reviewed and update in minimum, the policite diverse the following of subsistence needs ther they evacuate of are not limited to the dical, and pharmace is of energy to main to protect resident in safe and sanitary storage and sanitary storage in the LTC factor of the location of ondents in the LTC factor of care and trees in from the LTC facility must document in the LTC factor of care and trees in the LTC factor of care and trees in the safe and alternate in external sources in the external sources in the latternal in the LTC in the latternal sources in the latternal sources in the latternal in the LTC in the lattern	an at less and less a		013	(4) A means to shelter in place residents, staff, and volur remain in the LTC facility. (5) A system of medical document that preserves resident information, protects confidentiality of resident information, and secures maintains the availability records. (6) The use of volunteers in a emergency or other emergency o	mentation of the press surpling the press surpling the press surpling the press surpling the press in the pre	Ion If alth ge ts r the of	
FORM CMS.	2567(02-99) Previous Version	ns Obsoleie	Event ID: 20112	n	F	scility ID: QA030000021 If contin	uallon sheet	1 Page 3 of 30111 A DET URITY CELL THE	

CENTER	IS FOR MEDICARE	& MEDICAID SERVICES			OMB NO. 0938-0391		
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTI A. BUILDIN	PLE CONSTRUCTION G 02	COMP	SURVEY	
		096495	B. WING_		04/23/2018		
	HOVIDER OR SUPPLIER DLOMA HEALTH CAF	DER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RD RANCHO CORDOVA, CA 95670					
(X4) ID PHEFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECT (EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPROPRIECT)	ULD BE	(XS) COMPLETION DATE	
E 013	preserves resident confidentiality of resecures and maint (6) The use of volution other emergency such a process and role for Federally designate address surge need to the confidents in the event of operations to make the confidents of the declared by the Sesection 1135 of the and treatment at a by emergency material preparedness political p	dical documentation that Information, protects sident information, and ains the availability of records, anteers in an emergency or taffing strategles, including the or integration of State or ed health care professionals to de during an emergency. ant of arrangements with other other providers to receive ent of limitations or cessation aintain the continuity of sidents. LTC facility under a waiver occurrency, in accordance with a Act, in the provision of care in alternate care site identified nagement officials.	E 01	a studed	secretary, 1135 of n of care ernate car ency pdated by yed by the nittee. I to all sta cordinato ness Plan facility un ecretary, 1135 of the are and e care site managem	off by ron ader a line	
E 041		LTC Emergency Power	ΕQ	41		23 23 23	
FORM CMS-	2587(02-09) Provious Versio	ns Obsolote Event ID: Z01Li	21	Facility ID. CA030000021 If con	ntinuation she	et Page 4 of 30	
					วันไร้เคินอัดกลุก		

CENTER	<u>IS FOR MEDICARE</u>	& MEDICAID SERVICES				MB NO. I	0938-039	1_		
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILD		E CONSTRUCTION 02	(X3) DATE SURVEY COMPLETED				
	056495 PROVIDER OR SUPPLIER			B. WING			3/2018			
	PROVIDER OR SUPPLIER DLOMA HEALTH CAF	RE CENTER	STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RD RANCHO CORDOVA, CA 95670							
(X4) IO PREFIX TAG	(EACH DEFICIENC	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL BC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE	*		
E 041	(e) Emergency and standby power systems. The		E	041						
	hospital must imple power systems bat forth in paragraph policies and proce	d standby power systems. The ement emergency and standby sed on the emergency plan set (a) of this section and in the dures plan set forth in i) and (B) of this section.	÷			;	ař.			
and the state of t	[LTC facility and the emergency and st	525(e) 1 standby power systems. The e CAH] must implement andby power systems based on in set forth in paragraph (a) of		,						
The same of the sa	Emergency gener must be located in requirements foun Code (NFPA 99 at Amendments TIA 12-5, and TIA 12-6 and Tentative Inte 12-2, TIA 12-3, and	33.73(e)(1), \$485.626(e)(1) ator location. The generator accordance with the location of in the Health Care Facilities at Tentative Interim 12-2, TIA 12-3, TIA 12-4, TIA 5), Life Safety Code (NFPA 101 of TIA 12-4), and NFPA 110, ture is built or when an existing ing is renovated.					29131164 - 7 1			
	Emergency gener (hospital, CAH and the emergency po and maintenance	3.73(e)(2), \$485.625(e)(2) ator inspection and testing. The d LTC facility] must implement ower system inspection, testing, requirements found in the ties Code, NFPA 110, and Life	ł			PROGRAM	TH 3:16			
Management of the control of the con	Emergency gener	3.73(a)(3), §485.625(e)(3) ator fuel. (Hospitals, CAHs and maintain an onsite fuel source								

EUHM APPROVED

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 04/25/2018 FORM APPROVED OMB NO. 0938-0391

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A: BUILD		PLE CONSTRUCTION. 3 02		E SURVEY APLETED	
	05649S B. WING					04/23/2018		
(X4) ID		TEMENT OF DEFICIENCIES	םו		STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RD RANCHO CORDOVA, CA 93670 PROVIDER'S PLAN OF CORRECT	TION	(X5)	
PREFIX TAG	(EACH DEFICIENCY REGULATORY OR L	PREF		(EACH CORRECTIVE ACTION SHO CROSS-REFERENCED TO THE APPI DEFICIENCY)		COMPLETION		
E 041	Continued From pr	nge 5 sy generatore must have a plan	E	04 ⁻	E 013 Continued	agramatica source of the company	,	
	for how it will keep	emergency power systems			To ensure that this deficie	ent pract	ice	
	operational during by sources.	the emergency, unless it			does not reoccur and tha			
			1		residents are not affected	-		
	*[For hospitals at § and CAHs §485.62	482.15(h), LTC at §483.73(g), 5(a):1			Care Policy Committee w	ll review	and	
	The standards inco	prograted by reference in this			update Emergency Prepa	redness I	Plan	
·		ed for incorporation by frector of the Office of the			at least annually. Facility	Staff		
	Federal Register in	accordance with 5 U.S.C.			Development Coordinato	r will also	D	
		part 51. You may obtain the ources listed below. You may			conduct Education and trai		_	
•		ne CMS Information Resource	ł		drills and exercises, are utili	zed in this	5	
		rity Boulevard, Baltimore, MD	ł		facility to achieve proficient	• -		
		archives and Records RA). For information on the			emergency response and er			
:	availability of this n	naterial at NARA, call.			effectiveness of our EOP. In	-		
	202-741-6030, or (1		with state and federal regul	ations, ou	ìĹ	
		s.gov/lederal_register/code_of ns/lbr_locations.html.	1		facility conducts initial train	ing on the	EOP	
	if any changes in t	his edition of the Code are	<u> </u>		during the orientation of ne	w staff, a	nd	
	document in the F	ierence, CMS will publish a ederal Register to announce			annually to all staff.		05/23/201	
	Batterymarch Park				E 041			
	Quincy, MA 02169 1.617.770.3000.	· · · · · · · · · · · · · · · · · · ·			Temporary and Permane	nt Corre	ction	
	(i) NFPA 99, Health edition, Issued Aug	n Care Facilities Code, 2012			It is the policy of this faci	ity to		
	(ii) Technical Interi	m amendment (TIA) 12-2 to			maintain an Emergency F	lan that		
	NFPA 99, Issued A	ugust 11, 2011. PÅ 99, issued August 9, 2012.			includes provisions to en		site	
		PA 99, issued March 7, 2019.			fuel reserve to power the	emerge	ncy	
	(v) TIA 12-5 to NF	PA 99, Issued August 1, 2013.	1		generator for a minimum	-	-	
		PA 99, Issued March 3, 2014. e Safety Code, 2012 edition,			J. Santasa and A. San		05/23/201	

FORM CMS-2567(02-99) Provious Versions Obsoleto

Event ID: Z01L21

Facility ID: CA030000021

If continuation sheet Page 6 of 30

CENTER	,	& MEDICAID SERVICES				IO. 0938-0391		
STATEMENT	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(XZ) MULT A. BUILDI	TRUE CONSTRUCTION NO 02	(EX)	DATE SURVEY COMPLETED		
		056495	B. WING			04/23/2018		
	PROVIDER OR SUPPLIER DLOMA HEALTH CAF	NE CENTER		10410 COLOMA RD	REET ADDRESS, CITY, STATE, ZIP CODE 1410 COLOMA RD ANCHO CORDOVA, CA 95670			
(X4) ID PAEFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL BC IDENTIFYING INFORMATION)	PAGFIX TAG	PROVIDERS PI (EACH CORRECT CROSS-REFERENC	LAN OF CORRECTION IVE ACTION SHOULD BE IED TO THE APPROPRIATE FICIENCY)	COMPLETION DATE		
FORM CMS-	Issued August 11, (viii) TIA 12-1 to Nii 2011. (ix) TIA 12-2 to NF 2012. (x) TIA 12-3 to NF 2013. (xi) TIA 12-4 to NF 2013. (xii) NFPA 110, Strandby Power Sy TIAs to chapter 7, This REQUIREME by: Surveyor: 32973 Based on record relied to maintain a minimal power the emerge 117 residents and have an ineffective (EP) plan. Findings: During record revi Administrative Strandby Stra	PA 101, issued August 11, PA 101, issued October 30, PA 101, issued October 22, PA 101, issued October 22, andard for Emergency and stems, 2010 editlon, including issued August 6, 2009, INT is not met as evidenced eview and interview, the facility the emergency standby power evidenced by the failure to ncy generator. This affected ataff. This had the potential to be Emergency Preparedness ew and interview with aff on 4/23/18, the EP plan was riewed. actility was observed with a watt diesel generator, with an riuel tank. The gauge on the half-full (40 gallons). Upon confirmed that the fuel supply the equivalent of approximately the hour of run time, which ours of fuel supply reserve.		Plant Operation maintain 80 gal reserve tank of diesel will be mat least 96 gallo at the facility. least 96 hours be supplied in outage. To ensure that not reoccur an are not affecte provided by the Plant Operation Maintenance Sincluding requirements 196 gallon provide the re	If continuation	stre that tained tained tait at ter can ter can ter can ter to dents ter can ter to dents ter con the		
		i			(- -			

OMB NO. 0938-0391 CENTERS FOR MEDICARE & MEDICAID SERVICES STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/GLIA (x2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 02 056495 B. WING 04/23/2018 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RO CASA COLOMA HEALTH CARE CENTER RANCHO CORDOVA, CA 95670 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X6) COMPLETION (X4) ID PREFIX (EACH CORRECTIVE ACTION SHOULD BE GROSS-REFERENCED TO THE APPROPRIATE (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) PREFIX TAR K 000 Continued From page 7 K 000 E 041 Continued K 000 K 000 INITIAL COMMENTS The Administrator will monitor the Surveyor: 32973 generator fuel supply weekly for two K3 BUILDING: 01 months. If good compliance is K6 PLAN APPROVAL: 1963 & 1987 K7 SURVEY UNDER: 2012 EXISTING maintained, monitoring will be reduced STRUCTURE TYPE: ONE STORY. to Generator Checks that are CONSTRUCTION TYPE V. FULLY conducted monthly by the Plant SPRINKLERED. Operations Supervisor and reviewed The following reflects the findings of the California quarterly by the Administrator. Department of Public Health, during an annual Life Safety Code recertification survey. The 05/23/2018 findings are in accordance with 42 Code of Federal Regulations (CFR) §483.90(a)(b)(c)(j), National Fire Protection Association (NFPA) 101 -Life Safety Code, 2012 Edition, and NFPA 99 -Health Care Facilities Code, 2012 Edition. Representing the California Department of Public Health: 32973 The facility is not in substantial compliance with 42 CFR §483.90 for Long Term Care Facilities. Census: 117 K 161 Building Construction Type and Height K 161 CFR(s): NFPA 101 SS=D Building Construction Type and Height 2012 EXISTING Building construction type and stories meets Table 19.1.6.1, unless otherwise permitted by 19.1.6.2 through 19.1.6.7 19.1.6.4, 19.1.6.5 If continuation sheet Page 8 of FORM CMS-2567(02-99) Provious Versions Obsolete Event ID: 201121 Facility ID: CA030000021

ドレロは) みとどれひりとひ

CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING 02 B. WING 056495 04/23/2018 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RD CASA COLOMA HEALTH CARE CENTER RANCHO CORDOVA, CA 95870 PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE SUMMARY STATEMENT OF DEFICIENCIES (X4) ID PREFIX COMPLETION (NS) (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) PREFIX DEFICIENCY K 161 Continued From page 9 . K 161 K 211 could result in the passage of smoke to other areas in the event of a fire. Temporary and Permanent Correction Findings: It is the policy of this facility to provide During a tour of the facility with staff on 4/23/18. Means of Egress as required. It is the the walls and celling were observed. policy of this facility to maintain 90 At 11:34 a.m., the walls and ceiling in the Laundry minute fire rated door assemblies and Room, were observed. There was an approximately one inch diameter penetration, with to ensure that Fire Door Assemblies will a metal conduit traveling through it, located in the be inspected and tested not less than ceiling above the washing machines. annually, and a written record of the K 211 Means of Euress - General K 211 SSED | CFR(s): NFPA 101 inspection shall be signed and kept for inspection by the AHJ. Means of Egress - General Alsles, passageways, corridors, exit discharges, exit locations, and accesses are in accordance Plant Operation Supervisor will have with Chapter 7, and the means of egress is testing completed for all doors and continuously maintained free of all obstructions to full use in case of emergency, unless modified by certification of testing will be provided 18/19.2.2 through 18/19.2.11, to the Administrator for review. 18.2.1, 19.2.1, 7.1.10.1 This REQUIREMENT is not met as evidenced To ensure that this deficient practice by: Surveyor: 32973 does not reoccur and that future Based on observation, document review, and residents are not affected, the interview, the facility failed to maintain the 90 minute fire rated door assemblies. This was Administrator will provide inservice on evidenced by the absence of an annual testing requirement for 90 minute fire inspection and certification. This affected seven of seven smoke compartments, and could result rated door assemblies to Plant in the malfunction of the doors to contain fire to a Operations Supervisor and compartment. Maintenance Staff. 05/23/2018 NFPA 101. Life Safety Code, 2012 Edition Chapter 19 Existing Health Care Occupancies

FORM CMS-2567 (02-09) Provious Versians Obsolete

Event ID:Z01L21

Facility ID; CA030000021.

If continuation sheet Page 10 of 30

FURM APPROVED

PRINTED: 04/25/2018 FORM APPROVED DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES 16E0-8E60 ON BMO (X3) DATE BURVEY COMPLETED STATEMENT OF DEFICIENCIES (X1) PROVIDENSUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION AND PLAN OF CORRECTION IDENTIFICATION NUMBER: A. BUILDING 62 B. WING 056495 04/23/2018 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RD CASA COLOMA HEALTH CARE CENTER RANCHO CORDOVA, CA 95670 PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) (K5) COMPLETION DATE (X4) ID PREFIX PREFIX TAG TAG DEFICIENCY K 211 | Continued From page 10 K 211 19.1 General Requirements. K 211 continued 19.1.1 Application. 19.1.1.1 General. Administrator will review testing 19.1.1.1.3 General. The provisions of Chapter 4, quarterly to ensure that all required General, shall apply. testing is being completed as required. 4.5.3 Means of Egress. Administrator will report to the Quality 4.5.7 System Design/Installation, Any fire **Assurance Performance Improvement** protoction system, building service equipment, feature of protection. Committee at least annually during or safequard review of the facility's Emergency provided to achieve the goals of this Code shall be designed. Preparedness Plan. 05/23/2018 installed, and approved in accordance with applicable NFPA standards. 4.5.8 Maintenance. Whenever or wherever any device, equipment, system, condition, arrangement, level of protection, or any other feature is required for compliance with the provisions of this Code, such device, equipment, system, condition, arrangement, level of protection, or other teature shall thereafter bo

listed, labeled

maintenance:

protection rating by

and their accompanying

maintained, unless the Code exempts such

8.3.3.1 Openings required to have a fire

Table 8.3.4.2 shall be protected by approved.

lire door assemblies and fire window assemblies

hardware, including all frames, closing devices.

8.3.3 Fire Doors and Windows.

2

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE (A. BUILDING 02	CONSTRUCTION		E BURYE UPLETED	Υ
		056495	B. WING		04	/23/201	8
	PROVIDER OR SUPPLIER DLOMA HEALTH CAR	E CENTER	104	EET ADDRESS, CITY, STATE, ZIP 10 COLOMA RD NCHO CORDOVA, CA. 958:	CODE		
(X4) ID BREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTIV CROSS-REFERENCED TO TH DEFICIENCY	ON SHOULD BE LE APPROPRIATE	COMPL	ETION
K 211	anchorage, and sill requirements of NFPA 80, Standard Opening Protective except as otherwis NFPA 80, Standard Opening Protective Chapter 5 Care an 5.1* General. 5.1.1 Application. 5.1.1.1 This chapte maintenance of fire doors and fire to 5.2.14 Maintenance 5.2.14 Maintenance 5.2.14 Fire door as and tested not less than annually, inspection shall be signed and kep Findings: During a facility tot interview with staff inspection and tested requested. At 2:30 p.m., the fe	s in accordance with the I for Fire Doors and Other I's, e specified in this Code. I for Fire Doors and Other I's, 2010 edition. I Maintenance er shall cover the care and windows. e of Closing Mechanisms ng devices shall be kept in	K 211	DEFICIENCY			2010 IN 17 - 7
	cross-corridor doo openings, located certification for an available for review	rs, in the two hour wall inside the corridors. No nual testing and inspection was w. Upon interview, Staff 2 annual testing/inspection was				IS I.G &	7 PH 3:47

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICARD SERVICES

	ENTERS FOR MEDICARE & MEDICAID SERVICES				OMB NO. 093		
	TEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA PLAN OF CORRECTION UMBER:		A, BUILD		ECONSTRUCTION 12	COM (X3) DAT	E SURVEY PLETED
		056495	E, WING			04/23/2018	
	PROVIDER OR SUPPLIER DLOMA HEALTH CAR	E CENTER		10	REET ADDRESS, CITY, STATE, ZIP CODE 1410 COLOMA RO ANCHO CORDOVA, CA 85670	,	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES Y MUST BE PRECEDEO BY FULL SC (DENTIFYING INFORMATION)	PREF TAG		PROVIDER'S PLAN OF CORRECTING ACTION SHOULD CROSS-REFERENCED TO THE APPRODEFICENCY)	DBE	COMPLETION CATE
K 345 SS=D	Fire Alarm System A fire alarm system accordance with ar with the requireme Electric Code, and and Signaling Cod- acceptance, maint- available. 9.6.1.3, 9.6.1.5, NF This REQUIREME by: Surveyor: 32973 Based on observal Interview, the facili- alarm system (FAS failure to perform a This affected seve compartments, an maifunction or delia a fire. NFPA 101, Life Sa 19.3.4.1 General, be provided with a accordance with s 9.6.1.5* To ensure alarm system shall have an appropriate complying with the NFPA 70, Nationa	tion, document review, and ty falled to maintain the fire it. This was evidenced by the a semi-annual FAS inspection, of seven smoke discould result in a system ay in notification in the event of the elarm system in the elarm system in ection 9.6 operational integrity, the fire roved maintenance and testing applicable requirements of it.	K	345	K 345 Temporary and Permanent It is the policy of this facility maintain the Fire Alarm Systems and Main required. Plant Operations Supervisor schedule (FAS), fire alarm is annual inspection to be do months after testing comp 04/18/2018 to maintain se testing as required. To ensure that this deficient does not reoccur and that residents are not affected, be provided to Plant Opera Supervisor and Maintenan reviews required testing in fire alarm systems, includit doors semi-annually. Required the Ad quarterly and reviewed by Assurance Performance in Committee annually durin	to tem tenance r will ystem the six leted mi-annitions ce Staff tervals in the Cumprover	e as semi- ual ice ce will that of ng of sting ator ality nent

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

	OF DEFICIENCIES OF CONRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUI A. BUILD		E CONSTRUCTION		SURVE		
			B. WING			04/2	3		
	PROVIDER OR SUPPLIER DLOMA HEALTH CAP	RE CENTER		11	TREET ADDRESS, CITY, STATE, XIP CODE 0410 COLOMA RD NANCHO CORDOVA, CA 95670				
(X4) ID PREFIX DAT	(EACH DEFICIENC	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC (DENTIFYING INFORMATION)	IO PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPS DEFICIENCY)	BE	COMPLE DATE		
K.345	Code, 2010 Edition Chapter 14 Inspect 14.1 Application. 14.1.1 The Inspect of systems, their initiating device shall comply with the requirement 14.3 inspection. 14.3.1* Unless other visual inspections shall be performed schedules in Table 14.3.1 or more authority having jurisdiction. 14.3.2 Devices or for safety considerations (e.g. operations, energical equipment height) shall be permitted scheduled shutdown if approved by the 14.3.4 The visual ensure that there are no changerformance. Table 14.3.1 Visual ensure that there are no changerformance. Table 14.3.1 Visual ensure that there are no changerformance.	ition, Testing, and Maintenance ition, and ition appliances into a coordance with the ition accordance with the ition accordance with the ition accordance with the aquipment that is inaccessible in, continuous process and it, radiation, and excessive ito be inspected during was authority having jurisdiction, aspection shall be made to ges that affect equipment in inspection annually essors of unit trouble signals emergency voice/alarm quipment itators	K	345			LICTURE & SERVICE AND STREET AND	2016 HAY -7 PG 37 47	

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

	AN OF CORRECTION (X1) PROVIDERSUPPLIERICUS IDENTIFICATION NUMBER:		A. BUILD		LE CONSTRUCTION	COMPLETED			
	056495				the stage of the s	04/2	3/201	8	
	PROVIDER OR SUPPLIER DLOMA HEALTH CAP	RE CENTER		1	STREET AODRESS, CITY, STATE, ZIP CODE 10410 COLOMA RD RANCHO CORDOVA, CA 95670	•			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SCIDENTIFYING INFORMATION)	ID PREF TAG	ix:	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL OF CROSS-REFERENCED TO THE APPROP DEFICIENCY)	39C	COMPL DA		
K 945	10. Guard's tour et 11. Combination sy electronic monitori (b) Carbon monoxi 12. Interface equip 13. Alarm notificati 14. Exit marking at 15. Supervising stransmission equip 20. Mass notificati systems installed 14.6.2 Maintenance 17. Supervising stransmission equip 20. Mass notificati systems installed 14.6.2 Maintenance 14.6.2.1 Records test and for 1 year thereafter. 14.6.2.4* A record maintenance shall be provided information regard tests and all the a in Figure 14.6.2.4: (1) Date (2) Test frequency (3) Name of prope (4) Address (5) Name of personalntenance, tests, or combinatiousiness address, and telepton (1).	quipment stems (a) Fire extinguisher and device/systems and edectors/systems ament on appliances ation alarm systems-receivers alon alarm systems-receivers alon alarm systems-receivers and the alarm systems on system, non-supervised orier to adoption of this edition se, inspection, and Testing shall be retained until the next of all inspections, testing, and that includes the following ining policable information requested on performing inspection, and affiliation, phone number is, and representative of		345			105.4	2010 RAY - 7 PK 3: 47	

IN DEAL OF DESCRIPTION IN INCAPORIOATION IN INDEED.		(X2) MULTIPLE A. BUILDING (E CONSTRUCTION	(X3) DATE SL COMPLE	RVEY	
	056495 ME OF PROVIDER OR SUPPLIER		B. WING		04/23/201	
	HOVIDER OR SUPPLIER DLOMA HEALTH CAF	RE CENTER	10	Theey address, city, state, zip code P410 Coloma RD ANCHO CORDOVA, CA 8967D	•	
(X4) ID PREFIX TAG	(EACH DEFICIENC	NTEMENT OF DEFICIENCIES. Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROF DEFICIENCY)	DBE CC	(XS) MPLETION DATE
K 345	Continued From pa	age 16	K 345	к 353	and an exemple desired in the second.	
	automatic FAS. Th	ne current Annual Fire Alarm 4/17/18. No semi-annual		Temporary and Permanent C	orrection	
	inspection prior to	the annual testing was		It is the policy of this facility t	0	
		v. Upon Interview, Staff 2 FAS was inspected and tested		Maintain Maintenance and T		
ez aria	on an annual basis		K 353	CEDIAL NEDA 101 as required		
SS=D		Maintenance and Testing	K 353	policy of this facility to test si		
		Maintenance and Testing		System quarterly and to insp	ect	
	Automatic sprinkle	r and standpipe systems are]	sprinkler components.		
		and maintained in accordance ndard for the inspection,	1	The Plant Operations Supervi	isor will	
	Testing, and Maint	aining of Water-based Fire		replace the three pendant st		
		s. Records of system design, ection and testing are	:	sprinklers that are located di	rectiv	
	maintained in a se	cure location and readily		above the dish washing area		
•	available. a) Date sprinkler	system last checked		To ensure that this deficient		v
	b) Who provided	system test		does not reoccur and that fu		
	c) Water system	sundy source		residents are not affected, a		2
				will be provided to the Plant		
		RKS information on coverage for or partial automatic aprinkler	ľ	Operations Supervisor and		
	system.	• • • • • • • •		Maintenance staff by the Ad		ir
	9.7.5, 9.7.7, 9.7.8, This REQUIREME	and NFPA 26 ENT is not met as evidenced		that reviews facility policy to		
	by:			sprinklers inspected quarter		
	Surveyor: 32973 Based on observa	ition, document review, and		replace any sprinklers that s		
	Interview, the facil	ity falled to maintain the	1	of Leakage, Corrosion, Physi	cal 🔒	1411.0107
	This was evidence	omatic fire sprinkler system. ad by the failure to perform one		damage, Loss of fluid in the	giass bulb	. c
	of four quarterly to	est and inspections, and ents with corrosion. This		heat responsive element, *1	oading,	- -
		seven smake compartments,		Painting unless painted by t	ne sprinkl	ei i
				manufacturer.	05/	23/20

DEPARTMENT OF HEALTH AND HUMAN SERVICES. CENTERS FOR MEDICARE & MEDICAID SERVICES

	ATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 056495		(X2) MUL A. BUILD		CONSTRUCTION 2	(X3) DATE	SURVEY	
	056495 OF PROVIDER OR SUPPLIER				4118	04/23/2		
	ROVIDER OR SUPPLIER			104	REET ADDRESS, CITY, STATE, ZIP CODE 110 COLOMA RD NCHO CORDOVA, CA 95670			
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOU CROSS-REFERENCED TO THE APPRO DEFICIENCY)	LD BE	(X5) COMPLETI DATE	ON
	(8) Functional test (9)*Functional test operations (10) Check of all s (11) Loop resistant line-type heat detectors (12) Functional test control units (13) Functional test mass notification systems (14) Functional test system to silence fire alarm (15) Tests of intell system speakers (16) Other tests at manufacturer 'S published instruct (17) Other tests at having jurisdiction (18) Signatures of representative (19) Disposition of (e.g., system owner notified, proretested, device abandoned Findings: During a facility to	the detector(S) tested of detectors of required sequence of moke detectors se for all fixed-temperature, at of mass notification system at of signal transmission to st of ability of mass notification notification appliances igibility of mass notification is required by the equipment ions is required by the authority of tester and approved authority of problems identified during test oblem corrected/successfully d in place)		345		CERTIFICATION PROGRAM	2018 MAY - 7 PM 3: 47	HEAVE TO THE LEGISLATION OF THE PROPERTY OF TH

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

<u> </u>	10 T OF MILDION IL	& MEDICAID SERVICES			<u> </u>		0930-0391
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/BUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUI A, BUILC		E CONSTRUCTION 02	(X3) DATE COM	SURVEY
		056495	B. WING			04/2	23/2018
	PROVIDER OR SUPPLIER DLOMA HEALTH CAR	IE CENTER		10	TREET ADDRESS, CITY, STATE, ZIP CODE 0410 COLOMA RD ANCHO CORDOVA, CA 95670		
(X4) ID PREFIX TAB	(EACH DEFICIENC!	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	DEE	DATE
K 353	automatic fire sprin fire. NFPA 101, Life Set 19.3.5 Extinguishm 19.3.5.1 Buildings be protected throughout by an e sprinkler system in unless otherwise permitted by 19.3.1 9.7 Automatic Spri Equipment. 9.7.5 Maintenance sprinkler and standpipe systems inspected, tested, and mainta 25, Standard for the Inspection, Water-Based Fire Systems. NFPA 25, Standar and Maintenance Systems, 2011 Ed 4.3 Records 4.3.1* Records sh tests, and mainter components and s authority having ju Chapter 5 Sprinkle 5.1.1 Minimum Re 5.1.1.1 This chapt	the ineffective operation of the akler system in the event of a lety Code, 2012 Edition. The result of a state of the event of a lety Code, 2012 Edition. The result of a containing nursing homes shall approved, supervised automatic accordance with Section 9.7, 5.5. Inklers and Other Extinguishing and Testing. All automatic arequired by this Code shall be sined in accordance with NFPA. Testing, and Maintenance of Protection. In the Inspection, Testing, of Water-Based Fire Protection into a made for all inspections, the shall be made available to the unisdiction upon request.		353	Administrator will review testing will be reported annu Quality Assurance Performar Improvement Committee du review of Emergency Prepare Procedures.	ice and ially to nce: ring an edness	the

	F CORRECTION	IDENTIFICATION NUMBER:	A, BUILD		02		APLETED	
		056495	a. WING			04	/23/201	8
	PROVIDER OR SUPPLIER DLOMA HEALTH CAF	RE-CENTER		1	TREET ADDRESS, CITY, STATE, ZIP CODE 0410 COLOMA RD LANCHO CORDOVA, CA 95670			,
(X4) ID PRIEFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTIO (EACH GORRECTIVE ACTION SHOULD CROSS: REFERENCED TO THE APPROF DEFICIENCY)	380	COMPL DA	ETION
K 353	and maintenance of 5.2.1 Sprinklers. 5.2.1.1.1 Sprinklers. 5.2.1.1.1 Sprinklers. 1.2.1.1.2 Sprinklers. 1.2.1.1.2 Sprinklers. 1.2.1.2 Sprinklers. 1.3.1.2 Sprinklers. 1.3.1.2 Sprinklers. 1.3.1.2 Sprinklers. 1.3.3 Physical damage. 1.3.4 Loss of fluid in element. 1.3.4 Loss of fluid in element. 1.3.5 Waterflow All Waterflow alarms: shell be inspected free of physical damage. 1.3.3 Waterflow All Sa.3.1 Mechanical including, but not it shall be tested quarterly. 1.3.7.1 Fire departing the spected quarterly. 1.3.7.1 Fire departing the spected quarterly. 1.3.7.1 Fire departing the spected quarterly. 1.3.1 Sprinklers. 1.3.3 Sprinklers. 1.3.4 Sprinklers. 1.3.4 Sprinklers. 1.3.4 Sprinklers. 1.3.5 S	of sprinkler systems. Is shall not show signs of ree of corrosion, foreign and physical damage; and shall correct orientation (e.g., or sidewall). It is sidewall, it is sidewall, it is sidewall, it is sidewall, it is sidewall. It is sidewall, it is sidewall it is sidewall, it is shall be sidewall, it is sidewall it is sidewall it is sidewall, it is shall be sidewall, it is sidewall, it is sidewall, it is shall be sidewall, it is sidewall, it is sidewall, it is shall be sidewall, it is sidewall, it is sidewall, it is sidewall, it is shall be sidewall.	K	353			MV85054 ILL STATISTICS W	2016 HAY -7 PH 3: 47

REPORTED AT	TIEMETTI MIND MOMINIA DEMAIDED

CENTER	IS FOR MEDICARE	& MEDICAID SERVICES	OMB NO. 0938-0391						
BTATEMENT	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUI A. BUILD		CONSTRUCTION 12	(X3) DATE SURVEY COMPLETED			
l		056485	B. WING			04/3	23/2018		
NAME OF F	ROVIDER OR SUPPLIER			-	REETADDRESS, CITY, STATE, ZIP CODE				
CASACO	DLOMA HEALTH CAR	E CENTER			ANCHO CORDOVA, CA 95670				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	Tement of Deficiencies Y Must be preceded by Full SC Identifying Information)	PNET TAC		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE		
K 353	Continued From pa operating properly. (8) The fire departs in place and operat	nent connection clapper(s) is	K	353	K 355 Temporary and Permanent (Correct	ion		
	Findings:				It is the policy of this facility maintain portable fire exting required. Portable fire exting	ulshers			
During a facility tour, document review, as interview with staff on 4/23/18, the autom sprinkler system was observed.		on 4/23/18, the automatic fire			will be selected, installed, inst	pecte	i,		
	Kitchen, were obsesprinklers located area, were covered corrosion build-up. confirmed the finding. 2. At 1:05 p.m., the wet automatic fire testing and inspecsecond quarter (A)	ne sprinkler heads inside the erved. Three pendant style directly above the dish washing in a light green colored. Upon interview, Staff 2 ng. e facility was observed with a sprinkler system. No record for the orli, May, June) 2017-2018. aff 2 confirmed the finding.			NFPA 10, Standard for Portal Extinguishers. Plant Operations Staff will lo portable fire extinguisher in room so that the top of the fextinguisher is not more that above the floor.	wer the lau Ire			
K 355 SS=D	Portable Fire Extin CFR(s): NFPA 101 Portable Fire Extin Portable fire exting inspected, and man NFPA 10, Standar Extinguishers. 18.3.5.12, 19.3.5. This REQUIREMED by: Surveyor: 32973 Based on observe failed to maintain this was evidence.	guishers guishers guishers are selected, installed, intained in accordance with d for Portable Fire	K	355	To ensure that this deficient does not reoccur and that furesidents are not affected, in will be provided to the Plant Operations Supervisor and the Maintenance staff on NFPA Safety Code, 2012 including, requirement that fire exting weighing less that 40lbs shall installed so that the top of the extinguisher is not more that	ture ne 101 Life uishers I be ne fire	3		

FORM APPROVEO

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CUA IDENTIFICATION NUMBER:	A. BUILD		E CONSTRUCTION D2		SURVEY PLETED
		050495	B. WING		· · · · · · · · · · · · · · · · · · ·	04/2	23/2018
	PROVIDER OR SUPPLIER DLOMA HEALTH CAR	NE CENTER		10	TREET ADDRESS, CITY, STATE, ZIP CODE 0410 COLOMA RD IANCHO CORDOVA, CA 95870		
(X4) ID PREFIX TAG	EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC (DENTIFYING INFORMATION)	10 PREF TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	o ve	(X5) COMPLETION DATE
K 355	smoke compartme Inability of staff to rextinguisher in the NFPA 101 Life Saff 19.3.5.12 Portable provided in all health care occupa 9.7.4.1. 9.7.4.1* Where recanother section of this Code, porta selected, installed, inspected, end ma NFPA 10, Standard Extinguishers. NFPA 10, Standard Extinguishers. NFPA 10, Standard Extinguishers. NFPA 10, Standard Extinguishers. 06.1.3.8 Installation 6.1.3.8.1 Fire extinguisher is not the fire extinguisher is not the fire extinguisher is not the fitor. 6.1,3.8.2 Fire extingreater than 40 lb (18.14 lb installed so that the top of than 3 1/2 ft (1.07 m) above the 6.1.3.8.3 in no care the bottom	es. This affected one of seven interpretations, and could result in the readity access the fire event of a fire. ety Code, 2012 edition fire extinguishers shall be ancies in accordance with quired by the provisions of the fire extinguishers shall be sintained in accordance with d for Portable Fire. If of the extinguishers shall be installed fire extinguishers having a gross weight all be installed so that the top timore than 5 ft (1.53 m) above inguishers having a gross weight the fire extinguisher is not more effoor. If it is a fire extinguisher is not more than 5 ft (1.53 m) above inguishers having a gross weight the fire extinguisher is not more effoor.		355	K 355 Continued Fire extinguishers will be inspired the Plant Operations Supervious quarterly to ensure they are repair and that they are at the height. Documentation of inwill be maintained and review Administrator quarterly.	ected l sor in good e requi spectio	ired ns

		AND HUMAN SERVICES & MEDICAID SERVICES			O	FORM A		
STATEMENT	OF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CUA IDENTIFICATION NUMBER:	(X2) MUI		CONSTRUCTION	(X3) DATE		
		050495	B. WING		•	04/2	3/2018	В
NAME OF P	ADVIDER OR SUPPLIER			ST	REET ADDRESS, CITY, STATE, ZIP CODE			
CASA CO	LOMA HEALTH CAR	E CENTER			410 COLOMARD			
	011111111111111111111111111111111111111	True or angulations		HA	ANCHO CORDOVA, CA 95670			
(X4) ID PREFIX TAG	(EACH DEFICIENC!	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION	PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CONRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE _	COMPLE COMPLE TOATI	201
K 355	Continued From pa	ige 21	K	355		-		HAY -
	Findings:					•	ĒŽ.	1
	During a tour of the on 4/23/18, the por observed.	facility and interview with staff table fire extinguishers were					PRAGRAM	P:: 3: 4
	located in the Laur extinguisher was n of the operative ha floor. The extingul pounds. Upon Inte	cortable ABC fire extinguisher dry Room, was observed. The nounted to the wall with the top ndle at 62 inches above the sher weighed less than 40 erview. Staff 2 confirmed the					AM	
	finding.	N 4184 B-	ر ا	200	K 362	٠,		- 1
K 362 SS=D	Corridore - Constru CFR(s): NFPA 101		"	362	Temporary and Permanent	Correct	tion	
i.	Corridors - Constru 2012 EXISTING	uction of Wells			it is the policy of this facility			
	Corridors are sepa constructed with a rating. In fully sprit partitions are only smoke. In nonspri to the underside of the ceiling. Corrido underside of ceiling by Code.	trated from use areas by walls t least 1/2-hour fire resistance akiered smoke compartments, required to resist the transfer of akiered buildings, walls extend the floor or roof deck above or walls may terminate at the gs where specifically permitted			that corridors are separated areas by walls constructed walls constructed walls constructed was been sprinklered smoke comparts partitions are only required the transfer of smoke.	vith at 3 in fully ments,	V4-	
	in accordance with compartments the fire resistance of g if the walls have a rating the underside of ti	assemblies in corridor walls are a Section 8.3, but in sprinklered are no restrictions in area or plass or frames, the resistance rating, give the lifthe walls terminate at the ceiting, give brief description acribing the ceiting throughout			Plant Operations Supervisor celling penetration in celling 69 with a material that is ap capable of maintaining the stresstance of the smoke barr	, by Roo proved smoke rier.	m	
	19.3.6.2, 19.3.6.2					ι		

DEPARTMENT OF HEALTH AND HUMAN SERVICES

CENTER	S FOR MEDICARE	& MEDICAID SERVICES				MB NO.	0938-0391
STATEMENT AND PLAN O	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		E CONSTRUCTION D2	(X3) DATE COMP	SURVEY LETED
		056495	B. WING			04/2	3/2018
NAME OF P	ROVIDER OR SUPPLIER			87	REET ADDRESS, CITY, STATE, ZIP CODE	*	
CASA CO	LOMA HEALTH CAR	E CENTER:			0410 COLOMA RD		
				R	ANCHO CORDOVA, CA 95670		
(X4) ID PREFIX TAG	(EACH DEFICIENC)	NTEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(MS) COMPLETION DATE
K 362	Continued From pa		ĸ	362	K 362 continued		
	by:	NT is not met as evidenced			To ensure that this deficient	practic	e
	Surveyor: 32973	ion, the facility failed to			does not reoccur and that fu		
	maintain the integr	ity of the building corridor			residents are not affected b	-	
	construction. This	was evidenced by an unscaled This affected one of seven			deficient practice, inservice		
	smoke compartme	nts, and could result in the].		provided by the Administrat		e
		to other areas in the event of a il facility evacuation.			Plant Operations Supervisor		
			ĺ		Maintenance staff that cove		•
	Findings:				policy to maintain partitions		
	During a tour of the	a facility with staff on 4/23/18,			resist the transfer of smoke,	includit	ng.
	the corridor walls a	and ceiling were observed.	}		sealing penetrations.		
	At 11:40 a.m., ther	e was an approximately			Plant Operations Supervisor		ect
	corridor celling by	eter penetration located in the . Room 69.	ĺ		corridors weekly for one mor		
K 363	Corridor - Doors		K	363			a)
SS=D	CFA(s): NFPA 101				present. If no penetrations a	re toun	id.
	Carridor - Doors	t t			Monitoring will be reduced t		eriy
		orridor openings in other than as of vertical openings, exits, or			surveillance that is conducte		
	hazardous areas r	esist the passage of smoke	}		maintenance and reviewed t	y the	
		3/4 inch solid-bonded core erial capable of resisting fire for			Administrator Quarterly.	and the	na /an.1.0 .
	at least 20 minutes	a. Doors in fully sprinklered				105/A	3/2018
	smoke compartment the passage of sm	ents are only required to resist toke. Comidor doors and doors	f			=-	
	to rooms containing	g flammable or combustible.				15	H.
		sitive latching hardware. Roller ited by CMS regulation. These				تبر نیز	-
	requirements do n	ot apply to auxiliary spaces that				-	
		nmable or combustible material in bottom of door and floor				ICATION PROG	유
ĺ		ceeding 1 Inch. Powered doors				in O	٠. ا

		A LICENS AND OFFICES				FORM APPROVED
		& MEDICAID SERVICES				MB NO. 0938-0391
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	A. BUILO		CONSTRUCTION 2	(X3) DATE SURVEY COMPLETED
	4	056495	B. WING			04/23/2018
NAME OF P	AOVIDER OR SUPPLIER			STF	REET ADDRESS, CITY, STAYE, ZIP CODE	
040400	N ONE WESTER OF	E OFLITED		104	110 COLOMA RD	1
CASA CC	DLOMA HEALTH CAR	EGENTER		RA	INCHO CORDOVA, CA 95670	
(X4) ID PRIEFIX TAG	LEACH DEFICIENCY	ITEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	DE COMPLÉTION
K 363	Continued From pa	ige 23 1.9 are permissible if provided	K	363	K 363	1
	with a device capal	ote of keeping the door closed of is applied. There is no	'		Temporary and Permanent	Correction
	impediment to the	closing of the doors. Hold open e when the door is pushed or			It is the policy of this facility	
	pulled are parmitte	d. Nonrated protective plates are permitted, Dutch doors			Corridor doors and doors to	· '
		are permitted. Door frames			containing flammable or con	nhustible
	shall be labeled an	d made of steel or other		ì	materials have positive latch	1
		anco with 8.3, unless the			•	= 1
		nt is sprinklered. Fixed fire		- 1	hardware. It is the policy of	
		s are allowed per 8.3. In rtments there are no		- 1	to maintain doors that are n	ot
	restrictions in area frames in window	or fire resistance of glass or			obstructed from fully closing	and latch.
:		Parts 403, 418, 460, 482, 483,			Plant Operations Supervisor	made the
	and 485	S details of doors such as fire			following corrections:	
	protection ratings,	automatics closing devices,			1. The corridor door to the	
·	1	NT is not met as evidenced			One Utility room was adj	
	by: Surveyor: 32973	•		İ	that it fully closed and po	suvely
		tion and interview, the facility			latched.	
	failed to maintain t	he corridor doors. This was		-	2. Room 25 obstruction was	
	evidenced by door	s that were obstructed from			Arm chair that obstructe	d door
		tching. This affected three of partments, and could result in			from fully closing was rel	ocated so
	the inability to cont	tain smoke and/or fire to a	1		that it was not in the swi	• " "
	room.				the door.	ne paritor
	Findings:				3. The obstruction of the co	
	During a tour of th	e facility and interview with staff			door to Dining room 4 wa	as
		ors were observed.			removed. Arm chair was	
		he corridor door to the Station			from swing path of door,	05/23/2018
ľ	Doo Littley Doom	was observed. The decruise	I .	- 1	i e	02) 53) 5010

CENTERS FOR MEDICARE & MEDICAID SERVICES

FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(XI) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION (X A. BUILDING 02			(X3) ĐẠTE COM	(X3) DATE SURVEY COMPLETED	
L			056495	B. WING			04/23/2018		
l		ROVIDER OR SUPPLIER DLOMA HEALTH CAR	RE CENTER		STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RO RANCHO CORDOVA, CA 95670				
	(X4) ID PREFIX TAG	(EACH DEFICIENC)	NTEMENT OF DEFICIENCIES V MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFU TAG	\neg	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	COMPLETION DATE:	
	K 363	Continued From pa equipped with a se was opened to the close. The door fa latch. Upon intervi- finding. 2. At 11:14 a.m., the Room 25, was obs- obstructed from ful- arm chair stationed Upon interview, St. 3. At 11:45 a.m., the Room 4, was obsel with self-closing ar The door was obstruction of Buil CFR(s): NFPA 101 Subdivision of Buil Construction 2012 EXISTING Smoke barriers she fire resistance rath be permitted to ter Smoke dampers e penetrations in full an approved sprin	Ige 24 If-closing device. The door fullest extent, and allowed to fulle to fully close and positive ew. Staff 2 confirmed the ne corridor door to Resident erved. The door was ly closing and latching by an if in the swing path of the door. aff 2 confirmed the finding. The door was equipped at magnetic hold open devices, ructed from closing and chair placed against the door. aff 2 confirmed the finding. ding Spaces - Smoke Barrie	кз	63		practice cure this ovided ment not ing. Stricts iostruction struction reduc- ity fire of	e to aff d or ions ons ed drills f	CALIBURIA O
		19.3.7.3, 8.6.7.1(1 Describe any med in REMARKS.) hankal smoke control system ENT is not met as evidenced				OR PROGRAM	2018 HAY -7 PH 3:47	CHANITATI

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICARD SERVICES

	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CUA IDENTIFICATION NUMBER:	(X2) MUI A. BUILT		E CONSTAUCTION 02		SURVEY PLETED
		056495	B, WING			04/2	23/2018
1	PROVIDER OR SUPPLIER DLOMA HEALTH CAR	E CENTER		10	THEET ADDRESS, CITY, STATE, ZIP CODE 0410 COLOMA RD ANCHO CORDOVA, CA 96670		•
(X4) ID PREFIX TAG	(EACH DEFICIENC	NEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SCIDENTIFYING INFORMATION)	ID PREF TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CHOSS-REFERENCED TO THE APPROPE DEFICIENCY)	BE	(A) COMPLETION DATE
K 372	Based on observat failed to maintain it barrier walls. This penetration. This a compertments, and spread of smoke a facility, being unab residents to a full full free facility, being unab residents to a full full full failing, unless other following: (1) This requirement artium is used, and also shall apply: (a) Smoke barriers at an atrium wall compartments shall (2) Smoke dampen penetrations of sm heating, ventilating where an approves sprinkler system in been provided for to the smoke barriers to accommon plumbing, and compass through a wassembly construct through the celling of a smoke barrier	ion and Interview, the facility he integrity of the fire/smoke was evidenced by an unsealed fected two of seven smoke discussed could potentially allow the ind/or fire to other areas of the le to defend in-place, exposing acility evacuation. Fety Code, 2012 Edition. Fet		372	K 372 Temporary and Permanent of the policy of this facility smoke barriers that are consola ½ hour fire resistance ration. This facility will maintain the of the fire/smoke barrier wall. The Plant Operations Supervithe following correction: 1. The fire/smoke barrier wall in the attic above the 90 m cross-corridor doors by Rowith two inches unsealed penetration in the lower marea was sealed with a mathat is approved and capal maintaining the smoke resofthe smoke barrier.	to proving per 8 integrilis. sor ma all loca ninute pom 42 ight waterial bie of listance	ride i to .5. ty de ted

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Q [m111]m1	10 I OIT MEDIONIL	A MEDICAID SERVICES			CIVID NO.	0930-0381
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CUA IDENTIFICATION NUMBER:	(X2) MUL	TIPLE CONSTRUCTION ING 02	(X3) DATE COMP	BURVEY
		058495	B. WING		04/2	3/2018
CASA CO	PROVIDER OR SUPPLIER DLOMA HEALTH CAF			STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RD RANCHO CORDOVA, CA 95670		
(X4) IO PREFIX TAG	 (EACH DEFICIENC) 	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	PREFI		OULO BE	COMPLETION DATE
K 372	transfer of smoke. 8.5.6.3 Where a constructed as a fi shall be protected requirements of 8.1 a time period equal the assembly and smoke, unless the met. 8.5.6.4 Where sprimembrane of a fire buildings equipped automatic fire sprimescutcheon plates that the space aro does not exceed 1 between the edge sprinkler. 8.5.6.5 Where the sleeve to penetrate shall be securely a space between the filled with a material transfer of smoke. Findings: During a facility to 4/23/18, the fire/srobserved. At 12:30 p.m., the in the attic above to doors by Room 42 approximately two the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wal traveling through in the attic above the lower right wall traveling through in the attic above the lower right wall traveling through in the attic above the lower right wall the lower	smoke barrier is also re barrier, the penetrations in accordance with the 3.5 to limit the spread of the for I to the fire resistance rating of 8.5.6 to restrict the transfer of requirements of 8.5.6.4 are inklers penetrate a single resistance-rated assembly in I throughout with an approved rikler system, noncombustible shall be permitted, provided und each sprinkler penetration /2 in. (13 mm), measured of the membrane and the se penetrating item uses a se the smoke barrier, the sleeve set in the smoke barrier, and the set tem and the sleeve shall be all capable of restricting the		To ensure that this deficie does not reoccur and that residents are not affected Operations Supervisor will fire/smoke barrier walls a annually and when any cain the attic area. A Log of will be maintained by the Operations Supervisor and the Administrator quarter	t future Plant Il inspect t least sem bles are ru inspection Plant d reviewed	nl- in s i by /23/2018

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

	of deficiencies F Correction	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	V BRITDING 0	CONSTRUCTION 2	COMPLETED
		056405	8. WING		04/23/2018
(X4) (D		ATEMENT OF DEFICIENCIES	10 R/	REET ADDREGS, CITY, STATE, ZIP CODE 410 COLOMA RD ANCHO CORDOVA, CA 95670 PROVIDER'S PLAN OF CORRECTION	(ax) NC
PHÉFIX 1'AG		Y MUST BE PRECEDED BY FULL SC (DENTIFYING INFORMATION)	PREFIX	(EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROI DEFICIENCY)	
K 923	Continued From pa	nge 27	K 923		⊥
K 923	Gas Equipment - C CFR(s): NFPA 101	Cylinder and Container Storag	K 923	. К 923	
SS-D			.	Temporary and Permanent	Correction
		Cylinder and Container Storage and to 3,000 cubic feet	}	It is the malley of this feelite.	••
	Storage locations a	ere designed, constructed, and		It is the policy of this facility	
	ventilated in accord	dance with 5.1.3.3.2 and	}	maintain oxygen storage as	=
	>300 but <3,000 ci	ubic feet	•	is the policy of this facility th	• -
		are outdoors in an enclosure or		storage room door be equip	•
		Interior space of non- or le construction, with door (or		signage as required. The sig	
	gates outdoors) the	at can be secured. Oxidizing		Include the minimum: CAUT	
	separated from co sprinklered) or end	ed with flammables, and are mbustibles by 20 feet (5 feet if closed in a cabinet of		OXIDIZING GAS(ES) STORED SMOKING.	WITHIN NO
	1/2 hr. fire protecti			Sign was immediately placed	d on door
	Less than or equal	l to 300 cubic feet compartment, individual		by maintenance.	
	cylinders available	for immediate use in patient		To ensure that this deficient	practice
		aggregate volume of less than bic feet are not regulred to be		does not reoccur and the fu	ture
	stored in an enclos	sure. Cylinders must be	·	residents are not affected th	ne Staff
		autions as specified in 11.6.2. gn readable from 5 feet is on	\	Development Coordinator v	vill provide
		of a cylinder storage room, ludes the wording as a		inservice to all personnel or	facility
	minimum CAUTK	ON: OXIDIZING GAS(ES)		policy to maintain required	signage on
	STORED WITHIN	NO SMOKING." d so cylinders are used in order		oxygen storage rooms that i	ncludes the
	of which they are i	received from the supplier.		minimum: : CAUTION: OXID	IZING
		re segregated from full		GAS(ES) STORED WITHIN NO	SMOKING.
		acility employs cylinders with gauge, a threshold pressure			₩ 05/29/2018
	considered emply	is established. Empty cylinders	1		05/23/2018 T E
		old confusion. Cylinders stored otected from weather.			
	<u> </u>				MY -
FORM CMS-2	2567(02-99) Previous Varido	ns Obsoleto Event ID: Z01L2	t Fa	cilly ID: CA030000021 If continu	of teges legitariolism
					PH 3

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICARD SERVICES

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CUA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02			(X3) DATE SURVEY COMPLETED				
		056495	B. WING			04/23/2018				
NAME OF PROVIDER OR SUPPLIER CASA COLOMA HEALTH CARE CENTER				STREET ADDRESS, CITY, STATE, ZIP CODE 10410 CDLOMA RD RANCHO CORDOVA, CA 95670						
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		PREFIX (EACH CORRECTIVE ACTION BHO		PROVIDER'S PLAN OF CORRECTION SHOULD CROSS-REFERENCED TO THE APPROPRIES OF T	LO BE COMPLETION		ON		
K 923	REGULATORY OR LSC IDENTIFYING INFORMATION)		K	923		as daily onth to cained. coring w veillance operation the Saf	five If Vill e Ons	ווייים	ALIFORIIA CEPARTHENI	
	approximately 50	O cubic feet of stored oxygen. as not equipped with a No								

PRINTED: 04/25/2018 FORM APPROVED OMB NO. 0938-0391 DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X3) DATE SURVEY COMPLETED (X2) MULTIPLE CONSTRUCTION A. BUILDING 02 056495 B. WING 04/23/2018 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 10410 COLOMA RD CASA COLOMA HEALTH CARE CENTER RANCHO CORDOVA, CA 95670 PROVIDERS PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY) SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REBULATORY OR LSC IDENTIFYING INFORMATION) (XII) COMPLETION DATE (X4) ID PREFIX TAQ ID PREFIX TAG CERTIFICATION PROGRAM