AME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 2339 W. VALLEY BLVD. ALHAMBRA, CA 91803		DF DEFICIENCIES CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		01 - MAIN BUILDING 01 # 16279 CO	TE SURVEY MPLETED
ALHAMBRA, CA 91803 CAPID SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION) PREFIX TAG	IAME OF D	POWNED OR SUPPLIES	·.L			1/13/2016
Regulatory or List iteration Regulatory Representation Regulatory Regulatory Representation Regulatory Representation Regulatory Representation Regulatory Representation Regulatory Representation Regulatory Representation Regulatory Regulatory	-			1 :	2339 W. VALLEY BLVD.	
This facility was surveyed under 42 CFR Part 483.70(a), Life Safety Code NFPA 101, 2000 Edition, Chapter 19 Existing Health Care Occupancies, and other applicable codes. The following represents the findings of the Department of Public Health during the Life Safety Code Survey. Representing the Department of Public Health: Evaluator # 16279, REHS, HFE I Resident census: 38 Bed capacity: 43 Highest Scope & Severity: D NFPA 101 LIFE SAFETY CODE STANDARD One hour fire rated construction (with o hour fire-rated doors) or an approved automatic fire eximguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1 This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure that hazardous areas were maintained with a one hour fire rated construction, by falling to maintain one of two solled linen room doors to close automatically. In	PREFIX	(EACH DEFICIENC	CY MUST BE PRECEDED BY FULL	PREFIX	(EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE	(XS) COMPLETION DATE
483.70(a). Life Safety Code NFPA 101, 2000 Édition, Chapter 19 Existing Health Care Occupancies, and other applicable codes. The following represents the findings of the Department of Public Health during the Life Safety Code Survey. Representing the Department of Public Health: Evaluator # 16279, REHS, HFE I Resident census: 38 Bed capacity: 43 Highest Scope & Severity: D NFPA 101 LIFE SAFETY CODE STANDARD One hour fire rated construction (with o hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas when the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1 This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure that hazardous areas were maintained with a one hour fire rated construction, by failing to maintain one of two solled linen room doors to close automatically. In	K 000	INITIAL COMMEN	\TS	K 000)	
Department of Public Health during the Life Safety Code Survey. Representing the Department of Public Health: Evaluator # 16279, REHS, HFE I Resident census: 38 Bed capacity: 43 Highest Scope & Severity: D NFPA 101 LIFE SAFETY CODE STANDARD One hour fire rated construction (with o hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1 This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure that hazardous areas were maintained with a one hour fire rated construction, by failing to maintain one of two soiled linen room doors to close automatically. In		483.70(a), Life Sa Édition, Chapter 1	fety Code NFPA 101, 2000 9 Existing Health Care			
Evaluator #: 16279, REHS, HFE I Resident census: 38 Bed capacity: 43 Highest Scope & Severity: D NFPA 101 LIFE SAFETY CODE STANDARD One hour fire rated construction (with o hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1 This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure that hazardous areas were maintained with a one hour fire rated construction, by failing to maintain one of two solled linen room doors to close automatically. In		Department of Pu	blic Health during the Life			
Highest Scope & Severity: D NFPA 101 LIFE SAFETY CODE STANDARD One hour fire rated construction (with o hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1 This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure that hazardous areas were maintained with a one hour fire rated construction, by failing to maintain one of two soiled linen room doors to close automatically. In	*					
NFPA 101 LIFE SAFETY CODE STANDARD SS=D One hour fire rated construction (with o hour fire-rated doors) or an approved automatic fire extinguishing system in accordance with 8.4.1 and/or 19.3.5.4 protects hazardous areas. When the approved automatic fire extinguishing system option is used, the areas are separated from other spaces by smoke resisting partitions and doors. Doors are self-closing and non-rated or field-applied protective plates that do not exceed 48 inches from the bottom of the door are permitted. 19.3.2.1 This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure that hazardous areas were maintained with a one hour fire rated construction, by failing to maintain one of two soiled linen room doors to close automatically. In			38			
are a content a unal are approached at the later.		One hour fire rate fire-rated doors) of extinguishing system and/or 19.3.5.4 pithe approved autroption is used, the other spaces by sidoors. Doors are field-applied prote 48 inches from the permitted. 19.3 This STANDARD Based on observatiled to ensure the maintained with a construction, by fisoiled linen room.	AFETY CODE STANDARD ad construction (with o hour or an approved automatic fire tem in accordance with 8.4.1 rotects hazardous areas. When omatic fire extinguishing system e areas are separated from smoke resisting partitions and e self-closing and non-rated or ective plates that do not exceed be bottom of the door are 8.2.1 is not met as evidenced by: ration and interview, the facility hat hazardous areas were a one hour fire rated ailing to maintain one of two doors to close automatically. In	K 029	Supervisor checked all the doors of the facility. He did not find a similar deficiency except for one of the two doors of the soiled linen room in the basement which did not have an	

Any deficiency statement ending with an asterisk (*), denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

FORM CMS-2567(02-99) Previous Versions Obsolete

Facility ID: CA950000104

CENTE		& MEDICAID SERVICES			0		APPROVED 0938-0391
STATEMENT	OF DEFICIENCIES OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			E CONSTRUCTION 01 - MAIN BUILDING 01	(X3) DAT	E SURVEY PLETED
		055818	B. WING			08/	13/2016
NAME OF	PROVIDER OR SUPPLIER			S	TREET ADDRESS, CITY, STATE, ZIP CODE		
ROYAL C	SARDEN EXTENDED	CARE HOS		2	339 W. VALLEY BLVD.		
				F	ALHAMBRA, CA 91803		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTIO (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROP DEFICIENCY)	BE	(X5) COMPLETION DATE
	Findings: On August 12, 2016 11:05 a.m., the eval supervisor conducte tour of the facility. At 9:50 a.m., it was room (in the basem feet (sq. ft.). Upon conduced that this soil over 50 square feet doors (near the was a self-closing device and maintain the do (According to NFPA Edition, 19.3.2.1, all and spaces larger the storage of combusting quantities deemed in Having Jurisdiction, self-closing.) During this LSC tour was informed that a room must have self doors. He stated that self-closing device of possible. The deficient practice smoke compartment on August 12, 2016, above finding was as survey process and with the administrated.	from one area to another. 5, between 8:50 a.m. and luator and the maintenance ed a Life Safety Code (LSC) observed that the soiled linen ent) that was over 50 square closer observation, it was led linen room was slightly (sq. ft.) and one of the two ching machines) did not have et to automatically close, latch or in a closed position. 101, Life Safety Code, 2000 hazardous areas are rooms an 50 sq. ft., used for ble supplies and equipment in lazardous by the Authority and shall have doors that are of, the maintenance supervisor and shall have doors that are the would provide a son this door, as soon as the affected one of three ets. and August 13, 2016, the cknowledged during the during the exit conference, or and the maintenance			The Administrator in-serviced the Environmental Director and Maintenance Supervisor regarding importance of separating the soile linen area from the adjoining roor doors equipped with self-closing gathis would ensure that in the ever fire, the closed doors would not a smoke and/or fire to travel from room to adjoining areas or vice veres of the Maintenance Supervisor during daily rounds will check to ensure the hazardous areas are separated from other spaces by doors that are equivity self-closing devices. The Environmental Director will more ensure compliance and the findings be discussed with the QAA Commit for further recommendation if need to be described by the Date of compliance 08/31/16.	g the ed ns with gadget. In of a llow the rsa. In ghis hat mulipped enitor to swill tee ded.	
	7(02-99) Previous Versions C			Faci	lity ID: CA950000104 If continua	ition shee	t Page 2 of 4

CENTER	RS FOR MEDICARE	& MEDICAID SERVICES		ON	MB NO. 0938-0391
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTII A. BUILDIN	(X3) DATE SURVEY COMPLETED		
		055818	B. WING		08/13/2016
NAME OF	PROVIDER OR SUPPLIER			STREET ADDRESS, CITY, STATE, ZIP CODE	00/10/2010
ROYAL G	GARDEN EXTENDED	CARE HOS		2339 W. VALLEY BLVD. ALHAMBRA, CA 91803	
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)	BE COMPLETION
K 141 SS=D	Medical gas storage precautionary sign, ft, that is conspicuor gate of the storage shall include the foll CAUTION, OXIDIZI WITHIN, NO SMOK 8-3.1.11.3 (NFPA 98 This STANDARD is Based on observati review, the facility fa signs in areas where accordance with 19 where oxygen is bei Smoking" sign may emergencies. Findings: On August 13, 2016 10:50 a.m., the eval supervisor conducte tour of the facility. At 9:10 a.m., it was 6 (which was not in us oxygen tank, was ins Room 117. Upon cloobserved that a "No posted, outside of the	e areas shall have a readable from a distance of 5 usly displayed on each door or room or enclosure. The sign owing wording as a minimum: NG GAS(ES) STORED (ING. 18.3.2.4, 19.3.2.4, 19.3.2.4, 19.3.2.4, 19.3.2.4 NFPA 99 8.6.4.2. Areas ng stored without a "No increase the risk for fire between 8:55 a.m. and uator and the maintenance d a Life Safety Code (LSC) cobserved that a "crash" cart e), with a 25 cubic foot side the rehab room, next to ser observation, it was Smoking" sign was not	K 029	9 • On August 13, 2016, a "NO SMOKIN sign was immediately posted outside	ted exygen areas sk of cin- in- in- is cin- is cin- ity in- ed control of the control of the cin- is cin- ity in- ed control of the cin- ity in- ed control of the cin- ity in- ity in
ļ	director of nursing re	garding the missing "No ng this interview, the director			

DEMPIS MAILER OF THEMETH MIND HOMMIA OFWAINED

FORM APPROVED

		& MEDICAID SERVICES				FORM	APPROVED 0938-0391
TATEMEN OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01				(X3) DATE SURVEY COMPLETED	
055818			B. WING	·		08/	13/2016
	PROVIDER OR SUPPLIER				STREET ADDRESS, CITY, STATE, ZIP CODE		10/2010
ROYAL	SARDEN EXTENDED				2339 W. VALLEY BLVD. ALHAMBRA, CA 91803		:
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREFI TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD CROSS-REFERENCED TO THE APPROPE DEFICIENCY)	BE	(X5) COMPLETION DATE
K 141	Continued From pa of nursing stated the be posted outside the be posted, immedia	at a "No Smoking" sign should nis room and that a sign would	K 1	141			
	policy and procedur conducted. The poli	ew the facility's oxygen safety e (dated August 2002) was cy stated that "No Smoking" ly visible in areas where in use.					
	The deficient practic smoke compartmen	ce affected one of three ts.					
	acknowledged durin	, the above finding was g the survey process and erence, with the administrator e supervisor.					
						-	
1 1				-			
:							
1						!	