PRINTED: 12/13/2016 DEPARTMENT OF HEALTH AND HUMAN SERVICES FORM APPROVED CENTERS FOR MEDICARE & MEDICAID SERVICES OMB NO. 0938-0391 (X3) DATE SURVEY STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER (X2) MULTIPLE CONSTRUCTION A BUILDING 01, 02 055975 12/08/2016 NAME OF PROVIDER OR SUPPLIER STREET ADORESS CITY STATE ZIP CODE 1889 NATIONAL CITY BLVD HILLCREST MANOR SANITARIUM NATIONAL CITY, CA 91950 SUMMARY STATEMENT OF DEGICIENCIES PROVIDER'S PLAN OF CORRECTION COMPLETION DATE (X41 ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL EACH CORRECTIVE ACTION SHOULD BE PREFIX REGULATORY OR ESC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) K 000 The following plan of correction K 000 I INITIAL COMMENTS represents Hillcrest Manor Surveyor: 29626 Sanitarium's credible allegation of compliance. K3 BUILDING: 01 (ANNEX) K6 PLAN APPROVAL: 9/17/1968 The purpose of this plan of correction K7 SURVEY UNDER: 2012 EXISTING TYPE OF CONSTRUCTION: ONE STORY, is to comply with Federal and State WOOD FRAME AND STUCCO regulations that require a "plan of CONSTRUCTION, TYPE V (111), FULLY correction" be submitted whenever a SPRINKLERED. deficiency is cited by the surveying agency. This plan in no way indicates K3 BUILDING: 02 that the facility or its administration K6 PLAN APPROVAL: 9/17/1968 K7 SURVEY UNDER, 2012 EXISTING agree or admit that the deficiency in TYPE OF CONSTRUCTION: ONE STORY + fact occurred, nor it is an admission of BASEMENT, CONCRETE CONSTRUCTION, uny kind CALIFORNIA DEP REMENT OF PUBLIC HEALTH TYPE II (111), FULLY SPRINKLERED. LICENSING & DESTINICATION FEOGRAM The following reflects the findings of the California Department of Public Health, during an annual Life Salety Code recertification survey. The findings are in accordance with 42 Code of Federal Regulations (CFR) §483.70 (a) National Fire Protection Association (NFPA) 101 - Life Safety Code, 2012 Edition, and NFPA 99 - Health Care Facilities Code, 2012 Edition. FETY CODE UNIT BERNARTINO Representing the California Department of Public Health: 2 3 2016 29626 DICEUSING AND CERTIFICATION The facility is not in substantial-compliance with PH GO DISTRICT OFFICE SOUTH 42 CFR §483.70 for Long Term Care Facilities. Census = 60 K 161 NFPA 101 Building Construction Type and Height K 161 S\$=E Building Construction Type and Height LABORATORY DIRECTORS OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE TITLE 12/28/16

with an esterisk (1) denotes a deficiency which the institution may be excused from correcting providing it is determined that the sateguards provide sufficient protoction to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the data of survey whether or not a plan of correction is provided. For nursing homes, the above findings stated above are disclosable 91 days following the data of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 91 days. days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation

FORM CMS-2567(02-59) Previous Versions Obsolete

Event ID, 861021

Facility ID: CA080000004

dmin

If continuation sheet Page 1 of 8

1/26/17-POC Acceptable per foul

FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MU A. BUILL		, ,	(X3) DATE SURVEY COMPLETED		
		055975	B. WING	à		12	08/2016
	PROVIDER OR SUPPLIER	RIUM		1	STREET ADDRESS, CITY, STATE, ZIP COD 889 NATIONAL CITY BLVD. NATIONAL CITY, CA 91950		
(X4) ID PREFIX TAG	(EACH DEFICIENC	ATEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID PREF TAG	ťΧ	PROVIDER'S PLAN OF CORRI (EACH CORRECTIVE ACTION SI CROSS-REFERENCED TO THE AP DEFICIENCY)	HOULD BE	(X5) COMPLETION DATE
K 161	Table 19.1.6.1, unl 19.1.6.2 through 1 19.1.6.4, 19.1.6.5 Constructi	on type and stories meets ess otherwise permitted by 9.1.6.7 on Type 332), II (222) Any number of non-sprinklered and One story Maximum 3 stories Not allowed CALIFORM		OER I	K161 This deficiency was written of failure of the facility to maintegrity of the building strumaintain fire safety as evider damaged roof in Building 1 (A was covered with material not 108 or ANSI/UL 790. A. Plastic cover damaged are of the Building 1 not ASTM E108 removed and rean Anti Sta	intain the cture and need by a nnex) that meeting E on the he roof of meeting will be placed by	01/13/17
	6 V (111) 7 III (200) non-sprinklered 8 V (000) sprinklered	Not allowed Maximum 1 story	LIFE S	AFET	A Licensed Contractor exam TY CODE UNIT roof to identify need to be repai replaced.	areas that	12/16/16
	Sprinklered stories throughout by an a system in accordad 19.3.5). Give a brief description of smoke approval. Complements of the building of the building and according to the building according to the buil	s must be sprinklered approved, supervised automation of the ption, in REMARKS, of the number of stories, including on which patients are located, or fire barriers and dates of the sketch or attach small floor gras appropriate.			B. An application Building Permit Project will be su OSHPD in orde repair of the roo the Licensed C recommendation.	and a New abmitted to record to begin f based on contractor's	01/13/17

CENTER	(S FOR MEDICARE	& MEDICAID SERVICES				AND NO.	0938-0391
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILDI		CONSTRUCTION , 02	(X3) DATE COMP	SURVEY
		055975	B. WING			12/0	8/2016
NAME OF F	PROVIDER OR SUPPLIER			STF	REET ADDRESS, CITY, STATE, ZIP CODE		
HILLCRE	ST MANOR SANITAR	RIUM			9 NATIONAL CITY BLVD. TIONAL CITY, CA 91950		
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIES MUST BE PRECEDED BY FULL SC IDENTIFYING INFORMATION)	ID. PREFIX TAG	×	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPROVIDERICENCY)	D BE	(X5) COMPLETION DATE
	stilled the main trial the evidenced by a dar (Annex) that was comeeting ASTM E 1 create a hazardous leaking through the NFPA 101, Life Saf 4.5.7 System Desig protection system, feature of protection achieve the goals coinstalled, and approapplicable NFPA st ASTM E 108, Stantests of Roof Coverings Findings: During the facility to on 12/8/16, the extra observed. At 8:30 a.m., the rocompletely covered area measured approapplications are measured approapplications. It is a supervision of the plant Supervision of the	ion and interview, the facility the interstanct of the Building 1 overed with material not 08 or ANSI/UL 790. This could condition from fire and water roof. Lety Code, 2012 Edition in interstallation. Any fire building service equipment, in, or safeguard provided to of this Code shall be designed, oved in accordance with andards. In dard Test Methods for Fire trings. Methods for Fire Tests of Roof or Building-1 (Annex) was a with a plastic material. The proximately 2,000 square feet, or stated that the roof was that been leaking and it is estated that a roofer had dies scheduled to look at the		61	C. While waiting for approval from OSHPD to start working on the project of repairing the roof and diminutes of the project of repairing the roof and diminutes of the project. Sheeting will remain in place to prevent further damage and protect the residents from any hazardous condition. The Fire Retardant Plastic Sheeting will only be removed upon completion of the project. D. The Maintenan Supervisor will initiate check log and responsible in checking the roof of Building I and the interior of the Annex ensure that there are leaks when it is raining while the roof is being replaced/repaired. CALIFORNIA DEPARTMENT OF A LICENSING & CERTIFICATION.	ce a be the to no ing ing	01/13/17 To 04/13/17
	NFPA 101 Fire Alai Maintenance	m System - Testing and	K3	345	SAN BERNARDIN	0	

STAYEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER 055975			(X2) MUIL A BUNLO		E CONSTRUCTION 01, 02	(X3) DATE COMP	SURVEY PLETED
		055975	B WING			12/08/2016	
	PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL :		ID PREFI	PREFIX (EACH CORRECTIVE ACTION S			(XS) COMPLETION DATE
K 345		ge 3 Testing and Maintenance is tested and maintained in	K 3	345	A. The deficiency was due to for to replacing smoke alarms that more than 10 years old. The exbattery operated smoke detector	werc pired	12/13/2010
	with the requiremen Electric Code, and I and Signaling Code	nance and lesting are readily		ment date misser dan 180 petersyala in data beta date date date meneral data da data	rooms 12, 20, 30, 32, SWI, SW removed B. New battery operated smoke alarms were installed to replace expired smoke alarms in rooms 20, 30, 32, SWI, SW4 (see attarpictures, receipt, and log).	12,	12/13/201(
***************************************	Surveyor, 29626 Based on observational failed to maintain the evidenced by failing	on and interview, the facility eir smoke alarms. This was to replace smoke alarms that rears old. This could cause			C. All new battery operated sm alarms were tested and function correctly. One alarm tested were per facility policy and documen smoke detector check log.	ing ckly	17/13/2016
	the smoke alarms to properly respond to residents. This affect rooms in Building-2. NFPA 101, Life Safe 9.6.2.10.1.1 Where this Code, single-sta	maifunction and staff to not a fire, resulting in injury to cted 6 of 17 resident sleeping by Code, 2012 Edition required by another section of tion and multiple-station			D. Administrator will perform a random check of battery operated smoke alarms expiration date log to ensure scheduled checks are being done per facility policy.		12/14/201
	72, National Fire Alam unless otherwise pro 9.6.2.10.1.3, or 9.6.2		-		CADROREA E DECRETARA LIGERA E EL COMERCI		- O II - Automo
	NFPA 72 - National Fire Alarm Code, 2010 Edition 14.4.8.1 Unless otherwise recommended by the manufacturer's published instructions, single- and multiple-station smoke alarms installed in one- and two-family dwellings shall be replaced when 57(02-99) Previous Versions Obsoleta Event ID-B31021			English Control	ly ID. CADBOOOCOG4 LIFE SA HEEDRIGG	(athra cha	W-Dago A - 1 (

CENTER	(2 FOR MEDICARE	CENTERS FOR MEDICARE & MEDICAID SERVICES					0938-0391
	OF DEFICIENCIES F CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MUL A. BUILD		E CONSTRUCTION 01, 02	(X3) DATE SURVEY COMPLETED	
ì	055975		B. WING			12/08/2016	
NAME OF F	NAME OF PROVIDER OR SUPPLIER			Sī	TREET ADDRESS, CITY, STATE, ZIP CODE		
HILLCREST MANOR SANITARIUM					889 NATIONAL CITY BLVD. ATIONAL CITY, CA 91950		
(X4) ID PREFIX TAG	X (EACH DEFICIENCY MUST BE PRECEDED BY FULL					BE	(X5) COMPLETION DATE
K 345		to operability tests but shall be longer than 10 years from	КЗ	345			
,	Findings:		! ! !	·			
		our with the Plant Supervisor gle station smoke alarms were					To the state of th
-	observed in Sleepin allowed 10 year rep	e smoke alarm that was an ag Room 30 exceeded the alacement period. The device g date of 10/3/2006.					
	observed in Sleepin	e smoke alarm that was g Room 32 exceeded the lacement period. The device g date of 6/9/2006.					
	observed in Sleepin	e smoke alarm that was g Room 20 exceeded the lacement period. The device g date of 6/9/2006.			CALITYS KALMINASKUS (1990). LICENIANG A COLA BUDI.	e e e e	
		e smoke alarm that was na.Ronm.12.exceeded tha g date of 6/9/2006.			A6. 34 - 7		
-	observed in Sleepin allowed 10 year rep	e smoke alarm that was ig Room Ward 4 exceeded the lacement period. The device ig date of 10/3/2006.			LIFE SAFETY CODE UNIT SAN BERNARDINO		
	observed in Sleepin allowed 10 year rep	e smoke alarm that was g Room Ward 1 exceeded the lacement period. The device g date of 10/3/2006.					

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION	(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER.	1	TIPLE CONSTRUCTION NG 81, 02		E SURVEY PLETED
	055975	@ WING		12/	08/2016
NAME OF PROVIDER OR SUPPLIE HILLCREST MANOR SANIT			STREET ADURESS, CITY, STATE, ZIP CO 1889 NATIONAL CITY BLVD. NATIONAL CITY, CA 91950	DE	
PREFIX (EACH DEFICIEN	TATEMENT OF DEFICIENCIES OY MUST BE PRECEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORR (EACH CORRECTIVE ACTION S CROSS-REFERENCED TO THE AI DEFICIENCY)	HOULD BE	(XS) COMPLETION DATE
SS=C Testing Sprinkler System Automatic sprinkle inspected, tested, with NFPA 25, Sta Testing, and Main Protection System maintenance, insp maintained in a se available. a) Date sprinkler 2/2014 b) Who provided Arrow Autom c) Water system Sweetwater A Provide in REMAR any non-required c system. 9.7.5, 9.7.7, 9.7.8,	atic supply source uthority KS information on coverage for partial automatic sprinkler	K 35	The deficiency was written failing to complete monthly inspections of components to pipe sprinkler system. A. The sprinkler system gandle valve are visually inspected and logged (see attached log sprinkler inspection report). B. The sprinkler system chewas initiated for monthly visof the valves and gauges. C. The maintenance superviperform a monthly visual chapter system valves and consure all valves and gauges physical damage. D. The administrator will p	visual o the wet uges and mouthly g and latest eck log sual check isor will eck of the gauges to s have no	12/17/201 12/17/201 12/17/201
failed to maintain the sent of the components to the This may affect the system that may carresulting in injury to	eview and interview, the facility meir automatic sprinkler evidenced by failing to wet pipe sprinkler system. Operation of the sprinkler suse delay during a fire, presidents. This affected 1 of the sin Building-1 and 2 of 2 of 5 in Building-1 and 2 of 2 of 5 in Building-1	-	random check of the sprinkly valves and gauges log to conscionalizate with the facilities CALIFORMIA DEFAREMENT LICENSING & CERTIFICATION AND CERTIFICATION OF	er system sure es policy.	
NFPA 101, Life Saf 19.3.5.1 Buildings of be protected throug	ely Code, 2012 Edition containing nursing homes shall shout by an approved, tic sprinkler system in		LIFE SAFETY	CODE UNIT	

		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER-	(X2) MULTIPLE CONSTRUCTION A BUILDING 01, 02				(X3) DATE SURVEY COMPLETED	
		055975	B. WING			12/	08/2016	
NAME OF PROVIDER OR SUPPLIER HILLCREST MANOR SANITARIUM			STREET ADDRESS, CITY, STATE, ZIP CODE 1889 NATIONAL CITY BLVD. NATIONAL CITY, CA 91950					
(X4) ID TAĞ				x	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE DEFICIENCY) (ADDODUMENT		(XS) COMPLETION DATE	
	THE STREET OF STREET OF STREET		K	CALIFORNIA DE SERVICIO				
	electrically supervise 13.3.2.2* The valve in valves are in the follo (1) In the normal ope (2)*Sealed, locked, o (3) Accessible (4) Provided with corresponding to the form externa (6) Provided with app	nspection shall verify that the liwing condition: In or closed position r supervised rect wrenches It leaks			LIFE SAFETY SAN BERI			

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) MULTIPLE CONSTRUCTION A BUILDING 01, 02			(X3) DATE SURVEY COMPLICTED	
		055975	B WING			12/08/2016	
NAME. OF	PROVIDER OR SUPPLIER				ITY, STATE, ZIP CODE		
				1889 NATIONAL CIT	Y BLVD.		
(X4) ID PREFIX TAG	IX (EACH DEFICIENCY MUST BE PRECEDED BY FULL		ID PREFL TAG	X (EACH CORE	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD B CROSS-REFERENCED TO THE APPROPRI DEFICIENCY)		
	(EACH DEFICIENCY MUST BE PRECEDED BY FULL		КЗ		FE SAFZTY CODE L SAN BERMARDIN	t t	
RM CMS-256	7(02-99) Previous Versions Ob	solete Event ID: B81021		acility ID: CA060000004	If continu	ation sheet Page 8 of B	

DEPARTMENT OF HEALTH AND HUMAN SERVICES

AH "A" FORM

CENTERS F	OR MEDICARE & MEDICAID SERVICES			A FORM						
STATEMENT OF ISOLATED DEFICIENCIES WHICH CAUSE		PROVIDER #	MULTIPLE CONSTRUCTION	DATE SURVEY						
NO HARM WITH ONLY A POTENTIAL FOR MINIMAL HARM			A. BUILDING: 01, 02	COMPLETE:						
FOR SNFs ANI) NFs	055975	B WING	12/8/2016						
NAME OF PRO	NAME OF PROVIDER OR SUPPLIER		CITY, STATE, ZIP CODE							
HILLCREST MANOR SANITARIUM		1889 NATIONA NATIONAL CIT								
ID PREFIX TAG	SUMMARY STATEMENT OF DEFICH	ENCIES								
K 100	NFPA 101 General Requirements - Other									
	by the provided K-tags, but are deficit NFPA standard citation, should be inc This STANDARD is not met as evide Surveyor: 29626 Non-releasing metal bars were observe Building-1 (Annex). The bars were plincluding Rooms 1, 2, 3, 4, 5 and 6, as and gates that lead to the public way were	IARKS section any LSC Section 18.1 and 19.1 General Requirements that are not addressed K-tags, but are deficient. This information, along with the applicable Life Safety Code or citation, should be included on Form CMS-2567. RD is not met as evidenced by: 6 metal bars were observed to be installed on the exterior side of 14 windows located in nex). The bars were placed over 2 of 2 windows in each of the patient sleeping rooms, as 1, 2, 3, 4, 5 and 6, as well as over a storage room window, and a lavatory window. Doors								
K 232	Medicare and Medicaid Services (CMS), dated November 15, 2016, with the condition that the facility will provide a reasonable degree of fire safety and the identified requirement would not adversely affect resident. PUBLIC HEAUT or staff health and safety. NFPA 101 Aisle, Corridor, or Ramp Width									
	Aisle, Corridor or Ramp Width 2012 EXISTING The width of aisles or corridors (clear maintained to provide the convenient 19.2.3.4, exceptions 1-5. 19.2.3.4, 19.2.3.5 This STANDARD is not met as evide Surveyor: 29626	removal of nonambi	rving as exit access shall be at least 40 allatory patients on stretchers, except a	Shipqitteq7940						
	The corridor used as a means of egress to an exit door from sleeping rooms in Building-2, located between Ward 1 and the Day Room/Dining Room, did not meet the minimum required width of 48 inches per NFPA 101, 2012 Edition. The width of the corridor measured approximately 42 inches. A continues waiver was granted by the Centers for Medicare and Medicaid Services (CMS), dated August 10, 2007, with the condition that the facility will provide a reasonable degree of fire safety and the identified requirement would not adversely affect resident or staff health and safety.									

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of

The above isolated deficiencies pose no actual harm to the residents