



## CALIFORNIA DEVICE RECALL INFORMATION SHEET

### Hamilton Medical Recalls For Hamilton-C1/T1/MR1 For Degrading Capacitors

Recall Date	Product Description	Recalling Firm	Recall Reason
9/27/2023	<b>Hamilton-C1</b> REF: 161001, Portable Intensive Care Ventilator	<b>HAMILTON MEDICAL, INC.</b> Reno, Nevada	Degrading capacitors on the control board of ventilators and spare parts may leak electrolyte onto the control board causing a short circuit on the board and/or the capacitor to lose function and lead to interruption of ventilation.
9/27/2023	<b>Hamilton-T1</b> REF: 161006, Intensive Care and Transport Ventilator	<b>HAMILTON MEDICAL, INC.</b> Reno, Nevada	Degrading capacitors on the control board of ventilators and spare parts may leak electrolyte onto the control board causing a short circuit on the board and/or the capacitor to lose function and lead to interruption of ventilation.
9/27/2023	<b>Hamilton-T1</b> REF: 161009, Intensive Care and Transport Ventilator	<b>HAMILTON MEDICAL, INC.</b> Reno, Nevada	Degrading capacitors on the control board of ventilators and spare parts may leak electrolyte onto the control board causing a short

			circuit on the board and/or the capacitor to lose function and lead to interruption of ventilation.
9/27/2023	<b>Hamilton-Mr1</b> REF: 161010, Intensive Care Ventilator	<b>HAMILTON MEDICAL, INC.</b> Reno, Nevada	Degrading capacitors on the control board of ventilators and spare parts may leak electrolyte onto the control board causing a short circuit on the board and/or the capacitor to lose function and lead to interruption of ventilation.
9/27/2023	<b>Hamilton C1/T1/MR1</b> REF: MSP161502/12, Control Board Spare part for ventilator	<b>HAMILTON MEDICAL, INC.</b> Reno, Nevada	Degrading capacitors on the control board of ventilators and spare parts may leak electrolyte onto the control board causing a short circuit on the board and/or the capacitor to lose function and lead to interruption of ventilation.
9/27/2023	<b>Hamilton-T1</b> REF: MSP161339/02, ESM Shielding Set, Spare Part for ventilator	<b>HAMILTON MEDICAL, INC.</b> Reno, Nevada	Degrading capacitors on the control board of ventilators and spare parts may leak electrolyte onto the control board causing a short circuit on the board and/or the capacitor to lose function and lead to interruption of ventilation.

Recall Class	Product Identification	Distribution	Affected Dates
I	<b>Hamilton-C1</b> UDI: 07630002800747 & 07630002813426 / Affected Serial Numbers: 24177 24196 24216 24217 24219 24247 24250 24324 24360 24370 24431 24460 24467 24480 24487 24511 24523 24552 24556 24557 ...	164 Units Nationwide	26 July 2023 and prior
I	<b>Hamilton-T1</b> UDI: 07630002801850 & 07630002813532 / Affected Serial Numbers: 15929 17600 17661 17677 17698 17699 17741 17850 17877 17913 17925 17955 17957 17969 17975 17976 17982 17985 17986 17991 17993 17995 18009 18166 ...	76 Units Nationwide	26 July 2023 and prior
I	<b>Hamilton-T1</b> UDI: 07630002806091 & 07630002813549 / Affected Serial Numbers: 500816 501879 502181 502200 502587 502588 502589 502591 502647 502649 502650 502651 ...	1216 Units Nationwide	26 July 2023 and prior
I	<b>Hamilton-Mr1</b> UDI: 07630002800761 & 07630002813556 / Affected Serial Numbers: 3422 3423 3424 3425 3426 3427 3428 3429 3469 3503 3510 3800	12 Units Nationwide	26 July 2023 and prior
I	<b>Hamilton C1/T1/Mr1</b> UDI: 07630002805247 / Affected Serial Numbers: 4001901, 4002139, 4003445, 4003567, 4003576, 4005595	6 Units Nationwide	26 July 2023 and prior
I	<b>Hamilton-T1</b> UDI: 07630002800761 / Affected Serial Numbers:	4 Units Nationwide	26 July 2023 and prior

	4050193, 4050210, 4050194 and 4016669		
--	--	--	--

FOR ADDITIONAL INFORMATION, PLEASE VISIT THE [FDA WEBSITE](#)

---

CDPH Food and Drug Branch  
MS 7602 ● P.O. Box 997435 ● Sacramento, CA 95899-7435  
(916) 650-6500 ● (916) 650-6650 FAX  
Internet Address: [www.cdph.ca.gov](http://www.cdph.ca.gov)

