

California Device Recall Information Sheet

Food and Drug Branch – Device Recalls

CareFusion 303, Inc. BD Pyxis Medflex

Recall Date	Product Description	Recalling Firm	Recall Reason
04/11/2025	BD Pyxis Medflex, REF: 1119-00; BD Pyxis Medbank Main, REF: 1137-00; BD Pyxis Medflex 2.0, REF: 1139-00; BD Pyxis Medbank Tower Main, REF: 1145-00; BD Pyxis Medbank Mini Main, REF: 1147-00; BD Pyxis Medbank Facility Software, REF: 139090-01; BD Pyxis Medbank Tower Main 2HH1FH2HM2FM2FG1FF, REF: 169-100; BD Pyxis Medbank Mini 1HH-1FH-1HM, REF: 169-101; BD Pyxis Medbank Mini 1HH-1HM-1FM, REF: 169-102; BD Pyxis Medbank Mini 1HH-3HM, REF: 169-103; BD Pyxis Medbank Mini 2FH, REF: 169-104; BD Pyxis Medbank Mini 2FM, REF: 169-105; BD Pyxis Medbank Mini 2HH-1FH, REF: 169-106; BD Pyxis Medbank Mini 2HH-1FM, REF: 169-107; BD Pyxis Medbank Mini 2HH-2HM, REF: 169-108; BD Pyxis Medbank Mini 2HM-1FM, REF: 169-109; BD Pyxis Medbank Mini 3HH-1FG, REF: 169-110; BD Pyxis Medbank Mini 3HH-1HM, REF: 169-111; BD Pyxis Medbank Mini 4HH, REF: 169-112; BD Pyxis Medbank Mini 4HM, REF: 169-113; BD Pyxis Medbank Tower Main	CareFusion 303, Inc.	If "Clear All" selected medications is selected on patient profile, the automated dispensing cabinet may allow dispensing of medication without first requiring the RxVerify Validation Code be entered/without validation from a pharmacist, which could lead to unintended and incorrect medication removal.

	7HH-1HM-3FM RxNow, REF: 169-132; BD Pyxis Medbank Mini 1FH-1FM, REF: 169-137; BD Pyxis Medbank Tower Main 1FH-10HM-1FM, REF: 169-138; BD Pyxis Medbank Tower Main 2HH-4FH-2FM, REF: 169-139; BD Pyxis Medbank Tower Main, REF: 169-153; BD Pyxis Medbank Tower RxNow Main With Med Pri, REF: 169-155; BD Pyxis Medbank Tower RxNow Main With Pat Pri, REF: 169-156; BD Pyxis Medbank Mini Main With Cubie Drawers, REF: 169-159; BD Pyxis Medbank Mini Main With Matrix Drawers, REF: 169-160; BD Pyxis Medbank Mini Main With HH False Drawer, REF: 169-161; BD Pyxis Medbank Mini Main With FH False Drawer, REF: 169-162; BD Pyxis Medbank Tower Main 10HH-1FH-1FM, REF: 169-23; BD Pyxis Medbank Tower Main 10HH-2FH, REF: 169-24; BD Pyxis Medbank Tower Main 10HH-2FM, REF: 169-25; BD Pyxis Medbank Tower Main 12HH-1FF, REF: 169-26; BD Pyxis Medbank Tower Main 12HH-1FH, REF: 169-27; BD Pyxis Medbank Tower Main 12HH-1FM, REF: 169-28; BD Pyxis Medbank Tower Main 14HH, REF: 169-29; BD Pyxis Medbank Tower Main 1HH-1HM-2FM-4FF, REF: 169-30; BD Pyxis Medbank Tower Main 2FH-2HM-4FM, REF: 169-31; BD Pyxis Medbank Tower Main 2HH-10HM-1FM, REF: 169-32; BD Pyxis Medbank Tower Main 2HH-1FH-5FM, REF: 169-33; BD Pyxis Medbank Tower Main 2HH-2FH-4FM, REF: 169-34; BD Pyxis Medbank Tower Main 2HH-2FM-4FF, REF: 169-35; BD Pyxis Medbank Tower Main 2HH-4HM-4FF, REF: 169-36; BD Pyxis Medbank Tower Main 2HH-4HM-4FM, REF: 169-37; BD		
--	--	--	--

Pyxis Medbank Tower Main 2HH-6FM, REF: 169-38; BD Pyxis Medbank Tower Main 2HH-6HM-3FM, REF: 169-39; BD Pyxis Medbank Tower Main 2HH-8HM-2FM, REF: 169-40; BD Pyxis Medbank Tower Main 2HM-6FM, REF: 169-41; BD Pyxis Medbank Tower Main 3FH-4FM, REF: 169-42; BD Pyxis Medbank Tower Main 3HH-7HM-2FM, REF: 169-43; BD Pyxis Medbank Tower Main 4HH-10HM, REF: 169-44; BD Pyxis Medbank Tower Main 4HH-1FH-2HM-3FM, REF: 169-45; BD Pyxis Medbank Tower Main 4HH-1FH-4FM, REF: 169-46; BD Pyxis Medbank Tower Main 4HH-1FH-4HM-2FM, REF: 169-47; BD Pyxis Medbank Tower Main 4HH-1FH-6HM-1FM, REF: 169-48; BD Pyxis Medbank Tower Main 4HH-2FH-2HM-2FM, REF: 169-49; BD Pyxis Medbank Tower Main 4HH-2FH-3FM, REF: 169-50; BD Pyxis Medbank Tower Main 4HH-2HM-4FM, REF: 169-51; BD Pyxis Medbank Tower Main 4HH-3FH-2FM, REF: 169-52; BD Pyxis Medbank Tower Main 4HH-4FH-1FM, REF: 169-53; BD Pyxis Medbank Tower Main 4HH-4HM-3FM, REF: 169-54; BD Pyxis Medbank Tower Main 4HH-5FH, REF: 169-55; BD Pyxis Medbank Tower Main 4HH-5FM, REF: 169-56; BD Pyxis Medbank Tower Main 4HH-6HM-2FM, REF: 169-57; BD Pyxis Medbank Tower Main 4HH-8HM-1FM, REF: 169-58; BD Pyxis Medbank Tower Main 4HM-5FM, REF: 169-59; BD Pyxis Medbank Tower Main 5HH-3HM-3FM, REF: 169-60; BD Pyxis Medbank Tower Main 5HH-9HM, REF: 169-61; BD Pyxis Medbank Tower Main 6FH-1FM, REF: 169-62; BD Pyxis Medbank		
---	--	--

	Tower Main 6HH-1FH-2HM-2FM, REF: 169-63; BD Pyxis Medbank Tower Main 6HH-1FH-3FM, REF: 169-64; BD Pyxis Medbank Tower Main 6HH-2FH-2FM, REF: 169-65; BD Pyxis Medbank Tower Main 6HH-2FH-2HM-1FM, REF: 169-66; BD Pyxis Medbank Tower Main 6HH-4FH, REF: 169-67; BD Pyxis Medbank Tower Main 6HH-4FM, REF: 169-68; BD Pyxis Medbank Tower Main 6HH-4HM-2FM, REF: 169-69; BD Pyxis Medbank Tower Main 6HH-6HM-1FM, REF: 169-70; BD Pyxis Medbank Tower Main 6HH-8HM, REF: 169-71; BD Pyxis Medbank Tower Main 7FH, REF: 169-72; BD Pyxis M		
--	---	--	--

Recall Class	Product Identification	Distribution	Affected Dates
II	BD Pyxis MedBank Receiving Cabinet Software Software versions: 2.1.2.11, 2.2.1.8, 2.31.8, 2.3.2.1, 2.4.2.26 REF/UDI-DI: 1119-00/10885403512704; 1137-00; 1139-00/10885403512704; 1145-00/10885403517167; 1147-00/10885403517181; 139090-01; 169-100/10885403512568; 169-101/10885403512544; 169-102/10885403512544; 169-103/10885403512544; 169-104/10885403512544; 169-105/10885403512544; 169-106/10885403512544; 169-107/10885403512544; 169-108/10885403512544; 169-109/10885403512544; 169-110/10885403512544; 169-111/10885403512544; 169-112/10885403512544; 169-113/10885403512544; 169-132/10885403512568; 169-137/10885403512544;	California Department of Public Health was not impacted by this recall	October 2023 and Prior

169-138/10885403512568; 169-139/10885403512568; 169-153/10885403512568; 169-155/10885403512568; 169-156/10885403512568; 169-159/10885403512544; 169-160/10885403512544; 169-161/10885403512544; 169-162/10885403512544; 169-23/10885403512568; 169-24/10885403512568; 169-25/10885403512568; 169-26/10885403512568; 169-27/10885403512568; 169-28/10885403512568; 169-29/10885403512568; 169-30/10885403512568; 169-31/10885403512568; 169-32/10885403512568; 169-33/10885403512568; 169-34/10885403512568; 169-35/10885403512568; 169-36/10885403512568; 169-37/10885403512568; 169-38/10885403512568; 169-39/10885403512568; 169-40/10885403512568; 169-41/10885403512568; 169-42/10885403512568; 169-43/10885403512568; 169-44/10885403512568; 169-45/10885403512568; 169-46/10885403512568; 169-47/10885403512568; 169-48/10885403512568; 169-49/10885403512568; 169-50/10885403512568; 169-51/10885403512568; 169-52/10885403512568; 169-53/10885403512568; 169-54/10885403512568; 169-55/10885403512568; 169-56/10885403512568; 169-57/10885403512568; 169-58/10885403512568; 169-59/10885403512568; 169-60/10885403512568; 169-61/10885403512568;		
---	--	--

	169-62/10885403512568; 169-63/10885403512568; 169-64/10885403512568; 169-65/10885403512568; 169-66/10885403512568; 169-67/10885403512568; 169-68/10885403512568; 169-69/10885403512568; 169-70/10885403512568; 169-71/10885403512568; 169-72/10885403512568; 169-73/10885403512568; 169-74/10885403512568; 169-75/10885403512568; 169-76/10885403512568; 169-77/10885403512568; 169-78/10885403512568; 169-79/10885403512568; 169-80/10885403512568; 169-81/10885403512568; 139089-01		
--	---	--	--

For additional information, please visit the [FDA Website](#).