

**Mycobacterium chimaera Infections Associated with Exposure to  
Heater-Cooler Devices during Open Chest Cardiac Surgery**

**References**

**Publications**

Perkins K [CDC], et al., *Notes from the Field: Mycobacterium chimaera Contamination of Heater-Cooler Devices Used in Cardiac Surgery, United States*, MMWR 65(40), October 14, 2016

Sommerstein, R, et al., *Transmission of Mycobacterium chimaera from heater-cooler units during cardiac surgery despite an ultraclean air ventilation system*, Emerg Inf Dis (22)6, 2016

Haller S, et al., *Contamination during production of heater-cooler units by Mycobacterium chimaera potential cause for invasive cardiovascular infections: results of an outbreak investigation in Germany, April 2015 to February 2016*. Euro Surveill (21)17, 2016

Kohler P, et al., *Healthcare-associated prosthetic heart valve, aortic vascular graft, and disseminated Mycobacterium chimaera infections subsequent to open heart surgery*. Eur Heart J (36)40, 2015

Sax H, et al., *Prolonged Outbreak of Mycobacterium chimaera Infection After Open-Chest Heart Surgery*. Clin Infect Dis (61)1, 2015

Achermann Y, et al., *Prosthetic valve endocarditis and bloodstream infection due to Mycobacterium chimaera*. J Clin Microbiol (51)6, 2013

**CDC Guidance and Recommendations**

*Heater-Cooler Notification Toolkit*, October 13, 2016

<http://www.cdc.gov/HAI/outbreaks/heater-cooler.html>

*Interim Guide for the Identification of Possible Cases of Nontuberculous Mycobacterium Infections Associated with Exposure to Heater-Cooler Units*, May 13, 2016

<http://www.cdc.gov/hai/pdfs/outbreaks/Guide-for-Case-Finding.pdf>

*Non-tuberculous Mycobacterium (NTM) Infections and Heater-Cooler Devices: Interim Practical Guidance*, October 27, 2015

<http://www.cdc.gov/HAI/pdfs/outbreaks/CDC-Notice-Heater-Cooler-Units-final-clean.pdf>

CDC Contaminated Heater-Cooler Devices webpage

<http://www.cdc.gov/HAI/outbreaks/heater-cooler.html>

**FDA Safety Communications and Recommendations**

*UPDATED: Mycobacterium chimaera Infections Associated with Sorin Group Deutschland GmbH Stöckert 3T Heater-Cooler System*, FDA Safety Communication, October 13, 2016

<http://www.fda.gov/MedicalDevices/Safety/AlertsandNotices/UCM520191.htm>

*Mycobacterium chimaera Infections Associated with Sorin Group Deutschland GmbH Stöckert 3T Heater-Cooler System: FDA Safety Communication*, June 1, 2016

<http://www.fda.gov/MedicalDevices/Safety/AlertsandNotices/ucm504213.htm>

*Nontuberculous Mycobacterium Infections Associated with Heater-Cooler Devices: FDA Safety Communication*, October 15, 2015

<http://www.fda.gov/MedicalDevices/Safety/AlertsandNotices/ucm466963.htm>

**FDA Safety Communications and Recommendations (continued)**

*Brief Summary of the Medical Devices Advisory Committee, Circulatory System Devices Panel, Heater-Cooler Devices Meeting, June 2-3, 2016*

<http://www.fda.gov/downloads/AdvisoryCommittees/CommitteesMeetingMaterials/MedicalDevices/MedicalDevicesAdvisoryCommittee/CirculatorySystemDevicesPanel/UCM505732.pdf>

*FDA Heater-Cooler Devices webpage*

<http://www.fda.gov/MedicalDevices/ProductsandMedicalProcedures/CardiovascularDevices/Heater-CoolerDevices/default.htm>

**Manufacturer Instructions for Use, Maintenance, and Disinfection**

*Sorin Group, Heater-Cooler System 3T Operating Instructions, September 2015*

<http://www.livanova.sorin.com/products/cardiac-surgery/perfusion/hlm/3t>

For more information, please contact us at [HAIProgram@cdph.ca.gov](mailto:HAIProgram@cdph.ca.gov)