

State of California—Health and Human Services Agency

California Department of Public Health



Food and Drug Branch - Device Recalls

CALIFORNIA DEVICE RECALL INFORMATION SHEET

Caire, Inc. Recalls CAIRE Liberator Liquid Oxygen System Units due to inconsistencies in weld penetration on the inner bottle

Recall Date	Product Description	Recalling Firm	Recall Reason
12/14/2022	CAIRE Liberator 45, MODEL 13261699, Liquid Oxygen System Unit 10 devices	Caire, Inc., Ball Ground, Georgia	An audit discovered some inconsistencies in weld penetration on the longitudinal weld seam on the inner bottle of the device on some of the units.
12/14/2022	CAIRE Liberator 45, MODEL 13262253, Liquid Oxygen System Unit 70 Devices	Caire, Inc., Ball Ground, Georgia	An audit discovered some inconsistencies in weld penetration on the longitudinal weld seam on the inner bottle of the device on some of the units.
12/14/2022	CAIRE Liberator 30, MODEL 13337403, Liquid Oxygen System Unit 5 Devices	Caire, Inc., Ball Ground, Georgia	An audit discovered some inconsistencies in weld penetration on the longitudinal weld seam on the inner bottle of the device on some of the units.
12/14/2022	CAIRE Liberator 20, MODEL 13256195, Liquid Oxygen System Unit 3 Devices	Caire, Inc., Ball Ground, Georgia	An audit discovered some inconsistencies in weld penetration on the longitudinal weld seam on the inner bottle of the device on some of the units.

Recall Class	Product Identification	Distribution	Affected Dates
I	UDI/DI M766132616990, Serial Numbers: CBB3022310887, CBB3022310888, CBB3022310852, CBB3022310823, CBB3022310792, CBB3022310843, CBB3022310844, CBB3022310844, CBB3022310842, CBB3022310845	Worldwide Distribution including California	October 2022 and prior
	UDI/DI M766132622530, Serial Numbers: CBB3022311044, CBB3022311042, CBB3022311040, CBB3022311098, CBB3022311098, CBB3022311094, CBB3022311077, CBB3022311053, CBB3022311051, CBB3022311075, CBB3022311075, CBB3022311077, CBB3022311077, CBB3022311078, CBB3022311079, CBB3022311079, CBB3022311079, CBB3022311079, CBB3022311046, CBB3022311046, CBB3022311236, CBB3022311230, CBB3022311231, CBB3022311231, CBB3022311225, CBB3022311225, CBB3022311225, CBB3022311226, CBB3022311226, CBB3022311226, CBB3022311226, CBB3022311226, CBB3022311226, CBB3022311228, CBB3022311228, CBB3022311227, CBB3022311227, CBB3022311227, CBB3022311227, CBB3022311211, CBB3022311211, CBB3022311202, CBB3022311202, CBB3022311202, CBB3022311202, CBB3022311202, CBB3022311202, CBB3022311202, CBB302231155,	Worldwide Distribution including California	October 2022 and prior

T -	DD0000044405		
	CBB3022311135, CBB3022311171, CBB3022311106, CBB3022311109, CBB3022311108, CBB3022311084, CBB3022311083, CBB3022311082, CBB3022311082, CBB3022311131, CBB3022311131, CBB3022311136, CBB3022311136, CBB3022311178, CBB3022311178, CBB3022311179, CBB3022311179, CBB3022311179, CBB3022311177, CBB3022311177, CBB3022311177, CBB3022311177, CBB3022311175, CBB3022311176, CBB3022311176, CBB3022311176, CBB3022311169, CBB3022311169, CBB3022311169, CBB3022311169, CBB3022311169, CBB3022311169, CBB3022311169, CBB3022311169, CBB3022311176,		
	CBB3022311170, CBB3022311180, CBB3022311057,		
I U	DBB3022311129 JDI/DI M766133374030, Serial lumbers: CBB3022300368, CBB3022300390, CBB3022300470, CBB3022300472, CBB3022300479	Worldwide Distribution including California	October 2022 and prior
5	JDI/DI JDI/DI J766133374030M7661325619 JO, Serial Numbers: CBB3022320073, CBB3022320077, CBB3022320074	Worldwide Distribution including California	October 2022 and prior

FOR ADDITIONAL INFORMATION, PLEASE VISIT THE FDA WEBSITE

