



Food and Drug Branch – Device Recalls

CALIFORNIA DEVICE RECALL INFORMATION SHEET

Thoratec Corp. Recalls Heartmate Touch Communication System Due to Faulty Software and Controller System

Recall Date	Product Description	Recalling Firm	Recall Reason
2/14/2024	HeartMate Touch Communication System 1. HeartMate Touch Communication System, REF HMT1100 2. HeartMate Touch Communication System, Rental REF HMT1100-R 3. HeartMate Touch Communication System, HMT1150	THORATEC CORP. Pleasanton, California	This product is being recalled due to faulty software and controller systems that result in unexpected pump start and stop.

Recall Class	Product Identification	Distribution	Affected Dates
I	HeartMate Touch Communication System HeartMate Touch Communication System Model Number: HMT1100 UDI-DI Code: 05415067032058	1560 Units Nationwide including California	February, 2024 and prior

FOR ADDITIONAL INFORMATION, PLEASE VISIT THE [FDA WEBSITE](#)

