MAHC adopted new steps to prevent pool chlorine exposure incidents

The following were proposed by

- CDPH, Environmental & Occupational Emergency Preparedness Team
- Contra Costa County Environmental Health
- Contra Costa County Hazardous Materials

2018 Model Aquatic Health Code Code Language Vis. Department of Codes for Disson Control for Disson Control

INTERLOCK CONTROLS

- Disable chemical feeders in case of "no flow" or "low flow" conditions
- Include visual alarm for new installations and replacement equipment



BATHER EVACUATIONS



- Evacuate bathers when interlock is activated or recirculation pump is off
- Do not permit bathers to re-enter the water until the cause is understood

CHALLENGE TESTING

- Test the system and its components regularly to confirm that all safety features are functioning correctly
- Record dates of challenge tests



BACKWASH SCHEDULING



- Schedule backwash when venue is closed to bathers
- Do not permit bathers to enter the water until the system's function is ensured

NOTIFICATION

 If injuries or illnesses occurred, notify appropriate authority (such as local environmental health) within 24 hours



MORE INFO AND NEXT STEPS

- MAHC website: https://www.cdc.gov/mahc/index.html
- Use and adapt the MAHC for science-based best practices
- Improve facility operations, codes, inspection procedures, & outreach